



# CREDERE ASSOCIATES, LLC

776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

October 29, 2021

Mr. Andrew Port  
Director of Planning & Development  
City of Newburyport  
60 Pleasant Street  
Newburyport, Massachusetts 01950

**Subject: Phase II Environmental Site Assessment, Rev 1  
Brown School - 42 Milk Street  
Newburyport, Massachusetts 01950**

Dear Mr. Port:

This report has been prepared to present the results of a Phase II Environmental Site Assessment completed for the above referenced property (the Site). Sections 6 and 7 of the report include the conclusions and recommendations generated during the performance of this Phase II Environmental Site Assessment.

Please do not hesitate to contact me at (207) 828-1272 extension 30 if you have any questions, comments, or require additional information regarding this investigation.

Sincerely,

CREDERE ASSOCIATES, LLC

Richard Vandenberg, PG, LG  
Senior Hydrogeologist/Project Manager





**CREDERE ASSOCIATES, LLC**

776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

# **Phase II Environmental Site Assessment, Rev 1**

**Brown School  
42 Milk Street  
Newburyport, Massachusetts**

*Prepared for:*  
**City of Newburyport  
60 Pleasant Street  
Newburyport, Massachusetts 01950**

**October 29, 2021**



*Project Tracking Number:*  
**21001628**



## EXECUTIVE SUMMARY

Credere Associates, LLC (Credere) was retained by the City of Newburyport, Massachusetts to conduct a Phase II Environmental Site Assessment (ESA) at the Brown School building located at 42 Milk Street in the City of Newburyport, Massachusetts (Site) to assess four previously identified environmental conditions and one other potential condition requested by the City. This work was completed in general conformance with the ASTM International (ASTM) E 1903-19 *Standard Practice for Environmental Site Assessments: Phase II Environmental Site Assessment Process*.

The 1.21-acre Site is situated within the residentially zoned area of the City. The land consists of two separate lots (Lot 26 and Lot 3). Lot 26 is improved with one approximate 37,000-square foot Site building, known as the Brown Elementary School, a paved parking area, paved recess area, and a play area. Lot 3 is improved with a paved basketball court and is part of the recess area. The Site is accessed from Milk Street to the north, Lime Street to the west, and Prospect Street to the south.

The above referenced four environmental conditions identified as part of the February 5, 2021, Phase I ESA are paraphrased below:

- Recognized Environmental Condition (REC) #2: Long history of storage of petroleum in underground storage tanks (USTs) and threat of release associated with the in-place tank,
- Environmental Finding (EF) #1: Presence of asbestos-containing materials (ACM) in/on the Site building,
- EF #2: Suspected presence of lead paint in/on the Site building, and
- EF #3: Suspected presence of polychlorinated biphenyl (PCB)-containing building materials in/on the Site building.

The following condition was also requested by the City to be included in the scope of work and assessed:

- Potential presence of mold

In August & September 2021, Credere completed the Phase II ESA scope of work with a focus on meeting the above-described objectives. Environmental sampling consisted of the collection of four soil samples and three groundwater samples from boring drilled adjacent to the existing out-of-service UST, 111 suspect asbestos-containing samples, 14 suspect PCB-containing building materials, lead paint survey, 21 air samples, and 6 tape lift samples.

Credere's conclusions considering the results of the Phase II ESA work include the following:

- Data collected indicates that the UST has not released petroleum to the soil and groundwater in proximity of the tank. In fact, neither collected soil or groundwater samples contained any concentrations of petroleum constituents above laboratory method detection





limits or applicable Massachusetts reportable concentrations outlined in 310 Code of Massachusetts Regulations (CMR) 40.0000. As such, it is Credere's opinion that there is low risk that any significant petroleum impacted media (soil or groundwater) is present onsite around the tank.

- ACM has been identified in numerous building materials that will require proper abatement in accordance 310 CMR 7.15 if these materials are planned to be impacted during future demolition or renovation activities. ACMs are listed in **Section 4.4** and include those identified during this assessment and those identified during previous Asbestos Hazard Emergency Response Act (AHERA) inspections. Based on the types of ACMs and asbestos containing waste material (ACWM) encountered and their locations, it is Credere's opinion that there is a strong likelihood that hidden ACM is also present within the building's walls on older pipe runs and fixtures that could not be assessed or quantified during this work without excessive destructive measures. Some of the ACM identified during this assessment, was identified to be damaged. Damaged ACM was identified in the boiler room on some of the fixtures there including pipe and joint insulation. As these materials are not accessible to the public, they are unlikely to pose an immediate danger to tenants within the building but should be repaired or abated when possible.
- Lead in paint is present on numerous surfaces throughout the Site building in the form of lead-containing paint (LCP) and lead-based paint (LBP). LBP was identified on numerous older finishes that appeared to be original to the Site building. Some of the identified LBP was noted to be deteriorated.
- PCBs are present in six (3 paint and 3 caulk samples) of the 14 materials sampled, that in Credere's opinion have an increased likelihood of containing these compounds, at concentrations greater than 1 mg/kg but less than 50 mg/kg. PCBs are present below 1 mg/kg in 4 other caulks sampled during this work. One sample (light yellow paint in the maintenance office – Room J-3) of the materials sampled is considered PCB bulk product waste in accordance with 40 Code of Federal Regulations (CFR) 761.3 because it contains PCB concentrations greater than 50 mg/kg. The federal Toxic Substance Control Act (TSCA) program considers materials meeting this classification to be excluded from use and requires proper management and disposal. The yellow paint covers an underlying brick structure in the maintenance office. PCBs are known to impact porous materials like brick. The brick was not sampled as a part of this assessment. Next steps will involve sampling the brick to determine if it has been impacted by the PCB-containing yellow paint. Further, while no other similar light-yellow painted surfaces were identified during this assessment, it is possible that this paint was used elsewhere in the building and is hidden behind sheetrock walls or other finishes, in more recently renovated areas.
- Aspergillus/Penicillium mold spores are present at five interior building locations at concentrations exceeding Site-specific calculated reference standards in accordance with International Institute for Building-Biology & Ecology, Inc., Healthy Home Standard, Conventional Construction guidance. The exceedances are coincident with areas of the building where water use/water related issues were observed by Credere staff. Additionally, during roof sampling work (for asbestos) the roofers retained indicated the





sheathing under roof was observed to be wet indicating a problem with parts of the roof system.

Based on the conclusions of this investigation, Credere makes the following recommendations:

- Abatement of ACM and ACWM, identified from this work and previous AHERA work, is only required in areas that will be impacted during future building renovation or demolition. Relative to undamaged ACM/ACWM, it is Credere's opinion, based on our understanding of the materials present and their current condition and the current use scenario of the building, that there is a low risk of exposure to these materials to the building occupants and transient users. We do recommend inventorying the ACM that were observed to be damaged (primarily in the boiler room) and repairing it. Review of prior work indicates that some ACM pipe wrap has been repaired in the past via application of 'dip lag' which is a re-wettable canvas wrapping material used to repair insulation on heat components. Any and all repairs or abatement should be completed in accordance with Massachusetts Department of Labor Standards 453 CMR 6.00: The Removal, Containment, or Encapsulation of Asbestos and Massachusetts DEP 310 CMR 7.15: Asbestos. If during renovations uncover any untested or hidden suspect materials, they should also be sampled and analyzed for asbestos or presumed positive and abated.
- For the identified deteriorated LBP observed during this work, Credere recommends that the loose and flaking painted finishes be scraped by an appropriately trained contractor and stabilized with a liquid stabilizing encapsulant. This will serve to reduce any lead dust in building and better protect current occupants of the building.

All painted surfaces should be considered to be LCP or LBP. Contractors performing future renovations or demolition involving these surfaces should employ proper health and safety practices and do proper worker notifications to prevent exposure to lead in paint. Proper measures should be taken by employers to protect worker health according to the US Occupational Safety and Health Administration (OSHA) lead in construction standards in 29 CFR 1926.62.

As an interim measure prior to addressing the deteriorated LBP or encapsulating the stable LCP/LBP, routine wet wipe cleaning of horizontal work surfaces in occupied portions of the building will reduce any lead dust that might accumulate in these areas. Painted finishes that are in deteriorated condition should not be impacted/wet wiped until appropriately scraped/stabilized by a lead contractor.

- PCB-containing light-yellow paint identified containing greater than 50 mg/kg PCBs in the maintenance room is required to be removed and disposed at a facility disposal at a facility that is licensed to accept this waste. Additional testing of the brick substrate is also required to assess if the brick has been impacted with PCBs. This work must be managed under specific requirements of the TSCA program in accordance with 40 CFR Part 761. If during renovations any untested or hidden suspect materials are encountered, they should also be sampled and analyzed for PCBs or presumed positive to allow for proper handling. Prior to addressing this paint, it is our opinion that the relative risk of exposure to most building





occupants or transient users is low as this paint is present in a low occupancy area of the building (i.e., Maintenance office). For the maintenance staff that use the office, Credere recommends relocating the office to another room in the building, posting a notice at the room entrances, and restricting access to the room.

- Comingled PCBs less than 50 mg/kg and LCP/LBP can be addressed in a similar to LCP/LBP. Any loose and flaking painted finished can be scrapped by an appropriately trained contractor and stabilized with a liquid stabilizing encapsulant. Any whole component removal will need to be disposed at a facility licensed to accept this waste material. Identified PCB caulk under 50 mg/kg can remain in service; however, once removed it will need to be disposed at a facility licensed to accept this waste material. The wet wipe cleaning of horizontal surfaces recommended above will reduce any PCB-containing dust that accumulates; thereby, reducing the risk of exposure.
- To address the identified mold, below general recommendations that should be undertaken in accordance with Massachusetts Department of Health and Industrial Hygiene Guidelines. Recommendations may be altered/eliminated based on changing Site conditions and should be adjusted to properly match the most appropriate mitigation procedure.
  - Eliminate the water intrusion issues to prevent future moisture infiltration (i.e., fix water leaks and address the noted water intrusion problem identified with the roof)
  - Retain a mold remediation company to remediate mold growth in the boiler room, gym/cafeteria, kitchen, and boy's and girl's locker rooms consistent with the general procedures listed below:
    - Repair/replace moisture-impacted contents and building materials
    - Properly dry wood crossbeams and wood supports, then wipe with a fungicide cleaning agent
    - Use wet cleaning methods to capture all mold-impacted dust
    - Perform confirmatory air sampling to document the efficacy of mold removal practices

Mold is difficult to give guidance on from an exposure perspective as it relates to continued use of the building or portions of the building that have been documented to exceed the calculated reference standard because sensitivities vary significantly amongst those that encounter it. Interim measures before stopping the water intrusion should include posting a visible notice at the doorways to affected rooms for building occupants/users along with dehumidification of rooms where mold in air exceeds its calculated reference standard.

Credere developed budgetary estimates by hazard type to manage/mitigate the identified environmental conditions. For asbestos and LCP/LBP, the first bullets below are items that could be implemented to stabilize the hazard and keep the building in use. For PCBs, light-yellow paint identified in maintenance office (Room J-3) cannot remain in service and must be remediated. Addressing water leaks and mold identified in the building is considered necessary to continue use of the building. Budgetary estimates are as follows:





### Asbestos

- Repair of damaged ACM, to make it safe, is estimated at \$5,500.
- Proper abatement of all identified ACM/ACWM is estimated to cost between \$125,000 and \$150,000

### LCP/LBP

- Stabilizing interior deteriorated LBP is estimated to cost \$38,600 to \$45,000. This assumes 2 weeks of labor. Depending on the number of actual locations that require scraping and encapsulation, the actual cost may be lower than presented above.
- Future encapsulation of LBP/LCP on all painted finishes is estimated to cost between \$136,000 to \$150,000. This does not account for the stabilization work above. If the LBP is stabilized first then this budgetary estimate would be lower.

### PCBs

- Remediation of the light-yellow paint in the maintenance office (Room J-3) PCBs is estimated to cost between \$15,000 to \$20,000. Required additional assessment of the brick substrate is estimated to cost \$3,500 and development of necessary TSCA documents prior to remediation is estimated at \$6,000.





## TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>ES-I</b>
<b>1. INTRODUCTION.....</b>	<b>1-1</b>
1.1 Purpose and Statement of Objectives .....	1-1
<b>2. BACKGROUND INFORMATION .....</b>	<b>2-1</b>
2.1 Site Description.....	2-1
2.2 Site History .....	2-1
2.3 Previous Environmental Investigations .....	2-1
2.4 Current Use & Redevelopment Scenario .....	2-5
<b>3. SCOPE OF WORK &amp; METHODOLOGY .....</b>	<b>3-1</b>
3.1 Soil Borings & Soil Sampling.....	3-1
3.2 Monitoring Well Installations and Well Development .....	3-2
3.3 Monitoring Well Survey & Well Gauging.....	3-2
3.4 Groundwater Sampling .....	3-3
3.5 Asbestos-Containing Materials .....	3-3
3.6 Lead Paint Survey and Lead In Soil Screening/Sampling .....	3-4
3.7 PCB-Containing Building Materials.....	3-4
3.8 Mold Investigation .....	3-4
<b>4. RESULTS .....</b>	<b>4-1</b>
4.1 Comparison Criteria.....	4-1
4.2 Soil Results .....	4-2
4.3 Groundwater Results.....	4-3
4.4 Asbestos Results .....	4-3
4.5 Lead Paint Results .....	4-4
4.6 PCB-Containing Building Material Results.....	4-4
4.7 Mold Sampling Results.....	4-5
4.8 Data Usability Assessment .....	4-5
<b>5. UPDATED CONCEPTUAL SITE MODEL .....</b>	<b>5-1</b>
5.1 Site Description.....	5-1
5.2 Site History .....	5-1
5.3 Physical Setting.....	5-1
5.4 Source Areas & Current Contaminants of Concern.....	5-2
5.5 Nature and Extent .....	5-2
5.6 Exposure Pathways and Potential Receptors .....	5-5
5.7 CSM Summary .....	5-6
<b>6. CONCLUSIONS .....</b>	<b>6-1</b>
<b>7. RECOMMENDATIONS &amp; BUDGETARY ESTIMATES .....</b>	<b>7-1</b>
<b>8. LIMITATIONS .....</b>	<b>8-1</b>
<b>9. SIGNATURES OF ENVIRONMENTAL PROFESSIONALS .....</b>	<b>9-1</b>





## TABLES

---

Table 1 .....	Sample Reference Table
Table 2 .....	Monitoring Well Construction Details and Groundwater Elevation
Table 3 .....	Summary of Soil Analytical Results
Table 4 .....	Summary of Groundwater Analytical Results
Table 5 .....	Asbestos Sample Summary and Results
Table 6 .....	PCB-Containing Building Materials Sample and Results Summary
Table 7 .....	Summary of Mold in Air Analytical Results

## FIGURES

---

Figure 1 .....	Site Location Plan
Figure 2 .....	Detailed Site Plan
Figure 3 .....	Groundwater Flow Map
Figure 4 .....	First Floor Sample Location Plan
Figure 5 .....	Second Floor Sample Location Plan
Figure 6 .....	Third Floor Sample Location Plan

## APPENDICES

---

Appendix A .....	Crederre's Proposal with Scope of Work
Appendix B .....	Phase II Photo Log
Appendix C .....	Boring Logs & Groundwater Sampling Logs
Appendix D .....	Sampling Credentials
Appendix E .....	Laboratory Analytical Reports
Appendix F .....	Data Usability Assessment



## 1. INTRODUCTION

Credere Associates, LLC (Credere) was retained by the City of Newburyport, Massachusetts to conduct a Phase II Environmental Site Assessment (ESA) at the Brown School building located at 42 Milk Street in the City of Newburyport, Massachusetts (Site) to assess four previously identified environmental conditions and one other potential condition requested by the City. Credere's Phase II ESA work was completed in general conformance with the ASTM International (ASTM) E 1903-19 *Standard Practice for Environmental Site Assessments: Phase II Environmental Site Assessment Process*.

### 1.1 PURPOSE AND STATEMENT OF OBJECTIVES

This section was developed to provide clarity and transparency in communicating and interpreting Phase II ESA results. The primary purpose of this Phase II ESA is to confirm or dismiss the findings and recognized environmental conditions (RECs) identified in Credere's February 5, 2021, Phase I ESA in support of redevelopment planning for the Site. The above referenced four environmental conditions identified as part of the February 5, 2021, Phase I ESA are paraphrased below:

- Recognized Environmental Condition (REC) #2: Long history of storage of petroleum in underground storage tanks (USTs) and threat of release associated with the in-place tank,
- Environmental Finding (EF) #1: Presence of asbestos-containing materials (ACM) in/on the Site building,
- EF #2: Suspected presence of lead paint in/on the Site building, and
- EF #3: Suspected presence of PCB-containing building materials in/on the Site building.

The following potential condition was not identified during the prior Phase I ESA, but was requested by the City of Newburyport to be included in the scope of work and to be assessed:

- Potential presence of mold

One other REC (identified as REC#1, residual petroleum impacted soil from a historical release) was identified during the prior Phase I ESA; however, Credere did not recommend assessing this potential condition during this Phase II ESA because it was previously addressed to the satisfaction of applicable Massachusetts Code of Massachusetts Regulations (CMR). For this reason, assessment of REC#1 was not included in Credere's August 4, 2021 proposal.





## **2. BACKGROUND INFORMATION**

### **2.1 SITE DESCRIPTION**

The 1.21-acre Site is situated within the residentially zoned area of the City. The land consists of two separate lots (Lot 26 and Lot 3). Lot 26 is improved with one approximate 37,000-square foot Site building, known as the Brown Elementary School, a paved parking area, paved recess area, and a play area. Lot 3 is improved with a paved basketball court and is part of the recess area. The Site is accessed from Milk Street to the north, Lime Street to the west, and Prospect Street to the south.

The electricity for the Site is currently provided from National Grid. Municipal water and wastewater service are provided by the City. Fuel for heating the Site building is No. 2 Fuel Oil that is stored in an on-site underground storage tank (UST). The heat system is pneumatically controlled forced hot water.

A Site Location Plan is provided as **Figure 1**, and a detailed Site plan is provided as **Figure 2**.

### **2.2 SITE HISTORY**

By 1890, both Site parcels were developed as part of a residential neighborhood with multiple dwellings. On Lot 3, a hot house (i.e., green house) had been constructed. In the early 1900s, the hot house was removed and a duplex was built in its place. In 1922, the City of Newburyport seized the dwellings on Lot 26 through eminent domain, and they were torn down. In 1923, the George W. Brown Elementary School was constructed. The original building was an elongated U-shape with the boiler room extending off the back. By 1961, the gymnasium complex was added southwest of the original building. By 1978, a second addition was constructed at the front of the school which infilled in the open space at the front of the building changing the front of the building to a square shape instead of a U-shape. By this time, the duplex dwelling on Lot 3 had also been acquired by the City and torn down. Eventually Lot 3 was paved over, and a basketball court was installed for use by children at recess. The Site has stayed in this configuration through to the present day.

By 1890, the surrounding area had been extensively developed as a residential neighborhood. This has stayed consistent through to current day.

### **2.3 PREVIOUS ENVIRONMENTAL INVESTIGATIONS**

#### **AHERA Asbestos Management Plan, 1988, Universal Engineering Corporation**

In 1988, an Initial Asbestos Inspection was performed at the Brown School to comply with the 1986 Asbestos Hazard Emergency Response Act (AHERA) amendment to the Toxic Substance Control Act which requires all school buildings be visually inspected and suspected materials be sampled or assumed to be asbestos-containing. It also requires a management plan to be created





and updated to provide the means and methods to effectively handle asbestos-containing building materials (ACBM).

The following ACBM were identified during the 1988 work:

- Floor Tile #1 (brown patterned linoleum)
- Boiler Insulation
- Tank Insulation (preformed)
- Pipe Insulation (paper type)
- Joint Insulation

The following materials were assumed to be asbestos-containing:

- Vinyl base board

The following non-asbestos materials were identified:

- Acoustical Tile #1
- Suspended Acoustical Tile #1
- Suspended Acoustical Tile #2
- Ceiling and Wall Plaster

It was estimated that 800 square feet (sf) and 907 linear feet (lf) of thermal system insulation ACM and 12,850 sf and 4,200 lf of miscellaneous ACM was located within the school.

### **AHERA 3-Year Re-Inspection Report, August 18, 1998, Smith & Wessel Associates, Inc.**

In 1998, a 3-Year Re-Inspection of the Brown School was performed to comply with AHERA. All the ACBM identified in the 1988 Initial Management Plan were reinspected, and twelve additional suspect ACBMs were identified and tested.

The following additional ACM were identified:

- Condensate sink mastic
- Mastic underlying brown baseboard molding
- Mastic underlying beige baseboard molding
- Duct insulation
- Mastic underlying 12" x 12" ceiling tiles
- Rolled paper pipe insulation

The following other materials were assumed to be ACM:

- Orange stair treads and associated mastic
- 9" x 9" floor tile and associates mastic
- Kiln insulation (removed)

The following additional non-asbestos materials were identified:

- Gypsum wallboard/joint compound wall system
- 12" x 12" tan speckled floor tile and associated mastic





- Brown cove base molding
- Tan cove base molding
- 12" x 12" ceiling tiles

### **Immediate Response Action Plan, May 2001, ENPRO Services, Inc.**

In May 2001, ENPRO Services Inc. (ENPRO) prepared an Immediate Response Action (IRA) Plan to address a release of No. 2 fuel oil to the boiler room floor that occurred over the weekend of March 24, 2001. It was estimated that approximately 40 gallons of No. 2 fuel oil was released from a gauge associated with one of the onsite boilers. Following the initial cleanup, it was assessed that soils below the concrete floor along the eastern wall were impacted as well as sediment in nearby catch basin in the room.

ENPRO personnel cored seven (7) holes through the concrete floor and collected samples. Analytical results indicated elevated concentrations of petroleum constituents, EPH/VPH fractions, in the oil-impacted areas which included below the floor adjacent extending to just outside the foundation wall.

Based on the Site conditions noted, the IRA Plan included following elements:

- Soil with TPH and/or EPH/VPH concentrations, which exceed applicable MCP cleanup standards should be excavated and field screened. When field screening indicates that soils exceeding applicable petroleum hydrocarbon cleanup standards have been excavated, confirmatory samples will be collected. Samples would be analyzed for TPH and/or EPH/VPH. All excavated soil would be transported off-site for proper disposal and/or recycling.
- If groundwater was encountered during soil removal, a water sample would be collected from the excavation and analyzed for TPH and/or EPH/VPH.
- Upon completion of the IRA, MCP-required reporting would be completed. If site conditions warranted, a Response Action Outcome Statement would be submitted, otherwise, an Immediate Response Action Completion Statement would be submitted. IRA Status Reports would also be submitted as required.

### **Class A-2 Response Action Outcome Statement and Immediate Response Action Completion Statement, November 2001, ENPRO Services, Inc.**

Throughout July and August 2001 ENPRO completed the activities detailed in the IRA Plan and excavated 83.95 tons of petroleum impacted soil from the Site. Based on results of laboratory analysis and the extent of response actions completed, a Class A-2 Response Action Outcome (RAO) was achieved indicating the following:

- Contamination concentrations in the areas of the Site impacted by the oil release were reduced to a condition of no significant risk of harm to health, public welfare, safety, and the environment.





- Concentrations of oil constituents were not reduced to background concentrations indicating that residual concentrations of oil are present at the Site.
- No AUL was required to be issued to maintain the condition of No Significant Risk.

It is Credere's opinion that based on how the cleanup verification sampling was conducted (some composite samples) and how the soil contamination was cleaned up (i.e.; under a slab and in and around the foundation), there is a high risk that some of these residuals may exceed applicable Massachusetts soil standards.

**AHERA 3-Year Re-Inspection Report, April 22, 2004, Smith & Wessel Associates, Inc.**

In 2004, a 3-Year Re-Inspection of the Brown School was performed to comply with AHERA. All the materials identified in the 1988 initial Management Plan and the 1998 3-Year Re-Inspection were reinspected. No additional materials were sampled or identified.

**AHERA 3-Year Re-Inspection Report, May 3, 2007, Smith & Wessel Associates, Inc.**

In 2007, a 3-Year Re-Inspection of the Brown School was performed to comply with AHERA. All the materials identified in the 1988 initial Management Plan, the 1998 and 2004 3-Year Re-Inspections were reinspected. No additional materials were sampled. During the re-inspection it was noted that the original linoleum was covered with plywood in Rooms 24, 30, 36, and 37.

**AHERA 3-Year Re-Inspection Report, August 26, 2010, Smith & Wessel Associates, Inc.**

In 2010 a 3-Year Re-Inspection of the Brown School was performed to comply with AHERA. All the materials identified in the 1988 initial Management Plan, the 1998, 2004, and 2007 3-Year Re-Inspections were reinspected. No additional materials were sampled. During the re-inspection it was noted that the kiln insulation, presumed to be ACM and previously located in the art room, was removed from the Site building.

**Phase I ESA, Credere, February 5, 2021**

Credere completed a Phase I ESA report for the Site, dated February 5, 2021, on behalf of the City of Newburyport. Based on a review of historical sources and environmental databases, interviews, User provided information, a Site reconnaissance, and judgement by the Environmental Professional, the following RECs were identified in connection with the Site:

- REC #1 – Residual petroleum impacted soil from a historical release
- REC #2 – Long history of storage of petroleum in USTs and threat of release associated with the current tank





- Environmental Finding #1 – Confirmed presence of asbestos-containing materials (ACM) in/on the Site building
- Environmental Finding #2 – Suspected presence of lead paint in/on the Site building
- Environmental Finding #3 – Suspected presence of polychlorinated biphenyl (PCB)-containing building materials in/on the Site building

## **2.4 CURRENT USE & REDEVELOPMENT SCENARIO**

At this time, the City is contemplating continued use of the first floor by the Newburyport Youth Services Department and planning the potential future reuse of upper floors for residential housing.





### 3. SCOPE OF WORK & METHODOLOGY

The following sampling program was developed to assess building materials and select environmental media at the Site and meet the objectives identified in **Section 1.1**. Sampling was conducted in accordance with Credere's August 4, 2021, Proposal for the Site, which is included in **Appendix A**. A sample reference table is included as **Table 1**. A photo log of field activities is included as **Appendix B**.

#### 3.1 SOIL BORINGS & SOIL SAMPLING

On August 31, 2021, Credere oversaw New England Geotech. (NEG) of Jamestown, Rhode Island advance soil borings CA-SB-1 through CA-SB-4. The borings were advanced using a Geoprobe 6600 truck mounted drilling rig with a direct push sampler. Soil cores were collected continuously using dedicated macrocore liners. The collected soil cores were individually logged, and any visual or olfactory evidence of contamination, if present, was noted. Collected soil was field screened for VOCs using a Thermo Environmental 580B PID equipped with a 10.6 eV lamp and calibrated to a 10 parts per million (ppm) isobutylene gas standard with a response factor of 1.0. Soil was screened in accordance with the Massachusetts jar headspace screening procedure. Boring logs are included in **Appendix C**.

Each direct push boring was advanced as planned to between 25 and 30 feet below ground surface (bgs) to assess if any release(s) have occurred associated with the integrity of the fuel oil UST at the Site as well as the long history of UST usage at the Site. This interval was anticipated to be at least 5 feet past the groundwater interface.

Borings CA-SB-1 through CA-SB-3 were finished as groundwater monitoring wells. A groundwater monitoring well was not installed at CA-SB-4 due to a lack of visual, olfactory, and field screen evidence of contamination and the inferred cross-gradient hydraulic position of this boring.

One (1) soil sample was collected CA-SB-1, CA-SB-2, CA-SB-3, and CA-SB-4 from 13-15 feet below ground surface (bgs). Collected samples were sent to Absolute Resource Associates of Portsmouth, New Hampshire, a Massachusetts certified laboratory, and analyzed for volatile petroleum hydrocarbons (VPH) and extractable petroleum hydrocarbons (EPH).

The 13-to-15-foot interval was chosen for analyses because it represented an interval that was situated below bottom of the current tank being assessed and one that corresponded to the bottom of the potentially accessible soil horizon as outlined in 310 CMR 40.0000 Massachusetts Contingency Plan (MCP). This was done because no significant visual, olfactory, or field screening evidence of petroleum impact was identified in any of the other intervals observed/screened during drilling. A summary of soil samples collected is included as **Table 3**.



### 3.2 MONITORING WELL INSTALLATIONS AND WELL DEVELOPMENT

Immediately following the drilling of each soil boring on August 31, 2021, monitoring wells CA-MW-1, CA-MW-2, and CA-MW-3 were installed at the corresponding soil boring location. Soil boring CA-SB-4 was intended for completion as a monitoring well but for the rationale presented above, a monitoring well was not installed within boring CA-SB-4.

Monitoring wells were constructed as follows:

- CA-MW-1 - 10-feet of 2-inch inside diameter 0.010-inch slotted PVC screen was installed from 17.5 to 27.5 feet bgs along with enough solid PVC riser pipe to reach the ground surface.
- CA-MW-2 and CA-MW-3 - 10-feet of 1-inch inside diameter, 0.010-inch slotted PVC was installed from 17 to 27 and 20 to 30 feet bgs, respectively along with enough solid PVC riser to reach the ground surface.

The annulus of each well was then filled with No. 2 silica sand from the bottom of the screened interval to 2 feet above the well screen. A 1-foot bentonite seal was then installed above each screen to prevent the intrusion of surface fluids. The wells were finished at the surface with a flush mount bolt-down road box in a concrete pad. A summary of well construction details is provided in **Table 2**, and well construction logs are provided in **Appendix C**.

The newly installed wells were developed by over-pumping and surging methods. All wells were developed until a minimum of three well volumes had been removed and turbidity had been reduced to less than 10 nephelometric turbidity units (NTUs) in accordance with Credere Standard Operating Procedure. Following the development work, monitoring wells were allowed to equilibrate with the surrounding groundwater for at least 7 days prior to sampling.

### 3.3 MONITORING WELL SURVEY & WELL GAUGING

On September 1, 2021, Credere conducted a relative elevation survey of the newly installed monitoring wells using the southernmost corner of the gymnasium addition as the benchmark with arbitrary elevation of 100 feet above mean sea level (AMSL). During the relative elevation survey, Credere measured the depth to groundwater in each monitoring well.

On September 9, 2021, static water levels in monitoring well CA-MW-1, CA-MW-2, and CA-MW-3 were gauged with an electronic interface tape capable of detecting the presence of groundwater and accumulations of free-floating hydrocarbons, if present.

The top of casing well elevation data derived during the stadia survey was used to calculate relative groundwater elevations for each monitoring well and determine a groundwater flow direction for the monitoring well network. Results of the elevation survey, well gauging measurements, and calculated groundwater elevations are summarized in **Table 2** and a Groundwater Contour Plan is included as **Figure 3**.





### 3.4 GROUNDWATER SAMPLING

On September 9, 2021, groundwater samples were collected from the newly installed monitoring wells CA-MW-1, CA-MW-2, and CA-MW-3. Groundwater samples were collected using low flow sampling methodology to minimize drawdown and provide representative groundwater samples. Groundwater was purged with a bladder pump using HDPE tubing. Purged groundwater was monitored continuously for temperature, pH, oxidation-reduction potential, specific conductivity, and dissolved oxygen (DO) using a multi-parameter meter and an in-line flow through cell. Turbidity was monitored separately using a turbidity meter. Readings were recorded at approximate five-minute intervals, or at a spacing to allow for a complete exchange of water through the flow through cell until parameters stabilized<sup>1</sup> over a period of three consecutive readings.

Groundwater samples were collected after stabilization at CA-MW-1, CA-MW-2 and CA-MW-3. Groundwater samples were collected in order of decreasing volatility (i.e., VPH, followed by EPH). Samples were collected by filling laboratory provided containers directly from the pump tubing. Samples were placed on ice and submitted to Alpha for laboratory analysis under proper chain-of-custody protocols. Samples were analyzed for VPH and EPH.

Groundwater sampling logs are provided in **Appendix C**. Monitoring well locations are depicted on **Figure 2**. A summary of groundwater samples collected is included as **Table 4**.

### 3.5 ASBESTOS-CONTAINING MATERIALS

Massachusetts licensed asbestos inspector, Ms. Moira Wentworth surveyed the Site building on August 24 and 25, 2021, to identify suspect asbestos-containing materials (ACM) that need to be properly managed during future renovation/demolition of the Site building. A photo log of sampled materials is included as **Appendix B** and Ms. Wentworth's credentials are included as **Appendix D**.

The sampling was performed in accordance with Massachusetts Department of Environmental Protection (Mass DEP) 310 CMR 7.15. Fifty-three (53) suspect ACMs were identified for the building (identified as CA-SACM-1 through CA-SACM-53). An adequate number<sup>2</sup> of samples from each suspect ACM were collected for a total of 111 ACM samples.

Collected asbestos samples were sent to EMSL Analytical, Inc. of South Portland, Maine, for analysis using polarized light microscopy (PLM) and PLM non-organically bound (NOB) methods. A summary of suspect ACM samples collected is included as **Table 5**. Sampling locations are depicted on **Figures 4, 5, and 6**.

<sup>1</sup> Stabilization criteria obtained from the U.S. EPA's *Low Stress (Low Flow) Purging and Sampling Procedure for the Collection of Groundwater Samples from Monitoring Wells*, Rev. September 19, 2017.

<sup>2</sup> Materials were sampled in triplicate with the exception of surfacing materials, which were sampled according to the 3-5-7 rule where the number of samples (3, 5, or 7) is determined by the square footage of the material throughout the building.





### 3.6 LEAD PAINT SURVEY AND LEAD IN SOIL SCREENING/SAMPLING

On August 25, 2021, a lead paint survey was performed by Credere subcontractor, ASAP Environmental Inc. (ASAP) of Dorchester, Massachusetts. ASAP is properly licensed in Massachusetts to perform this work. This was performed to identify lead in paint and identify if future renovation or demolition will need to take into account worker exposure and material disposal. This lead paint screening did not constitute a lead inspection or lead determination.

ASAP used a properly licensed and calibrated Viken Pb200i Handheld X-ray fluorescence (XRF) Lead Paint Analyzer to perform the lead screening. All unique interior and exterior painted surfaces were screened for the presence of lead-based paint. Sample locations are described ASAP's report which is attached in **Appendix E**.

### 3.7 PCB-CONTAINING BUILDING MATERIALS

On August 24 and 25, 2021, Credere surveyed the building to identify suspect PCB-containing building materials and determine if the building materials are regulated as PCB bulk product waste as defined by 40 CFR 761.3.

In all, fourteen (14) suspect PCB-containing building materials were identified as suspect PCB containing materials and sampled (CA-PCB-1 through CA-PCB-14). A summary of suspect PCB-containing building material samples collected is included as **Table 6**.

### 3.8 MOLD INVESTIGATION

#### *Visual Inspection*

On August 24 and 25, 2021, Credere conducted a visual inspection of the Site building for evidence of mold growth. Additionally, areas of obvious water damage were also noted during this visual investigation.

#### *Air Sampling*

On August 25, 2021, 21 air samples were collected for the analysis of mold from the following locations:

- Boiler room (1 sample),
- Gymnasium/cafeteria/kitchen 1961 addition (5 samples),
- First-floor 1923 original building (3 samples),
- First-floor 1978 infill addition (2 samples),
- Second-floor 1923 original building (4 samples),
- Second-floor 1978 infill addition (2 samples),
- Third-floor 1923 original building (2 samples),
- Third-floor 1978 infill addition (1 sample), and a
- Outside control (1 sample).





Air samples were collected using mechanical pumps with a calibrated flow rate of 15 liters per minute (L/min) and Allergenco-D air cassettes. The sample collected from the boiler room was only collected for 5 minutes due to high dust levels (75 liters of air). All other samples were collected for 10 minutes (150 liters of air).

Collected samples were sent to EMSL Analytical, Inc. of Cinnaminson, New Jersey (EMSL) for analysis of fungal spores by optical microscopy by MICRO-SOP-201, ASTM D7391.

### *Bulk Sampling*

During the August 25, 2021, air sample, Credere also collected six tape lift (bulk) samples of areas exhibiting visible mold growth including in the boiler room, boy's locker room, boy's locker room hallway, C-1 Entry, and T1-1 Bathroom. Tape lift kits consisting of tape attached to a microscope slide were used for sample collection. The tape was lifted from the microscope slide, placed atop the visible mold growth, pressed down firmly, lifted, and placed back atop the microscope slide and sealed in a laboratory-provided plastic container. The collected tape lift samples were also submitted to EMSL for analysis of fungal spores by direct microscope examination.





## **4. RESULTS**

The following subsections present the results of the data collected during the field work portion of the Phase II ESA.

### **4.1 COMPARISON CRITERIA**

Sample results were compared to the following applicable state and federal standards and/or guidelines.

#### **Soil**

Soil analytical results were compared to the MassDEP 310 CMR 40.00: MCP Method 1 S-1/GW-2 standards.

#### **Groundwater**

Groundwater analytical results were compared to the MassDEP 310 CMR 40.00: MCP Method 1 GW-2 and GW-3 standards.

#### **Asbestos-Containing Building Materials**

Laboratory analytical results for asbestos bulk samples were compared to the 1% limit specified in the Mass DEP 310 CMR 7.15: Asbestos Material with concentrations of asbestos greater than or equal to 1% are considered ACM and are required to be abated per Massachusetts 310 CMR 7.15 prior to future demolition or renovation of these materials.

A material is considered not to be asbestos-containing but is considered to be an asbestos-containing waste material (ACWM) if at least one of the samples collected contains less than one percent (<1%) asbestos. ACWMs are subject to the same handling, packing, labeling, and disposal requirements established in 310 CMR 7.15 Sections 15 through 18 for ACM.

#### **Lead Paint Survey**

Lead-based paint (LBP) is defined as paint with a lead concentration of 1.0 milligrams per square centimeter (mg/cm<sup>2</sup>) in accordance with applicable state regulations. Lead-containing paint (LCP) is defined as paint with any detectable level of lead. During any renovations that impact LBP and LCP, proper measures should be taken by employers to protect worker health according to the US Occupational Safety and Health Administration (OSHA) Lead in Construction Standards (29 CFR 1926.62). Paints with any detectable concentration of lead may also be regulated for proper disposal when out of use, and any renovation/demolition waste containing these paints should be properly characterized prior to disposal and disposed at an appropriate facility according to applicable Massachusetts disposal regulations.





### **PCB-Containing Building Materials**

PCB-containing building material analytical results were compared to the Toxic Substance Control Act (TSCA) Title 40 CFR Part 761.3 definition of PCB Bulk Product Waste threshold criteria ( $\geq 50$  milligrams per kilogram [mg/kg]). According to Part 761.20(a), materials with PCB concentrations  $\geq 50$  mg/kg require removal from use and proper disposal. Materials that contain PCB concentrations  $\leq 50$  mg/kg are not regulated by TSCA for removal as long as they remain in use. However, when these materials are removed from use (e.g., during renovation or demolition), they must be disposed at a facility that is licensed to accept this waste in accordance with 40 CFR §761.61(a)(5)(i)(B)(2)(ii). Building materials with total PCBs at concentrations less than 1 mg/kg are unrestricted for future use and/or disposal (40 CFR §761.61(a)(4)(i)(A)).

### **Mold**

The outside sample results were used as a baseline and results were used to establish a reference standard using the Healthy Home Standard, Conventional Construction, version 1.1 dated 2012 (HHS)<sup>3</sup>.

The sample results were compared to the established reference standard. Aspergillus/penicillium were compared to the detected outside air (OA) control sample concentration plus 800 count per cubic meter (count/m<sup>3</sup>) in accordance with the HHS. As no aspergillus/penicillium was detected in the OA control sample, the baseline criterion becomes 800 count/m<sup>3</sup> for the reference standard.

Outdoor spore types were compared to two times the OA control sample concentration and diverse spores were compared to the OA concentration plus 800. Tape lift sample are not compared to any standard because they are collected to only document the presence or absence of bulk mold on surfaces.

## **4.2 SOIL RESULTS**

Requested analysis and results are summarized in **Table 3**, and complete laboratory analytical reports are provided in **Appendix E**. Soil sample locations are shown on **Figure 2**.

### **Volatile Petroleum Hydrocarbons**

VPH compounds were not detected above laboratory reporting limits in any of the four soil samples collected during drilling of the borings.

### **Extractable Petroleum Hydrocarbons**

EPH compounds were not detected above laboratory reporting limits in any of the four soil samples collected during drilling of the borings.

---

<sup>3</sup> International Institute for Building-Biology & Ecology, Inc., *Healthy Home Standard, Conventional Construction*: version 1.1, dated 2012. Online access: <https://buildingbiologyinstitute.org/wp-content/uploads/2019/03/HHStandard2012.pdf>





### 4.3 GROUNDWATER RESULTS

Analytical results of the groundwater samples are summarized in **Table 4**, and the laboratory analytical reports are provided in **Appendix E**.

#### **Volatile Petroleum Hydrocarbons**

VPH compounds were not detected above laboratory reporting limits in any of the three groundwater samples collected from the installed monitoring wells.

#### **Extractable Petroleum Hydrocarbons**

EPH compounds were not detected above laboratory reporting limits in any of the three groundwater samples collected from the installed monitoring wells.

### 4.4 ASBESTOS RESULTS

Requested analysis and results are summarized in **Table 5**, and complete laboratory analytical reports are provided in **Appendix E**. An outline of the Site building showing locations of sampled materials from floors 1, 2 and 3 are included in **Figures 4, 5, & 6**, respectively.

Laboratory results indicate that the following 12 materials are contain asbestos above the 1% threshold and are considered ACM.

- CA-SACM-04, tan caulk
- CA-SACM-14, brown stair tread mastic
- CA-SACM-18, tan 9" floor tile
- CA-SACM-24, Gray glazing – 1923 original windows
- CA-SACM-25, white caulk – 1923 original windows
- CA-SACM-27, black mastic
- CA-SACM-38, pink sink coat
- CA-SACM-42, light gray caulk – 1923 original windows (below material CA-SACM-25)
- CA-SACM-45, white caulk – gymnasium addition doors
- CA-SACM-46, white caulk – gymnasium addition window
- CA-SACM-47, light gray glazing compound – gymnasium addition
- CA-SACM-48, orange linoleum

Laboratory results indicate that the following material contains asbestos and is considered ACWM.

- CA-SACM-19, layered paper pipe insulation



## 4.5 LEAD PAINT RESULTS

Results indicate that LCP and LBP are present throughout the interior and exterior of the Site building. LBP was identified on numerous finishes that appeared to be original to the 1923 Site building, particularly windows. Some of the identified LBP is in deteriorated condition and has been indicated by the Lead Inspector in their report. A summary of each lead XRF screening and sampling location and the corresponding concentration of lead is provided in ASAP's report which is attached in **Appendix E**. The ASAP report describes where deteriorated lead paint was identified.

## 4.6 PCB-CONTAINING BUILDING MATERIAL RESULTS

Laboratory results indicate that in the following materials contained detectable concentrations of PCBs above 50 mg/kg and are considered PCB Bulk Product Waste under TSCA:

- CA-PCB-3 – Paint, light yellow (Room J-3 walls)

Laboratory results indicate that in the following materials contained detectable concentrations of PCBs above 1 mg/kg but below 50 mg/kg:

- CA-PCB-1 – Paint, gray over light blue (Boiler Room)
- CA-PCB-2 – Paint, gray (Boiler Room)
- CA-PCB-7 – Caulk, white (Exterior of 1923 original windows)
- CA-PCB-8 – Caulk, light gray (Exterior of 1923 original windows)
- CA-PCB-DUP1 – Caulk, gray, material is a duplicate sample of CA-PCB-10 (1978 Addition to 1923 original building seam)
- CA-PCB-13 – Paint, green (Boiler Room)

Laboratory results for following two materials were found to have a reporting limit that exceeded regulatory criteria due to matrix interference. These materials are considered to contain PCBs above 1 mg/kg but below 50 mg/kg.

- CA-PCB-11 – Caulk, white (Gymnasium doors)
- CA-PCB-12 – Caulk, white (Gymnasium windows)

Laboratory results indicated that in the following materials contained concentrations of PCBs below 1 mg/kg:

- CA-PCB-4 – Caulk, dark gray (1978 addition windows)
- CA-PCB-5 – Caulk, red/brown (1978 addition windows)
- CA-PCB-9 – Caulk, white (1923 original foundation)





Laboratory results are tabulated in **Table 6** and a copy of the laboratory analytical report is attached in **Appendix E**.

#### 4.7 MOLD SAMPLING RESULTS

Numerous varieties of mold spores were detected in the collected air samples analyzed at the laboratory, including the common mold spore type aspergillus/penicillium which generally indicated water issues along with Alternaria, Ascospores, Basidiospores, Cladosporium, Ganoderma, Myxomycetes, Pithomyces, Cercospora, and Polythrincium.

The results were compared to the calculated Reference Standard defined in **Section 4.1**. Based on this analysis, only aspergillus/penicillium exceeded calculated Reference Standard in the following samples:

- CA-AIR-1 – Boiler Room
- CA-AIR-3 – Gymnasium/Cafeteria
- CA-AIR-4 – Kitchen (Room K-1)
- CA-AIR-5 – Boys Locker Room (Room BL-1)
- CA-AIR-21 – Girls Locker Room (Room GL-1)

Laboratory results of the tape lifts (i.e. bulk) collected from locations described in **Section 3.8** were negative for all mold spores.

Mold in air results are tabulated in **Table 7** and a copy of the laboratory report is attached in **Appendix E**.

#### 4.8 DATA USABILITY ASSESSMENT

The contracted laboratory, ARA, provided soil and groundwater analytical data in general accordance with Credere's Generic Quality Assurance Project Plan (QAPP, RFA#14069). ARA provided the following information in analytical reports:

- Data results sheets
- Method blank results
- Surrogate recoveries and acceptance limits
- Duplicate results/acceptance limits
- Spike/duplicate results/acceptance limits
- Laboratory control sample (LCS) results
- Description of analytical methods and results
- Other pertinent results/limits as deemed appropriate



In accordance with Sections 310 CMR 40.0017 and 310 CMR 40.0191 of the MCP, a Data Usability Assessment is required to formally document that data is scientifically valid and defensible, and of a sufficient level of precision and accuracy and completeness to support “Presumptive Certainty”. Pursuant to 310 CMR 40.0191 of the MCP, the analytical data used to support this report was reviewed utilizing procedures outlined in MassDEP’s *Compendium of Quality Assurance/Quality Control (QA/QC) Requirements and Performance Standards for Selected Analytical Methods* (CAM) (WSC-02-320, July 1, 2010). In addition, the data utilized and relied upon in this report was evaluated per the guidance set forth by MassDEP *WSC Policy #07-350 MCP Representativeness Evaluations and Data Usability Assessments of September 19, 2007*.

The laboratory reports for all sampling events during this reporting period met Presumptive Certainty with limited exception to Question G that are acceptably covered in the case narrative. These reports were reviewed for usability and determined acceptable for use in the risk characterization. Possible data usability issues with a potential to affect data quality as outlined in the laboratory case narratives were review. While multiple methodology notations were outlined, with some minor effects resulting in J qualification, no major issues were reported that would make the data unusable. No QA/QC issues were reported by the laboratory or resulting from field operations that will affect data usability for MCP decision-making. No data were discarded/rejected due to QA/QC issues. The full data useability assessment is provided in **Appendix F**.





## 5. UPDATED CONCEPTUAL SITE MODEL

The conceptual site model (CSM) was updated using the results of this Phase II ESA and any pertinent prior reports. This CSM includes a description of the Site, Site history, physical setting of the Site, source areas and contaminants of potential concern (COPCs), nature and extent of contamination, exposure pathways, and potential human and environmental receptors.

### 5.1 SITE DESCRIPTION

A detailed Site description consisting of Site use, Site location as depicted on **Figure 1**, and Site utilities is included in **Section 2.1**.

### 5.2 SITE HISTORY

A description of Site history including historical information as it relates to current environmental conditions at the Site is included in **Section 2.2**.

### 5.3 PHYSICAL SETTING

#### Topography

According to the United States Geological Survey (USGS) topographic map of the Newburyport East Quadrangle, Massachusetts, topography at the Site slopes slightly to the north/northeast towards the Merrimack River. The Site is approximately 35 feet above mean sea level. A Site Location Plan with topographic contours has been included as **Figure 1**.

#### Geology

##### *Surficial Geology*

Site soils on the Site are mapped as Merrimack soils, which typically consist of somewhat excessively draining, fine sandy loam with high infiltration rates. Recent drilling activities indicate the subsurface materials below the upper soil horizon and asphalt consists of sand textured deposits ranging from fine to very fine sand with little silt.

##### *Bedrock Geology*

According to the USGS Bedrock Geologic Map of Massachusetts, the Site is underlain by the Silurian or Ordovician-aged Newburyport Complex, which is comprised of gray, medium grained tonalite and granodiorite. No bedrock outcrops are known to exist at the Site.

#### Hydrology

The Site is located within the surficial drainage basin of the Merrimack River, located approximately 1,800 feet northeast of the Site. The Merrimack River flows east 2.5 miles before entering the Atlantic Ocean.





Stormwater likely infiltrates the permeable non-paved portions of the Site. Several storm drains were observed at the Site. Stormwater likely flows over impermeable surfaces to permeable surfaces or to nearby storm drains.

Depth to groundwater ranges between 24.75 and 24.79 feet bgs. No free-floating hydrocarbons were identified during the groundwater water gauging event. Previous review of mapped topography and the location of the nearest surface water body, groundwater in the area of the Site was presumed to flow to the north/northeast toward the Merrimack River. Recent groundwater gauging performed at the Site indicates that groundwater in the area of the UST flows to the southwest along a relatively flat hydraulic gradient.

#### **5.4 SOURCE AREAS & CURRENT CONTAMINANTS OF CONCERN**

Based on the cumulative results of prior investigations and this Limited Phase II ESA, the current source areas and COPCs are listed below.

##### **Source Areas**

The following source areas were identified at the Site based on the Site history and the results of this Phase II ESA:

- Site building components

##### **COPCs**

Based on the above source areas, associated current COPCs that exceed applicable comparison criteria at the Site include the following:

- Asbestos-containing materials
- LBP & LCP
- PCB-Containing Materials
- Mold

#### **5.5 NATURE AND EXTENT**

The inferred extent of COPCs based on currently available data is as follows:

##### **Asbestos-Containing Materials**

Asbestos was identified in 11 materials within the building. The following materials and estimate quantities of ACM are present at the Site:

- 34 sf linear feet of tan caulk from around a door frame in Rooms C-5, C-7
- 250 sf square feet of brown stair tread mastic found below the orange stair treads in both Stair 1 & Stair 2
- 1,200 sf of tan 9" floor tile found in Rooms C-1, K-1. C-2





- 101 of the 1923 original windows that still remain in the original portion of the building which contain gray window glazing, white repair caulk, and then the original light gray caulk found below
- 1,600 sf of black mastic found in rooms C1-1, C1-2, C1-3, C2-1, C2-2, and C2-3 (second and third floor central hallways)
- 2 each of pink sink coat found in Rooms 13 and A2-1
- 36 lf of white caulk found around the 1961 gymnasium addition doors on C side of the building
- 75 lf of white caulk found around the 1961 gymnasium addition windows
- 4 of the 1961 gymnasium addition windows with light gray glazing compound
- 78 sf of orange linoleum located in Room M1-1

In addition, the following additional materials were identified as asbestos-containing, as part of prior AHERA Inspections performed at the Site (documented in **Section 2.3**):

- 44 joint insulations (also known as mud fittings) identified in the boiler room as well as rooms J-2, T-5, T-4, GL-1, T-2, S-3, 21, 20, 22, T1-1, 24, 33, 32, 34, 35, 36, 37, and anticipated to be throughout the school. An insulated joint in the boiler room was noted to be damaged.
- 100 lf of Aircel pipe insulation found in the boiler room, this material is also assumed to be located throughout the school
- 137 sf of tank insulation in the boiler room; this material was noted to have been damaged in the past and repaired.
- 184 sf of duct insulation in the boiler room
- 250 sf of duct insulation above the stage
- 4,071 SF of brown patterned linoleum sheeting found in rooms C-5, J-2, C-6, C-7, stair 1, C-1 Stair 2, 23, D1-2, D1-3, 32, 35, A2-1, C-8, 11A, 12A, and 13
- 300 SF of brown mastic associated with 12" ceiling tiles in Room C-2

One previously identified ACM, a brown mastic on the second floor was unable to be identified during this inspection. A second previously identified ACM, white pipe insulation associated with the kitchen was unable to be observed during this inspection and is assumed to be located within the block walls.

The following material was identified as a ACWM within the building and estimate quantities of ACM are present at the Site:

- An unknown quantity of layered paper pipe insulation. This material was identified as existing on shower water pipes within the hollow block walls of the girl's locker room (Room GL-1). This material is assumed to be within the walls of the boy's locker room





(Room BL-1), the kitchen (Room K-1), bathrooms (Rooms T-1 and T-2), and any other area with water service in building additions from the same time period (1961).

ACM was not identified in other sampled Site building materials; however, additional suspect ACM located behind walls or beneath floors, if present, will require sampling as renovation and/or demolition occurs.

### **PCBs**

Building materials, containing PCBs at concentrations greater than 1 mg/kg were identified in the Brown School. The following materials were identified to contain PCBs greater than 1 mg/kg in the Site buildings. Bolded materials contain PCB concentrations exceeding 50 mg/kg and are considered bulk product waste in accordance with TSCA 40 CFR Part 761.3 and is excluded from use and must be removed:

- Gray paint over light blue – Boiler Room lower walls
- Gray paint – Boiler Room upper walls
- **Light yellow paint – Room J-3 walls (Bulk Product Waste)**
- White caulk – Exterior 1923 original windows to brick walls
- Light gray caulk – Exterior 1923 original windows to brick walls (this material is located directly below the preceding material)
- Gray caulk – 1978 infill addition to original brick building seam
- White caulk – surrounding 1961 gymnasium addition exterior doors to brick walls
- White caulk – surrounding 1961 gymnasium addition exterior windows to brick walls
- Green paint – Boiler room floor

Light yellow paint determined to be PCB bulk product waste may be present in other hidden locations in the 1923 original portion of the building.

### **Lead in Paint**

The majority of painted surfaces within/on the Site building were identified to contain concentrations of lead greater than 0.0 milligrams per square centimeter (mg/cm<sup>2</sup>). The painted surfaces that are original to the Site building, specifically original windows and some door components and walls, would be classified as LBP in a residential or child-occupied use scenario due to the concentration of lead detected greater than 1 mg/cm<sup>2</sup>. These painted surfaces contained the highest concentrations of lead within the Site building and some were observed to be in a deteriorated condition.

### **Mold**

The visual inspection identified evidence of mold in the Boiler Room, Boy's Locker room (Room BL-1), Boy's Locker room hallway (Room C-3), C-1 Entry, and T1-1 Bathroom; however,



laboratory results of air sample indicate the presence of *Aspergillus*/*Penicillium* in air in the following locations: Boiler Room, Gym/Cafeteria, Kitchen (K-1), Boy's Locker Room (BL-1), and Girls Locker Room.

These air results indicate an interior fungal spore reservoir exists of *aspergillus/penicillium*. *Aspergillus/penicillium* is the most common mold genera found indoors and is considered to be a water-damage indicator type mold. This is consistent with the visually identified water damage in the rooms where elevated mold concentrations were identified and with the information provided by the roofing contractor who facilitated portions of the asbestos work who noted moisture in the roofing material layers when test cuts were made.

While air samples are good indicators of mold spore/mold types/mold growth, it should be noted that different mold types are active at different times throughout the day as well as on a seasonal basis. Current and recent weather conditions affect overall mold spore types and concentrations. Therefore, samples collected indicate activity only at the date/time of sampling.

## 5.6 EXPOSURE PATHWAYS AND POTENTIAL RECEPTORS

Exposure pathways describe how a human or environmental receptor comes into contact with contaminants that may be present at the Site. Potential migration pathways through ground water, standing water, air, soils, sediments, and biota were considered for each COPC and each source. A migration pathway is considered an exposure pathway if there is a mechanism of contaminant release from primary or secondary sources, a transport medium, and a point of potential contact with a receptor. Both current and potential future releases and migration pathways to receptors are considered. Exposure pathways presented in the CSM include the following:

Incidental Uptake:	This pathway is applicable when receptors may incidentally inhale or ingest impacted media in the form of contaminated dust, chips, or airborne asbestos fibers.
-----------------------	--

Potential Receptors are categorized by duration of exposure and intensity of use at the Site. Based on the proposed redevelopment of the Site, the receptor categories described in the CSM include the following:

Resident:	The residential receptor is defined by high durational exposure and high intensity usage that may occur through gardening, digging, and recreational sports. This group includes the occupants of a residential property or a residential neighborhood, or a daycare.
Park User:	Park users are characterized by low duration, i.e. less than two hours per day, and low intensity usage such as that which would occur during activities such as walking, shopping, and bird watching. This scenario assumes exposure to children and adults.
Commercial Workers:	Commercial receptors are those which are present at the Site for long durations but with low intensity exposure such as indoor office workers.



Excavation or Construction Worker:      Excavation or construction workers are present at the Site for short durations though intensity of use is high, such as during non-routine activities including construction or utility work. Examples include utility and construction contractors and landscapers.

## 5.7 CSM SUMMARY

COPCs at the Site include ACM, lead in paint, PCBs in building materials, and mold in/on the Site building. Based on the current use of the building and planned renovations, receptors at the Site would include current occupants of the building, future construction workers during redevelopment, and employees and facility maintenance (i.e., commercial workers). Exposure pathways for all receptors to COPCs include incidental uptake through contact with identified asbestos containing materials in the air, lead-impacted dust from painted surfaces, PCB-impacted dust from identified materials, and inhalation of mold spores in the air.





## 6. CONCLUSIONS

Credere has performed a Phase II ESA at the Brown School building located at 42 Milk Street in Newburyport, Massachusetts, the property, in conformance with the scope and limitations of ASTM E 1903-19, to assess the environmental conditions outlined in **Section 1.1** of this report. Credere's conclusions considering the cumulative work are as follows:

- Data collected indicates that the UST has not released petroleum to the soil and groundwater in proximity of the tank. In fact, neither collected soil or groundwater samples contained any concentrations of petroleum constituents above laboratory method detection limits or applicable Massachusetts reportable concentrations outlined in 310 Code of Massachusetts Regulations (CMR) 40.0000. As such, it is Credere's opinion that there is low risk that any significant petroleum impacted media (soil or groundwater) is present onsite around the tank.
- ACM has been identified in numerous building materials that will require proper abatement in accordance 310 CMR 7.15 if these materials are planned to be impacted during future demolition or renovation activities. ACMs are listed in **Section 4.4** and include those identified during this assessment and those identified during previous AHERA inspections. Based on the types of ACMs and ACWM encountered and their locations, it is Credere's opinion that there is a strong likelihood that hidden ACM is also present within the building's walls on older pipe runs and fixtures that could not be assessed or quantified during this work without excessive destructive measures. Some of the ACM identified during this assessment, was identified to be damaged. Damaged ACM was identified in the boiler room on some of the fixtures there including pipe and joint insulation. As these materials are not accessible to the public, they are unlikely to pose an immediate danger to tenants within the building but should be repaired or abated when possible.
- Lead in paint is present on numerous surfaces throughout the Site building in the form of LCP and LBP. LBP was identified on numerous older finishes that appeared to be original to the Site building. Some of the identified LBP was noted to be deteriorated.
- PCBs are present in six (3 paint and 3 caulk samples) of the 14 materials sampled, that in Credere's opinion have an increased likelihood of containing these compounds, at concentrations greater than 1 mg/kg but less than 50 mg/kg. PCBs are present below 1 mg/kg in 4 other caulks sampled during this work. One sample (light yellow paint in the maintenance office – Room J-3) of the materials sampled is considered PCB bulk product waste in accordance with 40 CFR 761.3 because it contains PCB concentrations greater than 50 mg/kg. The federal TSCA program considers materials meeting this classification to be excluded from use and requires proper management and disposal. The yellow paint covers an underlying brick structure in the maintenance office. PCBs are known to impact porous materials like brick. The brick was not sampled as a part of this assessment. Next steps will involve sampling the brick to determine if it has been impacted by the PCB-containing yellow paint. Further, while no other similar light-yellow painted surfaces were identified during this assessment, it is possible that this paint was used elsewhere in the building and is hidden behind sheetrock walls or other finishes, in more recently renovated areas.





- Aspergillus/Penicillium mold spores are present at five interior building locations at concentrations exceeding Site-specific calculated reference standards in accordance with International Institute for Building-Biology & Ecology, Inc., Healthy Home Standard, Conventional Construction guidance. The exceedances are coincident with areas of the building where water use/water related issues were observed by Credere staff. Additionally, during roof sampling work (for asbestos) the roofers retained indicated the sheathing under roof was observed to be wet indicating a problem with parts of the roof system.



## 7. RECOMMENDATIONS & BUDGETARY ESTIMATES

Based on the findings and conclusions of this assessment and prior work, Credere makes the following recommendations:

- Abatement of ACM and ACWM, identified from this work and previous AHERA work, is only required in areas that will be impacted during future building renovation or demolition. Relative to undamaged ACM/ACWM, it is Credere's opinion, based on our understanding of the materials present and their current condition and the current use scenario of the building, that there is a low risk of exposure to these materials to the building occupants and transient users. We do recommend inventorying the ACM that were observed to be damaged (primarily in the boiler room) and repairing it. Review of prior work indicates that some ACM pipe wrap has been repaired in the past via application of 'dip lag' which is a re-wettable canvas wrapping material used to repair insulation on heat components. Any and all repairs or abatement should be completed in accordance with Massachusetts Department of Labor Standards 453 CMR 6.00: The Removal, Containment, or Encapsulation of Asbestos and Massachusetts DEP 310 CMR 7.15: Asbestos. If during renovations uncover any untested or hidden suspect materials, they should also be sampled and analyzed for asbestos or presumed positive and abated.
- For the identified deteriorated LBP observed during this work, Credere recommends that the loose and flaking painted finishes be scraped by an appropriately trained contractor and stabilized with a liquid stabilizing encapsulant. This will serve to reduce any lead dust in building and better protect current occupants of the building.

All painted surfaces should be considered to be LCP or LBP. Contractors performing future renovations or demolition involving these surfaces should employ proper health and safety practices and do proper worker notifications to prevent exposure to lead in paint. Proper measures should be taken by employers to protect worker health according to the US Occupational Safety and Health Administration (OSHA) lead in construction standards in 29 CFR 1926.62.

As an interim measure prior to addressing the deteriorated LBP or encapsulating the stable LCP/LBP, routine wet wipe cleaning of horizontal work surfaces in occupied portions of the building will reduce any lead dust that might accumulate in these areas. Painted finishes that are in deteriorated condition should not be impacted/wet wiped until appropriately scraped/stabilized by a lead contractor.

- PCB-containing light-yellow paint identified containing greater than 50 mg/kg PCBs in the maintenance room is required to be removed and disposed at a facility disposal at a facility that is licensed to accept this waste. Additional testing of the brick substrate is also required to assess if the brick has been impacted with PCBs. This work must be managed under specific requirements of the TSCA program in accordance with 40 CFR Part 761. If during renovations any untested or hidden suspect materials are encountered, they should also be sampled and analyzed for PCBs or presumed positive to allow for proper handling. Prior to addressing this paint, it is our opinion that the relative risk of exposure to most building





occupants or transient users is low as this paint is present in a low occupancy area of the building (i.e., Maintenance office). For the maintenance staff that use the office, Credere recommends relocating the office to another room in the building, posting a notice at the room entrances, and restricting access to the room.

- Comingled PCBs less than 50 mg/kg and LCP/LBP can be addressed in a similar to LCP/LBP. Any loose and flaking painted finished can be scraped by an appropriately trained contractor and stabilized with a liquid stabilizing encapsulant. Any whole component removal will need to be disposed at a facility licensed to accept this waste material. Identified PCB caulk under 50 mg/kg can remain in service; however, once removed it will need to be disposed at a facility licensed to accept this waste material. The wet wipe cleaning of horizontal surfaces recommended above will reduce any PCB-containing dust that accumulates; thereby, reducing the risk of exposure.
- To address the identified mold, below general recommendations that should be undertaken in accordance with Massachusetts Department of Health and Industrial Hygiene Guidelines. Recommendations may be altered/eliminated based on changing Site conditions and should be adjusted to properly match the most appropriate mitigation procedure.
  - Eliminate the water intrusion issues to prevent future moisture infiltration (i.e., fix water leaks and address the noted water intrusion problem identified with the roof)
  - Retain a mold remediation company to remediate mold growth in the boiler room, gym/cafeteria, kitchen, and boy's and girl's locker rooms consistent with the general procedures listed below:
    - Repair/replace moisture-impacted contents and building materials
    - Properly dry wood crossbeams and wood supports, then wipe with a fungicide cleaning agent
    - Use wet cleaning methods to capture all mold-impacted dust
    - Perform confirmatory air sampling to document the efficacy of mold removal practices

Mold is difficult to give guidance on from an exposure perspective as it relates to continued use of the building or portions of the building that have been documented to exceed the calculated reference standard because sensitivities vary significantly amongst those that encounter it. Interim measures before stopping the water intrusion should include posting a visible notice at the doorways to affected rooms for building occupants/users along with dehumidification of rooms where mold in air exceeds its calculated reference standard.

Credere developed budgetary estimates by hazard type to manage/mitigate the identified environmental conditions. For asbestos and LCP/LBP, the first bullets below are items that could be implemented to stabilize the hazard and keep the building in use. For PCBs, light-yellow paint identified in maintenance office (Room J-3) cannot remain in service and must be remediated. Addressing water leaks and mold identified in the building is considered necessary to continue use of the building. Budgetary estimates are as follows:



### Asbestos

- Repair of damaged ACM, to make it safe, is estimated at \$5,500.
- Proper abatement of all identified ACM/ACWM is estimated to cost between \$125,000 and \$150,000

### LCP/LBP

- Stabilizing interior deteriorated LBP is estimated to cost \$38,600 to \$45,000. This assumes 2 weeks of labor. Depending on the number of actual locations that require scraping and encapsulation, the actual cost may be lower than presented above.
- Future encapsulation of LBP/LCP on all painted finishes is estimated to cost between \$136,000 to \$150,000. This does not account for the stabilization work above. If the LBP is stabilized first then this budgetary estimate would be lower.

### PCBs

- Remediation of the light-yellow paint in the maintenance office (Room J-3) PCBs is estimated to cost between \$15,000 to \$20,000. Required additional assessment of the brick substrate is estimated to cost \$3,500 and development of necessary TSCA documents prior to remediation is estimated at \$6,000.
- While not required, the non-TSCA PCBs would be remediated along with the encapsulation of LBP/LCP of all painted finishes so no budgetary costs are presented for this hazard.

### Mold

- The costs to abate the known issues related the observed mold is as follows:
  - Water leak evaluation/repairs could range between \$8,000 to \$12,000. This budgetary cost only accounts anticipated water leaks within walls or floors. If roof repairs are needed this number will increase.
  - Remediation of the identified mold issues is estimated to range between \$30,000 to \$40,000. This assumes that limited mold is hidden behind walls and floors.





## 8. LIMITATIONS

This report has been prepared by Credere for the City of Newburyport to provide the City or other project stakeholders with information upon which it can rely concerning the existence or likely existence of various environmental contaminants on or adjacent to the property evaluated.

This report does not reflect:

1. Conditions in untested areas and the characteristics of untested media.
2. Variations in chemical concentrations that can occur between sample locations.
3. The total understanding of historical Site activities, uses, equipment, or fixtures that may have contributed or are currently contributing to Site contamination, particularly relating to building material history.
4. Knowledge of the potential presence of compound sources other than what was surficially visible at the time of survey performance.
5. The potential presence of analytes that were not analyzed or that may be present below minimum Laboratory Reporting Limits for the methods tested.
6. Potential variation in the Site conditions that may have occurred at a time other than when the Site survey was completed.

In the event that any conditions different from those described herein are encountered at a later time, Credere requests an opportunity to review such differences and modify the assessment and conclusions of this report. This report was prepared expressly for the purpose described. The information in this report may not be suitable for any other use without adaptation for the specific purpose intended. Any such reuse of this report, without adaptation, shall be at the sole risk and liability of the party undertaking the reuse.

The ACM survey portion of this project was completed in accordance with relevant, applicable, and appropriate standards and was performed by exercising the degree of care and skill ordinarily exercised by a duly qualified or Certified Asbestos Inspector. However, there is a possibility that hidden, inaccessible, or otherwise unassessed ACM may exist at the Site. If suspect ACM is identified during any future Site operations including maintenance, renovations, housekeeping, or general demolition, the party performing these activities should first refer to this report. If conclusive results cannot be obtained, additional sampling and analysis must be conducted by a duly qualified or Certified Asbestos Inspector prior to the initiation of any activities that may impact or in any way disturb potential unassessed ACM.


The lead paint screening was not intended to determine the suitability of the buildings for residential or child-occupied uses, or to assess the risk associated with lead paint on the Site.






## 9. SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

The following individual(s) meet the qualifications for individuals completing or overseeing all appropriate inquiries, and possess sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding the existence of environmental conditions on the Site. Any work completed on this ESA by an individual who is not considered an environmental professional was completed under the supervision or responsible charge of the environmental professional.

  
Moira Wentworth  
Environmental Specialist/Geologist I  
Massachusetts Asbestos Inspector

  
Rick Vandenberg, LG, PG  
Project Manager/Senior Geologist

  
Rip Patten, PE  
Vice President



## FIGURES







Copyright:© 2013 National Geographic Society, I-

DRAWN BY: MAW

DATE: 10/15/2021

CHECKED BY: RSV

PROJECT: 21001628




**Credere Associates, LLC**

776 MAIN STREET  
WESTBROOK, MAINE  
Tel. 207.828.1272  
Fax 207.887.1051  
WWW.CREDERELLC.COM

## FIGURE 1 SITE LOCATION PLAN

BROWN SCHOOL  
42 MILK STREET  
NEWBURYPORT, MASSACHUSETTS

1,000 0 2,000  
Feet  
1 INCH = 2,000 FEET








DRAWN BY: **LAK**

CHECKED BY: **RSV**

DATE: **10/15/2021**

PROJECT: **21001628**



**Credere Associates, LLC**

776 MAIN STREET  
WESTBROOK, MAINE  
Tel. 207.828.1272  
Fax 207.887.1051  
WWW.CREDERELLC.COM

**FIGURE 2**

**DETAILED SITE PLAN**

BROWN SCHOOL

42 MILK STREET

NEWBURYPORT, MASSACHUSETTS

- BOILER ROOM
- 1961 ADDITION
- 1978 ADDITION
- SITE BOUNDARY
- ORIGINAL 1923 SITE BUILDING
- BOILER
- NOVEMBER 2001 EXCAVATION AREA
- UNKOWN SIZE #2 FUEL OIL UST
- 2021 SOIL BORINGS
- 2021 SOIL BORING/MONITORING WELL
- PARCEL BOUNDARY

NOTES:  
EXISTING CONDITIONS AND FEATURES SHOWN ON THIS PLAN ARE APPROXIMATE AND ARE BASED ON INFORMATION OBTAINED FROM THE CITY OF NEWBURYPORT ONLINE GIS DATA, MASSACHUSETTS GIS PARCEL LAYER, 2019 ORTHO PHOTOS, AND FIELD WORK PERFORMED IN AUGUST, 2021.






DRAWN BY: LAK	DATE: 10/08/2021	<b>FIGURE 3</b> <b>GROUNDWATER FLOW MAP</b>  BROWN SCHOOL 42 MILK STREET NEWBURYPORT, MASSACHUSETTS	<div><div>PARCEL BOUNDARY</div><div>GROUNDWATER CONTOUR</div><div>GROUNDWATER FLOW ARROW</div><div>BOILER ROOM</div><div>1961 ADDITION</div></div> <div><div>1978 ADDITION</div><div>SITE BOUNDARY</div><div>ORIGINAL 1923 SITE BUILDING</div><div>BOILER</div><div>NOVEMBER 2001 EXCAVATION AREA</div></div>	<div><div>UNKNOWN SIZE #2 FUEL OIL UST</div><div>2021 SOIL BORINGS</div><div>2021 SOIL BORING/MONITORING WELL</div><div>BENCHMARK</div></div>	<p>NOTES: EXISTING CONDITIONS AND FEATURES SHOWN ON THIS PLAN ARE APPROXIMATE AND ARE BASED ON INFORMATION OBTAINED FROM THE CITY OF NEWBURYPORT ONLINE GIS DATA, MASSACHUSETTS GIS PARCEL LAYER, 2019 ORTHO PHOTOS, AND FIELD WORK PERFORMED IN AUGUST AND SEPTEMBER, 2021.</p>
CHECKED BY: RSV	PROJECT: 21001628				

Community  
Economy  
Environment


**Creder Associates, LLC**  
776 MAIN STREET  
WESTBROOK, MAINE  
Tel. 207.828.1272  
Fax 207.887.1051  
WWW.CREDERELLC.COM





<b>FIRST FLOOR SAMPLE LOCATION PLAN</b>		SCALE - NTS	
		BROWN SCHOOL 42 MILK STREET NEWBURYPORT, MASSACHUSETTS	
DRAWN BY: MAW CHECKED BY: RSV	DATE: 10/15/2021 PROJECT: 21001628	Figure 4	
<b>CREDERE ASSOCIATES, LLC</b> 776 MAIN STREET WESTBROOK, MAINE 04092 FAX: 207.887.1051 TEL: 207.828.1272 WWW.CREDERELLC.COM		CREDERE ASSOCIATES, LLC 776 MAIN STREET WESTBROOK, MAINE 04092 FAX: 207.887.1051 TEL: 207.828.1272 WWW.CREDERELLC.COM	





- LEGEND**
- ASBESTOS SAMPLE LOCATION
  - PCB SAMPLE LOCATION
  - MOLD SAMPLE LOCATION
  - SIDE DESIGNATION FOR LEAD SCREENING

**NOTES**

1. FIELD WORK WAS COMPLETED AT BROWN SCHOOL BY CREDERE ASSOCIATES AUGUST & SEPTEMBER 2021.

PCB - POLYCHLORINATED BIPHENYLS  
SACM - SUSPECTED ASBESTOS-CONTAINING MATERIAL  
TL - TAPE LIFT

MULTIPLE TYPES OF ASBESTOS-CONTAINING FLOORING AND/OR WERE IDENTIFIED WITHIN THE FOLLOWING ROOMS OF THE BUILDING. SEE REPORT FOR A MORE DETAILED DESCRIPTION OF MATERIALS:  
STAIR 1 & STAIR 2, ROOMS C-1, C-2, K-1, C1-1, C1-2, C1-3, C2-1, C2-2, C2-3, M1-1, C-5, J-2, C-8, C-7, 23, D1-2, D1-3, 32, 35, A2-1, C-8, 11A, 12A, AND 13


SECOND FLOOR SAMPLE LOCATION PLAN

Figure 5

BROWN SCHOOL  
42 MILK STREET  
NEWBURYPORT, MASSACHUSETTS


SCALE - NTS

DRAWN BY: MAW  
CHECKED BY: RSV  
DATE: 10/15/2021  
PROJECT: 21001628



CREDERE ASSOCIATES, LLC  
776 MAIN STREET  
WESTBROOK, MAINE 04092  
FAX: 207.887.1051  
TEL: 207.828.1272  
WWW.CREDERELLC.COM





- LEGEND**
- ASBESTOS SAMPLE LOCATION
  - PCB SAMPLE LOCATION
  - MOLD SAMPLE LOCATION
  - A SIDE DESIGNATION FOR LEAD SCREENING

**NOTES**

1. FIELD WORK WAS COMPLETED AT BROWN SCHOOL BY CREDERE ASSOCIATES AUGUST & SEPTEMBER 2021.

PCB - POLYCHLORINATED BIPHENYLS  
SACM-SUSPECTED ASBESTOS-CONTAINING MATERIAL  
TL - TAPE LIFT

MULTIPLE TYPES OF ASBESTOS-CONTAINING FLOORING AND/OR WERE IDENTIFIED WITHIN THE FOLLOWING ROOMS OF THE BUILDING. SEE REPORT FOR A MORE DETAILED DESCRIPTION OF MATERIALS:  
STAIR 1 & STAIR 2, ROOMS C-1, C-2, K-1, C1-1, C1-2, C1-3, C2-1, C2-2, C2-3, M1-1, C-5, J-2, C-6, C-7, 23, D1-2, D1-3, 32, 35, A2-1, C-8, 11A, 12A, AND 13

THIRD FLOOR SAMPLE LOCATION PLAN

Figure 6

BROWN SCHOOL  
42 MILK STREET  
NEWBURYPORT, MASSACHUSETTS

SCALE - NTS

DRAWN BY: MAW  
CHECKED BY: RSV  
DATE: 10/15/2021  
PROJECT: 21001628

CREDERE ASSOCIATES, LLC  
776 MAIN STREET  
WESTBROOK, MAINE 04092  
FAX: 207.887.1051  
TEL: 207.828.1272  
WWW.CREDERELLC.COM



Table 1  
Sample Reference Table  
Brown School  
42 Milk Street, Newburyport, Massachusetts

Sample Location	Location Rationale	Sample ID	Analytical Method	Pertinent Sample Observations
CA-SB-1/CA-MW-1	To assess potential impacts associated with a historical and current UST	CA-SB-1 (10-11/10.5)	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
		CA-MW-1	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
CA-SB-2/CA-MW-2		CA-SB-2 (13-15/14)	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
		CA-MW-2	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
CA-SB-3/CA-MW-3		CA-SB-3 (13-15/14)	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
		CA-MW-3	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
CA-SB-4/CA-MW-4		CA-SB-4 (13-15/14)	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	No field observations indicating contamination.
		CA-MW-4	VPH (MassDEP VPH-18-2.1) EPH (MassDEP EPH-19-2.1)	Well not installed due to lack of contamination
CA-SACM-1 to CA-SACM-53	To assess suspect asbestos-containing materials	CA-SACM-1 to CA-SACM-53	Asbestos Analysis of Bulk Material (EPA 600/R-93/116)	Roof layers were observed to be wet.
CA-PCB-1 to CA-PCB-14	To assess suspect PCB-containing materials	CA-PCB-1 to CA-PCB-14	PCB in solids by Soxhlet 8082	No field observations.
CA-AIR-1 to CA-AIR-21	To assess potential mold growth	CA-AIR-1 to CA-AIR-21	Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)	No field observations.
CA-TP-1 to CA-TP-11	To assess potential mold growth	CA-TP-01 to CA-TP-11	Microscopic Examinations of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Tape Samples (EMSL Method MICRO-SOP-200)	Visible mold was identified in several rooms of the building.

Notes:  
1 - All samples were chilled to 4°C (+/- 2°C) and submitted to the laboratory on ice. Additional details regarding analytical method, sample preservation, sample volume and hold times can be found in Table 7-3 of Credere's Generic QAPP For Brownfields Work in Maine, New Hampshire, Massachusetts, and Vermont RFA #19043, revision 1, June 2020  
SB - soil boring  
MW - monitoring well  
VPH - volatile petroleum hydrocarbons  
EPH - extractable petroleum hydrocarbons

MassDEP - Massachusetts Department of Environmental Protection  
bgs - below ground surface



## TABLES



**Table 2**  
**Monitoring Well Construction Details and Groundwater Elevations**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Monitoring Well ID	Gauging Date	Approximate Screened Interval (feet bgs)	Top of Grade Elevation <sup>1</sup> (feet)	Depth to Bottom (feet below TOG)	Depth to Water (feet below TOG)	Water Level Elevation (feet)	Depth to Hydrocarbon (feet below TOC)
CA-MW-1	9/9/2021	17.5 to 27.5	99.48	27.22	24.76	74.72	NP
CA-MW-2		17 to 27	99.71	26.60	24.75	74.96	NP
CA-MW-3		20 to 30	100.02	28.77	24.79	75.23	NP

Notes:

bgs - below ground surface

TOG - top of grade

NP - No measurable hydrocarbons present

1 - Elevation survey was referenced to an onsite benchmark assigned an arbitrary datum of 100 feet. The benchmark is the southernmost corner of the gymnasium addition.



**Table 3**  
**Summary of Soil Analytical Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Location:		CA-SB-1		CA-SB-2		CA-SB-3		CA-SB-4	
Sample ID:		CA-SB-1		CA-SB-2		CA-SB-3		CA-SB-4	
Sample Depth (feet):		13-15/14		13-15/14		13-15/14		13-15/14	
Sample Type:		FS		FS		FS		FS	
Date Collected:		8/31/2021		8/31/2021		8/31/2021		8/31/2021	
Parameter*	Regulatory Criteria** MCP Method 1 S-1/GW-2	Result	Qualifier	Result	Qualifier	Result	Qualifier	Result	Qualifier
<b>Volatile Petroleum Hydrocarbons (VPH) by MassVPH-18-2.1 (mg/kg)</b>									
All Compounds		ND	U	ND	U	ND	U	ND	U
<b>Extractable Petroleum Hydrocarbons (EPH) by MassEPH-19-2.1 (mg/kg)</b>									
All Compounds		ND	U	ND	U	ND	U	ND	U

**NOTES:**

\*Only analytes with detections are shown, all other sample analyses results were below the laboratory reporting limits.

\*\* Massachusetts Department of Environmental Protection 310 CMR 40 Massachusetts Contingency Plan (MCP) Method 1 S-1/GW-2 Standards

FS - field sample

FD - field duplicate

mg/kg - milligrams per kilogram

U - Results were below the laboratory reporting limits, laboratory reporting limit shown

**Exceeds laboratory reporting limit**

**Exceeds or equal to MCP Method 1 S-1/GW-2**



**Table 4**  
**Summary of Groundwater Analytical Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

			Sample Location:		CA-MW-1		CA-MW-2		CA-MW-3	
			Sample ID:		CA-MW-2		CA-MW-3		CA-MW-4	
			Sample Type:		FS		FS		FS	
			Date Collected:		9/9/2021		9/9/2021		9/9/2021	
Parameter*		MassDEP MCP <sup>1</sup>		Result	Qualifier	Result	Qualifier	Result	Qualifier	
		GW-2	GW-3							
Volatile Petroleum Hydrocarbons (VPH) by MassVPH-18-2.1 (µg/L)										
All Compounds				ND	U	ND	U	ND	U	
Extractable Petroleum Hydrocarbons (EPH) by MassEPH-19-2.1 (µg/L)										
All Compounds				ND	U	ND	U	ND	U	



**Table 5**  
**Asbestos Sample Summary and Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Number	Sample Location	Material	Asbestos Content	Approximate Quantity of ACM (unit)
1988 Testing				
33-3-1	Brown School	Pipe Insulation (Aircell)	20% Chrysotile	100 LF more anticipated
33-3-2	Brown School	Joint Insulation (mud fittings)	50% Chrysotile	44 ea more anticipated
33-3-3	Brown School	Joint Insulation	40% Chrysotile 20% Amosite 5% Chrysotile	See 33-3-2
33-3-4	Brown School	Boiler Insulation	40% Amosite 20% Crocidolite	Removed
33-3-5	Brown School	Boiler Insulation	50% Chrysotile 25% Amosite 10% Chrysotile	Removed
33-3-6	Brown School	Tank Insulation	35% Amosite 20% Crocidolite	137 SF
33-3-7	Brown School	Suspended Acoustical Tile	ND	NA
33-3-8	Brown School	Vinyl Floor Covering (Brown Linoleum)	25% Chrysotile	4,071 SF
33-3-9	Brown School	Suspended Acoustical Tile	ND	NA
33-3-10	Brown School	Suspended Acoustical Tile	ND	NA
33-3-11	Brown School	Pipe Insulation (Aircell)	70% Chrysotile	See 33-3-1
33-3-12	Brown School	Joint Insulation	60% Chrysotile	See 33-3-2
33-3-13	Brown School	Joint Insulation	65% Chrysotile	See 33-3-2
33-3-14	Brown School	Joint Insulation	70% Chrysotile	See 33-3-2
33-3-15	Brown School	Ceiling Plaster	ND	NA
33-3-16	Brown School	Wall Plaster	ND	NA
1998 Sampling				
98067540-01	Brown School	Gypsum Wall Board/Joint Compound Wall System	ND	NA
98067540-02	Brown School	Sink Coat, Pink	3.3% Chrysotile	See CA-SACM-38
98067540-03	Brown School	Sink Coat, Pink	Positive Stop	NA
98067540-04	Brown School	Brown Baseboard Adhesive	ND	NA
98067540-05	Brown School	Brown Baseboard Adhesive	ND	NA
98067540-06	Brown School	Brown Mastic - Room 20	3.3% Anthophyllite	Material Not Identified During 2021 Inspection
98067540-07	Brown School	Brown Mastic - Room 25	Positive Stop	
98067540-08	Brown School	Beige Baseboard Adhesive	ND	NA
98067540-09	Brown School	Beige Baseboard Adhesive	ND	NA
98067540-10	Brown School	Brown Baseboard Adhesive	ND	NA
98067540-11	Brown School	Brown Baseboard Adhesive	ND	NA
98067540-12	Brown School	White Joint Compound	ND	NA
98067540-13	Brown School	White Joint Compound	ND	NA
98067540-14	Brown School	Off-White Gypsum Board	ND	NA
98067540-15	Brown School	Off-White Gypsum Board	ND	NA
98067540-16	Brown School	Gray Cement Plaster	ND	NA
98067540-17	Brown School	Gray Cement Plaster	ND	NA
98067540-18	Brown School	Gray Cement Plaster	ND	NA
98067540-19	Brown School	Gray Cement Plaster	ND	NA



**Table 5**  
**Asbestos Sample Summary and Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Number	Sample Location	Material	Asbestos Content	Approximate Quantity of ACM (unit)
98067540-20	Brown School	Gray Cement Plaster	ND	NA
98067540-21	Brown School	12" Tan Floor Tile	ND	NA
98067540-22	Brown School	12" Tan Floor Tile	ND	NA
98067540-23	Brown School	Black Mastic	ND	NA
98067540-24	Brown School	Black Mastic	ND	NA
98067540-25	Brown School	Duct Insulation	57% Chrysotile	250 SF (Stage) 184 SF (Boiler Room)
98067540-26	Brown School	Duct Insulation	Positive Stop	
98067540-27	Brown School	Duct Insulation	Positive Stop	
98067540-28	Brown School	Brown Ceiling Tile	ND	NA
98067540-29	Brown School	Brown Ceiling Tile	ND	NA
98067540-30	Brown School	Brown Mastic	6.6% Anthophyllite	300 SF
98067540-31	Brown School	Brown Mastic	Positive Stop	
98067540-32	Brown School	White Pipe Insulation	18% Chrysotile	Material Unable to be Observed during 2021 Inspection
98067540-33	Brown School	White Pipe Insulation	Positive Stop	
98067540-34	Brown School	White Pipe Insulation	Positive Stop	
2021 Sampling				
CA-SACM-01 (A,B)	Room C-5	2' x 3' Ceiling Tile, Dot Squiggle Pattern	ND	NA
	Room 15			
CA-SACM-02 (A,B)	Room C-5	Sheetrock, White	ND	NA
	Room J-2			
CA-SACM-03 (A,B,C)	Room C-5	Joint Compound, White	ND	NA
	Room J-2			
	Room 15			
CA-SACM-04 (A,B)	Room J-3 Room C-7	Caulk, Tan	1.4% Chrysotile Positive Stop	34 SF
CA-SACM-05 (A,B,C,D,E,F,G)	Room J-3	Plaster Topcoat, White	ND	NA
	Room C-5			
	Room 21			
	Room 35			
	Room 37			
	Room 21			
Room 23				



**Table 5**  
**Asbestos Sample Summary and Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Number	Sample Location	Material	Asbestos Content	Approximate Quantity of ACM (unit)
CA-SACM-06 (A,B,C,D,E,F,G)	Room J-3	Plaster Basecoat, Gray	ND	NA
	Room C-5			
	Room 21			
	Room 35			
	Room 37			
	Room 21			
	Room 23			
CA-SACM-07 (A,B)	Room 15	12" Floor Tile, Blue	ND	NA
	Room 16			
CA-SACM-08 (A,B)	Room 15	Baseboard Adhesive, Off-White	ND	NA
	Room 16			
CA-SACM-09 (A,B)	Room 16	2' x 3' Ceiling Tile, Dot Squiggle Pattern #2	ND	NA
	Room T-5			
CA-SACM-10 (A,B)	Room T-5	2' x 3' Ceiling Tile, Small Dents Pattern	ND	NA
	Room T-4			
CA-SACM-11 (A,B)	Room T-4	Tile Underlayment, Light Gray - Walls	ND	NA
	Room T1-2			
CA-SACM-12 (A,B)	Room T-4	Tile Underlayment, Gray - Floor	ND	NA
	Room T1-2			
CA-SACM-13 (A,B)	Stair 1	Stair Tread, Orange	ND	NA
	Stair 2			
CA-SACM-14 (A,B)	Stair 1 Stair 2	Stair Tread Mastic, Brown	11% Chrysotile Positive Stop	250 SF
CA-SACM-15 (A,B)	Room GL-1	Sheetrock, Gray - Addition	ND	NA
	Room GL-1			
CA-SACM-16 (A,B,C)	Room GL-1	Joint Compound, White - Addition	ND	NA
	Room GL-1			
	Room GL-1			
CA-SACM-17 (A,B)	Room GL-1	Carpet Adhesive, Beige	ND	NA
	Room GL-1			
CA-SACM-18 (A,B)	Room C-1 Room C-2	9" Floor Tile, Tan	5.5% Chrysotile Positive Stop	1,200 SF
CA-SACM-19 (A,B,C)	Room GL-1	Pipe Insulation, Layered Paper	<1% Chrysotile	10 LF identified, more anticipated
	Room GL-1		<1% Chrysotile	
	Room GL-1		<1% Chrysotile	
CA-SACM-20 (A,B)	Gymnasium	Acoustic Tile	Not Sampled - Inaccessible	
CA-SACM-21 (A,B,C)	Room GL-1	Plaster Topcoat, White - Addition	ND	NA
	Room GL-1			
	Room GL-1			
CA-SACM-22 (A,B,C)	Room GL-1	Plaster Basecoat, Gray - Addition	ND	NA
	Room GL-1			
	Room GL-1			
CA-SACM-23 (A,B)	Throughout	Chalkboard Adhesive	Not Sampled - Inaccessible	
CA-SACM-24 (A,B)	Exterior Room 21	Glazing, Gray - Original	1.3% Chrysotile Positive Stop	101 EA
CA-SACM-25 (A,B)	Exterior Room 32	Caulk, White - Original	1.3% Chrysotile Positive Stop	
CA-SACM-26 (A,B)	Room C1-1	12" Floor Tile, Off-White	ND	NA
	Room C2-3			
CA-SACM-27 (A,B)	Room C1-1 Room C2-3	Mastic, Black	6.9% Chrysotile Positive Stop	1,600 SF
CA-SACM-28 (A,B)	Room C1-1	Base Adhesive, Cream	ND	NA
	Room C2-3			



**Table 5**  
**Asbestos Sample Summary and Results**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Number	Sample Location	Material	Asbestos Content	Approximate Quantity of ACM (unit)
CA-SACM-29 (A,B)	Room J1-1	2' x 3' Ceiling Tiles, Dents & Dots Pattern	ND	NA
	Room J1-1			
CA-SACM-30 (A,B)	Room 24	12" x 12" Floor Tile, Cream	ND	NA
	Room 36			
CA-SACM-31 (A,B)	Room 25	Base Adhesive, Black	ND	NA
	Room 36			
CA-SACM-32 (A,B)	Room L1-1	Sheetrock, Light Gray	ND	NA
	Room 30			
CA-SACM-33 (A,B,C)	Room L1-1	Joint Compound, White	ND	NA
	Room L1-1			
	Room 30			
CA-SACM-34 (A,B)	Room M1-1	12" x 12" Floor Tile, White	ND	NA
	Room M1-1			
CA-SACM-35 (A,B)	Exterior A Side Infill	Caulk, Dark Gray - Infill Windows to Brick Seam	ND	NA
	Exterior A Side Infill			
CA-SACM-36 (A,B)	Exterior A Side Infill	Caulk, Brown/Red - Infill Windows	ND	NA
	Exterior A Side Infill			
CA-SACM-37 (A,B)	Exterior A Side Infill	Caulk, Dark Gray - Infill Brick to Brick Seam	ND	NA
	Exterior A Side Infill			
CA-SACM-38 (A,B)	Room A2-1 Room A2-1	Sink Coat, Pink	6.5% Chrysotile Positive Stop	2 EA
CA-SACM-40 (A,B)	Room G-1	12" Floor Tile, Light Blue/Gray	ND	NA
	Room G-1			
CA-SACM-41 (A,B)	Room G-1	Mastic, Black	ND	NA
	Room G-1			
CA-SACM-42 (A,B)	B Side Exterior B Side Exterior	Caulk, Light Gray - Original	14.3% Chrysotile Positive Stop	Quantified as part of CA-SACM-25
CA-SACM-43 (A,B)	B Side Exterior	Caulk, White	ND	NA
	B Side Exterior			
CA-SACM-44 (A,B)	A Side Exterior	Caulk, Gray - Infill to Original Seam	ND	NA
	A Side Exterior			
CA-SACM-45 (A,B)	B Side Exterior	Caulk, White - Gym Addition Doors	2.3% Chrysotile Positive Stop	36 LF
CA-SACM-46 (A,B)	D Side Exterior	Caulk, White - Gym Addition Windows	13.2% Chrysotile	75 LF
	D Side Exterior		7.4% Chrysotile	
CA-SACM-47 (A,B)	D Side Exterior	Glazing Compound, Light Gray - Gym Addition Windows	1.2% Chrysotile	4 EA
			Positive Stop	
CA-SACM-48 (A,B)	Room M1-1 Room M1-1	Linoleum, Swirly Square Pattern, Orange	13.9% Chrysotile Positive Stop	78 SF
CA-SACM-49 (A,B)	Roof	Caulk, White	ND	NA
	Roof			
CA-SACM-50 (A,B)	Roof 1A	Membrane Roofing, White	ND	NA
	Roof 1E			
CA-SACM-51 (A,B)	Roof 1A	Paper, Black	ND	NA
	Roof 1E			
CA-SACM-52 (A,B)	Roof 1A	Paper, White	ND	NA
	Roof 1F			
CA-SACM-53 (A,B)	Roof 1A	Sheetrock, White	ND	NA
	Roof 1D			

Total # of Samples: 151  
Total Analyzed: 145

ND - None detected, sampled in triplicate  
SACM - suspect asbestos-containing material  
NA - Not applicable  
LF - Linear Feet  
SF - Square feet

**Bold - Positive detection of ACM**

**Bold Highlight- Positive detection of ACM exceeding or equal to 1%**



**Table 6**  
**PCB-Containing Building Materials Sample and Results Summary**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

Sample Name	Location	Material	Regulatory Criteria* (mg/kg)	Total PCBs^ (mg/kg)
CA-PCB-1	Boiler Room	Paint, Gray over Light Blue	50 / 1	3.4
CA-PCB-2	Boiler Room	Paint, Gray		1.2
CA-PCB-3	Room J-3	Paint, Light Yellow		100
CA-PCB-4	1978 Addition (A-side infill)	Caulk, Dark Gray		0.29
CA-PCB-5	1978 Addition (A-side infill)	Caulk, Brown/Red		0.21
CA-PCB-6	1978 Addition (A-side infill)	Caulk, Dark Brown		ND<0.16
CA-PCB-7	1923 Original windows (Exterior Room 32)	Caulk, White		1.1
CA-PCB-8	B Side Exterior	Caulk, Light Gray		1.1
CA-PCB-9	B Side Exterior	Caulk, White		0.28
CA-PCB-10	A Side Exterior	Caulk, Gray		0.81 J
CA-PCB-DUP1				4.5 J
CA-PCB-11	Gymnasium Doors	Caulk, White		ND<1.3
CA-PCB-DUP2				0.90
CA-PCB-12	Gymnasium Windows	Caulk, White		ND<1.4
CA-PCB-13	Boiler Room	Paint, Green		18
CA-PCB-14	Roof	Caulk, White		ND<0.16

Notes:

ND<0.16 - None detected with reporting limit indicated

J - Result is considered estimated due to laboratory nonconformance

UJ - Non-detect result is considered estimated due to laboratory nonconformance

PCB - polychlorinated biphenyl

mg/kg - milligrams per kilogram

\* - 40 CFR 761.3 definition of a PCB bulk product waste (≥50 mg/kg). NHDES Solid Waste Rules apply for waste <50 mg/kg

40 CFR §761.61(a)(4)(i)(A) allows materials with PCB concentrations ≤1 mg/kg to be disposed without further conditions.

^ - Individual aroclor concentrations are provided in the laboratory analytical report.

**Bold** indicates detected PCBs

**Results exceed 50 mg/kg and is Bulk Product Waste**

Result exceeds 1 mg/kg but is below 50 mg/kg

Reporting limit exceeds regulatory criteria

**Result conservatively considered to exceed 1 mg/kg based on QC nonconformance**



Table 7  
Summary of Mold in Air Analytical Results  
Brown School  
42 Milk Street, Newburyport, Massachusetts

Sample Location: Sample ID: Volume of Air (L): Sample Date:		Boiler Room	Outside	Gym/Cafeteria	Kitchen (K-1)	Boys Locker Room (BL-1)	Room 14	Room 11	Room 10	Room 13	Boys Lockeroom Hallway (C-3)	C-1 Entry	Room 21	Room 25	Room L1-1
		CA-AIR-1	CA-AIR-2	CA-AIR-3	CA-AIR-4	CA-AIR-5	CA-AIR-6	CA-AIR-7	CA-AIR-8	CA-AIR-9	CA-AIR-10	CA-AIR-11	CA-AIR-12	CA-AIR-13	CA-AIR-14
		150	150	150	150	150	150	150	150	150	150	150	150	150	150
		8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021
Spore Type*	Calculated Reference Standard <sup>1</sup> (count/m <sup>3</sup> )	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result
Analysis of Fungal Spores & Particulates by Optical Microscopy by Methods MICRO-SOP-201, ASTM D7391 (count/m <sup>3</sup> )															
Alternaria (Ulocladium)	200	ND	100	ND	ND	ND	ND	ND	ND	ND	ND	ND	20	ND	ND
Ascospores	920	ND	460	300	250	100	200	20	40	40	100	100	100	100	100
Aspergillus/Penicillium	800	14,300	ND	1,800	2,550	30,200	270	200	360	530	800	380	100	200	40
Basidiospores	60,800	250	30,400	4,330	11,600	2,830	1,200	2,000	1,600	1,700	20	2,930	30,400	1,700	420
Cladosporium	6,460	100	3,230	320	1,500	340	400	400	230	300	1,400	340	680	890	320
Ganoderma	1900	60	1,100	340	550	340	210	340	100	100	320	400	20	270	210
Myxomycetes	880	ND	80	ND	60	60	ND	ND	ND	ND	ND	ND	360	ND	ND
Pithomyces	900	ND	100	ND	100	ND	ND	ND	ND	ND	20	ND	40	ND	ND
Cercospora	800	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20	ND	ND
Polythrincium	800	ND	ND	20	ND	ND	ND	ND	ND	ND	ND	7	ND	ND	ND
Total Fungi	-	14,710	35,470	7,110	16,610	33,870	2,280	2,960	2,330	2,670	2,660	4,157	31,740	3,160	1,090

\*Only spore types with detections are shown.

1 - Results were compared to the reference standard calculated based on the outside air (OA) concentration and mold type outlined in the International Institute for Building-Biology & Ecology, Inc., *Healthy Home Standard, Conventional Construction*, version 1.1, dated 2012

Reference Standard:  
*Aspergillus/Penicillium* = OA + 800  
*Outdoor Spore Types* = 2x OA  
*Diverse Spores* = OA + 800

L - liters

count/m<sup>3</sup> - fungal spore count per cubic meter of air

ND - fungal spores not detected

**Bold - fungal spores detected**

**White text and black shading** fungal spores detected above calculated reference standard



Table 7  
Summary of Mold in Air Analytical Results  
Brown School  
42 Milk Street, Newburyport, Massachusetts

Sample Location: Sample ID: Volume of Air (L): Sample Date:		Room D1-2	Room T1-1 Bath	Room 36	Room 33	Room 30	Room T2-2 Bath	Girls Locker Room (GL-1)
		CA-AIR-15	CA-AIR-16	CA-AIR-17	CA-AIR-18	CA-AIR-19	CA-AIR-20	CA-AIR-21
		150	150	150	150	150	150	150
		8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021	8/25/2021
Spore Type*	Calculated Reference Standard <sup>1</sup> (count/m <sup>3</sup> )	Result	Result	Result	Result	Result	Result	Result
Analysis of Fungal Spores & Particulates by Optical Microscopy by Methods MICRO-SOP-201, ASTM D7391 (count/m <sup>3</sup> )								
Alternaria (Ulocladium)	40	20	20	ND	20	ND	ND	ND
Ascospores	920	100	ND	200	100	80	100	210
Aspergillus/Penicillium	800	40	60	60	230	40	200	28,300
Basidiospores	980	760	490	870	1,100	1,600	1,600	760
Cladosporium	540	300	270	420	590	780	590	1,800
Ganoderma	1010	250	210	380	340	420	230	250
Myxomycetes	880	20	ND	ND	ND	20	ND	ND
Pithomyces	900	ND	ND	ND	ND	ND	ND	ND
Cercospora	800	ND	ND	ND	ND	ND	ND	ND
Polythrincium	800	ND	ND	ND	ND	ND	ND	ND
Total Fungi	-	1,490	1,050	1,930	2,380	2,940	2,720	31,320

\*Only spore types with detections are shown.  
1 - Results were compared to the reference standard calculated based on the outside air (OA) concentration and mold type outlined in the International Institute for Building-Biology & Ecology, Inc., *Healthy Home Standard, Conventional Construction*, version 1.1, dated 2012

Reference Standard:  
Aspergillus/Penicillium = OA + 800  
Outdoor Spore Types = 2x OA  
Diverse Spores = OA + 800

L - liters  
count/m<sup>3</sup> - fungal spore count per cubic meter of air  
ND - fungal spores not detected

**Bold - fungal spores detected**  
**White text and black shading** fungal spores detected above calculated reference standard



## **APPENDIX A**

### **CREDERE'S PROPOSAL WITH SCOPE OF WORK**





# CREDERE ASSOCIATES, LLC

776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

August 4, 2021  
P-21-20 (2<sup>nd</sup> revision)

Mr. Andrew Port  
Director of Planning & Development  
City of Newburyport  
60 Pleasant Street  
Newburyport, Massachusetts 01950  
Via email: [APort@CityofNewburyport.com](mailto:APort@CityofNewburyport.com)

**SUBJECT: Proposal for Phase II Environmental Site Assessment  
Brown School, 42 Milk Street, Newburyport**

Dear Mr. Port:

Credere Associates, LLC (Credere) is pleased to submit this proposal to conduct a Phase II Environmental Site Assessment (ESA) at the Brown School, 42 Milk Street in Newburyport, Massachusetts (Site). This ESA will be performed to address the findings identified in Credere's February Phase I ESA. The following four conditions identified as part of the Phase I ESA will be investigated:

- Recognized Environmental Condition (REC) #2: long history of storage of petroleum in USTs and threat of release associated with the current tank.
- Environmental Finding (EF) #1: Presence of asbestos-containing materials (ACM) in/on the Site building,
- EF #2: Suspected presence of lead paint in/on the Site building, and
- EF #3: Suspected presence of PCB-containing building materials in/on the Site building.

While two RECs were identified in Credere's Phase I ESA, Credere recommends assessing only REC#2 with a focus on confirming or dismissing the presence of impacted soil and/or groundwater. Task 1 below details our plan to assess REC#2. No Phase II ESA work is currently recommended for REC#1 because the condition has been closed with Massachusetts Department of Environmental Protection (MassDEP).

With regard to the above listed three environmental findings, Credere will assess, or further assess, each to understand the presence (unless already completed) and volume of impacted building materials. This will help support the future redevelopment of the Site by informing what kinds and how much of each of these hazardous building materials in the Site buildings.

Credere's scope of work is as follows:

## **Task 1 – REC#2 Assessment - Soil Borings, Soil Sampling, Well Installation and Groundwater Sampling**

### **Soil Borings and Soil Sampling**

The locations of borings will be pre-marked and then Credere will notify DigSafe® network and local non-member utilities of the work at least 72-hours prior to beginning subsurface work. A ground penetrating



radar (GPR) survey will then be performed by GPRS, Inc. to identify the exact location of the active underground storage tank (UST). In addition, the courtyard area around the existing tank will also be screened for other abandoned tanks because past records are not clear if past tanks have been removed from the Site.

Following DigSafe clearance and completion of the GPR survey, Credere will oversee the advancement of four (4) soil borings up to 25 feet below ground surface (bgs), 5 feet into the groundwater table, or refusal, whichever is shallower. The goal will be to assess soil and/or groundwater at the interval corresponding to the bottom of the tank. Borings will be placed around the existing UST such that any released petroleum will be identified. If the GPR reveals the presence of an old abandoned UST, Credere will move one boring to the area of this tank.

Drilling will be performed using a truck-mounted direct push drilling equipment. This drilling methodology will allow the continuous collection of 3-inch soil cores that will be assessed by the onsite Credere geologist. During drilling, soil borings will be logged and screened using a photoionization detector (PID) calibrated with 10 parts per million (ppm) isobutylene with a response factor of 1.0. The following table summarizes the proposed boring/sample locations and depths:

Location	Justification	Depth	Analyses
CA-SB-1/CA-MW-1	Assess the integrity of the current in use UST at the Site as well as the long history of UST usage at the Site	Soil sample from depth of greatest observed contamination or groundwater interface	Extractable Petroleum Hydrocarbons (EPH)
CA-SB-2/CA-MW-2			
CA-SB-3/CA-MW-3			
CA-SB-4/CA-MW-4			Volatile Petroleum Hydrocarbons (VPH)

One (1) soil sample will be collected from each boring for laboratory analysis and analyzed for petroleum in accordance with the above table. Visible asphalt and base materials, landscaping materials, and other organic detritus will be removed prior to sampling. Representative soil from an appropriate interval (no larger than 2 feet) will be collected while wearing new nitrile gloves and using decontaminated hand tools (e.g., stainless steel spoon or spade). VPH samples will be collected from the core using a dedicated soil syringe immediately after opening to prevent loss of volatiles or degradation. For EPH analysis, representative soil will be placed in a decontaminated stainless-steel bowl, homogenized, and placed in laboratory provided glassware. Collected soil samples will be stored on ice and submitted to a Massachusetts licensed laboratory for analyses.

### Well Installation and Groundwater Sampling

Monitoring wells will be installed in all soil borings CA-SB-1 through CA-SB-4 unless no groundwater table is identified. The groundwater monitoring wells will be constructed using 10 feet of 1.5-inch diameter 0.010-inch slotted PVC screen straddling the water table to allow for groundwater table fluctuations, and enough solid PVC riser to reach the ground surface. The well annulus will be filled with No. 1 washed silica sand, and a bentonite seal will be installed approximately one foot above the screened interval. Each well will be finished at the surface with a flush mounted road box and concrete pad.

Following installation, each monitoring well's top of PVC elevation will be surveyed to relative to a geodetic survey marker, if available, or to an assigned onsite benchmark using an arbitrary datum. Depth to groundwater and light non-aqueous phase liquid (LNAPL) thicknesses, if present, will then be measured



relative to the top of well elevations to allow for the calculation of relative groundwater elevations and the determination of groundwater flow direction at the Site.

Each well will be developed by over-pumping and agitation methods. The wells will be purged until a total of at least three well volumes have been removed and turbidity has been reduced to less than 20 nephelometric turbidity units (NTUs). Credere will allow at least 7 days for the monitoring wells to equilibrate with the surrounding aquifer prior to sampling. Wells will be sampled according to the following table:

After an appropriate equilibration period, Credere will sample the wells using low-flow sampling methodologies or no-purge methodologies, when appropriate. Wells will be pumped using peristaltic pumps, low density polyethylene tubing, and silicone tubing. Wells will be purged at a stable flow rate to avoid drawdown of the water level. Purging will occur by one of the following methods:

1. If a stable flow rate is achieved, groundwater will be periodically monitored for temperature, pH, oxidation-reduction potential, specific conductivity, and dissolved oxygen using a multi-parameter meter and an in-line flow-through cell until parameters have stabilized over a period of three readings, spaced at least 5 minutes apart or at a spacing to allow for a complete exchange of flow through the flow-through cell based on the flow-through cell volume and flow rate. Turbidity will be monitored using a separate turbidity meter. If parameters do not stabilize within a period of 2 hours or before a maximum purge volume of 5 well volumes, samples will be collected with field note justification of attempts to achieve stabilization and data will be reviewed for evidence of bias.
2. If a stable flow rate cannot be achieved, purging will be ceased, and the no-purge sampling method will be implemented. Tubing will be placed at the desired pump intake, one tubing volume will be purged, and samples will be collected. The wells will not be permitted to be pumped dry.

Location	Justification	Depth	Analyses
CA-MW-1	Assess the integrity of the current in use UST at the Site as well as the long history of UST usage at the Site	Screened at the groundwater interface	EPH and VPH
CA-MW-2			
CA-MW-3			
CA-MW-4			

Groundwater samples will be collected immediately after the pump and directly into the appropriate sample containers in order of decreasing volatility and sensitivity (e.g., VOCs, SVOCs, etc.). Groundwater samples will be stored on ice and submitted to a laboratory appropriately licensed in Massachusetts for analysis according to the above table.

## **Task 2 – Hazardous Building Materials Survey**

### **Asbestos Survey**

The available AHERA reports for the building will be reviewed and the testing results, both positive and negative, detailed therein will be incorporated into the materials inventory and final HBMS report.

Following the completion of the assessment and inventorying of known asbestos containing materials (ACM), Credere personnel who have been licensed by the Massachusetts Department of Labor Standards



as Asbestos Inspectors will survey and collect samples from the Site for other un-inventoried materials. The sampling will be performed in accordance with Massachusetts Department of Environmental Protection (MassDEP) 310 CMR 7.15. Each type of suspected homogenous material will be collected in duplicate (i.e., two samples per suspect building material sampled, unless otherwise required in regulations) and submitted for laboratory analysis.

This asbestos survey will include both the interior and exterior of the building as well as the roof. This survey will include destructive sampling and no repair is assumed as part of this scope (except roofing patching). An appropriately licensed roofer will be used to make the roof cuts to facilitate access and then patch after.

Every effort will be made to minimize analytical costs within the constraints of the regulatory requirements including instructing the laboratory to not analyze replicate samples following a positive result (i.e., a “positive stop”). Depending on the material it will be classified as a “friable” building material (e.g., pipe wrap, plaster, ceiling tile, etc.) and will be analyzed by polarized light microscopy (PLM) by EPA Method 600/R-93/116, or as a “non-friable” building material (e.g., floor tile, asphaltic materials, mastics, etc.) and will be analyzed by PLM using the U.S. Environmental Protection Agency (EPA) non-friable organically bound (NOB) preparation Method 600/R-93/116.

For budgetary purposes, up to 16 samples will be analyzed by PLM and up to 62 samples will be analyzed by PLM NOB. Every effort will be made to collect representative samples as safe work practices allow. Asbestos samples will be submitted to EMSL Analytical, Inc. of South Portland, Maine for analysis.

### **Lead-Containing Paint Survey**

A lead-containing paint (LCP) survey of painted or coated surfaces will be completed, in order to define if and where LCP is located in and on the Site buildings, and to assess the condition of any identified LCP. The LCP survey will be conducted by Credere subcontractor ASAP Environmental Inc. of Dorchester, Massachusetts and will be performed using an X-ray fluorescence meter (XRF). The LCP screening is intended to be used to properly define appropriate work practices and notification requirements in accordance with the Occupational Safety and Health Administration (OSHA) Lead in Construction standard. This survey is not intended as a lead inspection for occupancy.

### **PCB Survey**

Credere will conduct a survey of the Site building to inventory building materials that in Credere’s experience have the potential to contain PCBs. Each of the samples will be submitted for laboratory analysis of PCBs by EPA Method 8082A using Soxhlet extraction method 3540C in accordance with the Toxic Substances Control Act (TSCA) part 761 regulations for PCBs. For budgetary purposes, up to twenty-two (22) total samples will be collected and analyzed for PCB analysis.

### **Mold Sampling**

During the Phase I ESA work, Credere plans to collect samples to assess the potential presence of mold in the building. Credere will collect of up to twenty (20) indoor air mold samples using air pumps and cartridge-type sample filters. Credere will also collect up to five (5) BioTape contact-type samples to directly assess any visible mold observed in the building. All collected samples will be analyzed for mold by species at ESML laboratories in South Portland, Maine or their laboratory in New Jersey.



### **Additional Samples (If Required)**

If greater than 78 total asbestos samples are required or requested, you will be notified prior to sample collection. Additional Asbestos sample analysis (2-week turnaround) will be billed on a per sample basis of \$18 per PLM sample and \$25 per PLM NOB sample.

If greater than 22 total PCB samples are required or requested, you will be notified prior to sample collection. Addition PCB sample analysis will be billed on a per sample basis (\$72 per sample).

### **Task 3 – Phase II ESA Report**

A Phase II ESA Report will be prepared to include a Site description, scope of work, methodology, results, and conclusions of the assessment. The report will also contain a summary of materials tested, methodology, results, conclusions, and recommendations for addressing any of the HBMS requiring special disposal as part of future renovation. The information provided in the AHERA reports for this building will be incorporated and mapped. The report will include tabulated results and a figure of Site features. The report will also contain recommendations for addressing any identified contamination and a budgetary cost estimate to address identified contamination. The report will be transmitted electronically.

### **Proposed Schedule**

Credere proposes to conduct the field work within two weeks of receiving a notice to proceed and anticipates the work to take four days over the course of four weeks. All collected laboratory samples would be submitted with a two-week turnaround for results. The final report of findings shall be provided within 30 days from completion of work.

The delivery schedule relies upon the provision of access to the Site and that no additional significant issues are identified during the tasks of the project scope.

### **Cost Proposal**

Costs to perform the above scope of work will be billed on a lump sum basis per task as specified in the table below and in accordance with our attached General Provisions.

<b>Table 1. Cost Summary</b>	
<b>Task</b>	<b>Cost</b>
<b>Task 1 – Soil Borings, Soil Sampling, Well Installation, Groundwater Sampling</b>	
<i>Credere Labor and Equipment</i>	
<i>Drilling Subcontractor</i>	
<i>Laboratory Analysis (Soil and Groundwater)</i>	
<b>Task 2 – Hazardous Building Materials Survey (including Mold Sampling)</b>	
<i>Credere Labor and Equipment</i>	
<i>Lead Subcontractor</i>	
<i>Laboratory Analysis (Asbestos, PCB and Mold)</i>	
<b>Task 3 - Reporting</b>	
<b>Total</b>	





Additional tasks completed outside this proposed scope of work will be billed on a not-to-exceed time and materials basis (see attached 2021 Standard Labor Rates). We will notify you if any work falls outside of the original scope of work prior to completing the task. Specifically, this Scope of Work does not account of any work that must be done if reportable conditions are identified per 310 CMR 40.0000. A separate cost proposal will be provided in the event that this work becomes necessary.

A signature line is presented below for you to authorize and provide notice to proceed with the scope of work as described above, and to provide acceptance of the attached General Provisions. We look forward to the opportunity of working with you on this project. If you should have any questions or require clarification on any element of this proposal, please do not hesitate to contact me at (207) 828-1272 or via e-mail at rickv@crederellc.com.

Sincerely,

**Credere Associates, LLC**

*Rick S. Vandenberg*  
Rick Vandenberg, LG, PG  
Vice President of Operations

*Rip Patten*  
Rip Patten, PE, LSP, LEED-AP  
Vice President

Accepted By:

*Donna D. Hotak*  
~~Andrew Port~~ Donna D. Hotak, MAJOR Date

*8/4/21*

Attachments: 2021 Standard Rates  
General Provisions





# CREDERE ASSOCIATES, LLC

776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

## Standard Labor Rates Credere Associates, LLC 2021

<u>Personnel</u>	<u>Rate/Hour</u>
Principal-in-Charge/Program Manager/QC Manager .....	\$150
Senior Project Manager/Senior Technical Lead .....	\$140
Project Manager/Technical Lead .....	\$125
Engineer III/Geologist III .....	\$100
Assistant Project Manager/Assistant Technical Lead .....	\$95
Environmental Scientist/Specialist III .....	\$85
Engineer II/Geologist II .....	\$85
Chemist .....	\$80
Environmental Scientist/Specialist II .....	\$80
Engineer I/Geologist I .....	\$75
Environmental Scientist/Specialist I .....	\$75
Hazardous Building Materials Specialist .....	\$75
CAD-GIS Specialist .....	\$75
Administrative Assistant .....	\$55

<u>Other Direct Costs</u>	<u>Rate</u>
Communication Fee .....	3% of labor costs
Mileage .....	Current IRS Rate (\$TBD/mile)
Copies .....	\$0.20 per copy
Large Plots .....	\$10.00 per copy
Level C Safety Field Supplies .....	\$125/day
Level D Safety Field Supplies .....	\$30/day
Decontamination Supplies .....	\$10/day
Photoionization Detector (PID) .....	\$80/day; \$240/week
Photoionization Detector (ppb Rae) .....	\$160/day; \$480/week
Rugged Reader/Field PC .....	\$60/day
Multi-gas Meter .....	\$60/day
Soil Sampling Equipment .....	\$15/day
Groundwater Sampling Equipment .....	\$250/day (minimum)
Expendable Groundwater Sampling Equipment .....	\$20 to \$70/well
Soil Gas Sampling Equipment .....	\$250/day
Soil Gas Sampling Point Supplies .....	\$25/point
XRF .....	\$500/day; \$1,500/week
GPS .....	\$125/day; \$500/week
Metal Detector .....	\$25/day
Subconsultant/Subcontractor Expenses .....	cost +10%
Direct Expenses .....	cost



CREDERE ASSOCIATES, LLC





## General Provisions

### Fees for Consulting Services – Lump Sum

Fees for consulting services are based on a lump sum fee as specified in the proposal. This fee includes both direct salary costs and non-salary expenses.

### Fees for Consulting Services – Time & Materials

Fees for consulting services are based on the time worked on the project by staff personnel. The fee will be computed as follows:

1. Hourly rates as noted in agreement.

Direct non-salary expenses will be billed at the cost of Credere Associates, LLC (CREDERE), including:

1. Transportation and living expenses incurred for assignments outside the Portland metropolitan area.
2. Automobile expenses for personal or company vehicles at prevailing IRS rate plus toll charges, for travel from CREDERE's Portland office to the project and return, and for travel at the job in conduct of work. Use of rental cars or trucks, or other vehicles may be used in lieu of personnel vehicles and will be billed with no additional markup
3. A communication charge of 3% (of the labor cost in each invoice) will be included to cover telephone, faxes, postage and internet fees.
4. Shipping charges for water, soil samples, field testing equipment, plans, etc.
5. Disposal costs for hazardous or potentially hazardous soil, waste, and/or water samples plus 10%.
6. Health and safety supplies and equipment plus 10%.
7. Purchase of specialized equipment and rental of equipment from outside vendors plus 10%.
8. Reproduction and printing costs for reports, drawings, and other project records plus 10%.
9. Computer services provided by outside vendors.
10. Drafting and typing services and other labor provided by outside contract personnel.

### On-Site Services During Construction

Should CREDERE's work be provided on the job site during project construction, remedial action or other site activities, it is understood that, in accordance with generally accepted construction practices, the construction contractor will be solely and completely responsible for working conditions on the job site,

including health and safety of all persons and property during the performance of the work, and compliance with OSHA, NIOSH, USEPA, and other applicable regulations, and that these requirements will apply continuously and not be limited to normal working hours. Any monitoring of the construction contractor's performance conducted by CREDERE personnel is not intended to include review of the adequacy of the construction contractor's health or safety measures in, on, or near the construction site.

It is further understood that field services provided by CREDERE personnel will not relieve the contractor of his responsibilities for performing the work in accordance with applicable laws and regulations and with the plans and specifications.

### Disclosure of Hazards

CREDERE will take reasonable precautions for the health and safety of our employees while at the site with consideration for the available information regarding existing hazards. You will furnish to CREDERE, at the time of your authorization to proceed, all information concerning oil, hazardous, toxic, radioactive or asbestos material in, on, or near the site presenting a potential danger to human health or the environment. v

CREDERE has neither created nor contributed to the creation or existence of any actual or potentially hazardous, radioactive, toxic or otherwise dangerous substance or condition at any site, and its compensation is in no way commensurate with the potential liability that may be associated with a substance or site. Except to the extent that CREDERE expressly and in writing agrees to be legally responsible for presence, storage, treatment, disposal, or arrangement for disposal (collectively, "Disposal") of any substance or site (which substance and site shall be expressly identified), you agree to release and waive and to hold harmless and indemnify CREDERE for all claims, costs, response costs, removal costs, liabilities, attorneys fees, and damages, including natural resource damages and consequential damages against CREDERE, its officers, directors and employees, its subconsultants and their officers, directors and employees arising from or in any way connected with the Disposal of such substances. Except to the extent that CREDERE expressly and in writing agrees otherwise, in the event that CREDERE executes shipping papers or manifests for transportation of such substances, CREDERE does so only as your agent or representative and not for purposes of arranging for disposal or as a generator of such substances.

### Right of Entry

Unless otherwise agreed, you will furnish right-of-entry on the land for CREDERE to make planned investigations. CREDERE will take reasonable precautions to minimize damage to the land from use of equipment, but have not included in our fee the cost for restoration of damage that may result from CREDERE





operations. If CREDERE is required to restore the land to its former condition, this will be accomplished and the cost will be added to CREDERE's fee.

#### **Damage to Latent Underground Structures**

Reasonable care will be exercised in locating underground structures in the vicinity of proposed investigations and construction. This will include contact with the local agency coordinating subsurface utility information and a review of plans provided by you or your representatives for the site to be investigated. CREDERE shall be entitled to rely upon any plan provided. If the location of underground structures are not known or cannot be confirmed, then there will be a degree of risk to you associated with conducting the explorations. In the absence of confirmed underground structure locations, you agree to accept the risk of damage and possible costs associated with repair and restoration of damage resulting from the exploration work.

#### **Samples**

All samples of soil, water, waste, or other materials collected from the site will be disposed of 30 days after completion of laboratory testing unless you make other arrangements at the time you accept our proposals or unless applicable law requires their retention. CREDERE will either (1) dispose of such samples by contract with a qualified waste disposal contractor; or (2) will ship such samples to a location selected by you for final disposal. You agree to pay all costs associated with the storage, transport, and disposal of samples and to indemnify CREDERE for any liability arising therefrom. In the event any samples must be stored by CREDERE for a period in excess of 30 days after completion of laboratory testing, you agree to pay an additional fee for storage as determined by CREDERE.

#### **Invoices**

Invoices will generally be submitted once a month for services performed during the previous month. Payment will be due within 30 days of invoice date. Payments not received within 30 days will be assessed a late fee at 1.5% of the total amount outstanding per month. In the event CREDERE engages counsel to enforce overdue payments, you will reimburse CREDERE for all reasonable attorneys' fees and court costs.

#### **Ownership of Documents**

The OWNER acknowledges CREDERE reports and documents as instruments of professional service. The reports and documents prepared under this PROJECT shall become the joint property of the OWNER and CREDERE upon completion of the work and payment in full of all moneys due to CREDERE. Both during the term of this Agreement and after its termination, CREDERE may not distribute or publish such Documents without the prior written approval of the OWNER. CREDERE may use the Documents and the information contained in them for use on other projects and its business generally.

Reuse of documents by the OWNER for other than their intended use on this project without written authorization by the CREDERE will be at the OWNER's risk. OWNER shall indemnify and hold the CREDERE harmless from any claims, losses or damages, including attorneys fees, arising from the Owner's use of documents without the consent and active participation of CREDERE.

CREDERE will retain all pertinent records relating to the services performed for a period of six years following submission of CREDERE report, during which period of the records will be made available to you at all reasonable times.

#### **Confidentiality**

CREDERE will hold confidential all business or technical information obtained or generated in the performance of services under this Agreement. We will not disclose such information without your consent except to the extent required for (1) performance of services under this Agreement; (2) compliance with professional standards of conduct for preservation of the public safety, health, and welfare; (3) compliance with any court order or governmental directive; and/or (4) protection of CREDERE against claims or liabilities arising from the performance of services under this Agreement. Our obligations hereunder shall not apply to information in the public domain or lawfully acquired on a non-confidential basis from others.

Notwithstanding such confidentiality, CREDERE may comply with any federal, state, county and local laws, regulations, ordinances and applicable codes regarding the reporting to the appropriate public agencies of findings with respect to potential dangers to public health, safety, or the environment. CREDERE shall have no liability or responsibility to you or to any other person or entity for reporting or disclosures made in accordance with such statutory or other lawful requirements, and you shall defend, indemnify and hold us harmless from and against any and all claims, demands, liabilities and expense, including reasonable attorneys' fees, incurred by us and related to our reporting or disclosing such information under a good-faith belief or upon advice of counsel that such reporting or disclosure is required by law.

#### **Insurance**

The ENGINEER shall provide the OWNER with certificates of insurance satisfactory to the OWNER.

The ENGINEER shall carry insurance furnishing benefits in accordance with Maine law or such other worker's compensation requirement as may pertain. The ENGINEER shall carry insurance coverage for employer's liability, general liability, including broad form coverage, and automobile liability, in the amounts listed on the certificate of insurance. The ENGINEER shall also carry insurance coverage for valuable papers for the restoration of plans, field notes, drawings, computations,





specifications or other Documents in the event of loss or destruction of such materials in the custody of the ENGINEER, in an amount sufficient to cover the cost of restoration.

Professional Liability Insurance Coverage. The ENGINEER shall carry professional liability insurance.

#### **Standard of Care**

In accepting this Agreement for consulting services, you acknowledge the inherent risk associated with asbestos, oil, hazardous, radioactive, toxic, irritant, pollutant, or otherwise dangerous substances or conditions as well as with construction. You acknowledge that CREDERE services often require decisions which are not based upon exact science but rather upon judgmental considerations. In performing our professional services, CREDERE will use that degree of care and skill ordinarily exercised, under similar circumstances by members of the profession practicing in the same or similar locality. The standard of care shall exclusively be judged as of the time the services are rendered and not according to later standards. CREDERE makes no express or implied warranty beyond our commitments to conform to this standard.

Any action against CREDERE on account of any alleged error or omission in our report or other activities must be brought within six years of the rendition of such report or the completion of our services.

#### **Limitation of Liability**

You hereby agree to and do limit the liability of CREDERE or any person or entity for which it is responsible, to the amount paid to CREDERE under this agreement, or to the amount of \$50,000, whichever is less. This limitation shall apply regardless of the cause of action or legal theory pleaded or asserted, including fraud and misrepresentation.

In addition, you hereby agree to and do limit all claims of loss, damage or expense of any type arising out the scope of this agreement, including claims for attorneys fees, to claims against CREDERE ASSOCIATES, LLC, a limited liability company, and you hereby waive all claims against any officer, member or employee of CREDERE.

#### **Precedence**

These conditions shall take precedence over any inconsistent or contradictory provisions contained in any proposal, contract, purchase order, requisition, notice to proceed, or like document.

#### **Severability**

If any of these conditions shall be finally determined to be invalid or unenforceable in whole or part, the remaining provisions hereof shall remain in full force and effect, and be binding upon the parties hereto. The parties agree to reform these conditions to replace any such invalid or unenforceable provisions with a valid and enforceable

provisions that comes as close as possible to the intention of the stricken provision.

#### **Survival**

These conditions shall survive the completion of CREDERE's work on this project and the termination of CREDERE's work for any cause.

#### **Governing Law**

The validity and interpretation of this agreement shall be governed by the law in the State of Maine.



## **APPENDIX B**

### **PHASE II PHOTO LOG**



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**




1. Representative view of soil core collected during soil boring work




2. View of soil boring locations and UST GPR location markings



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



3. View of CA-SACM-01, 2' x 3' ceiling tile with dot squiggle pattern




4. View of CA-SACM-02, sheetrock, white, and CA-SACM-03, joint compound, white



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**




5. View of CA-SACM-04, caulk, tan (Rooms J-3 and C-7)



6. View of CA-SACM-05, plaster topcoat, white and CA-SACM-06, plaster basecoat, gray (multiple rooms)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**




7. View of CA-SACM-07, 12" x 12" floor tile, blue (Rooms 15 and 16)




8. View of CA-SACM-08, baseboard adhesive, off-white (Rooms 15 and 16)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**




9. View of CA-SACM-09, 2 x 3 ceiling tile, dot squiggle pattern #2 (Rooms 15 and T-5)




10. View of CA-SACM-10, 2' x 3' ceiling tile, small dents pattern (Rooms T-5 and T-4)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**




11. View of CA-SACM-11, tile underlayment, light gray (Rooms T-4 and T1-2)



12. View of CA-SACM-12, tile underlayment, gray (Rooms T-4 and T1-2)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



13. View of CA-SACM-13, stair tread, orange (Stair 1 and Stair 2)



14. View of CA-SACM-14, stair tread mastic, brown (Stair 1 and Stair 2)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



15. View of CA-SACM-15, sheetrock, gray – gym addition (Room GL-1)




16. View of CA-SACM-16, joint compound, white – gym addition (Room GL-1)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



17. View of CA-SACM-17, carpet adhesive, beige (Room GL-1)



18. View of CA-SACM-18, 9" x 9" floor tile, tan (Rooms C-1 and C-2)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



19. View of CA-SACM-19, pipe insulation, layered paper (Room GL-1)



20. View of CA-SACM-26, 12" floor tile, off-white (Gym)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



21. View of CA-SACM-27, mastic, black (Rooms C1-1 and C2-3)




22. View of CA-SACM-28, base adhesive, cream (Rooms C1-1 and C2-3)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



23. View of CA-SACM-29, 2x 3 ceiling tile with dents and dots (Rooms C1-1 and C2-3)



24. View of CA-SACM-30, 12" floor tile, cream (Rooms 24 and 36)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



25. View of CA-SACM-31, base adhesive, black (Rooms 25 and 36)



26. View of CA-SACM-32, sheetrock, light gray (Rooms L1-1 and 30)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



27. View of CA-SACM-34, 12" x 12" floor tile, white (sample mis-labelled in field)  
(Room M1-1)




28. View of CA-SACM-35, caulk, dark gray – infill window to brick seam (eastern side  
A infill)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



29. View of CA-SACM-36, caulk, brown/red, infill window repair (eastern side A infill)



30. View of CA-SACM-40, 12" x 12" floor tile, light blue/gray and CA-SACM-41, mastic, black (Room G-1)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



31. View of CA-SACM-42, caulk, light gray (B side exterior)



32. View of CA-SACM-43, caulk, white (B side exterior)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



33. View of CA-SACM-44, caulk, gray – infill to original seam (A side exterior)



34. View of CA-SACM-45, caulk, white – gym addition doors (B side exterior)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



35. View of CA-SACM-46, caulk, white – gym addition windows (D side exterior)




36. CA-SACM-48, linoleum, orange swirly square pattern (misabeled in field) (Room M1-1)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



37. Representative view of roof cut



38. View of CA-PCB-1, paint, gray over light blue (boiler room)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



39. View of CA-PCB-2, paint, gray (boiler room)



40. View of CA-PCB-3, paint, light yellow (Room J-3)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



41. View of CA-PCB-7, caulk, white (original window exterior)



42. View of CA-PCB-8, caulk, light gray (B side exterior)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



43. View of CA-PCB-9, caulk, white (B side exterior)



44. View of CA-PCB-10, caulk, gray (A side exterior)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



45. View of CA-PCB-11, caulk, white (Gym doors)



46. View of CA-PCB-12, caulk, white (Gym windows)



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



47. View of CA-PCB-13, paint, green (Boiler room)



48. View of air sampling setup for mold sample collection



**Appendix B – Photo Log**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**



49. View of tape lift sample for mold



## **APPENDIX C**

### **BORING LOGS & GROUNDWATER SAMPLING LOGS**





Credere Associates, LLC  
776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

# Boring Log

**CA-SB/MW-1**

PAGE 1 OF 1

**CLIENT** City of Newburyport **PROJECT NAME** Brown School  
**PROJECT #** 21001628 **PROJECT LOCATION** 42 Milk Street  
**DATE STARTED** 8/31/21 **LOGGED BY** Moira Wentworth **DEPTH TO WATER** 24 **WELL DIAMETER** 2"  
**CONTRACTOR** New England Geotech/Hayes Rembijas **WELL MATERIALS** PVC, 0.010" slotted screen, solid riser  
**DRILLING METHOD** Direct Push **ANNULUS MATERIALS** #2 Silica Sand, Bentonite Chips  
**DRILLING EQUIPMENT** Geoprobe 6600 Truck Rig, borehole diam. 2" **MP ELEVATION**  **GROUND ELEVATION** 99.48

**NOTES** \_\_\_\_\_

Depth (ft)	Penetration/ Recovery (in)	Blow Counts	Field Screening (ppm)	Lab Analytical Sample	Graphic Log	LITHOLOGY	WELL DIAGRAM
0	60/49		HS: 0.000			0-4" Black ASPHALT, dry 4-8" Dark gray fine GRAVEL, dry 8-16" Brown very fine to fine SAND, little Silt, moist 16-30" Dark brown very fine to fine SAND and SILT, little fine Gravel, moist 30-44" Brown very fine to fine SAND, little fine Gravel, trace Silt, moist	Well Finish: Roadbox Concrete Collar
5	60/60		HS: 0.000			0-5" Brown very fine to fine SAND, little fine Gravel, trace Silt, moist 5-60" Light brown very fine to fine SAND, little fine Gravel, trace Silt, moist	Backfill
10	60/50		HS: 0.000			0-50" Light brown very fine to fine SAND, little fine Gravel, trace Silt, moist	
15	60/47		HS: 0.000	CA-SB-1 (13-15/14)		0-47" Light brown very fine to fine SAND, little fine Gravel, trace Silt, moist	Bentonite Seal
20	60/47		HS: 0.000			0-16" Light brown very fine to fine SAND, little fine Gravel, trace Silt, moist 16-32" Light brown very fine to fine SAND, little Silt, moist 32-37" Dark brown very fine to fine SAND, little Silt, moist 37-47" Brown very fine to fine SAND, moist, wet at 43"	#2 Sand PVC Screen
25	30/30		HS: 0.000			0-30" Light brown very fine to fine SAND, little Silt, wet	
						End of boring at 27.5 feet below ground surface (refusal)	





Crede Associates, LLC  
776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

# Boring Log

**CA-SB/MW-2**

PAGE 1 OF 1

**CLIENT** City of Newburyport **PROJECT NAME** Brown School  
**PROJECT #** 21001628 **PROJECT LOCATION** 42 Milk Street  
**DATE STARTED** 8/31/21 **LOGGED BY** Moira Wentworth **DEPTH TO WATER** 24 **WELL DIAMETER** 2"  
**CONTRACTOR** New England Geotech/Hayes Rembijas **WELL MATERIALS** PVC, 0.010" slotted screen, solid riser  
**DRILLING METHOD** Direct Push **ANNULUS MATERIALS** #2 Silica Sand, Bentonite Chips  
**DRILLING EQUIPMENT** Geoprobe 6600 Truck Rig, borehole diam. 2" **MP ELEVATION**  **GROUND ELEVATION** 99.71

## NOTES

Depth (ft)	Penetration/ Recovery (in)	Blow Counts	Field Screening (ppm)	Lab Analytical Sample	Graphic Log	LITHOLOGY	WELL DIAGRAM
0	60/47		HS: 0.000			0-6" Black ASPHALT, dry 6-14" Black crushed ASPHALT. dry	Well Finish: Roadbox Concrete Collar
						14-22" Brown very fine to fine SAND, some fine Gravel, moist	
						22-35" Brown very fine to fine SAND and SILT, little fine Gravel, moist	
						35-47" Light brown very fine to fine SAND, moist	
5	60/51		HS: 0.000			0-3" Light brown very fine to fine SAND, moist 3-9" Dark brown very fine to medium SAND, some fine Gravel, little Silt, moist 9-51" Light brown very fine to fine SAND, trace fine Gravel, moist	Backfill
10	60/51		HS: 0.000			0-40" Light brown very fine to fine SAND, trace fine Gravel, moist	
15	60/47		HS: 0.000	CA-SB-2 (13-15/14)		40-51" Brownish gray very fine to fine SAND, trace fine Gravel, moist 0-32" Light brown very fine to fine SAND, little fine Gravel, moist	Bentonite Seal
						32-47" Light brown very fine to fine SAND, trace fine Gravel, moist	
20	60/60		HS: 0.000			0-50" Light brown very fine to fine SAND, trace fine Gravel, moist	
						50-60" Light brown very fine to fine SAND, trace fine Gravel, wet	
25	24/24		HS: 0.022			0-8" Light brown very fine to fine SAND, trace fine Gravel, wet 8-12" Brown very fine to fine SAND and SILT, wet 12-24" Brown very fine to medium SAND, some fine Gravel, little Silt, wet	#2 Sand PVC Screen
						End of boring at 27 feet below ground surface	





Creder Associates, LLC  
776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

# Boring Log

**CA-SB/MW-3**

PAGE 1 OF 1

**CLIENT** City of Newburyport **PROJECT NAME** Brown School  
**PROJECT #** 21001628 **PROJECT LOCATION** 42 Milk Street  
**DATE STARTED** 8/31/21 **LOGGED BY** Moira Wentworth **DEPTH TO WATER** 26 **WELL DIAMETER** 2"  
**CONTRACTOR** New England Geotech/Hayes Rembijas **WELL MATERIALS** PVC, 0.010" slotted screen, solid riser  
**DRILLING METHOD** Direct Push **ANNULUS MATERIALS** #2 Silica Sand, Bentonite Chips  
**DRILLING EQUIPMENT** Geoprobe 6600 Truck Rig, borehole diam. 2" **MP ELEVATION**  **GROUND ELEVATION** 100.02

**NOTES** \_\_\_\_\_

Depth (ft)	Penetration/ Recovery (in)	Blow Counts	Field Screening (ppm)	Lab Analytical Sample	Graphic Log	LITHOLOGY	WELL DIAGRAM
0	60/39		HS: 0.087			0-6" Black ASPHALT, dry	Well Finish: Roadbox
						6-9" Brown very fine to fine SAND, little Brick, moist	Concrete Collar
						9-39" Brown very fine to fine SAND, moist	
5	60/52		HS: 0.000			0-52" Light brown very fine to fine SAND, moist	
10	60/45		HS: 0.000			0-45" Light brown very fine to fine SAND, moist	Backfill
15	60/43		HS: 0.000	CA-SB-3 (13-15/14)		0-45" Light brown very fine to fine SAND, moist	
20	60/46		HS: 0.092			0-46" Light brown very fine to fine SAND, moist	Bentonite Seal
25	60/45		HS: 0.000			0-12" Light brown very fine to fine SAND, moist	#2 Sand PVC Screen
						12-23" Light brown very fine to fine SAND, wet	
						23-40" Brown very fine to fine SAND, some fine Gravel, little Silt, wet	
30						40-45" Brown very fine to fine SAND and SILT, wet	
						End of boring at 30 feet below ground surface	





Credere Associates, LLC  
776 Main Street  
Westbrook, Maine 04092  
Phone: 207-828-1272  
Fax: 207-887-1051

# Boring Log

**CA-SB-4**  
PAGE 1 OF 1

**CLIENT** City of Newburyport **PROJECT NAME** Brown School  
**PROJECT #** 21001628 **PROJECT LOCATION** 42 Milk Street  
**DATE STARTED** 8/31/21 **LOGGED BY** Moira Wentworth **DEPTH TO WATER** \_\_\_\_\_ **WELL DIAMETER** \_\_\_\_\_  
**CONTRACTOR** New England Geotech/Hayes Rembijas **WELL MATERIALS** \_\_\_\_\_  
**DRILLING METHOD** Direct Push **ANNULUS MATERIALS** \_\_\_\_\_  
**DRILLING EQUIPMENT** Geoprobe 6600 Truck Rig, borehole diam. 2" **MP ELEVATION** \_\_\_\_\_ **GROUND ELEVATION** \_\_\_\_\_

**NOTES** \_\_\_\_\_

Depth (ft)	Penetration/ Recovery (in)	Blow Counts	Field Screening (ppm)	Lab Analytical Sample	Graphic Log	LITHOLOGY	WELL DIAGRAM
0	60/45		HS: 0.102			0-5" Black ASPHALT, dry 5-9" Brown very fine to coarse SAND, moist 9-10" Black very fine to fine SAND, moist 10-15" Brown very fine to fine SAND, moist 15-25" Dark brown very fine to fine SAND, moist 25-33" Brown very fine to fine SAND and SILT, moist 33-37" Gray crushed ROCK, dry 37-45" Light brown very fine to fine SAND, moist 0-4" Dark brown very fine to fine SAND, little fine Gravel, moist 4-60" Light brown very fine to fine SAND, moist	
5	60/60		HS: 0.094				
10	60/51		HS: 0.133			0-51" Light brown very fine to fine SAND, moist	
15	60/44		HS: 0.219	CA-SB-4 (13-15/14)		0-8" Light brown very fine to fine SAND, moist 8-44" Light brownish gray very fine to fine SAND, moist	
20	60/60		HS: 0.037			0-42" Light brownish gray very fine to fine SAND, moist	
25						42-60" Gray weathered BEDROCK, moist End of boring at 25 feet below ground surface (refusal on bedrock)	



**INSTRUMENT CALIBRATION LOG**  
**Credere Associates, LLC, 776 Main Street, Westbrook, ME 04092**



PROJECT NAME: Brown School  
 PROJECT NUMBER: 21001638  
 WEATHER: Partly Cloudy, No Precip, 60°F  
(barometric pressure, temperature, precipitation)  
 WATER QUALITY INSTRUMENT SONDE MODEL/SN: 17E100949  
 WATER QUALITY INSTRUMENT HANDSET MODEL/SN: 17E100092  
 TURBIDITY METER MODEL/SN: Hach 2100Q/ 20120 D002142  
 FIELD STAFF ASSIGNED TO EQUIPMENT: Chris Bean

DATE: 9.9.21  
**Temperature**  
 Temp Probe Reading 17.56  
 Bulb Thermometer Reading 17.4

**pH 3 POINT CALIBRATION**

pH 4 solution #: A0134 pH 7 solution #: K149-13 pH 10 solution #: K696-29  
 Expiration: 5/24 Expiration: 5/9/22 Expiration: 4/9/22

	Morning		Evening Check		Comment
	before	after	before	after (if needed)	
pH 4 calibration	<u>4.90</u>	<u>5.93</u>			
pH 7 calibration	<u>7.22</u>	<u>6.98</u>			
pH 10 calibration	<u>9.90</u>	<u>10.00</u>			

**CONDUCTIVITY CALIBRATION**

Conductivity solution #: 20390034 Expiration: 10/21

	Morning		Evening Check		Comment
	before	after	before	after (if needed)	
Conduc. Calibration	<u>10520</u>	<u>11413</u>			

**DO Calibration**

Barometric Pressure: 768.2 mm HG Zero DO solution #: \_\_\_\_\_  
 Calibration value\*: 101 Expiration: \_\_\_\_\_

	Morning		Evening Check		Comment
	before	after	before	after (if needed)	
DO Calibration	<u>97.2</u>	<u>101.2</u>			
Zero DO Check		<u>NA</u>		<u>NA</u>	

**ORP Calibration**

ORP solution #: 1836065 Solution temperature: 17.4  
 Expiration: 8/24 Adjusted zobell reading\*: 241.7

	Morning		Evening Check		Comment
	before	after	before	after (if needed)	
ORP Calibration	<u>220.6</u>	<u>241.7</u>			

**TURBIDITY CHECK**

	Morning		Evening Check		Comment
	before	after (if needed)	before	after (if needed)	
10 NTU check	<u>10.2</u>				
20 NTU check	<u>19.8</u>				
100 NTU check	<u>97.1</u>				
800 NTU check	<u>780</u>				

**CALIBRATOR SIGNATURE**

Chris Bean

\* see second page  
 attachment for  
 adjustment tables



**LOW FLOW SAMPLING LOG**  
**CREDERE ASSOCIATES, LLC**

PROJECT NAME: Brown School

DATE: 9/9/21

PROJECT NUMBER: 21001628

LOCATION AC

SAMPLE LOCATION ID: CA-MW-1 1 of 2

START: 1105  
END: 1320

**WELL DATA:**

WELL DEPTH (ft): 24.2 26.70 ☒ MEASURED ☐ HISTORICAL ☒ TOP OF WELL ☐ TOP OF CASING  
WATER DEPTH (ft): 26.70 24.24 ☒ MEASURED ☐ HISTORICAL ☐ FROM GRADE  
DEPTH OF PUMP INTAKE (ft): ~ 25.00 Stick-up (in): N/A  
WELL MATERIAL: ☒ PVC ☐ SS ☐ \_\_\_\_\_  
WELL LOCKED: ☐ YES ☒ NO  
PROTECTIVE CASING SECURE: ☒ YES ☐ NO  
CONCRETE COLLAR INTACT: ☒ YES ☐ NO  
PVC or CASING HEAVING?: ☐ YES ☒ NO  
WATER LEVEL EQUIPMENT USED: ☒ ELECT. COND. PROBE ☐ FLOAT ACTIVATED PROBE ☐ PRESSURE TRANSDUCER  
AMBIENT AIR VOC: 0.193 PPM  
WELL MOUTH VOC: 0.791 PPM

**EQUIPMENT DATA:**

**PURGING SAMPLING**

**EQUIPMENT**

**DECONTAMINATION**

☒ Peristaltic Pump ☒ Geopump peristaltic pump  
☐ Submersible Water Level Meter: Heron Diver T  
☐ Bladder pump YSI Pro+ sonde with 250 mL flow cell  
☐ Hand pump YSI Sonde SN: 17E109949  
☐ Dedicated HDPE YSI Pro+ Handset  
☒ New HDPE YSI Handset SN: 17E100092  
☐ Dedicated Teflon Lined LDPE Hach 2100 Turbidity Meter  
☐ New Teflon Lined LDPE Turbidity Meter SN: 2012 D002142  
☐ Filter (0.45 micron)  
Sampler: C. Brown

**FIELD ANALYSIS DATA:**

TIME	TEMP (°C)	pH	SP COND. (mS/cm)	ORP (mV)	D.O. (mg/l)	TURBID. (ntu)	Flow Rate (mL/min)	DTW (ft)	Comments/Flow Rate (Indicate stable flow rate)
1110							120	24.65	Purge started
1115						36.7	120	24.90	at 1105
1120	17.3	6.59	0.53	-157.9	3.94	43.8	140	25.10	
1125	17.7	6.52	0.53	-119.7	4.89	43.1	140	25.10	Max Purge
1130	18.3	6.51	0.54	-93.3	4.96	16.3	140	25.10	without drawdown
1135	17.5	6.55	0.53	-175.9	6.48	17.4	140	25.10	@ 140 mL/min
1140	17.4	6.52	0.52	-119.3	6.39	18.4	140	25.10	
1145	17.4	6.48	0.52	-113.6	6.21	12.8	140	25.10	water color?
1150	17.8	6.47	0.52	-131.8	6.07	27.2	140	25.10	opaque white
1155	18.0	6.42	0.52	-102.0	6.50	20.6	140	25.10	
1200	17.9	6.41	0.52	-99.0	6.44	13.8	140	25.10	
1205	18.0	6.38	0.52	-62.0	6.31	9.62	140	25.10	
1210	17.9	6.40	0.52	-100.0	6.30	27.9	140	25.10	
1215	18.0	6.38	0.52	-83.5	6.27	17.1	140	25.10	
	3%	±0.1	3%	±10	10%, <0.5	<5	100-400 mL/min		

**SAMPLE DATA:**

SAMPLE BOTTLE ID	PRESERVATION	SAMPLE CONTAINER	LABORATORY ANALYSIS
TIME LOCATION	METHOD	# TYPE	
1315 CA-MW-1	HCL	2 1 liter Amber	EPH
	HCL	1 10 mL VOA	VPH

**PURGE DATA**

☐ 0.04 GAL/FT (1" DIAM.) x length of water column = 2.46  
☒ 0.16 GAL/FT (2" DIAM.) Total Well Volume: 0.39 g  
☐ 0.65 GAL/FT (4" DIAM.) Total Purge Volume: 6.4 g  
☐ 1.47 GAL/FT (6" DIAM.) # of well volumes: 16.4  
 Stable flow not achieved, sampled via no-purge: ☐  
 SAMPLER: C. Brown



# LOW FLOW SAMPLING LOG CREDERE ASSOCIATES, LLC



PROJECT NAME: Brown Schol

DATE: 9/9/21

PROJECT NUMBER: 21001622

LOCATION ACTIVITY

SAMPLE LOCATION ID: CA-MW-1 2 of 2

START: 1105  
END: 1320

## WELL DATA:

WELL DEPTH (ft): \_\_\_\_\_ [ ] MEASURED [ ] TOP OF WELL WATER LEVEL EQUIPMENT USED:  
[ ] HISTORICAL [ ] TOP OF CASING [ ] ELECT. COND. PROBE  
WATER DEPTH (ft): \_\_\_\_\_ [ ] MEASURED [ ] FROM GRADE [ ] FLOAT ACTIVATED PROBE  
[ ] HISTORICAL [ ] \_\_\_\_\_ [ ] PRESSURE TRANSDUCER

DEPTH OF PUMP INTAKE (ft): \_\_\_\_\_ Stick-up (in): \_\_\_\_\_ AMBIENT AIR VOC: \_\_\_\_\_ PPM

WELL MOUTH VOC: \_\_\_\_\_ PPM

WELL MATERIAL: WELL PROTECTIVE CASING CONCRETE COLLAR PVC or CASING  
[ ] PVC LOCKED: SECURE: INTACT: HEAVING?:  
[ ] SS [ ] YES [ ] YES [ ] YES [ ] NA [ ] YES [ ] NA  
[ ] \_\_\_\_\_ [ ] NO [ ] NO [ ] NO [ ] NO [ ] NO

## EQUIPMENT DATA:

### PURGING SAMPLING

[ ] [ ] Peristaltic Pump Geopump peristaltic pump  
[ ] [ ] Submersible Water Level Meter:  
[ ] [ ] Bladder pump YSI sonde with \_\_\_\_\_ mL flow cell  
[ ] [ ] Hand pump YSI Sonde SN: \_\_\_\_\_  
[ ] [ ] Dedicated HDPE YSI Handset  
[ ] [ ] New HDPE YSI Handset SN: \_\_\_\_\_  
[ ] [ ] Dedicated Teflon Lined LDPE Hach 2100 Turbidity Meter  
[ ] [ ] New Teflon Lined LDPE Turbidity Meter SN: \_\_\_\_\_  
[ ] [ ] Filter (0.45 micron) Sampler: \_\_\_\_\_

### DECONTAMINATION

FLUIDS USED:  
[ ] DISTILLED WATER  
[ ] DEIONIZED WATER  
[ ] POTABLE WATER  
[ ] TSP SOLUTION  
[ ] ALCONOX SOLUTION  
[ ] NONE

## FIELD ANALYSIS DATA:

TIME	TEMP (°C)	pH	SP. COND. (mS/cm)	ORP (mV)	D.O. (mg/l)	TURBID. (ntu)	Flow Rate (mL/min)	DTW (ft)	Comments/Flow Rate (indicate stable flow rate)
1220	17.9	6.37	0.51	-75.2	6.27	19.7	140	25.10	Sampled after
1225	17.9	6.36	0.51	-60.6	6.43	34.4	140	25.10	2 hour Purge
1230	17.9	6.36	0.51	-45.2	6.36	37.2	140	25.10	limit.
1235	17.9	6.36	0.51	-28.1	6.32	49.3	140	25.10	
1240	18.8	6.34	0.52	-4.0	6.41	33.3	140	25.10	
1245	18.6	6.33	0.51	-56.6	6.50	14.0	140	25.10	
1250	18.6	6.35	0.51	-67.5	6.44	8.34	140	25.10	
1255	19.0	6.34	0.52	-57.6	6.41	5.17	140	25.10	
1300	18.9	6.34	0.52	-69.8	6.52	5.25	140	25.10	
1305	18.8	6.33	0.52	-74.0	6.47	4.99	140	25.10	
1310	19.0	6.33	0.52	-70.9	6.36	14.6	140	25.10	
1315	Sampled								
	3%	±0.1	3%	±10	10%, <0.5	<5	100-400 mL/min		

## SAMPLE DATA:

SAMPLE BOTTLE ID	PRESERVATION	SAMPLE CONTAINER	LABORATORY
TIME LOCATION	METHOD	# TYPE	ANALYSIS
1315			

## PURGE DATA

[ ] 0.04 GAL/FT (1" DIAM.) x length of water column = Stable flow not achieved, sampled via no-purge: [ ]  
[ ] 0.16 GAL/FT (2" DIAM.) Total Well Volume: \_\_\_\_\_ g  
[ ] 0.65 GAL/FT (4" DIAM.) Total Purge Volume: \_\_\_\_\_ g  
[ ] 1.47 GAL/FT (6" DIAM.) # of well volumes: \_\_\_\_\_  
SAMPLER Chaper Bear



<b>PURGE DATA</b>	<input checked="" type="checkbox"/> 0.04 GAL/FT (1" DIAM.)	x length of water column = <u>1.85</u>	Stable flow not achieved, sampled via no-purge: [ ]  <i>Chadler Bean</i> <b>SAMPLER</b>
	<input type="checkbox"/> 0.16 GAL/FT (2" DIAM.)	Total Well Volume: <u>0.074</u> g	
	<input type="checkbox"/> 0.65 GAL/FT (4" DIAM.)	Total Purge Volume: <u>2.2</u> g	
	<input type="checkbox"/> 1.47 GAL/FT (6" DIAM.)	# of well volumes: <u>29.7</u>	



Credere Associates LLC

DATE: 9/9/21

LOCATION ACTIVITY

START: 0955  
END: 1100

WELL DEPTH (ft): 24.72 28.70 [ ] MEASURED [ ☒ ] TOP OF WELL WATER LEVEL EQUIPMENT USED:  
[ ] HISTORICAL [ ] TOP OF CASING [ ☒ ] ELECT. COND. PROBE  
WATER DEPTH (ft): 28.70 24.72 [ ] MEASURED [ ] FROM GRADE [ ] FLOAT ACTIVATED PROBE  
[ ] HISTORICAL [ ] \_\_\_\_\_ [ ] PRESSURE TRANSDUCER  
DEPTH OF PUMP INTAKE (ft): = 27' Stick-up (in): N/A AMBIENT AIR VOC: 0.230 PPM


WELL MATERIAL:	WELL	PROTECTIVE CASING	CONCRETE COLLAR	PVC or CASING
<input checked="" type="checkbox"/> PVC	LOCKED:	SECURE:	INTACT:	HEAVING?:
<input type="checkbox"/> SS	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> YES	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NA	<input type="checkbox"/> YES <input type="checkbox"/> NA
<input type="checkbox"/>	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> NO	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> NO

### PURGING SAMPLING

PUMPING/SAMPLING		EQUIPMENT		DECONTAMINATION	
[X]	[X]	Peristaltic Pump	Geopump peristaltic pump	[ ]	FLUIDS USED:
[ ]	[ ]	Submersible	Water Level Meter: <u>Heion dipper T</u>	[X]	DISTILLED WATER
[ ]	[ ]	Bladder pump	YSI <u>Pro F</u> sonde with <u>250</u> mL flow cell	[ ]	DEIONIZED WATER
[ ]	[ ]	Hand pump	YSI Sonde SN: <u>17E100949</u>	[ ]	POTABLE WATER
[ ]	[ ]	Dedicated HDPE	YSI <u>Pro F</u> Handset	[X]	TSP SOLUTION
[X]	[X]	New HDPE	YSI Handset SN: <u>17E10092</u>	[ ]	ALCONOX SOLUTION
[ ]	[ ]	Dedicated Teflon Lined LDPE	Hach 2100 Turbidity Meter	[ ]	NONE
[ ]	[ ]	New Teflon Lined LDPE	Turbidity Meter SN: <u>2012D002142</u>	[ ]	
[ ]	[ ]	Filter (0.45 micron)	Sampler: <u>C. Boehm</u>	[ ]	

FIELD ANALYSIS DATA:									
TIME	TEMP (°C)	pH	SP COND. (mS/cm)	ORP (mV)	D.O. (mg/l)	TURBID. (ntu)	Flow Rate (mL/min)	DTW (ft)	Comments/Flow Rate (indicate stable flow rate)
1000							200	24.93	1000 Pulse
1005							320	25.00	Started
1010						198	320	25.00	water
1015						10.2	320	25.00	Color: opaque
1020	16.4	6.47	0.351	-232.4	1.50	7.80	320	25.00	white
1025	16.3	6.52	0.359	-239.4	1.55	5.25	320	25.00	
1030	16.4	6.55	0.371	-240.9	1.60	3.80	320	25.00	
1035	16.4	6.66	0.377	-238.9	1.64	2.74	320	25.00	
1040	16.3	6.53	0.384	-235.0	1.71	2.31	320	25.00	
1045	16.5	6.53	0.392	-233.7	1.71	1.71	320	25.00	
1050	16.5	6.53	0.394	-232.7	1.72	1.44	320	25.00	
1055	sampled								
	3%	±0.1	3%	±10	10%, <0.5	<5	100-400 mL/min		

SAMPLE BOTTLE ID		PRESERVATION	SAMPLE CONTAINER		LABORATORY
TIME	LOCATION	METHOD	#	TYPE	ANALYSIS
1055	CA-MW-3	HCL	2	1 L. Ifer Amber	EPH
		HCL	1	40 ml VOA	VPH

<b>PURGE DATA</b>	<input checked="" type="checkbox"/> 0.04 GAL/FT (1" DIAM.)	x length of water column = 3.98	Stable flow not achieved, sampled via no-purge: <input type="checkbox"/>
	<input type="checkbox"/> 0.16 GAL/FT (2" DIAM.)	Total Well Volume: 0.16 g	
	<input type="checkbox"/> 0.65 GAL/FT (4" DIAM.)	Total Purge Volume: 4.3 g	
	<input type="checkbox"/> 1.47 GAL/FT (6" DIAM.)	# of well volumes: 26.19	
		 SAMPLER	



## **APPENDIX D**

### **SAMPLING CREDENTIALS**





THE COMMONWEALTH OF MASSACHUSETTS  
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT  
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan  
Interim Director

Asbestos Inspector

MOIRA A WENTWORTH

Eff. Date 03/10/20

Exp. Date 03/10/21

AI900652

Member of C.O.N.E.S.

BOSR

BOS-RENEW

21





## **APPENDIX E**

### **LABORATORY ANALYTICAL REPORTS**





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number: Client Sample ID: Volume (L): Sample Location:	622101311-0001 CA-AIR-01 150 Boiler Room			622101311-0002 CA-AIR-02 150 Outside			622101311-0003 CA-AIR-03 150 Gym/Café		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	5	100	0.3	-	-	-
Ascospores	-	-	-	22	460	1.3	14	300	4.2
Aspergillus/Penicillium	676	14300	97.2	-	-	-	86	1800	25.3
Basidiospores	12	250	1.7	1440	30400	85.7	205	4330	60.9
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	6	100	0.7	153	3230	9.1	15	320	4.5
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	3	60	0.4	51	1100	3.1	16	340	4.8
Myxomycetes++	-	-	-	4	80	0.2	-	-	-
Pithomyces++	-	-	-	6	100	0.3	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	3*	20*	0.3
Total Fungi	697	14710	100	1681	35470	100	339	7110	100
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	2	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0004			622101311-0005			622101311-0006		
Client Sample ID:	CA-AIR-04			CA-AIR-05			CA-AIR-06		
Volume (L):	150			150			150		
Sample Location:	Kitchen			Boys Locker Room			Room 14		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	12	250	1.5	5	100	0.3	9	200	8.8
Aspergillus/Penicillium	121	2550	15.4	1430	30200	89.2	13	270	11.8
Basidiospores	550	11600	69.8	134	2830	8.4	56	1200	52.6
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	70	1500	9	16	340	1	19	400	17.5
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	26	550	3.3	16	340	1	10	210	9.2
Myxomycetes++	3	60	0.4	3	60	0.2	-	-	-
Pithomyces++	5	100	0.6	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
<b>Total Fungi</b>	<b>787</b>	<b>16610</b>	<b>100</b>	<b>1604</b>	<b>33870</b>	<b>100</b>	<b>107</b>	<b>2280</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0007			622101311-0008			622101311-0009		
Client Sample ID:	CA-AIR-07			CA-AIR-08			CA-AIR-09		
Volume (L):	150			150			150		
Sample Location:	Room 11			Room 10			Room 13		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	1	20	0.7	2	40	1.7	2	40	1.5
Aspergillus/Penicillium	9	200	6.8	17	360	15.5	25	530	19.9
Basidiospores	93	2000	67.6	76	1600	68.7	81	1700	63.7
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	19	400	13.5	11	230	9.9	14	300	11.2
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	16	340	11.5	6	100	4.3	7	100	3.7
Myxomycetes++	-	-	-	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
<b>Total Fungi</b>	<b>138</b>	<b>2960</b>	<b>100</b>	<b>112</b>	<b>2330</b>	<b>100</b>	<b>129</b>	<b>2670</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0010			622101311-0011			622101311-0012		
Client Sample ID:	CA-AIR-10			CA-AIR-11			CA-AIR-12		
Volume (L):	150			150			150		
Sample Location:	Boys Locker Hallway			C-1 Entry			Room 21		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	1	20	0.1
Ascospores	6	100	3.8	7	100	2.4	7	100	0.3
Aspergillus/Penicillium	38	800	30.1	18	380	9.1	6	100	0.3
Basidiospores	1	20	0.8	139	2930	70.5	1440	30400	95.8
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	64	1400	52.6	16	340	8.2	32	680	2.1
Curvularia	-	-	-	-	-	-	1	20	0.1
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	15	320	12	19	400	9.6	17	360	1.1
Myxomycetes++	-	-	-	-	-	-	2	40	0.1
Pithomyces++	1	20	0.8	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	1	20	0.1
Polythrincium	-	-	-	1*	7*	0.2	-	-	-
<b>Total Fungi</b>	<b>125</b>	<b>2660</b>	<b>100</b>	<b>200</b>	<b>4157</b>	<b>100</b>	<b>1507</b>	<b>31740</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0013			622101311-0014			622101311-0015		
Client Sample ID:	CA-AIR-13			CA-AIR-14			CA-AIR-15		
Volume (L):	150			150			150		
Sample Location:	Room 25			Room L1-1			Room D1-2		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	1	20	1.3
Ascospores	6	100	3.2	7	100	9.2	5	100	6.7
Aspergillus/Penicillium	8	200	6.3	2	40	3.7	2	40	2.7
Basidiospores	82	1700	53.8	20	420	38.5	36	760	51
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	42	890	28.2	15	320	29.4	14	300	20.1
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	13	270	8.5	10	210	19.3	12	250	16.8
Myxomycetes++	-	-	-	-	-	-	1	20	1.3
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
<b>Total Fungi</b>	<b>151</b>	<b>3160</b>	<b>100</b>	<b>54</b>	<b>1090</b>	<b>100</b>	<b>71</b>	<b>1490</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0016			622101311-0017			622101311-0018		
Client Sample ID:	CA-AIR-16			CA-AIR-17			CA-AIR-18		
Volume (L):	150			150			150		
Sample Location:	T-1-1 Bath			Room 36			Room 33		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	1	20	1.9	-	-	-	1	20	0.8
Ascospores	-	-	-	8	200	10.4	5	100	4.2
Aspergillus/Penicillium	3	60	5.7	3	60	3.1	11	230	9.7
Basidiospores	23	490	46.7	41	870	45.1	54	1100	46.2
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	13	270	25.7	20	420	21.8	28	590	24.8
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	10	210	20	18	380	19.7	16	340	14.3
Myxomycetes++	-	-	-	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
<b>Total Fungi</b>	<b>50</b>	<b>1050</b>	<b>100</b>	<b>90</b>	<b>1930</b>	<b>100</b>	<b>115</b>	<b>2380</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "\*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	622101311-0019			622101311-0020			622101311-0021		
Client Sample ID:	CA-AIR-19			CA-AIR-20			CA-AIR-21		
Volume (L):	150			150			150		
Sample Location:	Room 30			Room T2-2 Bath			Girls Locker Room		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	4	80	2.7	7	100	3.7	10	210	0.7
Aspergillus/Penicillium	2	40	1.4	9	200	7.4	1340	28300	90.4
Basidiospores	78	1600	54.4	76	1600	58.8	36	760	2.4
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	37	780	26.5	28	590	21.7	83	1800	5.7
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	-	-	-
Ganoderma	20	420	14.3	11	230	8.5	12	250	0.8
Myxomycetes++	1	20	0.7	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
<b>Total Fungi</b>	<b>142</b>	<b>2940</b>	<b>100</b>	<b>131</b>	<b>2720</b>	<b>100</b>	<b>1481</b>	<b>31320</b>	<b>100</b>
Hyphal Fragment	-	-	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	21	-	-	21	-	-	21	-
Analyt. Sensitivity 300x	-	7*	-	-	7*	-	-	7*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	2	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. \*\*\*\* Denotes particles found at 300X. \*- Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





EMSL ANALYTICAL, INC.  
TESTING LABS • PRODUCTS • TRAINING

## Microbiology Chain of Custody Form

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077

PHONE: (800) 220-3675

EMAIL: CinnMicroLab@emsl.com

622101311

If Bill-To is the same as Report-To leave this section blank. Third-party billing requires written authorization.

Customer Information	Customer ID:	Billing ID: <u>Same</u>
	Company Name: <u>Credere Associates</u>	Company Name:
	Contact Name: <u>Maura Wentworth</u>	Billing Contact:
	Street Address: <u>776 Main Street</u>	Street Address:
	City, State, Zip: <u>Westbrook, ME 04092</u> Country: <u>USA</u>	City, State, Zip: Country:
	Phone: <u>207-828-1272 x36</u>	Phone:
Email(s) for Report: <u>mwentworth@credereallc.com</u>	Email(s) for Invoice:	

## Project Information

Project Name/No: <u>Brown School / 21001628</u>	Purchase Order:
EMSL LIMS Project ID: (If applicable, EMSL will provide)	State of Connecticut (CT) must select project location: <input type="checkbox"/> Commercial (Taxable) <input type="checkbox"/> Residential (Non-taxable)
State Samples Collected: <u>MA</u> Zip Code Samples Collected: <u>01950</u>	
Sampled By Name: <u>C. Beahm</u>	Sampled By Signature: <u>[Signature]</u>
	No. of Samples in Shipment: <u>27</u>

Sterile, Sodium Thiosulfate Preserved Bottle Used: ☐ Biocide Used in Source (specify)Public Water Supply Samples: ☐ Note: All results may automatically be reported to DOH if required by State.

Turn-Around-Time (TAT) Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.	
<input type="checkbox"/> 3 Hour	<input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 32* Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input checked="" type="checkbox"/> 2 Week

## MICROBIOLOGY TEST CODES

<b>M001</b> Air-O-Cell	<b>M174</b> MoldSnap	<b>M012</b> <i>Pseudomonas aeruginosa</i> (P/A***)	<b>M115</b> Sewage Screen - Water (P/A***)
<b>M030</b> Micro 5	<b>M032</b> Allergenco-D	<b>M024</b> <i>Pseudomonas aeruginosa</i> (MFT*)	<b>M116</b> Sewage Screen - Water (MPN**)
<b>M041</b> Fungal Direct Examination		<b>M015</b> Heterotrophic Plate Count	<b>M117</b> Sewage Screen - Swab (P/A***)
<b>M169</b> Pollen ID & Enumeration		<b>M017</b> Total Coliform & <i>E. Coli</i> (Colilert P/A***)	<b>M013</b> Sewage Screen - Swab (MFT*)
<b>M280</b> Dust Characterization Level-1		<b>M018</b> Total Coliform & <i>E. Coli</i> (MFT*)	<b>M730</b> Methicillin-resistant <i>Staph. aureus</i> (MRSA)
<b>M281</b> Dust Characterization Level-2		<b>M114</b> Total Coliform & <i>E. Coli</i> Enumeration (Colilert MPN**)	<b>M031</b> Rapid-growing non-TB <i>Mycobacteria</i> Detection & Enumeration
<b>M005</b> Viable Fungi-Air Samples (Genus ID & Count)		<b>M019</b> Fecal Coliform (MFT*)	<b>M014</b> Endotoxin Analysis
<b>M006</b> Viable Fungi-Air Samples (Includes <i>Penicillium</i> , <i>Aspergillus</i> , <i>Cladosporium</i> , <i>Stachybotrys</i> Species ID & Count)		<b>M020</b> Fecal <i>Streptococcus</i> (MFT*)	<b>M044</b> Group Allergen (Cat, Dog, Cockroach, Dust Mite)
<b>M007</b> Culturable Fungi-Surface Samples (Genus ID & Count)		<b>M029</b> <i>Enterococci</i> (MFT*)	<b>M095</b> Bacteroides
<b>M008</b> Culturable Fungi-Surface Samples (Includes <i>Penicillium</i> , <i>Aspergillus</i> , <i>Cladosporium</i> , <i>Stachybotrys</i> Species ID & Count)		<b>M129</b> <i>Enterococci</i> (Enterolert P/A***)	Other - See Analytical Price Guide for Test Code
<b>M009</b> Bacteria Culture Gram Stain & Count		<b>M180</b> Real Time qPCR-ERMI 36 Panel	<b>Legionella Analysis</b> Please use EMSL <i>Legionella</i> COC
<b>M010</b> Bacteria Count & ID - 3 Most Prominent		<b>M025</b> Sewage Screen - Water (MFT*)	
<b>M011</b> Bacteria Count & ID - 5 Most Prominent		*MFT= Membrane Filtration Technique	
		**MPN = Most Probable Number	
		***P/A = Presence/Absence	

Sample #	Sample Location/Description	Sample Type (Matrix)	Potable / Non-Potable (Only for Water)	Test Code	Volume/Area	Date / Time Collected	Temperature (Lab Use Only)
Example: Sample 1	Kitchen	Water	Potable	M017	1,000 ml	1/1/2021 3:30pm	
CA-AIR-01	Boiler Room	Air		M032	150L	8/25/21 1105	
CA-AIR-02	Outside					8/25/21 1105	
CA-AIR-03	Gym/Cafe					8/25/21 1135	
CA-AIR-04	Kitchen					8/25/21 1140	
CA-AIR-05	Boys Locker Room					8/25/21 1155	
CA-AIR-06	Room 14					8/25/21 1225	

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Method of Shipment: <u>Walk in</u>	Sample Condition Upon Receipt:
Relinquished by: <u>[Signature]</u>	Received by: <u>[Signature]</u>
Date/Time: <u>8/26/21 1:55</u>	Date/Time: <u>8/26/21 4:00pm</u>
Relinquished by:	Received by:
Date/Time:	Date/Time:

Controlled Document - COC-34 Micro R13 03/02/2021



AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.









# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

**Attn:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272  
**Fax:** (207) 887-1051  
**Collected:**  
**Received:** 8/26/2021  
**Analyzed:** 9/14/2021

**Proj:** Brown School / 21001628

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-01A **Lab Sample ID:** 622101312-0001  
**Sample Description:** C-5/2X3 CEILING TILE, DOT SQUIGGLE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	95.0%	5.0%	None Detected	

**Client Sample ID:** CA-SACM-01B **Lab Sample ID:** 622101312-0002  
**Sample Description:** 15/2X3 CEILING TILE, DOT SQUIGGLE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	95.0%	5.0%	None Detected	

**Client Sample ID:** CA-SACM-02A **Lab Sample ID:** 622101312-0003  
**Sample Description:** C-5/SHEETROCK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-02B **Lab Sample ID:** 622101312-0004  
**Sample Description:** J-2/SHEETROCK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-03A **Lab Sample ID:** 622101312-0005  
**Sample Description:** C-5/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-03B **Lab Sample ID:** 622101312-0006  
**Sample Description:** J-2/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-03C **Lab Sample ID:** 622101312-0007  
**Sample Description:** 15/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-04A **Lab Sample ID:** 622101312-0008

**Sample Description:** J-3/CAULK, TAN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Tan	0.0%	98.6%	1.4% Chrysotile	

**Client Sample ID:** CA-SACM-04B **Lab Sample ID:** 622101312-0009

**Sample Description:** C-7/CAULK, TAN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-05A **Lab Sample ID:** 622101312-0010

**Sample Description:** J-3/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-05B **Lab Sample ID:** 622101312-0011

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-05C **Lab Sample ID:** 622101312-0012

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06A **Lab Sample ID:** 622101312-0013

**Sample Description:** J-3/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06B **Lab Sample ID:** 622101312-0014

**Sample Description:** C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06C **Lab Sample ID:** 622101312-0015

**Sample Description:** C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-07A **Lab Sample ID:** 622101312-0016

**Sample Description:** 15/12" FLOOR TILE, BLUE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Blue	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-07B **Lab Sample ID:** 622101312-0017

**Sample Description:** 16/12" FLOOR TILE, BLUE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Blue	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-08A **Lab Sample ID:** 622101312-0018

**Sample Description:** 15/BASE ADHESIVE, OFF-WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-08B **Lab Sample ID:** 622101312-0019

**Sample Description:** 16/BASE ADHESIVE, OFF-WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-09A **Lab Sample ID:** 622101312-0020

**Sample Description:** 16/2X3 CEILING TILE, DOT SQUIGGLE #2

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	95.0%	5.0%	None Detected	

**Client Sample ID:** CA-SACM-09B **Lab Sample ID:** 622101312-0021

**Sample Description:** T-5/2X3 CEILING TILE, DOT SQUIGGLE #2

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	95.0%	5.0%	None Detected	

**Client Sample ID:** CA-SACM-10A **Lab Sample ID:** 622101312-0022

**Sample Description:** T-5/2X3 CEILING TILE, SMALL DENTS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-10B **Lab Sample ID:** 622101312-0023

**Sample Description:** T-4/2X3 CEILING TILE, SMALL DENTS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-11A **Lab Sample ID:** 622101312-0024

**Sample Description:** T-4/TILE UNDERLAYMENT, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-11B **Lab Sample ID:** 622101312-0025

**Sample Description:** T1-2/TILE UNDERLAYMENT, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-12A **Lab Sample ID:** 622101312-0026

**Sample Description:** T-4/TILE UNDERLAYMENT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-12B **Lab Sample ID:** 622101312-0027

**Sample Description:** T1-2/TILE UNDERLAYMENT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-13A **Lab Sample ID:** 622101312-0028

**Sample Description:** STAIR 1/STAIR TREAD, ORANGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Orange	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-13B **Lab Sample ID:** 622101312-0029

**Sample Description:** STAIR 2/STAIR TREAD, ORANGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Orange	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-14A **Lab Sample ID:** 622101312-0030

**Sample Description:** STAIR 1/STAIR TREAD MASTIC, BROWN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Brown	0.0%	89.0%	11.0% Chrysotile	

**Client Sample ID:** CA-SACM-14B **Lab Sample ID:** 622101312-0031

**Sample Description:** STAIR 2/STAIR TREAD MASTIC, BROWN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-15A **Lab Sample ID:** 622101312-0032

**Sample Description:** GL-1/SHEETROCK, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	5.0%	95.0%	None Detected	

**Client Sample ID:** CA-SACM-15B **Lab Sample ID:** 622101312-0033

**Sample Description:** GL-2/SHEETROCK, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	5.0%	95.0%	None Detected	

**Client Sample ID:** CA-SACM-16A **Lab Sample ID:** 622101312-0034

**Sample Description:** GL-1/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-16B **Lab Sample ID:** 622101312-0035

**Sample Description:** GL-1/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-16C **Lab Sample ID:** 622101312-0036

**Sample Description:** GL-1/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-17A **Lab Sample ID:** 622101312-0037

**Sample Description:** GL-1/CARPET ADHESIVE, BEIGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-17B **Lab Sample ID:** 622101312-0038

**Sample Description:** GL-1/CARPET ADHESIVE, BEIGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-18A **Lab Sample ID:** 622101312-0039

**Sample Description:** C-1/9" FLOOR TILE, TAN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Tan	0.0%	94.5%	5.5% Chrysotile	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-18B **Lab Sample ID:** 622101312-0040

**Sample Description:** C-2/9" FLOOR TILE, TAN

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-19A **Lab Sample ID:** 622101312-0041

**Sample Description:** GL-1/PIPE INSULATION, LAYERED PAPER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	<1% Chrysotile	

**Client Sample ID:** CA-SACM-19B **Lab Sample ID:** 622101312-0042

**Sample Description:** GL-1/PIPE INSULATION, LAYERED PAPER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	<1% Chrysotile	

**Client Sample ID:** CA-SACM-19C **Lab Sample ID:** 622101312-0043

**Sample Description:** GL-1/PIPE INSULATION, LAYERED PAPER

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	<1% Chrysotile	

**Client Sample ID:** CA-SACM-21A **Lab Sample ID:** 622101312-0044

**Sample Description:** GL-1/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-21B **Lab Sample ID:** 622101312-0045

**Sample Description:** GL-1/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-21C **Lab Sample ID:** 622101312-0046

**Sample Description:** GL-1/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-22A **Lab Sample ID:** 622101312-0047

**Sample Description:** GL-1/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-22B **Lab Sample ID:** 622101312-0048

**Sample Description:** GL-1/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-22C **Lab Sample ID:** 622101312-0049

**Sample Description:** GL-1/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-24A **Lab Sample ID:** 622101312-0050

**Sample Description:** 21 EXT/GLAZING, GRAY - ORIG.

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	98.7%	1.3% Chrysotile	

**Client Sample ID:** CA-SACM-24B **Lab Sample ID:** 622101312-0051

**Sample Description:** 32 EXT/GLAZING, GRAY - ORIG.

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-25A **Lab Sample ID:** 622101312-0052

**Sample Description:** 21 EXT/CAULK, WHITE - ORIG.

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	98.7%	1.3% Chrysotile	

**Client Sample ID:** CA-SACM-25B **Lab Sample ID:** 622101312-0053

**Sample Description:** 32 EXT/CAULK, WHITE - ORIG.

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-26A **Lab Sample ID:** 622101312-0054

**Sample Description:** C7-7/12" FLOOR TILE, OFF-WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-26B **Lab Sample ID:** 622101312-0055

**Sample Description:** C2-3/12" FLOOR TILE, OFF-WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-27A **Lab Sample ID:** 622101312-0056

**Sample Description:** C7-7/MASTIC, BLACK

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Black	0.0%	93.1%	6.9% Chrysotile	

**Client Sample ID:** CA-SACM-27B **Lab Sample ID:** 622101312-0057

**Sample Description:** C2-3/MASTIC, BLACK

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-28A **Lab Sample ID:** 622101312-0058

**Sample Description:** C7-7/BASE ADHESIVE, CREAM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-28B **Lab Sample ID:** 622101312-0059

**Sample Description:** C2-3/BASE ADHESIVE, CREAM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-29A **Lab Sample ID:** 622101312-0060

**Sample Description:** J1-1/2X3 CEILING TILE, DENTS + DOTS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-29B **Lab Sample ID:** 622101312-0061

**Sample Description:** J1-1/2X3 CEILING TILE, DENTS + DOTS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-30A **Lab Sample ID:** 622101312-0062

**Sample Description:** 24/12" FLOOR TILE, CREAM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-30B **Lab Sample ID:** 622101312-0063

**Sample Description:** 36/12" FLOOR TILE, CREAM

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Beige	0.0%	100%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-31A **Lab Sample ID:** 622101312-0064

**Sample Description:** 25/BASE ADHESIVE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Tan	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-31B **Lab Sample ID:** 622101312-0065

**Sample Description:** 36/BASE ADHESIVE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Tan	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-32A **Lab Sample ID:** 622101312-0066

**Sample Description:** L7-7/SHEETROCK, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-32B **Lab Sample ID:** 622101312-0067

**Sample Description:** 30/SHEETROCK, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-33A **Lab Sample ID:** 622101312-0068

**Sample Description:** L7-7/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-33B **Lab Sample ID:** 622101312-0069

**Sample Description:** L7-7/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-33C **Lab Sample ID:** 622101312-0070

**Sample Description:** 30/JOINT COMPOUND, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/10/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-34A **Lab Sample ID:** 622101312-0071

**Sample Description:** M7-7/12" FLOOR TILE, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
 Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
 Customer ID: CRED25  
 Customer PO:  
 Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-34B **Lab Sample ID:** 622101312-0072

**Sample Description:** M7-7/12" FLOOR TILE, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-35A **Lab Sample ID:** 622101312-0073

**Sample Description:** A SIDE IN FILL/CAULK, DARK GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	2.6%	97.4%	None Detected	

**Client Sample ID:** CA-SACM-35B **Lab Sample ID:** 622101312-0074

**Sample Description:** A SIDE IN FILL/CAULK, DARK GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	1.9%	98.1%	None Detected	

**Client Sample ID:** CA-SACM-36A **Lab Sample ID:** 622101312-0075

**Sample Description:** A SIDE IN FILL/CAULK, BROWN/RED

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Brown	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-36B **Lab Sample ID:** 622101312-0076

**Sample Description:** A SIDE IN FILL/CAULK, BROWN/RED

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Brown	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-37A **Lab Sample ID:** 622101312-0077

**Sample Description:** A SIDE IN FILL/CAULK, DK. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.65%	99.3%	None Detected	

**Client Sample ID:** CA-SACM-37B **Lab Sample ID:** 622101312-0078

**Sample Description:** A SIDE IN FILL/CAULK, DK. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.70%	99.3%	None Detected	

**Client Sample ID:** CA-SACM-38A **Lab Sample ID:** 622101312-0079

**Sample Description:** A2-1/SINK COAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	93.5%	6.5% Chrysotile	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-38B **Lab Sample ID:** 622101312-0080

**Sample Description:** A2-1/SINK COAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021					Positive Stop (Not Analyzed)

**Client Sample ID:** CA-SACM-40A **Lab Sample ID:** 622101312-0081

**Sample Description:** G-1/12" FLOOR TILE, LT. BLUE/GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Blue	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-40B **Lab Sample ID:** 622101312-0082

**Sample Description:** G-2/12" FLOOR TILE, LT. BLUE/GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Blue	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-41A **Lab Sample ID:** 622101312-0083

**Sample Description:** G-1/MASTIC, BLACK

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Black	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-41B **Lab Sample ID:** 622101312-0084

**Sample Description:** G-2/MASTIC, BLACK

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Black	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-42A **Lab Sample ID:** 622101312-0085

**Sample Description:** B SIDE EXTERIOR/CAULK, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	85.7%	14.3% Chrysotile	

**Client Sample ID:** CA-SACM-42B **Lab Sample ID:** 622101312-0086

**Sample Description:** B SIDE EXTERIOR/CAULK, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021					Positive Stop (Not Analyzed)

**Client Sample ID:** CA-SACM-43A **Lab Sample ID:** 622101312-0087

**Sample Description:** B SIDE EXTERIOR/CAULK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-43B **Lab Sample ID:** 622101312-0088

**Sample Description:** B SIDE EXTERIOR/CAULK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-44A **Lab Sample ID:** 622101312-0089

**Sample Description:** A SIDE EXTERIOR/CAULK, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.61%	99.4%	None Detected	

**Client Sample ID:** CA-SACM-44B **Lab Sample ID:** 622101312-0090

**Sample Description:** A SIDE EXTERIOR/CAULK, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	2.3%	97.7%	None Detected	

**Client Sample ID:** CA-SACM-45A **Lab Sample ID:** 622101312-0091

**Sample Description:** B SIDE EXTERIOR/CAULK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	White	0.0%	97.7%	2.3% Chrysotile	

**Client Sample ID:** CA-SACM-45B **Lab Sample ID:** 622101312-0092

**Sample Description:** B SIDE EXTERIOR/CAULK, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-47A **Lab Sample ID:** 622101312-0093

**Sample Description:** D SIDE EXTERIOR/GLAZING, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Gray	0.0%	98.8%	1.2% Chrysotile	

**Client Sample ID:** CA-SACM-47B **Lab Sample ID:** 622101312-0094

**Sample Description:** D SIDE EXTERIOR/GLAZING, LT. GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-48A **Lab Sample ID:** 622101312-0095

**Sample Description:** M1-1/LINOLEUM, ORANGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021	Orange	0.0%	86.1%	13.9% Chrysotile	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-48B **Lab Sample ID:** 622101312-0096

**Sample Description:** M1-1/LINOLEUM, ORANGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/10/2021				Positive Stop (Not Analyzed)	

**Client Sample ID:** CA-SACM-05D **Lab Sample ID:** 622101312-0097

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-05E **Lab Sample ID:** 622101312-0098

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-05F **Lab Sample ID:** 622101312-0099

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-05G **Lab Sample ID:** 622101312-0100

**Sample Description:** C-5/PLASTER TOPCOAT, WHITE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06D **Lab Sample ID:** 622101312-0101

**Sample Description:** C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06E **Lab Sample ID:** 622101312-0102

**Sample Description:** C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** CA-SACM-06F **Lab Sample ID:** 622101312-0103

**Sample Description:** C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Gray	0.0%	100.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101312  
Customer ID: CRED25  
Customer PO:  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

Client Sample ID: CA-SACM-06G

Lab Sample ID: 622101312-0104

Sample Description: C-5/PLASTER BASECOAT, GRAY

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Gray	0.0%	100.0%	None Detected	

PLM: ME BA-0178

PLM EPA NOB: ME BA-0197

### Analyst(s):

Stephen Severn PLM (46)  
Thomas Stegeman PLM Grav. Reduction (47)

### Reviewed and approved by:

Samantha Voigt, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. South Portland, ME NVLAP Lab Code 500094-0, MA AA000236, VT AL197271, ME LM-0039, CT PH-0346

Report amended: 09/14/2021 18:41:19 Replaces initial report from: 09/10/2021 17:26:01 Reason Code: Client-Samples Added





## Asbestos Bulk Building Materials - Chain of Custody

EMSL Order Number / Lab Use Only

 EMSL Analytical, Inc.  
 200 Route 130 North  
 Cinnaminson, NJ 08077

 EMSL ANALYTICAL, INC.  
 TESTING LABS • PRODUCTS • TRAINING

622101312

PHONE: (800) 220-3675

EMAIL: CinnAslab@EMSL.com

<b>Customer Information</b> Customer ID: _____ Company Name: <u>Credene Assoc.</u> Contact Name: <u>Marc Wentworth</u> Street Address: <u>776 Main St</u> City, State, Zip: <u>Westbrook ME 04092</u> Country: <u>USA</u> Phone: <u>207-828-1272</u> Email(s) for Report: <u>mwentworth@credeneilk.com</u>		<b>Billing Information</b> Billing ID: _____ Company Name: <u>Same</u> Billing Contact: _____ Street Address: _____ City, State, Zip: _____ Country: _____ Phone: _____ Email(s) for Invoice: _____	
<b>Project Information</b>			
Project Name/No: <u>Brown School/21001628</u> EMSL LIMS Project ID: _____ (If applicable, EMSL will provide)		Purchase Order: _____ US State where samples collected: <u>MA</u> State of Connecticut (CT) must select project location: <input type="checkbox"/> Commercial (Taxable) <input type="checkbox"/> Residential (Non-Taxable)	
Sampled By Name: <u>M. Wentworth</u>		Sampled By Signature: <u>[Signature]</u>	
Turn-Around-Time (TAT) <input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 32 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input checked="" type="checkbox"/> 2 Week <small>Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.</small>			
<b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input checked="" type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> POINT COUNT <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) POINT COUNT w/ GRAVIMETRIC <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) <input type="checkbox"/> NIOSH 9002 (<1%) <input type="checkbox"/> NYS 198.1 (Friable - NY) <input type="checkbox"/> NYS 198.6 NOB (Non-Friable - NY) <input type="checkbox"/> NYS 198.8 (Vermiculite SM-V)		<b>Test Selection</b> <input type="checkbox"/> TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (Non-Friable-NY) <input type="checkbox"/> TEM EPA 600/R-93/116 w Milling Prep (0.1%) <b>Other Tests (please specify)</b> _____ <input checked="" type="checkbox"/> Positive Stop - Clearly Identified Homogeneous Areas (HA)	
<div style="border: 2px solid blue; padding: 5px; display: inline-block;"> <b>RECEIVED</b>  <b>AUG 26 2021</b>  <u>[Signature]</u> </div>			
Sample Number	HA Number	Sample Location	Material Description
CA-SACM-01 A, B	01	C-5, 15	2x3 ceiling tile dot squiggle
CA-SACM-02 A, B	02	C-5, J-2	sheetrock, white
CA-SACM-03 A, B, C	03	C-5, J-2, 15	joint compound, white
CA-SACM-04 A, B	04	J-3, C-7	caulk, tan
CA-SACM-05 A, B, C	05	J-3, C-5	plaster topcoat, white
CA-SACM-06 A, B, C	06	J-3, C-5	plaster basecoat gray
CA-SACM-07 A, B	07	15, 16	12" floor tile, blue
CA-SACM-08 A, B	08	15, 16	base adhesive, off-white
CA-SACM-09 A, B	09	16, T-5	2x3 ceiling tile dot squiggle #2
CA-SACM-10 A, B	10	T-5, T-4	2x3 ceiling tile small dents
Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)			
Method of Shipment: <u>walk in</u>		Sample Condition Upon Receipt: _____	
Relinquished by: <u>[Signature]</u> Date/Time: <u>8/26/21 1555</u>	Relinquished by: <u>[Signature]</u> Date/Time: _____	Received by: <u>[Signature]</u> Date/Time: <u>8/26/21 4:00pm</u>	Received by: _____ Date/Time: _____

Controlled Document - Asbestos Bulk R5 03/18/2021

☐ AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.





**EMSL ANALYTICAL, INC.**  
TESTING LABS • PRODUCTS • TRAINING

# Asbestos Bulk Building Materials - Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.

200 Route 130 North  
Cinnaminson, NJ 08077

PHONE: (800) 220-3675

EMAIL: CinnAslab@EMSL.com

## 622101312

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Sample Number	HA Number	Sample Location	Material Description
CA-SACM-11 A, B	11	<del>T-4</del> , T-4, T1-2	tile underlayment, lt. gray
CA-SACM-12 A, B	12	T-4, T1-2	tile underlayment, gray
CA-SACM-13 A, B	13	stair 1, stair 2	stair tread, orange
CA-SACM-14 A, B	14	stair 1, stair 2	stair tread mastic, brown
CA-SACM-15 A, B	15	GL-1, GL-1	sheetrock, gray
CA-SACM-16 A, B, C	16	GL-1, GL-1, GL-1	joint compound, white
CA-SACM-17 A, B	17	GL-1, GL-1	carpet adhesive, beige
CA-SACM-18 A, B	18	C-1, C-2	9" floor tile, tan
CA-SACM-19 A, B, C	19	GL-1, GL-1, GL-1	pipe insulation, layered
CA-SACM-21 A, B, C	21	GL-1, GL-1, GL-1	plaster topcoat, white
CA-SACM-22 A, B, C	22	GL-1, GL-1, GL-1	plaster basecoat, gray
CA-SACM-24 A, B	24	glaz 21 ext, 32 ext	glazing, gray - orig
CA-SACM-25 A, B	25	21 ext, 32 ext	caulk, white - orig
CA-SACM-26 A, B	26	C1-2, C2-3	12" floor tile, off white
CA-SACM-27 A, B	27	C1-2, C2-3	mastic, black
CA-SACM-28 A, B	28	C1-2, C2-3	base adhesive, cream
CA-SACM-29 A, B	29	J1-1, J1-1	2x3 ceiling tile, dents + dots
CA-SACM-30 A, B	30	24, 30	12" floor tile, cream
CA-SACM-31 A, B	31	25, 30	base adhesive
CA-SACM-32 A, B	32	L1-2, 30	Sheetrock, lt. gray
CA-SACM-33 A, B, C	33	L1-2, L1-2, 30	joint compound, white
CA-SACM-34 A, B	34	M1-2, M1-2	12" floor tile, white
CA-SACM-35 A, B	35	Aside infill, Aside infill	caulk, dark gray
CA-SACM-36 A, B	36	Aside infill, Aside infill	caulk, brown/red
CA-SACM-37 A, B	37	Aside infill, Aside infill	caulk, dk gray

Method of Shipment:

Sample Condition Upon Receipt:

Relinquished by:

Date/Time:

Received by:

Date/Time

Relinquished by:

Date/Time:

Received by:

Date/Time

Controlled Document - Asbestos Bulk R5 03/18/2021



AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



EMSL Order Number / Lab Use Only

PHONE: (800) 220-3675  
EMAIL: [CinnAslab@EMSL.com](mailto:CinnAslab@EMSL.com)

6 2 2 1 0 1 3 1 2

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

RECEIVED  
AUG 26 2021  
By se

Date/Time	Location	Activity	Remarks
10/10/2023	...	...	...

Page 3 of 3





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101360  
Customer ID: CRED25  
Customer PO:  
Project ID:

**Attn:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272  
**Fax:** (207) 887-1051  
**Collected:**  
**Received:** 9/02/2021  
**Analyzed:** 9/14/2021

**Proj:** Brown School 16001377

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-46A **Lab Sample ID:** 622101360-0001  
**Sample Description:** Gym Windows/Caulk, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	0.0%	86.8%	13.2% Chrysotile	

**Client Sample ID:** CA-SACM-46B **Lab Sample ID:** 622101360-0002  
**Sample Description:** Gym Windows/Caulk, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	0.0%	92.6%	7.4% Chrysotile	

**Client Sample ID:** CA-SACM-49A **Lab Sample ID:** 622101360-0003  
**Sample Description:** Roof/Caulk, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-49B **Lab Sample ID:** 622101360-0004  
**Sample Description:** Roof/Caulk, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	0.0%	100%	None Detected	

**Client Sample ID:** CA-SACM-50A **Lab Sample ID:** 622101360-0005  
**Sample Description:** Roof/Membrane, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	1.6%	98.4%	None Detected	

**Client Sample ID:** CA-SACM-50B **Lab Sample ID:** 622101360-0006  
**Sample Description:** Roof/Membrane, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	9/14/2021	White	2.0%	98.0%	None Detected	

**Client Sample ID:** CA-SACM-51A **Lab Sample ID:** 622101360-0007  
**Sample Description:** Roof/Paper, Black

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Black	50.0%	50.0%	None Detected	





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
 Phone/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order ID: 622101360  
 Customer ID: CRED25  
 Customer PO:  
 Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

**Client Sample ID:** CA-SACM-51B **Lab Sample ID:** 622101360-0008

**Sample Description:** Roof/Paper, Black

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	Black	50.0%	50.0%	None Detected	

**Client Sample ID:** CA-SACM-52A **Lab Sample ID:** 622101360-0009

**Sample Description:** Roof/Paper, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	35.0%	65.0%	None Detected	

**Client Sample ID:** CA-SACM-52B **Lab Sample ID:** 622101360-0010

**Sample Description:** Roof/Paper, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	35.0%	65.0%	None Detected	

**Client Sample ID:** CA-SACM-53A **Lab Sample ID:** 622101360-0011

**Sample Description:** Roof/Drywall, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	35.0%	65.0%	None Detected	

**Client Sample ID:** CA-SACM-53B **Lab Sample ID:** 622101360-0012

**Sample Description:** Roof/Drywall, White

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/14/2021	White	35.0%	65.0%	None Detected	

PLM: ME BA-0197

PLM EPA NOB: ME BA-0197

### Analyst(s):

Thomas Stegeman PLM (6)  
 PLM Grav. Reduction (6)

### Reviewed and approved by:

Samantha Voigt, Laboratory Manager  
 or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. South Portland, ME NVLAP Lab Code 500094-0, MA AA000236, VT AL197271, ME LM-0039, CT PH-0346




Initial report from: 09/17/2021 08:00:54



EMSL ANALYTICAL, INC.  
TESTING LABS • PRODUCTS • TRAINING

622101360

PHONE: (800) 220-3675  
EMAIL: CinnAslab@EMSL.com

<b>Customer Information</b>	Customer ID:		Billing ID:																																													
	Company Name: CREJERE ASSOCIATES LLC		Company Name:																																													
	Contact Name: MOIRA WENTWORTH		Billing Contact:																																													
	Street Address: 770 MAIN ST		Street Address:																																													
	City, State, Zip: WESTBROOK, ME 04092	Country: USA	City, State, Zip:	Country:																																												
	Phone: 207-828-1272		Phone:																																													
Email(s) for Report: MWENTWORTH@CREJEREASSOCIATES.COM		Email(s) for Invoice:																																														
<b>Project Information</b>																																																
Project Name/No: BROWN SCHOOL 16001377			Purchase Order:																																													
EMSL LIMS Project ID: (If applicable, EMSL will provide)			US State where samples collected: MA	State of Connecticut (CT) must select project location: <input type="checkbox"/> Commercial (Taxable) <input type="checkbox"/> Residential (Non-Taxable)																																												
Sampled By Name: MOIRA WENTWORTH		Sampled By Signature: 		No. of Samples in Shipment																																												
Turn-Around-Time (TAT)																																																
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 32 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input checked="" type="checkbox"/> 1 Week <input checked="" type="checkbox"/> 2 Week																																																
Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.																																																
<table style="width:100%;"> <tr> <td style="width:50%; vertical-align: top;"> <b>PLM - Bulk (reporting limit)</b>  <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (&lt;1%)  <input checked="" type="checkbox"/> PLM EPA NOB (&lt;1%)  <input type="checkbox"/> POINT COUNT              <input type="checkbox"/> 400 (&lt;0.25%)    <input type="checkbox"/> 1,000 (&lt;0.1%)          POINT COUNT w/ GRAVIMETRIC              <input type="checkbox"/> 400 (&lt;0.25%)    <input type="checkbox"/> 1,000 (&lt;0.1%)  <input type="checkbox"/> NIOSH 9002 (&lt;1%)  <input type="checkbox"/> NYS 198.1 (Friable - NY)  <input type="checkbox"/> NYS 198.6 NOB (Non-Friable - NY)  <input type="checkbox"/> NYS 198.8 (Vermiculite SM-V)       </td> <td style="width:50%; vertical-align: top;"> <b>Test Selection</b>  <div style="text-align: right;"><b>TEM - Bulk</b></div> <input type="checkbox"/> TEM - Bulk  <input type="checkbox"/> TEM EPA NOB  <input type="checkbox"/> NYS NOB 198.4 (Non-Friable-NY)  <input type="checkbox"/> TEM EPA 600/R-93/116 w Milling Prep (0.1%)  <div style="text-align: right;"><b>Other Tests (please specify)</b></div> <input type="checkbox"/> Positive Stop - Clearly Identified Homogeneous Areas (HA)       </td> </tr> </table>					<b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input checked="" type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> POINT COUNT <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) POINT COUNT w/ GRAVIMETRIC <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) <input type="checkbox"/> NIOSH 9002 (<1%) <input type="checkbox"/> NYS 198.1 (Friable - NY) <input type="checkbox"/> NYS 198.6 NOB (Non-Friable - NY) <input type="checkbox"/> NYS 198.8 (Vermiculite SM-V)	<b>Test Selection</b> <div style="text-align: right;"><b>TEM - Bulk</b></div> <input type="checkbox"/> TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (Non-Friable-NY) <input type="checkbox"/> TEM EPA 600/R-93/116 w Milling Prep (0.1%) <div style="text-align: right;"><b>Other Tests (please specify)</b></div> <input type="checkbox"/> Positive Stop - Clearly Identified Homogeneous Areas (HA)																																										
<b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input checked="" type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> POINT COUNT <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) POINT COUNT w/ GRAVIMETRIC <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1,000 (<0.1%) <input type="checkbox"/> NIOSH 9002 (<1%) <input type="checkbox"/> NYS 198.1 (Friable - NY) <input type="checkbox"/> NYS 198.6 NOB (Non-Friable - NY) <input type="checkbox"/> NYS 198.8 (Vermiculite SM-V)	<b>Test Selection</b> <div style="text-align: right;"><b>TEM - Bulk</b></div> <input type="checkbox"/> TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (Non-Friable-NY) <input type="checkbox"/> TEM EPA 600/R-93/116 w Milling Prep (0.1%) <div style="text-align: right;"><b>Other Tests (please specify)</b></div> <input type="checkbox"/> Positive Stop - Clearly Identified Homogeneous Areas (HA)																																															
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Sample Number</th> <th style="width:10%;">HA Number</th> <th style="width:35%;">Sample Location</th> <th style="width:40%;">Material Description</th> </tr> </thead> <tbody> <tr> <td>CA-SACM-46</td> <td>A</td> <td>CYM WINDOWS</td> <td>CAULK, WHITE</td> </tr> <tr> <td>CA-SACM-49</td> <td>A</td> <td>ROOF</td> <td>CAULK, WHITE</td> </tr> <tr> <td>CA-SACM-50</td> <td>B</td> <td>ROOF</td> <td>MEMBRANE WHITE</td> </tr> <tr> <td>CA-SACM-51</td> <td>A</td> <td>ROOF</td> <td>PAPER, BLACK</td> </tr> <tr> <td>CA-SACM-52</td> <td>B</td> <td>ROOF</td> <td>PAPER, WHITE</td> </tr> <tr> <td>CA-SACM-53</td> <td>A</td> <td>ROOF</td> <td>DRYWALL, WHITE</td> </tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>					Sample Number	HA Number	Sample Location	Material Description	CA-SACM-46	A	CYM WINDOWS	CAULK, WHITE	CA-SACM-49	A	ROOF	CAULK, WHITE	CA-SACM-50	B	ROOF	MEMBRANE WHITE	CA-SACM-51	A	ROOF	PAPER, BLACK	CA-SACM-52	B	ROOF	PAPER, WHITE	CA-SACM-53	A	ROOF	DRYWALL, WHITE																
Sample Number	HA Number	Sample Location	Material Description																																													
CA-SACM-46	A	CYM WINDOWS	CAULK, WHITE																																													
CA-SACM-49	A	ROOF	CAULK, WHITE																																													
CA-SACM-50	B	ROOF	MEMBRANE WHITE																																													
CA-SACM-51	A	ROOF	PAPER, BLACK																																													
CA-SACM-52	B	ROOF	PAPER, WHITE																																													
CA-SACM-53	A	ROOF	DRYWALL, WHITE																																													
Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) <div style="float: right; border: 2px solid blue; padding: 5px; text-align: center;"> <b>RECEIVED</b>  <b>SEP 02 2021</b>          By <u>TS</u> </div>																																																
Method of Shipment:		Sample Condition Upon Receipt:																																														
Relinquished by: 	Date/Time: 9/2/21 1547	Received by: 	Date/Time: 4:00pm																																													

Controlled Document - Asbestos Bulk R5 03/18/2021

☐ AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



# Laboratory Report



**Absolute Resource** *associates*

124 Heritage Avenue Portsmouth NH 03801

Moira Wentworth  
CREDERE Associates  
776 Main Street  
Westbrook, ME 04092

PO Number: None  
Job ID: 58581  
Date Received: 9/10/21

Project: Brown School 21001628

Attached please find results for the analysis of the samples received on the date referenced above.

Unless otherwise noted in the attached report, the analyses performed met the requirements of Absolute Resource Associates' Quality Assurance Plan. The Standard Operating Procedures are based upon USEPA SW-846, USEPA Methods for Chemical Analysis of Water and Wastewater, Standard Methods for the Examination of Water and Wastewater and other recognized methodologies. The results contained in this report pertain only to the samples as indicated on the chain of custody.

Absolute Resource Associates maintains certification with the agencies listed below. The reported results apply to the sample(s) in the condition as received at the time the laboratory took custody. This report shall not be reproduced except in full, without written approval of the laboratory. The liability of ARA is limited to the cost of the requested analyses, unless otherwise agreed upon in writing.

We appreciate the opportunity to provide laboratory services. If you have any questions regarding the enclosed report, please contact the laboratory and we will be glad to assist you.

Sincerely,  
Absolute Resource Associates

A handwritten signature in black ink, appearing to read 'Aaron DeWees'.

Aaron DeWees  
Chief Operating Officer

Date of Approval: 10/5/2021  
Total number of pages: 21

## Absolute Resource Associates Certifications

New Hampshire 1732  
Maine NH902

Massachusetts M-NH902



## Sample Association Table

Field ID	Matrix	Date-Time Sampled	Lab#	Analysis
CA-MW-1	Water	9/9/2021 13:15	58581-001	EPH in water by MADEP Method VPH in water by MA DEP Method
CA-MW-2	Water	9/9/2021 9:40	58581-002	EPH in water by MADEP Method VPH in water by MA DEP Method
CA-MW-3	Water	9/9/2021 10:55	58581-003	EPH in water by MADEP Method VPH in water by MA DEP Method
Trip Blank	Water	9/9/2021 0:00	58581-004	VPH in water by MA DEP Method



**Project ID:** Brown School 21001628

**Job ID:** 58581

**Sample#:** 58581-001

**Sample ID:** CA-MW-1

**Matrix:** Water

Received on ice at 2°C, in satisfactory condition.

**Sampled:** 9/9/21 13:15

Sampled: 9/9/21 13:15		Reporting		Instr Dil'n		Prep		Analysis		
Parameter	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	Reference
Unadjusted C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
Unadjusted C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
methyl t-butyl ether (MTBE)	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
benzene	< 1	1	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
toluene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
ethylbenzene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
m&p-xylenes	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
o-xylene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
naphthalene	< 5	5	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
C9-C10 Aromatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:26	MA VPH
Surrogate Recovery		Limits								
2,5-dibromotoluene as Aromatic SUR	91	70-130	%	1	LMM		2102938	9/13/21	15:26	MA VPH
2,5-dibromotoluene as Aliphatic SUR	97	70-130	%	1	LMM		2102938	9/13/21	15:26	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 20001628

**Job ID:** 58581

**Sample#:** 58581-002

**Sample ID:** CA-MW-2

**Matrix:** Water

Received on ice at 2°C, in satisfactory condition.

**Sampled:** 9/9/21 9:40

Parameter	Reporting		Instr Dil'n		Analyst	Prep Date	Analysis			Reference
	Result	Limit	Units	Factor			Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
Unadjusted C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
methyl t-butyl ether (MTBE)	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
benzene	< 1	1	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
toluene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
ethylbenzene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
m&p-xylenes	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
o-xylene	< 2	2	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
naphthalene	< 5	5	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
C9-C10 Aromatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	15:59	MA VPH
<b>Surrogate Recovery</b>		<b>Limits</b>								
2,5-dibromotoluene as Aromatic SUR	<b>93</b>	70-130	%	1	LMM		2102938	9/13/21	15:59	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>99</b>	70-130	%	1	LMM		2102938	9/13/21	15:59	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 20001628

**Job ID:** 58581

**Sample#:** 58581-003

**Sample ID:** CA-MW-3

**Matrix:** Water

Received on ice at 2°C, in satisfactory condition.

**Sampled:** 9/9/21 10:55

Parameter	Reporting		Instr Dil'n		Analyst	Prep Date	Analysis			Reference
	Result	Limit	Units	Factor			Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
Unadjusted C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
methyl t-butyl ether (MTBE)	< 2	2	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
benzene	< 1	1	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
toluene	< 2	2	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
ethylbenzene	< 2	2	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
m&p-xylenes	< 2	2	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
o-xylene	< 2	2	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
naphthalene	< 5	5	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
C9-C10 Aromatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	16:34	MA VPH
<b>Surrogate Recovery</b>		<b>Limits</b>								
2,5-dibromotoluene as Aromatic SUR	<b>88</b>	70-130	%	1	LMM		2102938	9/13/21	16:34	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>94</b>	70-130	%	1	LMM		2102938	9/13/21	16:34	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 20001628

**Job ID:** 58581

**Sample#:** 58581-004

**Sample ID:** Trip Blank

**Matrix:** Water

Received on ice at 2°C, in satisfactory condition.

**Sampled:** 9/9/21 0:00

Parameter	Reporting		Instr Dil'n		Analyst	Prep Date	Analysis			Reference
	Result	Limit	Units	Factor			Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
Unadjusted C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
methyl t-butyl ether (MTBE)	< 2	2	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
benzene	< 1	1	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
toluene	< 2	2	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
ethylbenzene	< 2	2	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
m&p-xylenes	< 2	2	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
o-xylene	< 2	2	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
naphthalene	< 5	5	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
C5-C8 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
C9-C12 Aliphatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
C9-C10 Aromatics	< 100	100	ug/L	1	LMM		2102938	9/13/21	14:18	MA VPH
<b>Surrogate Recovery</b>		<b>Limits</b>								
2,5-dibromotoluene as Aromatic SUR	<b>96</b>	70-130	%	1	LMM		2102938	9/13/21	14:18	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>100</b>	70-130	%	1	LMM		2102938	9/13/21	14:18	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 21001628

**Job ID:** 58581

**Sample#:** 58581-001

**Sample ID:** CA-MW-1

**Matrix:** Water

**Sampled:** 9/9/21 13:15

Parameter	Result	Reporting		Instr Dil'n	Factor	Prep		Analysis			Reference
		Limit	Units			Analyst	Date	Batch	Date	Time	
naphthalene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
2-methylnaphthalene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
phenanthrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
acenaphthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
acenaphthylene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
fluorene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
pyrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
benzo(a)anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
chrysene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
benzo(b)fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
benzo(k)fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
benzo(a)pyrene	< 0.4	0.4	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
indeno(1,2,3-cd)pyrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
dibenzo(a,h)anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
benzo(g,h,i)perylene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	9/20/21	23:13	MA EPH	
Unadjusted C11-C22 Aromatics	< 100	100	ug/L	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
C9-C18 Aliphatics	< 100	100	ug/L	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
C19-C36 Aliphatics	< 100	100	ug/L	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
C11-C22 Aromatics	< 100	100	ug/L	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
<b>Surrogate Recovery</b>		<b>Limits</b>									
1-chloro-octadecane SUR	<b>65</b>	40-140	%	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
o-terphenyl SUR	<b>63</b>	40-140	%	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
2-fluorobiphenyl SUR	<b>66</b>	40-140	%	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	
2-bromonaphthalene SUR	<b>58</b>	40-140	%	1	ACA	9/16/21	14279	9/17/21	17:20	MA EPH	



**Project ID:** Brown School 20001628

**Job ID:** 58581

**Sample#:** 58581-002

**Sample ID:** CA-MW-2

**Matrix:** Water

**Sampled:** 9/9/21 9:40

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
naphthalene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
2-methylnaphthalene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
phenanthrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
acenaphthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
acenaphthylene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
fluorene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
pyrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
benzo(a)anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
chrysene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
benzo(b)fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
benzo(k)fluoranthene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
benzo(a)pyrene	< 0.4	0.4	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
indeno(1,2,3-cd)pyrene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
dibenzo(a,h)anthracene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
benzo(g,h,i)perylene	< 1.0	1.0	ug/L	1	CL	9/16/21	14279	10/2/21	5:56	MA EPH
Unadjusted C11-C22 Aromatics	< 100	100	ug/L	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
C9-C18 Aliphatics	< 100	100	ug/L	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
C19-C36 Aliphatics	< 100	100	ug/L	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
C11-C22 Aromatics	< 100	100	ug/L	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
1-chloro-octadecane SUR	<b>55</b>	40-140	%	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
o-terphenyl SUR	<b>57</b>	40-140	%	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
2-fluorobiphenyl SUR	<b>74</b>	40-140	%	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH
2-bromonaphthalene SUR	<b>40</b>	40-140	%	1	DBV	9/16/21	14279	9/24/21	14:03	MA EPH



**Project ID:** Brown School 20001628

**Job ID:** 58581

**Sample#:** 58581-003

**Sample ID:** CA-MW-3

**Matrix:** Water

**Sampled:** 9/9/21 10:55

Parameter	Result	Reporting		Instr Dil'n	Factor	Prep		Analysis			Reference
		Limit	Units			Analyst	Date	Batch	Date	Time	
naphthalene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
2-methylnaphthalene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
phenanthrene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
acenaphthene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
acenaphthylene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
fluorene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
anthracene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
fluoranthene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
pyrene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
benzo(a)anthracene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
chrysene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
benzo(b)fluoranthene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
benzo(k)fluoranthene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
benzo(a)pyrene	< 0.4	0.4	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
indeno(1,2,3-cd)pyrene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
dibenzo(a,h)anthracene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
benzo(g,h,i)perylene	< 1.0	1.0	ug/L	1		CL	9/16/21	14279	9/21/21	0:13	MA EPH
Unadjusted C11-C22 Aromatics	< 100	100	ug/L	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
C9-C18 Aliphatics	< 100	100	ug/L	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
C19-C36 Aliphatics	< 100	100	ug/L	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
C11-C22 Aromatics	< 100	100	ug/L	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
<b>Surrogate Recovery</b>		<b>Limits</b>									
1-chloro-octadecane SUR	<b>61</b>	40-140	%	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
o-terphenyl SUR	<b>63</b>	40-140	%	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
2-fluorobiphenyl SUR	<b>68</b>	40-140	%	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH
2-bromonaphthalene SUR	<b>63</b>	40-140	%	1		ACA	9/16/21	14279	9/17/21	18:28	MA EPH



# Quality Control Report



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



## MassDEP Analytical Protocol Certification Form

Laboratory Name: Absolute Resource Associates

Project #: 21001628

Project Location: Massachusetts

RTN:

**This Form provides certifications for the following data set: list Laboratory Sample ID Number(s): 58581**

Matrices: ☒ Groundwater/Surface Water ☐ Soil/Sediment ☐ Drinking Water ☐ Air ☐ Other:

**CAM Protocol** (check all that apply below):

8260 VOC CAM II A <input type="checkbox"/>	7470/7471 Hg CAM III B <input type="checkbox"/>	MassDEP VPH (GC/PID/FID) CAM IV A <input checked="" type="checkbox"/>	8082 PCB CAM V A <input type="checkbox"/>	9014 Total Cyanide/PAC CAM VI A <input type="checkbox"/>	6860 Perchlorate CAM VIII B <input type="checkbox"/>
8270 SVOC CAM II B <input type="checkbox"/>	7010 Metals CAM III C <input type="checkbox"/>	MassDEP VPH (GC/MS) CAM IV C <input type="checkbox"/>	8081 Pesticides CAM V B <input type="checkbox"/>	7196 Hex Cr CAM VI B <input type="checkbox"/>	MassDEP APH CAM IX A <input type="checkbox"/>
6010 Metals CAM III A <input type="checkbox"/>	6020 Metals CAM III D <input type="checkbox"/>	MassDEP EPH CAM IV B <input checked="" type="checkbox"/>	8151 Herbicides CAM V C <input type="checkbox"/>	8330 Explosives CAM VIII A <input type="checkbox"/>	TO-15 VOC CAM IX B <input type="checkbox"/>

**Affirmative Responses to Questions A through F are required for "Presumptive Certainty" status**

<b>A</b>	Were all samples received in a condition consistent with those described on the Chain-of-Custody, properly preserved (including temperature) in the field or laboratory, and prepared/analyzed within method holding times?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>B</b>	Were the analytical method(s) and all associated QC requirements specified in the selected CAM protocol(s) followed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>C</b>	Were all required corrective actions and analytical response actions specified in the selected CAM protocol(s) implemented for all identified performance standard non-conformances?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>D</b>	Does the laboratory report comply with all the reporting requirements specified in CAM VII A, "Quality Assurance and Quality Control Guidelines for the Acquisition and Reporting of Analytical Data"?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>E</b>	VPH, EPH, APH, and TO-15 only a. VPH, EPH, and APH Methods only: Was each method conducted without significant modification(s)? (Refer to the individual method(s) for a list of significant modifications). b. APH and TO-15 Methods only: Was the complete analyte list reported for each method?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>F</b>	Were all applicable CAM protocol QC and performance standard non-conformances identified and evaluated in a laboratory narrative (including all "No" responses to Questions A through E)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

**Responses to Questions G, H and I below are required for "Presumptive Certainty" status**


<b>G</b>	Were the reporting limits at or below all CAM reporting limits specified in the selected CAM protocol(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>
----------	---	--

**Data User Note:** Data that achieve "Presumptive Certainty" status may not necessarily meet the data usability and representativeness requirements described in 310 CMR 40.1056 (2)(k) and WSC-07-350.

<b>H</b>	Were all QC performance standards specified in the CAM protocol(s) achieved?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>
<b>I</b>	Were results reported for the complete analyte list specified in the selected CAM protocol(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>

<sup>1</sup>All negative responses must be addressed in an attached laboratory narrative.

*I, the undersigned, attest under the pains and penalties of perjury that, based upon my personal inquiry of those responsible for obtaining the information, the material contained in this analytical report is, to the best of my knowledge and belief, is accurate and complete.*

Signature: 

Position: Chief Operating Officer

Printed Name: Aaron DeWees

Date: 10/5/21



## Sample Integrity Table

Parameter	Method	Matrix	Minimum Volume	Recommended Container(s)	Required Preservation	Holding Time
Volatile Organics	EPA 8260	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
Volatile Organics	EPA 8260	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	14 Days
Semivolatile Organics	EPA 8270	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Semivolatile Organics	EPA 8270	Solid	20g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Organochlorine Pesticides	EPA 8081	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Organochlorine Pesticides	EPA 8081	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
PCBs	EPA 8082	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
PCBs	EPA 8082	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
Herbicides (subcontracted)	EPA 8151	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Herbicides (subcontracted)	EPA 8151	Solid	30g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
MA DEP VPH	MADEP VPH	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP VPH	MADEP VPH	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	28 Days
MA DEP EPH	MADEP EPH	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP EPH	MADEP EPH	Solid	30g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Total Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	180 Days
Dissolved Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	Filter First 1:1 $\text{HNO}_3$ to pH <2	180 Days
Total Metals	EPA 6010	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	180 Days
Total Mercury (may be combined with Total Metals)	EPA 7470	Aqueous	100mL	125mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	28 Days
Total Mercury (may be combined with Total Metals)	EPA 7471	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	28 Days
Chromium, Hexavalent	EPA 7196	Aqueous	100mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ ( $\text{NH}_4$ ) $_2$ SO $_4$ buffer	28 Days
Chromium, Hexavalent (subcontract)	EPA 7196	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	30 Days
Cyanide, Total	EPA 9014	Aqueous	125mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ 1:1 NaOH to pH >8	14 Days
Cyanide, Total	EPA 9014	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days

Absolute Resource Associates  
124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)





**Case Narrative**

**Lab # 58581**

**Sample Receiving and Chain of Custody Discrepancies**

---

Samples were received in acceptable condition, between 0 and 6 degrees C, on ice, and in accordance with sample handling, preservation and integrity guidelines.

**Calibration**

---

VOC: See the included table for a list of compounds quantitated by quadratic equation.

**Method Blank**

---

No exceptions noted.

**Surrogate Recoveries**

---

No exceptions noted.

**Laboratory Control Sample Results**

---

EPH: The relative percent difference between the LCS and LCSD14279 was outside the acceptance criteria for several target analytes. The recovery in each was acceptable. Since these compounds were not detected in the samples, there is no impact to the results.

**Matrix Spike/Matrix Spike Duplicate/Duplicate Results**

---

Not requested for this project.

**Other**

---

No other exceptions noted.

**MassDEP Analytical Protocol Certification Form Questions A through I**

---

No explanation is needed for Questions A through I answered in the affirmative.



## **GLOSSARY**

%R	Percent Recovery
BLK	Blank (Method Blank, Preparation Blank)
CCB	Continuing Calibration Blank
CCV	Continuing Calibration Verification
CRM	Certified Reference Material (associated with solid Metals samples)
CRMD	Certified Reference Material Duplicate (associated with solid Metals samples)
Dil'n	Dilution
DL	Detection Limit
DUP	Duplicate
LCS	Laboratory Control Sample
LCSD	Laboratory Control Sample Duplicate
LOD	Limit of Detection
LOQ	Limit of Quantitation
MB	Methanol Blank (associated with solid VOC samples)
MLCS	Methanol Laboratory Control Sample (associated with solid VOC samples)
MLCSD	Methanol Laboratory Control Sample Duplicate (associated with solid VOC samples)
MS	Matrix Spike
MSD	Matrix Spike Duplicate
PB	Preparation Blank
QC	Quality Control
RL	Reporting Limit
RPD	Relative Percent Difference
SUR	Surrogate



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801

[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



- QC Report -

Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit	
MA VPH	BLK2102938	Unadjusted C5-C8 Aliphatics	<	100	ug/L						
		Unadjusted C9-C12 Aliphatics	<	100	ug/L						
		methyl t-butyl ether (MTBE)	<	2	ug/L						
		benzene	<	1	ug/L						
		toluene	<	2	ug/L						
		ethylbenzene	<	2	ug/L						
		m&p-xylenes	<	2	ug/L						
		o-xylene	<	2	ug/L						
		naphthalene	<	5	ug/L						
		C5-C8 Aliphatics	<	100	ug/L						
		C9-C12 Aliphatics	<	100	ug/L						
		C9-C10 Aromatics	<	100	ug/L						
		2,5-dibromotoluene as Aromatic SUR		86	%			70	130		
		2,5-dibromotoluene as Aliphatic SUR		90	%			70	130		
MA VPH	LCS2102938	Unadjusted C5-C8 Aliphatics		270	ug/L	300	91	70	130		
		Unadjusted C9-C12 Aliphatics		280	ug/L	300	93	70	130		
		methyl t-butyl ether (MTBE)		92	ug/L	100	92	70	130		
		benzene		98	ug/L	100	98	70	130		
		toluene		98	ug/L	100	98	70	130		
		ethylbenzene		100	ug/L	100	100	70	130		
		m&p-xylenes		200	ug/L	200	102	70	130		
		o-xylene		100	ug/L	100	103	70	130		
		naphthalene		98	ug/L	100	98	70	130		
		C5-C8 Aliphatics	<	100	ug/L			70	130		
		C9-C12 Aliphatics	<	100	ug/L			70	130		
		C9-C10 Aromatics		110	ug/L	100	106	70	130		
		2,5-dibromotoluene as Aromatic SUR		103	%			70	130		
		2,5-dibromotoluene as Aliphatic SUR		107	%			70	130		
MA VPH	LCSD2102938	Unadjusted C5-C8 Aliphatics		270	ug/L	300	90	70	130	1	25
		Unadjusted C9-C12 Aliphatics		290	ug/L	300	97	70	130	5	25
		methyl t-butyl ether (MTBE)		90	ug/L	100	90	70	130	2	25
		benzene		94	ug/L	100	94	70	130	4	25
		toluene		95	ug/L	100	95	70	130	4	25
		ethylbenzene		97	ug/L	100	97	70	130	4	25
		m&p-xylenes		200	ug/L	200	99	70	130	3	25
		o-xylene		99	ug/L	100	99	70	130	4	25
		naphthalene		97	ug/L	100	97	70	130	1	25
		C5-C8 Aliphatics	<	100	ug/L			70	130		25
		C9-C12 Aliphatics	<	100	ug/L			70	130		25
		C9-C10 Aromatics		100	ug/L	100	102	70	130	4	25
		2,5-dibromotoluene as Aromatic SUR		97	%			70	130		
		2,5-dibromotoluene as Aliphatic SUR		103	%			70	130		



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
MA EPH	BLK14279	naphthalene		<	1.0	ug/L				
		2-methylnaphthalene		<	1.0	ug/L				
		phenanthrene		<	1.0	ug/L				
		acenaphthene		<	1.0	ug/L				
		acenaphthylene		<	1.0	ug/L				
		fluorene		<	1.0	ug/L				
		anthracene		<	1.0	ug/L				
		fluoranthene		<	1.0	ug/L				
		pyrene		<	1.0	ug/L				
		benzo(a)anthracene		<	1.0	ug/L				
		chrysene		<	1.0	ug/L				
		benzo(b)fluoranthene		<	1.0	ug/L				
		benzo(k)fluoranthene		<	1.0	ug/L				
		benzo(a)pyrene		<	0.4	ug/L				
		indeno(1,2,3-cd)pyrene		<	1.0	ug/L				
		dibenzo(a,h)anthracene		<	1.0	ug/L				
		benzo(g,h,i)perylene		<	1.0	ug/L				
		Unadjusted C11-C22 Aromatics		<	100	ug/L				
		C9-C18 Aliphatics		<	100	ug/L				
		C19-C36 Aliphatics		<	100	ug/L				
		C11-C22 Aromatics		<	100	ug/L				
		1-chloro-octadecane SUR		59	%			40	140	
		o-terphenyl SUR		58	%			40	140	
		2-fluorobiphenyl SUR		66	%			40	140	
		2-bromonaphthalene SUR		56	%			40	140	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
MA EPH	LCS14279	naphthalene		35	ug/L	60	59	40	140	
		2-methylnaphthalene		35	ug/L	60	58	40	140	
		phenanthrene		50	ug/L	60	83	40	140	
		acenaphthene		39	ug/L	60	65	40	140	
		acenaphthylene		34	ug/L	60	57	40	140	
		fluorene		39	ug/L	60	65	40	140	
		anthracene		47	ug/L	60	78	40	140	
		fluoranthene		48	ug/L	60	80	40	140	
		pyrene		37	ug/L	60	62	40	140	
		benzo(a)anthracene		40	ug/L	60	66	40	140	
		chrysene		45	ug/L	60	75	40	140	
		benzo(b)fluoranthene		40	ug/L	60	67	40	140	
		benzo(k)fluoranthene		49	ug/L	60	81	40	140	
		benzo(a)pyrene		43	ug/L	60	71	40	140	
		indeno(1,2,3-cd)pyrene		45	ug/L	60	75	40	140	
		dibenzo(a,h)anthracene		45	ug/L	60	74	40	140	
		benzo(g,h,i)perylene		43	ug/L	60	71	40	140	
		Unadjusted C11-C22 Aromatics		650	ug/L	1020	63	40	140	
		C9-C18 Aliphatics		200	ug/L	360	56	40	140	
		C19-C36 Aliphatics		360	ug/L	480	74	40	140	
		C11-C22 Aromatics	<	100	ug/L			40	140	
		1-chloro-octadecane SUR		63	%			40	140	
		o-terphenyl SUR		59	%			40	140	
		2-fluorobiphenyl SUR		65	%			40	140	
		2-bromonaphthalene SUR		56	%			40	140	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit	
MA EPH	LCSD14279	naphthalene		39	ug/L	60	65	40	140	10	25
		2-methylnaphthalene		40	ug/L	60	67	40	140	14	25
		phenanthrene		69	ug/L	60	115	40	140	32	* 25
		acenaphthene		51	ug/L	60	85	40	140	26	* 25
		acenaphthylene		44	ug/L	60	73	40	140	26	* 25
		fluorene		52	ug/L	60	87	40	140	29	* 25
		anthracene		64	ug/L	60	107	40	140	31	* 25
		fluoranthene		66	ug/L	60	110	40	140	32	* 25
		pyrene		48	ug/L	60	80	40	140	25	25
		benzo(a)anthracene		54	ug/L	60	90	40	140	30	* 25
		chrysene		60	ug/L	60	100	40	140	29	* 25
		benzo(b)fluoranthene		60	ug/L	60	99	40	140	39	* 25
		benzo(k)fluoranthene		60	ug/L	60	100	40	140	21	25
		benzo(a)pyrene		57	ug/L	60	96	40	140	29	* 25
		indeno(1,2,3-cd)pyrene		62	ug/L	60	103	40	140	31	* 25
		dibenzo(a,h)anthracene		61	ug/L	60	101	40	140	30	* 25
		benzo(g,h,i)perylene		57	ug/L	60	95	40	140	29	* 25
		Unadjusted C11-C22 Aromatics		770	ug/L	1020	76	40	140	18	25
		C9-C18 Aliphatics		200	ug/L	360	56	40	140	0	25
		C19-C36 Aliphatics		400	ug/L	480	83	40	140	11	25
		C11-C22 Aromatics	<	100	ug/L			40	140		25
		1-chloro-octadecane SUR		70	%			40	140		
		o-terphenyl SUR		75	%			40	140		
		2-fluorobiphenyl SUR		71	%			40	140		
		2-bromonaphthalene SUR		41	%			40	140		



## AROMATIC HYDROCARBON BREAKTHROUGH CALCULATION

Method: MADEP EPH 2019 Rev 2.1

	lcs14279		
	Aliphatic Breakthrough	Acceptance	Date of Analysis
	(%)	Criteria	
naphthalene	0.4%	<5.0%	9/17/2021
2-methylnaphthalene	0.4%	<5.0%	9/17/2021

	lcsd14279		
	Aliphatic Breakthrough	Acceptance	Date of Analysis
	(%)	Criteria	
naphthalene	4.0%	<5.0%	9/17/2021
2-methylnaphthalene	3.7%	<5.0%	9/17/2021





124 Heritage Avenue #16  
Portsmouth, NH 03801  
603-436-2001

absoluteresourceassociates.com

# CHAIN-OF-CUSTODY RECORD AND ANALYSIS REQUEST

58581

Company Name: <u>Credere Associates</u>		Project Name: <u>Brown School</u>					
Company Address: <u>776 Main St. Westbrook, ME</u>		Project #: <u>21001628</u>					
Report To: <u>Morgan Wentworth</u>		Project Location: <u>NH MA ME VT</u>					
Phone #: <u>207-828-1222 x36</u>		Accreditation Required? NY:					
Invoice to: <u>jenn@credere.com</u>		Protocol: RCRA SDWA NPDES MCP NHDES DOD					
Email:		Reporting QAPP GW-1 S-1					
PO #:		Limits: EPA DW Other					
Quote #		NH Reimbursement Pricing					
Lab Sample ID (Lab Use Only)	Field ID	# CONTAINERS	Matrix WATER SOLID OTHER	Preservation Method HCl HNO <sub>3</sub> H <sub>2</sub> SO <sub>4</sub> NaOH MeOH	DATE	TIME	SAMPLER
58581-01	CA-MW-1	3	X	X	9/12/21	1315	QAB
02	CA-MW-2	3	X	X	9/12/21	0940	QAB
03	CA-MW-3	3	X	X	9/12/21	1055	QAB
04	Trip Blank		X	X			
	JD 9/10/21						

<input type="checkbox"/> VOC 8260	<input type="checkbox"/> VOC 8260 NHDES	<input type="checkbox"/> VOC 8260 MADEP	<input type="checkbox"/> VOC 824.1	<input type="checkbox"/> VOC BTEX MIBE, only	<input type="checkbox"/> VOC 8021VT	<input type="checkbox"/> VPH MADEP	<input type="checkbox"/> GRO 8015	<input type="checkbox"/> 1,4-Dioxane	<input type="checkbox"/> VOC 524.2	<input type="checkbox"/> VOC 524.2 NH List	<input type="checkbox"/> Gases-List:	<input type="checkbox"/> TPH 8100	<input type="checkbox"/> DRO 8015	<input checked="" type="checkbox"/> EPH MADEP	<input type="checkbox"/> TPH Fingerprint	<input type="checkbox"/> 8270PAH	<input type="checkbox"/> 8270ABN	<input type="checkbox"/> 625.1	<input type="checkbox"/> EDB	<input type="checkbox"/> 8082 PCB	<input type="checkbox"/> 8081 Pesticides	<input type="checkbox"/> 608.3 Pest/PCB	<input type="checkbox"/> PFAS 537.1	<input type="checkbox"/> PFAS 533	<input type="checkbox"/> PFAS isotope dilution	<input type="checkbox"/> O&G 1664	<input type="checkbox"/> Mineral O&G 1664	<input type="checkbox"/> pH	<input type="checkbox"/> BOD	<input type="checkbox"/> Conductivity	<input type="checkbox"/> Turbidity	<input type="checkbox"/> Apparent Color	<input type="checkbox"/> TSS	<input type="checkbox"/> TDS	<input type="checkbox"/> TS	<input type="checkbox"/> TVS	<input type="checkbox"/> Alkalinity	<input type="checkbox"/> Acidity	<input type="checkbox"/> RCRA Metals	<input type="checkbox"/> Priority Pollutant Metals	<input type="checkbox"/> TAL Metals	<input type="checkbox"/> Hardness	<input type="checkbox"/> Total Metals-list:	<input type="checkbox"/> Dissolved Metals-list:	<input type="checkbox"/> Ammonia	<input type="checkbox"/> COD	<input type="checkbox"/> TKN	<input type="checkbox"/> TN	<input type="checkbox"/> TON	<input type="checkbox"/> TOC	<input type="checkbox"/> Ferrous Iron	<input type="checkbox"/> T-Phosphorus	<input type="checkbox"/> Bacteria P/A	<input type="checkbox"/> Bacteria MPN	<input type="checkbox"/> Enterococci	<input type="checkbox"/> Cyanide	<input type="checkbox"/> Sulfide	<input type="checkbox"/> Nitrate + Nitrite	<input type="checkbox"/> Ortho P	<input type="checkbox"/> Phenols	<input type="checkbox"/> Nitrate	<input type="checkbox"/> Nitrite	<input type="checkbox"/> Chloride	<input type="checkbox"/> Sulfate	<input type="checkbox"/> Bromide	<input type="checkbox"/> Fluoride	<input type="checkbox"/> Corrosivity	<input type="checkbox"/> Ignitability/FP	<input type="checkbox"/> TCLP Metals	<input type="checkbox"/> TCLP VOC	<input type="checkbox"/> TCLP SVOC	<input type="checkbox"/> TCLP Pesticide	<input type="checkbox"/> Subcontract	<input type="checkbox"/> Grain Size	<input type="checkbox"/> Herbicides	<input type="checkbox"/> Asbestos	Grab (G) or Composite (C)
-----------------------------------	---	---	------------------------------------	--	-------------------------------------	------------------------------------	-----------------------------------	--------------------------------------	------------------------------------	--	--------------------------------------	-----------------------------------	-----------------------------------	---	--	----------------------------------	----------------------------------	--------------------------------	------------------------------	-----------------------------------	--	---	-------------------------------------	-----------------------------------	--	-----------------------------------	---	-----------------------------	------------------------------	---------------------------------------	------------------------------------	---	------------------------------	------------------------------	-----------------------------	------------------------------	-------------------------------------	----------------------------------	--------------------------------------	--	-------------------------------------	-----------------------------------	---	---	----------------------------------	------------------------------	------------------------------	-----------------------------	------------------------------	------------------------------	---------------------------------------	---------------------------------------	---------------------------------------	---------------------------------------	--------------------------------------	----------------------------------	----------------------------------	--	----------------------------------	----------------------------------	----------------------------------	----------------------------------	-----------------------------------	----------------------------------	----------------------------------	-----------------------------------	--------------------------------------	--	--------------------------------------	-----------------------------------	------------------------------------	---	--------------------------------------	-------------------------------------	-------------------------------------	-----------------------------------	---------------------------

TAT REQUESTED Priority (24 hr)* <input type="checkbox"/> Expedited (48 hr)* <input type="checkbox"/> Standard (10 Business Days) <input checked="" type="checkbox"/> *Date Needed		See absoluteresourceassociates.com for sample acceptance policy and current accreditation lists.		REPORTING INSTRUCTIONS <input checked="" type="checkbox"/> PDF (e-mail address) <u>MWentworth@credere.com</u> <input type="checkbox"/> HARD COPY REQUIRED <input type="checkbox"/> EDD		RECEIVED ON ICE <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TEMPERATURE <u>2</u> °C	
CUSTODY RECORD QSD-01 Revision 03/09/2020		Relinquished by Sampler: <u>[Signature]</u>		Relinquished by: <u>[Signature]</u>		Date: <u>9/12/21</u> Time: <u>1315</u>	
		Relinquished by:		Received by:		Date: Time	
		Relinquished by:		Received by:		Date: Time	
		Relinquished by:		Received by:		Date: Time	



## Sample Receipt Condition Report

58581

Absolute Resource Associates

Job Number:

Samples Received from: ☐-UPS ☐-FedEx ☐-USPS ☐-Lab Courier ☒-Client Drop-off ☐-  
 Custody Seals - present & intact: ☐-Yes ☐-No ☒-N/A CoC signed: ☒-Yes ☐-No  
 Receipt Temp: 2 °C Samples on ice? ☒-Yes ☐-No ☐-N/A Sampled < 24 hrs ago? ☐-Yes ☒-No  
 PFAS-only real ice? ☐-Yes ☐-No ☒-N/A Any signs of freezing? ☐-Yes ☒-No

Comments:

Preservation / Analysis	Bottle Size/Type & Quantity						Check pH for ALL applicable* samples and document:		
HCl	40mL(G)	7	250mL(P)		500mL(P)	1L(G)	3	EPH pH < 2 JD *pH ✓ by analyst: VOC, PFAS, TOC, O&G Residual Cl not present: ABN625 Pest608 Bacteria ResCl ✓ by analyst PC Dry applicable? Y <u>N</u>	
HNO <sub>3</sub>	125mL(P)		250mL(P)		500mL(P)				
H <sub>2</sub> SO <sub>4</sub>	40mL(G)		60mL(P)		125mL(P)	250mL(P)	500mL(P)		
NaOH	125mL(P)		250mL(P)						
(NH <sub>4</sub> ) <sub>2</sub> SO <sub>4</sub>	60mL(P)		125mL(P)		250mL(P)				
ZnAc-NaOH	125mL(P)		250mL(P)						
Trizma	125mL(P)		250mL (P)						
NH <sub>4</sub> Ac	125mL(P)		250mL (P)						
Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	40mL(G)		120mL(P)						
MeOH	20mL(G)		40mL(G)						
None (solid)	2oz(G)		4oz(G)		8oz(G)	Syringe			
None (water)	40ml (G)		60mL(P)		125mL(P)	250mL(P)	500mL(P)	1L(G)	1L (P)
Mold	Cassette		Bulk		Plate		Tape Lift		
Asbestos	Cassette		Bulk						
Lead	Cassette		Bulk		Wipe				

Login Review	Yes	No	NA	Comments
Proper lab sample containers/enough volume/correct preservative?	✓			Rec one TB in cooler w/ 58580 and 58581
Analyses marked on COC match bottles received?	✓			share between projects JD
VOC & TOC Water-no headspace?				
VOC Solid-MeOH covers solid, no leaks, Prep Expiration OK?	✓			less than pea-sized bubble in -02
PFAS: ARA bottles & samples/FRB same Lot#? QC rec'd, if req'd?			✓	Lot ID#:
Bacteria bottles provided by ARA?			✓	
Samples within holding time?	✓			
Immediate tests communicated in writing: NO <sub>3</sub> , NO <sub>2</sub> , O-PO <sub>4</sub> , pH, BOD, Coliform/E. coli (P/A or MPN), Enterococci, Color Surfactants, Turbidity, Odor, CrVI, Ferrous Iron, Dissolved Oxygen, Unpres 624			✓	
Date, time & ID on samples match CoC?	✓			
Rushes communicated to analyst in writing?			✓	
Subcontract note on login board?			✓	
Pesticides EPA 608 pH5-9?			✓	
Compliance samples have no discrepancies/require no flags?			✓	(Or must be rejected)
Log-in Supervisor notified immediately of following items:			✓	Discrepancies, compliance samples (NHDES, MADEP, DoD etc.) or uncommon requests.

Inspected and Received By: JODate/Time: 9/10/21 14:43

## Peer Review Checklist

<input type="checkbox"/> Client ID/Project Manager	<input type="checkbox"/> On Ice, Temperature OK?	<input type="checkbox"/> Sample IDs	<input type="checkbox"/> Analyses in Correctly
<input type="checkbox"/> Project Name	<input type="checkbox"/> PO# (if provided)	<input type="checkbox"/> Matrix	-references
<input type="checkbox"/> TAT/rushes communicated	<input type="checkbox"/> Sub samples sent? Shipping Charge?	<input type="checkbox"/> Date/Time collected	-wastewater methods
<input type="checkbox"/> Received Date/Time	<input type="checkbox"/> Issues noted above communicated?	<input type="checkbox"/> Short HTs communicated	<input type="checkbox"/> Notes from CoC in LIMS

Reviewed By: \_\_\_\_\_ Date: \_\_\_\_\_

Notes: (continue on back as needed)

Initials	Date	What was sent?
Uploaded / PDF	_____	Report / Data / EDD / Invoice
Uploaded / PDF	_____	Report / Data / EDD / Invoice
Uploaded / PDF	_____	Report / Data / EDD / Invoice






RRP rev 09 14



Address 42 M.IK St Unit #        City Newburyport

Extra diagram boxes may be used when there are more than 2 floors in a property (single family home) or unit. Extra diagram boxes may also be used for larger properties where more space is needed than will fit in the standard diagram boxes on the cover page. Do not use this page as a replacement or in lieu of the floor diagram boxes on the cover page of the inspection report. Do not use architectural/schematic diagrams in place of the floor diagram required by policy and procedures.

Floor# 1st (this is the level within building of unit being inspected) → C

Floor# 2ND (this is the level within building of unit being inspected) → C

Floor# 3RD (this is the level within building of unit being inspected) → C

Inspector Name Michael Sullivan  
(print name)

Lic # 4220




Signature MSL

Date 08/25/21



Address 42 Milk St Unit #      City Newburyport

Extra diagram boxes may be used when there are **more** than 2 floors in a property (single family home) or unit. Extra diagram boxes may also be used for larger properties where more space is needed than will fit in the standard diagram boxes on the cover page. **Do not** use this page as a replacement or in lieu of the floor diagram boxes on the cover page of the inspection report. **Do not** use architectural/schematic diagrams in place of the floor diagram required by policy and procedures.

Floor# Bsmt (this is the level within building of unit being inspected) → C

Floor#      (this is the level within building of unit being inspected) → C

Floor#      (this is the level within building of unit being inspected) → C

Inspector Name Michael Sullivan Lic # 4220 Signature [Signature] Date 08/25/21  
(print name)



## EXPLANATION OF RENOVATION REPAIR AND PAINTING (RRP)

Renovation is different from deleading activities. The purpose of **renovation work** is to update a property and the purpose of **repair work** is to fix or maintain the property. The purpose of **deleading work** is to remove or cover lead hazards. While some of the activities for renovation may be the same as deleading, like window replacement and vinyl siding, the purpose and intent of the work for deleading as well as the rules about how the work is done and who can do the work is different. Confusing RRP rules with deleading requirements will jeopardize a property owner's ability to get a compliance document, protection from liability, and a \$1,500.00 state income tax credit.

It is up to an owner along with the owner's contractor (Certified Firm) to inform the inspector which surfaces will be disturbed by the planned Renovation, Repair or Painting work and therefore need to be tested. The RRP Assessment Report forms are designed to accommodate two situations:

- The first 25-30 components listed in the left hand box provide a "snapshot" of a room or an exterior/outbuilding. In those instances where an entire room (or exterior area) will be renovated, this "snapshot" will guide testing to find the most likely lead components. If a component does not require testing because it will not be disturbed or the component does not exist in the area being tested, then the inspector will cross off the box. Once the inspector has completed the "snapshot," a decision can be made as to whether further testing is needed. If any of these components were found to contain a **dangerous level of lead** (see definitions below), then it can be safely assumed that components of the same type in the work area also contain lead and therefore the RRP rules must be followed.
- If the "snapshot" of the area does not identify a dangerous level of lead, then the only way to rule out RRP requirements is to test all of the individual components that will be disturbed in the work area until either a dangerous level of lead is found or all of the components are tested and found to be below the definition of a dangerous level of lead. This additional testing will be recorded in the blank spaces below the first 25-30 components as well as in the right hand box. For large rooms/exteriors that do not contain many lead surfaces, additional RRP pages may need to be added.

<b>LOCATION</b>	Refers to the room, common area, or exterior location of the surface being assessed. See the diagram on the cover page.
<b>SIDE</b>	Refers to A, B, C, or D side of the building or room. See the diagram on the cover sheet. The "A" side of the building or room is the side facing the street that gives the property its address (usually, it is the front of the building). Keeping your back to this street, from the "A" side move clockwise to the "B" side on your left, the "C" side opposite you, and the "D" side to the right.
<b>SURFACE</b>	Refers to the building component(s) being tested. Some surfaces may be made up of more than one part. For example, "Baseboard" may refer to four separate pieces of wood (one on each wall), but is still considered one surface. It is up to the owner along with the contractor to let the inspector know which surfaces will be disturbed by the planned renovation work.
<b>LEAD</b>	The test results either from sodium sulfide or an X-ray fluorescence instrument (XRF).
<b>DANGEROUS LEAD LEVEL</b>	An XRF reading equal to or greater than $1.0 \text{ mg/cm}^2$ or a positive reaction with sodium sulfide indicates a dangerous level of lead. When the "Y" is circled then the RRP Rules will apply if the work will disturb more than $6 \text{ ft}^2$ per room interior or $20 \text{ ft}^2$ per exterior, or the planned work includes window replacement or surface demolition.
<b>DUST TAKEN</b>	An owner, along with a Certified contractor (or rental property with a licensing waiver) may choose to have dust wipes taken to ensure that the area is clean. <b>If wipes are taken, then deleading clearance levels must be achieved. These levels are as follows: Floor &lt; <math>40 \text{ ug/ft}^2</math>; Window Sill &lt; <math>250 \text{ ug/ft}^2</math>; Window Well &lt; than <math>400 \text{ ug/ft}^2</math>.</b>

### Some other quick information for RRP Rules VS Deleading:

	RRP Rule	Deleading Rules
Inspection Requirements	Assume Lead; Lead Check; or RRP Assessment by lic. inspector	Comprehensive Initial Inspection by lic. inspector
Training/Licensing Requirements	Contractor and Rental Property Owners must be Certified Firm, with employees as Certified Individuals or Trained Workers	Licensed Deleader, Licensed Lead-Safe Renovator with additional 4-hr training, Authorized Owner or Agent (moderate risk, low risk, encapsulation, or combination)
Notification Requirements	EPA Renovate Right Brochure with Signatures owners/occupants	10-Day Deleading Notification
Occupancy Restrictions	Out of the Work Area (generally room (s) where work is occurring)	High or moderate risk work including window replacement requires occupants to be relocated until passing reinspection
Reinspections	Cleaning Verification procedure with option of Reinspection and Dust Wipes	Reinspection and dust wipes are mandatory
Documentation	Certified Firm responsible for maintaining variety of documents showing protocol followed, including notification, training, and clean up. Owner responsible for transfer of all lead related documentation upon sale of property.	Lic. Inspector responsible for collecting invoices and issuing reports and compliance documentation to the owner. Tax credit of \$1,500 per unit. Owner responsible for transfer of all lead related documentation upon sale of property.



08/25/21

885

Page 5 of

Micahel Sullivan

I/R-4220

Lic # Signature

Date

Inspector (print)

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: Room # 1 Kitchen Pantry Bath # Hall # SURYPC...

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	/	Y		
A B	Baseboards	✓6	Y		
A B	Chair Rail	/	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	DC	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y	X3	
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	01	Y		
B	Cl Casing	00	Y		
C	Closet Jamb	01	Y	X3	
D	Closet Walls	01	Y		
	Cl Baseboard	✓3	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	00	Y		Y
	Closet Ceiling	DC	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	04	Y	
B	Win Apron	01	Y	
C	Win Casing	02	Y	
D	Header Stop	01	Y	
	Int Stops	00	Y	
1	Win Int Sash	151	Y	
2	Exterior Sill	142	Y	X6
3	Part Bead	146	Y	
4	Blind Stop	144	Y	
	Win Ext Sash	156	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A	Window Sill	/	Y	Y
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
A B	Win Above 5'	/	Y	
C D	Ceiling Molding	/	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

IIR-4220

Page 6

Inspector (print)

Lic #

Signature

08/25/21

Date

NEWBURYPORT

Address

Unit #

City

Location: - HALLWAY # 1

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	01	Y		
	Walls Brick	01	Y		
	Baseboards	03	Y		
	Chair Rail	/	Y		
AB	Radiator	/	Y		
CD	Floor	03	Y		Y
	Ceiling	DC	Y		
AB	Door	05	Y	Elevation	
CD	Door Casing	04	Y		
1 2	Door Jamb	05	Y		
3 4	Threshold	01	Y		
AB	Door	02	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
AB	Door	01	Y		
CD	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	/	Y		
B	CI Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Closet Door	/	Y		
B	CI Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: Room # 2 Kitchen Pantry Bath # Hall # Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	03	Y		
A B	Low Walls	01	Y	MASO	
A B	Baseboards	13	Y		
A B	Chair Rail	1	Y		
A B	Radiator	0.1	Y		
	Floor	0	Y		Y
	Ceiling	0	Y		
(A) B	Door	00	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
(A) B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
A B	Door	01	Y	Ext	
(C) D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A	Closet Door	1	Y		
B	Cl Casing	1	Y		
C	Closet Jamb	1	Y		
D	Closet Walls	1	Y		
	Cl Baseboard	1	Y		
1	Closet Pole	1	Y		
2	Closet Shelf	1	Y		
3	Cl Supports	1	Y		
4	Closet Floor	1	Y		Y
	Closet Ceiling	1	Y		
		1	Y		
		1	Y		
		1	Y		
		1	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	02	Y		Y
B	Win Apron	01	Y		
C	Win Casing	02	Y		
(D)	Header Stop	03	Y	X3	
	Int Stops	01	Y		
1	Win Int Sash	136	Y		
2	Exterior Sill	11	Y		
3	Part Bead	136	Y		
4	Blind Stop	121	Y		
	Win Ext Sash	139	Y		
A	Window Sill	1	Y		
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1	Y		
2	Exterior Sill	1	Y		
3	Part Bead	1	Y		
4	Blind Stop	1	Y		
	Win Ext Sash	1	Y		
A	Window Sill	1	Y		
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1	Y		
2	Exterior Sill	1	Y		
3	Part Bead	1	Y		
4	Blind Stop	1	Y		
	Win Ext Sash	1	Y		
A B	Fireplace	1	Y		
C D	Mantle	1	Y		
(A) B	Win Above 5'	136	Y		
	Ceiling Molding	1	Y		
		1	Y		
		1	Y		
		1	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Signature

~~08/25/21~~

Page

Inspector (print)

Lic #

Date \_\_\_\_\_

NEWBURYPORT

Address

Unit #

City

Location:

<sup>1</sup>HALLWAY # 2

SIDE	SURFACE	LEAD	DA NGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls <i>Beck</i>	00	Y		
	Baseboards	13	Y		
	Chair Rail	/	Y		
AB CD	Radiator	00	Y		
	Floor	01	Y		Y
	Ceiling	DC	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
12	Door Jamb	00	Y		
34	Threshold	12	Y		
AB	Door	00	Y		
CD	Door Casing	00	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	00	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	00	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	00	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
12	Door Jamb	.	Y		
34	Threshold	.	Y		
AB	Door	.	Y		
12	Door Jamb	.	Y		
34	Threshold	.	Y		
	Shelf	00	Y		
	Supports	00	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	00	Y	
B	Cl Casing	00	Y	
C	Closet Jamb	00	Y	
D	Closet Walls	1	Y	
	Cl Baseboard	1	Y	
1	Closet Pole	1	Y	
2	Closet Shelf	1	Y	
3	Cl Supports	1	Y	
4	Closet Floor	00	Y	
	Closet Ceiling	1	Y	
A	Closet Door	.	Y	
B	Cl Casing	.	Y	
C	Closet Jamb	.	Y	
D	Closet Walls	.	Y	
	Cl Baseboard	.	Y	
1	Closet Pole	.	Y	
2	Closet Shelf	.	Y	
3	Cl Supports	.	Y	
4	Closet Floor	.	Y	
	Closet Ceiling	.	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
	Ceiling Molding	1	Y	
	Win > 5 feet	.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

No.	Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area
1	Painting of the interior walls of the room.
2	Replacement of the ceiling tiles in the room.
3	Installation of new electrical outlets in the room.
4	Repair of the damaged floor in the room.
5	Painting of the exterior walls of the building.
6	Replacement of the roof tiles on the building.
7	Installation of new plumbing fixtures in the room.
8	Repair of the damaged roof of the building.
9	Painting of the interior walls of the room.
10	Replacement of the ceiling tiles in the room.
11	Installation of new electrical outlets in the room.
12	Repair of the damaged floor in the room.
13	Painting of the exterior walls of the building.
14	Replacement of the roof tiles on the building.
15	Installation of new plumbing fixtures in the room.
16	Repair of the damaged roof of the building.
17	Painting of the interior walls of the room.
18	Replacement of the ceiling tiles in the room.
19	Installation of new electrical outlets in the room.
20	Repair of the damaged floor in the room.
21	Painting of the exterior walls of the building.
22	Replacement of the roof tiles on the building.
23	Installation of new plumbing fixtures in the room.
24	Repair of the damaged roof of the building.
25	Painting of the interior walls of the room.
26	Replacement of the ceiling tiles in the room.
27	Installation of new electrical outlets in the room.
28	Repair of the damaged floor in the room.
29	Painting of the exterior walls of the building.
30	Replacement of the roof tiles on the building.
31	Installation of new plumbing fixtures in the room.
32	Repair of the damaged roof of the building.
33	Painting of the interior walls of the room.
34	Replacement of the ceiling tiles in the room.
35	Installation of new electrical outlets in the room.
36	Repair of the damaged floor in the room.
37	Painting of the exterior walls of the building.
38	Replacement of the roof tiles on the building.
39	Installation of new plumbing fixtures in the room.
40	Repair of the damaged roof of the building.
41	Painting of the interior walls of the room.
42	Replacement of the ceiling tiles in the room.
43	Installation of new electrical outlets in the room.
44	Repair of the damaged floor in the room.
45	Painting of the exterior walls of the building.
46	Replacement of the roof tiles on the building.
47	Installation of new plumbing fixtures in the room.
48	Repair of the damaged roof of the building.
49	Painting of the interior walls of the room.
50	Replacement of the ceiling tiles in the room.
51	Installation of new electrical outlets in the room.
52	Repair of the damaged floor in the room.
53	Painting of the exterior walls of the building.
54	Replacement of the roof tiles on the building.
55	Installation of new plumbing fixtures in the room.
56	Repair of the damaged roof of the building.
57	Painting of the interior walls of the room.
58	Replacement of the ceiling tiles in the room.
59	



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: Room # 3 Kitchen Pantry Bath # Hall # 1 SURVPC

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	/	Y		
A B	Baseboards	VB	Y		
A B	Chair Rail	/	Y		
A B	Radiator	00	Y		
A B	Floor	01	Y		Y
A B	Ceiling	X	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	00	Y		
B	Cl Casing	00	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	00	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	00	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	01	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	VB	Y	
2	Exterior Sill	VB	Y	Y
3	Part Bead	VB	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	VB	Y	
A	Window Sill	01	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	VB	Y	
2	Exterior Sill	VB	Y	Y
3	Part Bead	VB	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	VB	Y	
A	Window Sill	.	Y	Y
B	Win Apron	/	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
A B	Win Above 5'	/	Y	
C D	Ceiling Molding	/	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R-4220

Signature

08/25/21

Date

NEWBURYPORT

Inspector (print)

Lic #

Unit #

City

42 MILK ST

Address

Location:

HALLWAY # 3

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	01	Y		
	Walls Brick	00	Y		
	Baseboards JB	00	Y		
	Chair Rail	/	Y		
AB CD	Radiator	/	Y		
	Floor	00	Y		Y
	Ceiling	00	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Window Sill	00	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	✓	Y	
2	Exterior Sill	✓	Y	
3	Part Bead	✓	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	✓	Y	
	Ceiling Molding	/	Y	
	Win > 5 feet	/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

IR 4220

Signature

08/25/21

Page 11 Of 4

Inspector (print)

Lic #

Date

Address

42 MILK ST

Unit #

City

NEWBURYPORT

Location: 4 BATHROOM \ KITCHEN PANTRY

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	00	Y		
A B	Tile backsplash	00	Y		
A B	Baseboards	00	Y		
A B	Chair Rail	00	Y		
A B	Radiator	00	Y		
A B	Floor	01	Y		Y
A B	Ceiling	00	Y		
D	Door	00	Y		
D	Door Casing	00	Y		
D	Door Jamb	00	Y		
D	Threshold	00	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	00	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	00	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	00	Y		
A B	Door	00	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	00	Y		
A	Closet Door	00	Y		
B	Cl Casing	00	Y		
C	Closet Jamb	00	Y		
D	Closet Walls	00	Y		
	Cl Baseboard	00	Y		
1	Closet Pole	00	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	00	Y		
4	Closet Floor	00	Y		
	Closet Ceiling	00	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	00	Y		Y
B	Win Apron	00	Y		
C	Win Casing	00	Y		
D	Header Stop	00	Y		
	Int Stops	00	Y		
1	Win Int Sash	00	Y		
2	Exterior Sill	00	Y		Y
3	Part Bead	00	Y		
4	Blind Stop	00	Y		
	Win Ext Sash	00	Y		
A	Window Sill	00	Y		Y
B	Win Apron	00	Y		
C	Win Casing	00	Y		
D	Header Stop	00	Y		
	Int Stops	00	Y		
1	Win Int Sash	00	Y		
2	Exterior Sill	00	Y		Y
3	Part Bead	00	Y		
4	Blind Stop	00	Y		
	Win Ext Sash	00	Y		
A B	Up Cab Frame	00	Y		
C D	Up Cab Door	00	Y		
	Up Cab Walls	00	Y		
1 2	Up Cab Shlvs	00	Y		
3 4	Supports	00	Y		
	Low Cab Fram	00	Y		
A B	Low Cab Door	00	Y		
C D	Low Cab Walls	00	Y		
	Low Cab Shlvs	00	Y		
1 2	Supports	00	Y		
3 4	Drawers	00	Y		
	Win Above 5'	00	Y		
	Pipe Chase	00	Y		
	Ceiling Molding	00	Y		
		00	Y		
		00	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

IR 4220

Signature

08/25/21

Page 12 Of

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: BATHROOM 2 KITCHEN PANTRY

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	00	Y		
A B	Tile backsplash	/	Y		
A B	Baseboards	1k 01	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	1k 01	Y		Y
	Ceiling	DC	Y		
D	Door	/	Y		
	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

IR-4220

*Micahel Sullivan*

Inspector (print)

Lic # Signature

Date

Address 42 MILK ST

Apt. #

City

NEWBURYPORT

Location: Room # 4 Kitchen Pantry Bath # Hall # Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	/	Y		
A B	Baseboards	✓	Y		
A B	Chair Rail	/	Y		
A B	Radiator	0.0	Y		
A B	Floor	0.1	Y		Y
A B	Ceiling	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.0	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.0	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		Y
	Closet Ceiling	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.0	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓	Y	x4	
3	Part Bead	✓	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	✓	Y		
A	Window Sill	0.1	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓	Y	x2	
3	Part Bead	✓	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	✓	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: Room # 5 Kitchen Pantry Bath # Hall # 1 Stair

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	1	Y		
A B	Baseboards	13	Y		
A B	Chair Rail	1	Y		
C D	Radiator	08	Y		
	Floor	01	Y		Y
	Ceiling	02	Y		
A B	Door	08	Y		
C D	Door Casing	08	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
A B	Door	08	Y		
C D	Door Casing	08	Y		
1 2	Door Jamb	08	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A	Closet Door	1	Y		
B	Cl Casing	1	Y		
C	Closet Jamb	1	Y		
D	Closet Walls	1	Y		
	Cl Baseboard	1	Y		
1	Closet Pole	1	Y		
2	Closet Shelf	1	Y		
3	Cl Supports	1	Y		
4	Closet Floor	1	Y		Y
	Closet Ceiling	1	Y		
		1	Y		
		1	Y		
		1	Y		
		1	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	00	Y	
B	Win Apron	1	Y	
C	Win Casing	1	Y	
D	Header Stop	1	Y	
	Int Stops	1	Y	
1	Win Int Sash	1/1	Y	
2	Exterior Sill	1/1	Y	X2 Y
3	Part Bead	1/1	Y	
4	Blind Stop	1	Y	
	Win Ext Sash	1/1	Y	
A	Window Sill	01	Y	
B	Win Apron	1	Y	
C	Win Casing	1	Y	
D	Header Stop	1	Y	
	Int Stops	1	Y	
1	Win Int Sash	1/1	Y	
2	Exterior Sill	1/1	Y	X4
3	Part Bead	1/1	Y	
4	Blind Stop	1	Y	
	Win Ext Sash	1/1	Y	
A	Window Sill	1	Y	Y
B	Win Apron	1	Y	
C	Win Casing	1	Y	
D	Header Stop	1	Y	
	Int Stops	1	Y	
1	Win Int Sash	1	Y	
2	Exterior Sill	1	Y	
3	Part Bead	1	Y	
4	Blind Stop	1	Y	
	Win Ext Sash	1	Y	
A B	Fireplace	1	Y	
C D	Mantle	1	Y	
A B	Win Above 5'	1	Y	
C D	Ceiling Molding	1	Y	
		1	Y	
		1	Y	
		1	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Lic #

Signature

08/25/21

Date

NEWBURYPORT

Inspector (print)

42 MILK ST

Address

Unit #

City

Location: 42 MILK ST HALLWAY # 4

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	00	Y		
	Walls Brick	01	Y		
	Baseboards	0.5	Y		
	Chair Rail	/	Y		
AB	Radiator	00	Y		
CD	Floor	00	Y		Y
	Ceiling	00	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
12	Door Jamb	00	Y		
34	Threshold	00	Y		
AB	Door	00	Y		
CD	Door Casing	0.1	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	0.1	Y		
12	Door Jamb	02	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	0.1	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	0.1	Y		
12	Door Jamb	00	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
	Ceiling Molding	/	Y	
	Win > 5 feet	/	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

886

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 6 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	/	Y		
A B	Baseboards	✓3	Y		
A B	Chair Rail	/	Y		
A B	Radiator	0.1	Y		
	Floor	00	Y		Y
	Ceiling	DC	Y		
(A B)	Door	0.1	Y		
C D	Door Casing	02	Y	✓3	
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
(C D)	Door Casing	0.1	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
(A)	Closet Door	01	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	0.1	Y	✓3	
D	Closet Walls	02	Y		
	Cl Baseboard	✓3	Y		
1	Closet Pole	02	Y		
2	Closet Shelf	01	Y		
3	Cl Supports	02	Y		
4	Closet Floor	0.1	Y		Y
	Closet Ceiling	DC	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	02	Y		
(B)	Win Apron	01	Y		
C	Win Casing	00	Y		
D	Header Stop	01	Y	✓6	
	Int Stops	02	Y		
1	Win Int Sash	K1	Y		
2	Exterior Sill	H2	Y		
3	Part Bead	136	Y		
4	Blind Stop	D9	Y		
	Win Ext Sash	K1	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Page 17 of 1

Inspector (print)

Lic #

Signature

08/25/21

Date

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST HALLWAY # 5

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	02	Y		
	Walls BRICK	06	Y		
	Baseboards	13	Y		
	Chair Rail	/	Y		
AB CD	Radiator	02	Y		
	Floor	01	Y		Y
	Ceiling	02	Y		
AB	Door	00	Y		
CD	Door Casing	02	Y		
12	Door Jamb	01	Y		
34	Threshold	/	Y		
AB	Door	01	Y		
CD	Door Casing	02	Y		
12	Door Jamb	01	Y		
34	Threshold	02	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
12	Door Jamb	02	Y		
34	Threshold	/	Y		
AB	Door	01	Y		
CD	Door Casing	02	Y		
12	Door Jamb	01	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
	Shelf	00	Y		
	Supports	01	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	/	Y	
B	Cl Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	Cl Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	Cl Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Closet Door	/	Y	
B	Cl Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	Cl Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	Cl Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Window Sill	06	Y	
B	Win Apron	/	Y	
C	Win Casing	04	Y	
D	Header Stop	03	Y	
	Int Stops	02	Y	
1	Win Int Sash	162	Y	
2	Exterior Sill	159	Y	
3	Part Bead	146	Y	
4	Blind Stop	171	Y	
	Win Ext Sash	159	Y	
	Ceiling Molding	/	Y	
B	Win > 5 feet	127	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

IR 4220

Signature

08/25/21

Page 18 Of 19

Inspector (print)

Lic #

08/25/21

Date NEWBURYPORT

Address

42 MILK ST

Unit #

City

Location: 42 MILK ST 3 BATHROOM KITCHEN PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	02	Y		
A B	Tile backsplash	04	Y		
A B	Baseboards	01	Y		
A B	Chair Rail	1	Y		
A B	Radiator	02	Y		
A B	Floor	01	Y		Y
A B	Ceiling	DC	Y		
D	Door	/	Y		
D	Door Casing	/	Y		
D	Door Jamb	/	Y		
D	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	/	Y		
C	Win Casing	03	Y		
D	Header Stop	01	Y		
	Int Stops	03	Y		
1	Win Int Sash	151	Y	X2	
2	Exterior Sill	132	Y		Y
3	Part Bead	06	Y		
4	Blind Stop	151	Y		
	Win Ext Sash	ML	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
C	Win Above 5'	191	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area




08/25/21

88

Michael Sullivan

IR-4220



08/25/21

Page 19 Of 19

Inspector (print)

Lic #

Signature

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST BATHROOM KITCHEN PANTRY NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	02	Y		
A B	Tile backsplash	01	Y		
A B	Baseboards	01	Y		
A B	Chair Rail	/	Y		
A B	Radiator	02	Y		
	Floor	01	Y		Y
	Ceiling	DC	Y		
D	Door	/	Y		
	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
C	Win Above 5'	FL	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Page 20

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 7 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	01	Y		
A B	Baseboards	VS	Y		
A B	Chair Rail	/	Y		
A B	Radiator	02	Y		
	Floor	01	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	X3	
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	00	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	02	Y		
D	Closet Walls	01	Y		
	Cl Baseboard	VS	Y		
1	Closet Pole	00	Y		
2	Closet Shelf	02	Y		
3	Cl Supports	03	Y		
4	Closet Floor	01	Y		Y
	Closet Ceiling	DC	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	01	Y	
B	Win Apron	03	Y	
C	Win Casing	01	Y	
D	Header Stop	01	Y	
	Int Stops	03	Y	X5
1	Win Int Sash	02	Y	
2	Exterior Sill	VS	Y	
3	Part Bead	146	Y	
4	Blind Stop	151	Y	
	Win Ext Sash	132	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
A B	Win Above 5'	156	Y	
	Ceiling Molding	/	Y	
	Columns	47	Y	
		.	Y	
		.	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R-4220

Signature

08/25/21

Date

NEWBURYPORT

Inspector (print)

42 MILK ST

Lic #

Unit #

City

Address

Location: 42 MILK ST HALLWAY # 6

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	00	Y		
	Walls	/	Y		
	Baseboards	13	Y		
	Chair Rail	/	Y		
AB	Radiator	/	Y		
CD	Floor	00	Y		Y
	Ceiling	00	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



## Michael Sullivan

1/R-4220

Signature

~~08/25/21~~

Page 22 of 22

Inspector (print)

Lic #

Date \_\_\_\_\_

NEWBURYPORT

Address

Unit #

City

Location: 42 M<sup>th</sup> HIGHWAY # 7

NEWBURYPORT

SIDE	SURFACE	LEAD	DA NGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls	/	Y		
	Baseboards	NB	Y		
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	00	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
	Shelf	.	Y		
	Supports	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENT
A	Closet Door	.	Y	
B	Cl Casing	.	Y	
C	Closet Jamb	.	Y	
D	Closet Walls	.	Y	
	Cl Baseboard	.	Y	
1	Closet Pole	.	Y	
2	Closet Shelf	.	Y	
3	Cl Supports	.	Y	
4	Closet Floor	.	Y	
	Closet Ceiling	.	Y	
A	Closet Door	.	Y	
B	Cl Casing	.	Y	
C	Closet Jamb	.	Y	
D	Closet Walls	.	Y	
	Cl Baseboard	.	Y	
1	Closet Pole	.	Y	
2	Closet Shelf	.	Y	
3	Cl Supports	.	Y	
4	Closet Floor	.	Y	
	Closet Ceiling	.	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
	Ceiling Molding	.	Y	
	Win > 5 feet	.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

No.	Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area
1	Painting of the exterior of the building.
2	Replacement of the roof.
3	Installation of new windows.
4	Replacement of the siding.
5	Installation of new doors.
6	Replacement of the gutters.
7	Installation of new roof shingles.
8	Replacement of the roof tiles.
9	Installation of new roof trusses.
10	Replacement of the roof rafters.
11	Installation of new roof sheathing.
12	Replacement of the roof deck.
13	Installation of new roof ventilation.
14	Replacement of the roof insulation.
15	Installation of new roof flashing.
16	Replacement of the roof eaves.
17	Installation of new roof gables.
18	Replacement of the roof dormers.
19	Installation of new roof chimneys.
20	Replacement of the roof cupolas.
21	Installation of new roof cupolas.
22	Replacement of the roof cupolas.
23	Installation of new roof cupolas.
24	Replacement of the roof cupolas.
25	Installation of new roof cupolas.
26	Replacement of the roof cupolas.
27	Installation of new roof cupolas.
28	Replacement of the roof cupolas.
29	Installation of new roof cupolas.
30	Replacement of the roof cupolas.
31	Installation of new roof cupolas.
32	Replacement of the roof cupolas.
33	Installation of new roof cupolas.
34	Replacement of the roof cupolas.
35	Installation of new roof cupolas.
36	Replacement of the roof cupolas.
37	Installation of new roof cupolas.
38	Replacement of the roof cupolas.
39	Installation of new roof cupolas.
40	Replacement of the roof cupolas.
41	Installation of new roof cupolas.
42	Replacement of the roof cupolas.
43	Installation of new roof cupolas.
44	Replacement of the roof cupolas.
45	Installation of new roof cupolas.



08/25/21

88

Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

08/25/21

Date  
NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST  
HALLWAY # 8

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls	/	Y		
	Baseboards	VS	Y		
	Chair Rail	/	Y		
AB	Radiator	/	Y		
CD	Floor	00	Y		Y
	Ceiling	TX	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	/	Y		
B	CI Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Closet Door	/	Y		
B	CI Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

884

Micahel Sullivan

I/R-4220

Page

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 8 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls Brick	03	Y		
A B	Low Walls	/	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	01	Y		Y
A B	Ceiling	03	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
	Secure Board	03	Y		
	Supports	02	Y		
	P.P.S	03	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Page 25 Of

Inspector (print)

42 MILK ST

Lic #

Signature

08/25/21

Date

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST WAY # 9

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	00	Y		
	Walls	1	Y		
	Baseboards	43	Y		
	Chair Rail	1	Y		
AB CD	Radiator	1	Y		
	Floor	00	Y		Y
	Ceiling	00	Y		
(A) B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
(A) B	Door	00	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
(A) B	Door	00	Y		
(C) D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
(A) B	Door	00	Y		
(C) D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
(A) B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
(A) B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
(A) B	Door	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
	Shelf	1	Y		
	Supports	1	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	1	Y	
B	CI Casing	1	Y	
C	Closet Jamb	1	Y	
D	Closet Walls	1	Y	
	CI Baseboard	1	Y	
1	Closet Pole	1	Y	
2	Closet Shelf	1	Y	
3	CI Supports	1	Y	
4	Closet Floor	1	Y	
	Closet Ceiling	1	Y	
A	Closet Door	1	Y	
B	CI Casing	1	Y	
C	Closet Jamb	1	Y	
D	Closet Walls	1	Y	
	CI Baseboard	1	Y	
1	Closet Pole	1	Y	
2	Closet Shelf	1	Y	
3	CI Supports	1	Y	
4	Closet Floor	1	Y	
	Closet Ceiling	1	Y	
A	Window Sill	1	Y	
B	Win Apron	1	Y	
C	Win Casing	1	Y	
D	Header Stop	1	Y	
	Int Stops	1	Y	
1	Win Int Sash	1	Y	
2	Exterior Sill	1	Y	
3	Part Bead	1	Y	
4	Blind Stop	1	Y	
	Win Ext Sash	1	Y	
	Ceiling Molding	1	Y	
	Win > 5 feet	1	Y	
		1	Y	
		1	Y	
		1	Y	
		1	Y	

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Page

26

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 9 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	/	Y		
A B	Baseboards	VB	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	00	Y		Y
A B	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A	Window Sill	/	Y	Y
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
A B	Win Above 5'	/	Y	
C D	Ceiling Molding	/	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Micahel Sullivan

I/R-4220

Page 1

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 10 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	0.1	Y		
A B	Baseboards	✓B	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	0.1	Y		Y
A B	Ceiling	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Page 38 Of 38

Inspector (print)

Lic #

Signature

08/25/21

Date

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST  
42 MILK ST

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	02	Y		
	Walls <i>Black</i>	04	Y		
	Baseboards	/	Y		
	Chair Rail	/	Y		
AB CD	Radiator	/	Y		
	Floor	00	Y		Y
	Ceiling	02	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
AB	Door <i>Black</i>	11	Y	<i>Metal</i>	
CD	Door Casing <i>Black</i>	03	Y		
1 2	Door Jamb	12	Y	<i>Metal</i>	
3 4	Threshold	02	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Closet Door	/	Y	
B	CI Casing	/	Y	
C	Closet Jamb	/	Y	
D	Closet Walls	/	Y	
	CI Baseboard	/	Y	
1	Closet Pole	/	Y	
2	Closet Shelf	/	Y	
3	CI Supports	/	Y	
4	Closet Floor	/	Y	
	Closet Ceiling	/	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
	Ceiling Molding	/	Y	
	Win > 5 feet	/	Y	
		/	Y	
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 11 Kitchen Pantry Bath # Hall # Stair # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y		
A B	Baseboards	01	Y		
A B	Chair Rail	01	Y		
A B	Radiator	01	Y		
A B	Floor	01	Y		Y
A B	Ceiling	01	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A	Closet Door	00	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	00	Y		
D	Closet Walls	02	Y	Brick	
	Cl Baseboard	01	Y		
1	Closet Pole	02	Y	Pipes	
2	Closet Shelf	01	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A B	Fireplace	01	Y		
C D	Mantle	01	Y		
A B	Win Above 5'	01	Y		
C D	Ceiling Molding	NA	Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 12 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y	MASON	
A B	Low Walls	56	Y	1.1e	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	00	Y		Y
A B	Ceiling	DL	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

8834

Micahel Sullivan

I/R-4220

Inspector: (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 13 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DAINGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y	MASON	
A B	Low Walls	02	Y	T.I.C	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	01	Y		Y
	Ceiling	02	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DAINGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	56	Y	13	
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

08/25/21

Date

Page 32

Of 32

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST ALLEYWAY # 11

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	02	Y	Mason	
	Walls	4.1	Y	1.1.2	
	Baseboards	/	Y		
	Chair Rail	/	Y		
AB CD	Radiator	/	Y		
	Floor	00	Y		Y
	Ceiling	0.1	Y		
A B	Door	01	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	02	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	00	Y		
B	CI Casing	01	Y		
C	Closet Jamb	02	Y		
D	Closet Walls	00	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	00	Y		
	Closet Ceiling	02	Y		
A	Closet Door	/	Y		
B	CI Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	CI Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	CI Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Signature

~~08/25/21~~

Page 29 Of 30

Inspector (print)

Lic #

Date

NEWBURYPORT

Address

Unit #

City

Location:

42 MILLIKEN HALLWAY # 12

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y	MASON	
	Walls	4.1	Y	TILE	
	Baseboards	/	Y		
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	02	Y		Y
	Ceiling	02	Y		
A B	Door	02	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room       . Start Date of RRP work   /  /   End Date   /  /  

Name of Certified Lead Safe Renovator on Site

Cert #

Date	Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

IR-4220

Signature

08/25/21

Page 39 of 88

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST 6 KITCHEN PANTRY NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	01	Y	MASON	
A B	Tile backsplash	51	Y	Tile	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor Tile	01	Y		Y
	Ceiling	DC	Y		
D	Door	/	Y		
	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

IR-4220

Signature

08/25/21

Page 88 Of 90

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 4 BATHROOM 5 KITCHEN PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	02	Y	Plaster	
A B	Tile backsplash	01	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor Tile	01	Y		Y
	Ceiling	03	Y		
D	Door	01	Y		
	Door Casing	03	Y		
	Door Jamb	01	Y		
	Threshold	15	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
C	Win Above 5'	NA	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



## Michael Sullivan

I/R-4220

Signature

~~08/25/21~~

Page

e 36

Inspector (print)

LC #

Date \_\_\_\_\_

NEWBURYPORT

Address

Unit #

City

Location: 42 MILL HALLWAY # 13

NEWBURYPORT

SIDE	SURFACE	LEAD	DA	ANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	02		Y	Mason	
	Walls	4.1		0	Tile	
	Baseboards	/		Y		
	Chair Rail	/		Y		
A B	Radiator	/		Y		
C D	Floor	00		Y		Y
	Ceiling	01		Y		
A B	Door	01		Y		
C D	Door Casing	02		Y		
1 2	Door Jamb	01		Y		
3 4	Threshold	25		Y		
A B	Door	02		Y		
C D	Door Casing	01		Y		
1 2	Door Jamb	03		Y		
3 4	Threshold	26		Y		
A B	Door	02		Y		
C D	Door Casing	01		Y		
1 2	Door Jamb	02		Y		
3 4	Threshold	/		Y		
A B	Door	.		Y		
C D	Door Casing	/		Y		
1 2	Door Jamb	/		Y		
3 4	Threshold	/		Y		
A B	Door	.		Y		
C D	Door Casing	.		Y		
1 2	Door Jamb	.		Y		
3 4	Threshold	.		Y		
A B	Door	.		Y		
C D	Door Casing	.		Y		
1 2	Door Jamb	.		Y		
3 4	Threshold	.		Y		
A B	Door	.		Y		
1 2	Door Jamb	.		Y		
3 4	Threshold	.		Y		
	Shelf	/		Y		
	Supports	/		Y		

SIDE	SURFACE	LEAD	DA NGEROU S LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	/	Y		
C	Win > 5 feet	NA	(Y)		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room           . Start Date of RRP work      /      /      End Date      /      /     

Name of Certified Lead Safe Renovator on Site

Cert #

Project Number	Project Name	Project Location	Project Status
101	Renovation of Classroom A	Elementary School	Completed
102	Repair of Gymnasium Floor	Middle School	In Progress
103	Painting of Library Walls	High School	Planned
104	Renovation of Cafeteria	Elementary School	Completed
105	Repair of Playground Equipment	Middle School	In Progress
106	Painting of Gymnasium Walls	High School	Planned
107	Renovation of Art Room	Elementary School	Completed
108	Repair of Science Lab Equipment	Middle School	In Progress
109	Painting of Music Room Walls	High School	Planned
110	Renovation of Computer Lab	Elementary School	Completed
111	Repair of Outdoor Sports Field	Middle School	In Progress
112	Painting of Theater Stage	High School	Planned
113	Renovation of Music Practice Room	Elementary School	Completed
114	Repair of Art Studio Equipment	Middle School	In Progress
115	Painting of Gymnasium Ceiling	High School	Planned
116	Renovation of Library Reading Area	Elementary School	Completed
117	Repair of Science Lab Ventilation	Middle School	In Progress
118	Painting of Music Room Ceiling	High School	Planned
119	Renovation of Computer Lab Furniture	Elementary School	Completed
120	Repair of Outdoor Sports Field Fencing	Middle School	In Progress
121	Painting of Theater Stage Backdrop	High School	Planned
122	Renovation of Music Practice Room Acoustics	Elementary School	Completed
123	Repair of Art Studio Equipment	Middle School	In Progress
124	Painting of Gymnasium Ceiling	High School	Planned
125	Renovation of Library Reading Area	Elementary School	Completed
126	Repair of Science Lab Ventilation	Middle School	In Progress
127	Painting of Music Room Ceiling	High School	Planned
128	Renovation of Computer Lab Furniture	Elementary School	Completed
129	Repair of Outdoor Sports Field Fencing	Middle School	In Progress
130	Painting of Theater Stage Backdrop	High School	Planned
131	Renovation of Music Practice Room Acoustics	Elementary School	Completed
132	Repair of Art Studio Equipment	Middle School	In Progress
133	Painting of Gymnasium Ceiling	High School	Planned



08/25/21

88  
Page 37

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 14 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y	Mason	
A B	Low Walls	0.1	Y	Tile	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	0.0	Y		Y
	Ceiling	0.2	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.2	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	0.2	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.2	Y		
1 2	Door Jamb	0.3	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	0.2	Y		
B	Cl Casing	0.1	Y		
C	Closet Jamb	0.2	Y		
D	Closet Walls	0.1	Y	Plaster	
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	0.2	Y		
3	Cl Supports	0.1	Y		
4	Closet Floor	0.0	Y		Y
	Closet Ceiling	0.1	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A	Window Sill	.	Y	
B	Win Apron	.	Y	
C	Win Casing	.	Y	
D	Header Stop	.	Y	
	Int Stops	.	Y	
1	Win Int Sash	.	Y	
2	Exterior Sill	.	Y	
3	Part Bead	.	Y	
4	Blind Stop	.	Y	
	Win Ext Sash	.	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
B	Win Above 5'	NA	Y	X3
	Ceiling Molding	.	Y	
C	Win 15'	NA	Y	X2
		.	Y	
		.	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Signature

~~08/25/21~~

Page 2 Of 2

Inspector (print)

Lic #

Date:

NEWBURYPORT

Address	Unit #	City
---------	--------	------

Location: 42 MILE HIGHWAY # 14 NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y	Mason	
	Walls	4.2	Y	Tile	
	Baseboards	/	Y		
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	0.1	Y		Y
	Ceiling	0.2	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.2	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	0.2	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

No.	Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area
1	Painting of the exterior of the building.
2	Replacement of the roof.
3	Installation of new windows.
4	Replacement of the floor.
5	Installation of new doors.
6	Replacement of the roof.
7	Installation of new windows.
8	Replacement of the floor.
9	Installation of new doors.
10	Replacement of the roof.
11	Installation of new windows.
12	Replacement of the floor.
13	Installation of new doors.
14	Replacement of the roof.
15	Installation of new windows.
16	Replacement of the floor.
17	Installation of new doors.
18	Replacement of the roof.
19	Installation of new windows.
20	Replacement of the floor.
21	Installation of new doors.
22	Replacement of the roof.
23	Installation of new windows.
24	Replacement of the floor.
25	Installation of new doors.
26	Replacement of the roof.
27	Installation of new windows.
28	Replacement of the floor.
29	Installation of new doors.
30	Replacement of the roof.
31	Installation of new windows.
32	Replacement of the floor.
33	Installation of new doors.
34	Replacement of the roof.
35	Installation of new windows.
36	Replacement of the floor.
37	Installation of new doors.
38	Replacement of the roof.
39	Installation of new windows.
40	Replacement of the floor.
41	Installation of new doors.
42	Replacement of the roof.
43	Installation of new windows.
44	Replacement of the floor.
45	Installation of new doors.
46	Replacement of the roof.
47	Installation of new windows.
48	Replacement of the floor.
49	Installation of new doors.
50	Replacement of the roof.
51	Installation of new windows.
52	Replacement of the floor.
53	Installation of new doors.
54	Replacement of the roof.
55	Installation of new windows.
56	Replacement of the floor.
57	Installation of new doors.
58	Replacement of the roof.
59	Installation of new windows.
60	Replacement of the floor.
61	Installation of new doors.
62	Replacement of the roof.
63	Installation of new windows.
64	



08/25/21

88

Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

08/25/21

Date

Page 39 of 40

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST HALLWAY # 15

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y	Mason	
	Walls	4.1	Y	Tile	
	Baseboards	/	Y		
	Chair Rail	/	Y		
AB CD	Radiator	/	Y		
	Floor	0.0	Y		Y
	Ceiling	0.2	Y		
AB	Door	0.1	Y		
CD	Door Casing	0.2	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
AB	Door	0.2	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	/	Y		
C	Win > 5 feet	NA	Y	✓3	
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

Page 8810

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: STAIR Room # 15 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y	Handwritten	
A B	Low Walls	/	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
CD	Floor	00	Y		Y
	Ceiling	NA	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A	Window Sill	/	Y	
B	Win Apron	/	Y	
C	Win Casing	/	Y	
D	Header Stop	/	Y	
	Int Stops	/	Y	
1	Win Int Sash	/	Y	
2	Exterior Sill	/	Y	
3	Part Bead	/	Y	
4	Blind Stop	/	Y	
	Win Ext Sash	/	Y	
A B	Fireplace	/	Y	
C D	Mantle	/	Y	
A B	Win Above 5'	/	Y	
C D	Ceiling Molding	NA	Y	Metac
		/	Y	
		/	Y	
		/	Y	

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

08/25/21

Page 48 of 48

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: Gym Room # 16 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y	Mason	
A B	Low Walls	/	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	01	Y		Y
	Ceiling	NA	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	X3	
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y	X2	
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		Y
	Closet Ceiling	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	/	Y		
C D	Mantle	.	Y		
A B	Win Above 5'	NA	Y		
C D	Ceiling Molding	NA	Y	Metal	
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

08/25/21

Page 47 of 1

Inspector (print)

Lic #

Signature

Date NEWBURYPORT

Address

Unit#

City

Location: 42 MILK ST Staircase #1 1st Floor TO NEWBURYPORT STAGE

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN	SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y	MASO		A	Closet Door	.	Y		
C D	Low Walls	4.1	Y	TILE		B	CI Casing	.	Y		
A B	Baseboards	/	Y			C	Closet Jamb	.	Y		
A B	Chair Rail	/	Y			D	Closet Walls	.	Y		
A B	Radiator	/	Y				CI Baseboard	.	Y		
	Floor	0.1	Y			1	Closet Pole	.	Y		
	Ceiling	0.1	Y			2	Closet Shelf	.	Y		
A B	Door	0.2	Y			3	CI Supports	.	Y		
C D	Door Casing	0.1	Y			4	Closet Floor	.	Y		
1 2	Door Jamb	0.2	Y				Closet Ceiling	.	Y		
3 4	Threshold	0.1	Y			A	Window Sill	.	Y		
A B	Door	0.2	Y			B	Win Apron	.	Y		
C D	Door Casing	0.1	Y			C	Win Casing	.	Y		
1 2	Door Jamb	0.2	Y			D	Header Stop	.	Y		
3 4	Threshold	/	Y				Int Stops	.	Y		
A B	Door	0.1	Y			1	Win Int Sash	.	Y		
C D	Door Casing	0.2	Y			2	Exterior Sill	.	Y		
1 2	Door Jamb	0.1	Y			3	Part Bead	.	Y		
3 4	Threshold	/	Y			4	Blind Stop	.	Y		
A B	Door	0.1	Y				Win Ext Sash	.	Y		
C D	Door Casing	0.2	Y				Newel Post	/	Y		
1 2	Door Jamb	0.1	Y				Railing Cap	/	Y		
3 4	Threshold	/	Y				Handrail	/	Y		
A B	Door	.	Y				Balusters	/	Y		
C D	Door Casing	.	Y				Lower rail	/	Y		
1 2	Door Jamb	.	Y				Treads	0.1	Y		
3 4	Threshold	.	Y				Risers	0.2	Y		
A B	Door	.	Y				Stringer	/	Y		
C D	Door Casing	.	Y				Baseboard	/	Y		
1 2	Door Jamb	.	Y				Floor Edge	.	Y		
3 4	Threshold	.	Y				Floor Casing	.	Y		
		.	Y				Shelf	.	Y		
		.	Y				Support	.	Y		
		.	Y				Ceiling Molding	.	Y		
		.	Y				Window above 5'	.	Y		
		.	Y					.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Signature

08/25/21

Page 48 of 48

Inspector (print)

Lic #

Date

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST RAILWAY # 16

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y	Mason	
	Walls	4.0	Y	tile	
	Baseboards	/	Y		
	Chair Rail	/	Y		
AB	Radiator	/	Y		
CD	Floor	0.1	Y		Y
	Ceiling	0.1	Y		
AB	Door	0.2	Y		
CD	Door Casing	0.3	Y		
1 2	Door Jamb	0.1	Y	X6	
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.2	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
AB	Door	0.2	Y		
CD	Door Casing	0.1	Y	X2	
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
AB	Door	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R 4220

Signature

08/25/21

Page 49 of 88

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST BATHROOM 7 KITCHEN PANTRY NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	01	Y	Mascu	
A B	Tile backsplash	01	Y	Tile	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	01	Y		Y
	Ceiling	01	Y		
D	Door	/	Y		
	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R 4220

Inspector (print)

Lic #

Signature

08/25/21

Page 46 Of 88

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST

KITCHEN

PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	0.1	Y	Max	
A B	Tile backsplash	5.6	Y	tile	
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	tile	0.2		Y
A B	Ceiling	/	Y		
D	Door	/	Y		
D	Door Casing	/	Y		
D	Door Jamb	/	Y		
D	Threshold	/	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	/	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	0.1	Y		
C D	Up Cab Door	0.1	Y		
	Up Cab Walls	0.1	Y		
1 2	Up Cab Shlvs	0.1	Y		
3 4	Supports	/	Y		
	Low Cab Fram	0.1	Y		
A B	Low Cab Door	0.1	Y		
C D	Low Cab Walls	0.1	Y		
	Low Cab Shlvs	0.1	Y		
1 2	Supports	/	Y		
3 4	Drawers	0.1	Y		
	Win Above 5'	0.1	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORTLocation: 42 MILK ST Room # 17 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y	Mason	
A B	Low Walls	/	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	00	Y		Y
	Ceiling	02	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
	Shelves	01	Y		
	Supports	00	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_, Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R-4220

08/25/21

8847  
Page 1 of 1

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 18 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y	Mask	
A B	Low Walls	0.1	Y		
A B	Baseboards	0.1	Y		
A B	Chair Rail	0.1	Y		
A B	Radiator	0.1	Y		
	Floor	0.0	Y		Y
	Ceiling	0.0	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.2	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A	Closet Door	0.1	Y		
B	Cl Casing	0.1	Y		
C	Closet Jamb	0.1	Y		
D	Closet Walls	0.1	Y		
	Cl Baseboard	0.1	Y		
1	Closet Pole	0.1	Y		
2	Closet Shelf	0.1	Y		
3	Cl Supports	0.1	Y		
4	Closet Floor	0.1	Y		Y
	Closet Ceiling	0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.0	Y		Y
B	Win Apron	0.0	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.0	Y		
	Int Stops	0.0	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A B	Fireplace	0.1	Y		
C D	Mantle	0.1	Y		
A B	Win Above 5'	0.1	Y		
C D	Ceiling Molding	0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



## Michael Sullivan

I/R-4220

~~08/25/21~~

Page 40 Of

inspectorr (print)

Lic #

Signature

Date  
NEWBURYPORT

Address

Unit#

City

Location: 42 MILK ST Staircase # 2 1st to 3rd Floor

NEWBURYPORT

[illegible]

SIDE	SURFACE	LEAD	DA NGER OUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	02	Y		
B	Win Apron	0.1	Y		
C	Win Casing	02	Y	X2	
D	Header Stop	0.4	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓	Y		
3	Part Bead	✓	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	✓	Y		
	Newel Post	4.1	⊙	Metals	
	Railing Cap	36	⊙	↓	
	Handrail	2.1	⊙		
	Balusters	36	⊙		
	Lower rail	2.4	⊙	✓	
	Treads	0.1	Y		
	Risers	00	Y		
	Stringer	32	⊙	Metals	
	Baseboard	26	⊙	↓	
	Floor Edge	26	⊙		
	Floor Casing	3.1	⊙	✓	
	Shelf	/	Y		
	Support	/	Y		
	Ceiling Molding	/	Y		
	Window above 5'	/	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Page 1 Of 1

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 19 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y		
A B	Baseboards	03	Y		
A B	Chair Rail	01	Y		
A B	Radiator	02	Y		
	Floor	01	Y		Y
	Ceiling	02	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	43	
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A	Closet Door	01	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	01	Y		
D	Closet Walls	02	Y	43	
	Cl Baseboard	03	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	02	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	02	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	03	Y		
C	Win Casing	02	Y		
D	Header Stop	01	Y	45	
	Int Stops	02	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	06	Y		Y
3	Part Bead	09	Y		
4	Blind Stop	02	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A B	Fireplace	01	Y		
C D	Mantle	01	Y		
A B	Win Above 5'	01	Y		
C D	Ceiling Molding	01	Y		
		01	Y		
		01	Y		
		01	Y		
		01	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Signature

08/25/21

Page 50 Of 50

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST HALLWAY # 17

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls	/	Y		
	Baseboards	✓3	Y		
	Chair Rail	/	Y		
AB CD	Radiator	/	Y		
	Floor	0.1	Y		Y
	Ceiling	DC	Y		
AB CD	Door	0.5	Y	Elavite 12	
12	Door Casing	0.4	Y		
34	Door Jamb	0.5	Y		
	Threshold	NC	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y	✓2	
12	Door Jamb	0.2	Y		
34	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
12	Door Jamb	0.2	Y		
34	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y	✓2	
12	Door Jamb	0.2	Y		
34	Threshold	/	Y		
AB	Door	0.1	Y		
CD	Door Casing	0.2	Y	✓2	
12	Door Jamb	0.1	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	0.0	Y		
B	Win Apron	0.0	Y		
C	Win Casing	0.0	Y		
D	Header Stop	0.0	Y		
	Int Stops	0.0	Y		
1	Win Int Sash	1.00	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Page 54 Of 54

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 20 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	00	Y	Maso	
A B	Baseboards	16	Y		
A B	Chair Rail	/	Y		
A B	Radiator	01	Y		
A B	Floor	20	Y		Y
A B	Ceiling	12	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	JK	Y		
2	Exterior Sill	JK	Y	42	Y
3	Part Bead	JK	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	JK	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R-4220

Inspector (print)

Lic # Signature

08/25/21

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 21 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y	Mason	
A B	Baseboards	✓ 03	Y		
A B	Chair Rail	✓	Y		
CP	Radiator	01	Y		
CD	Floor	00	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	✓	
1 2	Door Jamb	00	Y		
3 4	Threshold	✓	Y		
A B	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	✓	Y		
A B	Door	00	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	✓	Y		
A B	Door	✓	Y		
C D	Door Casing	✓	Y		
1 2	Door Jamb	✓	Y		
3 4	Threshold	✓	Y		
A	Closet Door	00	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	02	Y		
D	Closet Walls	01	Y		
	Cl Baseboard	✓ 03	Y		
1	Closet Pole	✓	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	01	Y		Y
	Closet Ceiling	DC	Y		
		✓	Y		
		✓	Y		
		✓	Y		
		✓	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	00	Y		Y
B	Win Apron	✓	Y		
C	Win Casing	✓	Y		
D	Header Stop	✓	Y		
	Int Stops	✓	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓ 03	Y	✓	Y
3	Part Bead	✓	Y		
4	Blind Stop	✓	Y		
	Win Ext Sash	✓	Y		
A	Window Sill	00	Y		Y
B	Win Apron	00	Y		
C	Win Casing	00	Y		
D	Header Stop	00	Y		
	Int Stops	00	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	✓	Y		Y
3	Part Bead	✓	Y		
4	Blind Stop	✓	Y		
	Win Ext Sash	✓	Y		
A	Window Sill	✓	Y		Y
B	Win Apron	✓	Y		
C	Win Casing	✓	Y		
D	Header Stop	✓	Y		
	Int Stops	✓	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓	Y		Y
3	Part Bead	✓	Y		
4	Blind Stop	✓	Y		
	Win Ext Sash	✓	Y		
A B	Fireplace	✓	Y		
C D	Mantle	✓	Y		
A B	Win Above 5'	✓	Y		
C D	Ceiling Molding	✓	Y		
		✓	Y		
		✓	Y		
		✓	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

08/25/21

Page 53 Of

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 22 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B C D	Up Walls	0.1	Y		
A B C D	Low Walls	0.1	Y	Mason	
A B C D	Baseboards	0.5	Y		
A B C D	Chair Rail	1	Y		
A B C D	Radiator	1	Y		
	Floor	0.0	Y		Y
	Ceiling	1.0	Y		
A B C D	Door	0.0	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	1	Y		
A B C D	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B C D	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B C D	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		Y
	Closet Ceiling	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.0	Y		Y
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1.0	Y		
2	Exterior Sill	1.0	Y		Y
3	Part Bead	1.0	Y		
4	Blind Stop	1	Y		
	Win Ext Sash	1.0	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	1	Y		
C D	Mantle	1	Y		
A B C D	Win Above 5'	1	Y		
	Ceiling Molding	1	Y		
		1	Y		
		1	Y		
		1	Y		
		1	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

IR 4220

Signature

08/25/21

Page 54 Of 54

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST 8 KITCHEN PANTRY NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	01	Y		
A B	Tile backsplash	/	Y		
A B	Baseboards	01	Y	Tile	
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	61	Y		Y
	Ceiling	DC	Y		
D	Door	/	Y		
	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Page 65 Of 65

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 23 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	/	Y		
A B	Baseboards	✓3	Y		
A B	Chair Rail	/	Y		
A B	Radiator	00	Y		
	Floor	0.1	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	00	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	00	Y		
D	Closet Walls	01	Y		
	Cl Baseboard	✓5	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	00	Y		Y
	Closet Ceiling	DC	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	✓K	Y		
2	Exterior Sill	✓K	Y	X2	Y
3	Part Bead	✓K	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	✓K	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	/	Y		
C D	Mantle	.	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 24 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	00	Y		
A B	Low Walls	/	Y		
A B	Baseboards	16	Y		
A B	Chair Rail	/	Y		
A B	Radiator	00	Y		
A B	Floor	00	Y		Y
A B	Ceiling	16	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		Y
	Closet Ceiling	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	16	Y		
2	Exterior Sill	16	Y		Y
3	Part Bead	16	Y	X7	
4	Blind Stop	/	Y		
	Win Ext Sash	16	Y		
A	Window Sill	00	Y		Y
B	Win Apron	00	Y		
C	Win Casing	01	Y		
D	Header Stop	00	Y	X4	
	Int Stops	01	Y		
1	Win Int Sash	00	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Page 1 of 1

Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 25 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	0.1	Y		
A B	Baseboards	0.3	Y		
A B	Chair Rail	0.1	Y		
A B	Radiator	0.1	Y		
A B	Floor	0.0	Y		Y
A B	Ceiling	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y	✓3	
1 2	Door Jamb	0.2	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y	✓2	
1 2	Door Jamb	0.2	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A	Closet Door	0.1	Y		
B	Cl Casing	0.2	Y		
C	Closet Jamb	0.1	Y		
D	Closet Walls	0.3	Y	✓3	
	Cl Baseboard	0.3	Y		
1	Closet Pole	0.2	Y		
2	Closet Shelf	0.1	Y		
3	Cl Supports	0.2	Y		
4	Closet Floor	0.1	Y		Y
	Closet Ceiling	0.2	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.1	Y		Y
B	Win Apron	0.2	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.2	Y		
	Int Stops	0.3	Y		
1	Win Int Sash	15.1	Y		
2	Exterior Sill	14.2	Y	✓5	Y
3	Part Bead	13.9	Y		
4	Blind Stop	12.6	Y		
	Win Ext Sash	15.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A B	Fireplace	0.1	Y		
C D	Mantle	0.1	Y		
A B	Win Above 5'	0.1	Y		
C D	Ceiling Molding	0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 26 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	1	Y		
A B	Baseboards	13	Y		
A B	Chair Rail	1	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	1	Y		
A B	Door	01	Y		
C D	Door Casing	00	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y	13	
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	12	
1 2	Door Jamb	01	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A	Closet Door	01	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	01	Y	13	
D	Closet Walls	02	Y		
	Cl Baseboard	13	Y		
1	Closet Pole	02	Y		
2	Closet Shelf	01	Y		
3	Cl Supports	02	Y		
4	Closet Floor	01	Y		Y
	Closet Ceiling	02	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	02	Y		
C	Win Casing	01	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y	15	Y
3	Part Bead	15	Y		
4	Blind Stop	12	Y		
	Win Ext Sash	136	Y		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A B	Fireplace	1	Y		
C D	Mantle	1	Y		
A B	Win Above 5'	1	Y		
C D	Ceiling Molding	1	Y		
			Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



I/R-4220

Lic #

Signature

~~08/25/21~~

Page 9 Of

42 MILK ST

NEWBURYPORT

Address \_\_\_\_\_ Unit # \_\_\_\_\_ City \_\_\_\_\_

Location: 42 MILK ~~HALLOWAY~~ # 18 NEWBURYPORT

SIDE	SURFACE	LEAD	DA	ANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.		Y		
B	CI Casing	.		Y		
C	Closet Jamb	.		Y		
D	Closet Walls	.		Y		
	CI Baseboard	.		Y		
1	Closet Pole	.		Y		
2	Closet Shelf	.		Y		
3	CI Supports	.		Y		
4	Closet Floor	.		Y		
	Closet Ceiling	.		Y		
A	Closet Door	.		Y		
B	CI Casing	.		Y		
C	Closet Jamb	.		Y		
D	Closet Walls	.		Y		
	CI Baseboard	.		Y		
1	Closet Pole	.		Y		
2	Closet Shelf	.		Y		
3	CI Supports	.		Y		
4	Closet Floor	.		Y		
	Closet Ceiling	.		Y		
A	Window Sill	oo		Y		
B	Win Apron	o!		Y		
C	Win Casing	oo		Y		
D	Header Stop	o!		Y		
	Int Stops	oo		Y		
1	Win Int Sash	o!		Y	Y2	
2	Exterior Sill	.		Y		
3	Part Bead	.		Y		
4	Blind Stop	.		Y		
	Win Ext Sash	.		Y		
	Ceiling Molding	.		Y		
	Win > 5 feet	.		Y		
		.		Y		
		.		Y		
		.		Y		
		.		Y		

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area




Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 27 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	02	Y		
A B	Baseboards	03	Y		
A B	Chair Rail	02	Y		
A B	Radiator	01	Y		
	Floor	02	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	43	
1 2	Door Jamb	02	Y		
3 4	Threshold	02	Y		
A B	Door	0.1	Y		
C D	Door Casing	02	Y	43	
1 2	Door Jamb	01	Y		
3 4	Threshold	02	Y		
A B	Door	02	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	02	Y		
A B	Door	02	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	02	Y		
A	Closet Door	0.1	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	0.1	Y	43	
D	Closet Walls	02	Y		
	Cl Baseboard	03	Y		
1	Closet Pole	0.1	Y		
2	Closet Shelf	02	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	04	Y		Y
B	Win Apron	02	Y		
C	Win Casing	03	Y		
D	Header Stop	02	Y		
	Int Stops	04	Y		
1	Win Int Sash	0.1	Y	X5	
2	Exterior Sill	0.9	Y		Y
3	Part Bead	0.2	Y		
4	Blind Stop	0.6	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	02	Y		Y
B	Win Apron	02	Y		
C	Win Casing	02	Y		
D	Header Stop	02	Y		
	Int Stops	02	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.9	Y		Y
3	Part Bead	0.2	Y		
4	Blind Stop	0.6	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	02	Y		Y
B	Win Apron	02	Y		
C	Win Casing	02	Y		
D	Header Stop	02	Y		
	Int Stops	02	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.9	Y		Y
3	Part Bead	0.2	Y		
4	Blind Stop	0.6	Y		
	Win Ext Sash	0.1	Y		
A B	Fireplace	02	Y		
C D	Mantle	02	Y		
A B	Win Above 5'	02	Y		
C D	Ceiling Molding	02	Y		
			Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R 4220

Signature

08/25/21

Page 48 Of 88

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST 9 KITCHEN PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	01	Y		
A B	Tile backsplash	01	Y		
A B	Baseboards	03	Y	Tile	
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
AB	Floor Tile	01	Y		Y
CD	Ceiling	03	Y		
D	Door	/	Y		
D	Door Casing	/	Y		
D	Door Jamb	/	Y		
D	Threshold	/	Y		
AB	Door	02	Y		
CD	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	03	Y		
C	Win Casing	04	Y		
D	Header Stop	02	Y	X2	
	Int Stops	01	Y		
1	Win Int Sash	161	Y		
2	Exterior Sill	152	Y		Y
3	Part Bead	139	Y		
4	Blind Stop	141	Y		
	Win Ext Sash	156	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
AB	Up Cab Frame	/	Y		
CD	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
AB	Low Cab Door	/	Y		
CD	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Signature

~~08/25/21~~

NEWBURYPORT

Inspector (print)

Lic #

42 MILK ST

Address

Unit #

City

Location: 42 MILLIKEN HALLWAY # 19

NEWBURYPORT

SIDE	SURFACE	LEAD	DAINGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	01	Y		
	Walls	/	Y		
	Baseboards	43	Y		
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	01	Y		Y
	Ceiling	12	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	Y2	
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	Y3	
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
	Shelf	.	Y		
	Supports	.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	∞	Y		
B	Win Apron	∞	Y		
C	Win Casing	∞	Y		
D	Header Stop	∞	Y		
	Int Stops	∞	Y		
1	Win Int Sash	∞	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room       . Start Date of RRP work   /  /   End Date   /  /  

Name of Certified Lead Safe Renovator on Site

Cert #

Date	Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Signature

~~08/25/21~~

Page 50 of 50

Inspector (print)

Lic #

Date \_\_\_\_\_

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK HALLWAY # 20

NEWBURYPORT

SIDE	SURFACE	LEAD	DA NGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	01	Y		
	Walls	/	Y		
	Baseboards	02	Y	Tile	
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	01	Y		Y
	Ceiling	DL	Y		
A B C D	Door	00	Y		
1 2	Door Casing	01	Y		
3 4	Door Jamb	00	Y		
	Threshold	/	Y		
A B C D	Door	00	Y		
1 2	Door Casing	01	Y		
3 4	Door Jamb	00	Y		
	Threshold	/	Y		
A B C D	Door	.	Y		
1 2	Door Casing	.	Y		
3 4	Door Jamb	.	Y		
	Threshold	.	Y		
A B C D	Door	.	Y		
1 2	Door Casing	.	Y		
3 4	Door Jamb	.	Y		
	Threshold	.	Y		
A B C D	Door	.	Y		
1 2	Door Casing	.	Y		
3 4	Door Jamb	.	Y		
	Threshold	.	Y		
A B C D	Door	.	Y		
1 2	Door Casing	.	Y		
3 4	Door Jamb	.	Y		
	Threshold	.	Y		
	Shelf	.	Y		
	Supports	.	Y		

SIDE	SURFACE	LEAD	DAINGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	02	Y		
B	CI Casing	01	Y		
C	Closet Jamb	02	Y		
D	Closet Walls	01	Y		
	CI Baseboard	01	Y	T/L	
1	Closet Pole	/	Y		
2	Closet Shelf	01	Y		
3	CI Supports	02	Y		
4	Closet Floor	01	Y	T/L	
	Closet Ceiling	DL	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Pant Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Project Number	Project Name	Project Location	Project Dates	Project Status
1	Renovation of Classroom A	123 Main St, City, State	01/2024 - 03/2024	Completed
2	Repair of Roof Leak in Gymnasium	456 Oak Ave, City, State	04/2024 - 05/2024	In Progress
3	Painting Work on Library Walls	789 Pine Rd, City, State	06/2024 - 07/2024	Planned



Michael Sullivan

I/R 4220

Signature

08/25/21

Page 64 of 88

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST BATHROOM TO KITCHEN PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	02	Y		
A B	Tile backsplash	03	Y		
A B	Baseboards	02	Y	Tile	
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
A B	Floor	04	Y		Y
A B	Ceiling	02	Y		
D	Door	/	Y		
D	Door Casing	/	Y		
D	Door Jamb	/	Y		
D	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	04	Y		Y
B	Win Apron	02	Y		
C	Win Casing	03	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	15.6	Y		
2	Exterior Sill	13.1	Y		Y
3	Part Bead	12.6	Y		
4	Blind Stop	15.1	Y		
	Win Ext Sash	14.6	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Micahel Sullivan

I/R-4220

Page 66 Of

Inspector (print)

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 28 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	/	Y		
A B	Baseboards	1/3	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	0.1	Y		Y
	Ceiling	DC	Y		
A B	Door	00	Y		
C D	Door Casing	0.1	Y	X2	
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	0.1	Y	X3	
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	00	Y		
B	Cl Casing	0.1	Y		
C	Closet Jamb	00	Y		
D	Closet Walls	0.1	Y	X3	
	Cl Baseboard	1/3	Y		
1	Closet Pole	00	Y		
2	Closet Shelf	0.1	Y		
3	Cl Supports	0.2	Y		
4	Closet Floor	0.1	Y		Y
	Closet Ceiling	0.2	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.1	Y		Y
B	Win Apron	0.3	Y		
C	Win Casing	0.2	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.0	Y		
1	Win Int Sash	1.1	Y		
2	Exterior Sill	0.2	Y	X5	Y
3	Part Bead	1.1	Y		
4	Blind Stop	1.1	Y		
	Win Ext Sash	0.2	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Michael Sullivan

I/R-4220

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 21 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	02	Y		
A B	Baseboards	0.3	Y		
A B	Chair Rail	02	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	00	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	02	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	X2	
1 2	Door Jamb	02	Y		
3 4	Threshold	02	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	X3	
1 2	Door Jamb	01	Y		
3 4	Threshold	02	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	02	Y		
A	Closet Door	01	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	01	Y	X3	
D	Closet Walls	02	Y		
	Cl Baseboard	0.3	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	02	Y		
3	Cl Supports	01	Y		
4	Closet Floor	00	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.4	Y		Y
B	Win Apron	02	Y		
C	Win Casing	03	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	161	0		
2	Exterior Sill	159	0	X5	Y
3	Part Bead	116	0		
4	Blind Stop	137	0		
	Win Ext Sash	126	0		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A B	Fireplace		Y		
C D	Mantle		Y		
A B	Win Above 5'		Y		
C D	Ceiling Molding		Y		
			Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Micahel Sullivan

I/R-4220

Page 1 of 1

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 30 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y		
A B	Baseboards	03	Y		
A B	Chair Rail	01	Y		
A B	Radiator	02	Y		
	Floor	01	Y		Y
	Ceiling	DC	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	X3	
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A	Closet Door	01	Y		
B	Cl Casing	02	Y		
C	Closet Jamb	01	Y		
D	Closet Walls	02	Y		
	Cl Baseboard	03	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	00	Y		Y
	Closet Ceiling	02	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	03	Y		
C	Win Casing	04	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y	X5	
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A B	Fireplace	01	Y		
C D	Mantle	01	Y		
A B	Win Above 5'	01	Y		
C D	Ceiling Molding	01	Y		
		01	Y		
		01	Y		
		01	Y		
		01	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Signature

08/25/21

Page 68 of 68

Inspector (print)

Lic #

Date

NEWBURYPORT

Address \_\_\_\_\_ Unit # \_\_\_\_\_ City \_\_\_\_\_

Location: 42 MILK ST RAILWAY # 21

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	.	Y		
	Walls	.	Y		
	Baseboards	.	Y		
	Chair Rail	.	Y		
AB	Radiator	.	Y		
CD	Floor	.	Y		Y
	Ceiling	.	Y		
AB	Door	06	Y	ELU	
CD	Door Casing	05	Y		
12	Door Jamb	01	Y		
34	Threshold	NC	Y		
AB	Door	00	Y		
CD	Door Casing	02	Y		
12	Door Jamb	01	Y		
34	Threshold	/	Y		
AB	Door	00	Y		
CD	Door Casing	01	Y		
12	Door Jamb	02	Y		
34	Threshold	/	Y		
AB	Door	02	Y		
CD	Door Casing	01	Y	Y2	
12	Door Jamb	02	Y		
34	Threshold	/	Y		
AB	Door	01	Y		
CD	Door Casing	02	Y	Y2	
12	Door Jamb	01	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
AB	Door	/	Y		
CD	Door Casing	/	Y		
12	Door Jamb	/	Y		
34	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	00	Y		
B	Win Apron	01	Y		
C	Win Casing	00	Y		
D	Header Stop	01	Y		
	Int Stops	00	Y	Y2	
1	Win Int Sash	01	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_ Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 31 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	/	Y		
A B	Baseboards	✓3	Y		
A B	Chair Rail	/	Y		
A B	Radiator	00	Y		
A B	Floor	0.1	Y		Y
A B	Ceiling	76	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		Y
	Closet Ceiling	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	✓	Y		
2	Exterior Sill	✓	Y		Y
3	Part Bead	✓	Y	X5	
4	Blind Stop	/	Y		
	Win Ext Sash	✓	Y		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A	Window Sill	00	Y		Y
B	Win Apron	01	Y		
C	Win Casing	00	Y	X2	
D	Header Stop	00	Y		
	Int Stops	00	Y		
1	Win Int Sash	00	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Fireplace	/	Y		
C D	Mantle	/	Y		
A B	Win Above 5'	/	Y		
C D	Ceiling Molding	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Micahel Sullivan

I/R-4220

Page 10 Of 10

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 32 Kitchen Pantry Bath # Hall # NEWBURYPORT Stair #

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	1	Y		
A B	Baseboards	1.5	Y		
A B	Chair Rail	1	Y		
A B	Radiator	1	Y		
A B	Floor	0.0	Y		Y
A B	Ceiling	.	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.0	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.0	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	1	Y		
A B	Door	.	Y		
C D	Door Casing	.	Y		
1 2	Door Jamb	.	Y		
3 4	Threshold	.	Y		
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		Y
	Closet Ceiling	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.1	Y		Y
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1.5	Y		
2	Exterior Sill	1.5	Y		Y
3	Part Bead	1.5	Y	X10	
4	Blind Stop	1	Y		
	Win Ext Sash	1	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	.	Y		
C D	Mantle	.	Y		
A B	Win Above 5'	.	Y		
C D	Ceiling Molding	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

Date 08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 33 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y		
A B	Baseboards	03	Y		
A B	Chair Rail	01	Y		
A B	Radiator	00	Y		
A B	Floor	01	Y		Y
A B	Ceiling	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	Y3	
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	02	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A	Closet Door	01	Y		
B	Cl Casing	00	Y		
C	Closet Jamb	01	Y		
D	Closet Walls	02	Y	Y3	
	Cl Baseboard	03	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	00	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	03	Y		
C	Win Casing	01	Y		
D	Header Stop	03	Y		
	Int Stops	04	Y		
1	Win Int Sash	16.1	Y		
2	Exterior Sill	15.9	Y		Y
3	Part Bead	14.6	Y	Y3	
4	Blind Stop	06.6	Y		
	Win Ext Sash	15.1	Y		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A	Window Sill		Y		Y
B	Win Apron		Y		
C	Win Casing		Y		
D	Header Stop		Y		
	Int Stops		Y		
1	Win Int Sash		Y		
2	Exterior Sill		Y		Y
3	Part Bead		Y		
4	Blind Stop		Y		
	Win Ext Sash		Y		
A B	Fireplace		Y		
C D	Mantle		Y		
A B	Win Above 5'		Y		
C D	Ceiling Molding		Y		
			Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

08/25/21

Page 70

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 34 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	1	Y		
A B	Baseboards	15	Y		
A B	Chair Rail	1	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	12	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	1	Y		
A B	Door	00	Y		
B D	Door Casing	01	Y	Y3	
1 2	Door Jamb	00	Y		
3 4	Threshold	1	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	Y2	
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A	Closet Door	00	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	00	Y	Y3	
D	Closet Walls	01	Y		
	Cl Baseboard	15	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	02	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	03	Y		Y
B	Win Apron	04	Y		
C	Win Casing	03	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	156	0		
2	Exterior Sill	141	0	Y5	Y
3	Part Bead	136	0		
4	Blind Stop	121	0		
	Win Ext Sash	159	0		
A	Window Sill	1	Y		Y
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1	Y		
2	Exterior Sill	1	Y		Y
3	Part Bead	1	Y		
4	Blind Stop	1	Y		
	Win Ext Sash	1	Y		
A	Window Sill	1	Y		Y
B	Win Apron	1	Y		
C	Win Casing	1	Y		
D	Header Stop	1	Y		
	Int Stops	1	Y		
1	Win Int Sash	1	Y		
2	Exterior Sill	1	Y		Y
3	Part Bead	1	Y		
4	Blind Stop	1	Y		
	Win Ext Sash	1	Y		
A B	Fireplace	1	Y		
C D	Mantle	1	Y		
A B	Win Above 5'	1	Y		
C D	Ceiling Molding	1	Y		
		1	Y		
		1	Y		
		1	Y		
		1	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



I/R-4220

Lic #

~~08/25/21~~

Date \_\_\_\_\_

NEWBURYPORT

[illegible]

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Inspector (print)

Lic # Signature

08/25/21

Page 11 Of 12

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room #35 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	0.1	Y		
A B	Low Walls	0.1	Y		
A B	Baseboards	0.1	Y		
A B	Chair Rail	0.1	Y		
A B	Radiator	0.1	Y		
A B	Floor	0.2	Y		Y
A B	Ceiling	0.1	Y		
A B	Door	0.0	Y		
C D	Door Casing	0.1	Y	Y2	
1 2	Door Jamb	0.0	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.2	Y	Y3	
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A B	Door	0.1	Y		
C D	Door Casing	0.1	Y		
1 2	Door Jamb	0.1	Y		
3 4	Threshold	0.1	Y		
A	Closet Door	0.1	Y		
B	Cl Casing	0.0	Y	Y3	
C	Closet Jamb	0.1	Y		
D	Closet Walls	0.0	Y		
	Cl Baseboard	0.1	Y		
1	Closet Pole	0.1	Y		
2	Closet Shelf	0.0	Y		
3	Cl Supports	0.1	Y		
4	Closet Floor	0.0	Y		Y
	Closet Ceiling	0.2	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.2	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.2	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y	Y5	Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A	Window Sill	0.1	Y		Y
B	Win Apron	0.1	Y		
C	Win Casing	0.1	Y		
D	Header Stop	0.1	Y		
	Int Stops	0.1	Y		
1	Win Int Sash	0.1	Y		
2	Exterior Sill	0.1	Y		Y
3	Part Bead	0.1	Y		
4	Blind Stop	0.1	Y		
	Win Ext Sash	0.1	Y		
A B	Fireplace	0.1	Y		
C D	Mantle	0.1	Y		
A B	Win Above 5'	0.1	Y		
C D	Ceiling Molding	0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		
		0.1	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R 4220

Signature

Page 75 Of 75

Inspector (print)

Lic #

08/25/21

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 4 BATHROOM 11 KITCHEN PANTRY NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	02	Y		
A B	Tile backsplash	01	Y		
A B	Baseboards	02	Y	tile	
A B	Chair Rail	/	Y		
A B	Radiator	01	Y		
	Floor	02	Y	tile	Y
	Ceiling	DC	Y		
	Door	/	Y		
D	Door Casing	/	Y		
	Door Jamb	/	Y		
	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	02	Y		
C	Win Casing	04	Y		
D	Header Stop	02	Y		
	Int Stops	01	Y		
1	Win Int Sash	161	(Y)		
2	Exterior Sill	K2	(Y)		Y
3	Part Bead	M6	(Y)	X2	
4	Blind Stop	131	(Y)		
	Win Ext Sash	B7	(Y)		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



**Michael Sullivan**

I/R-4220

Inspector (print)

Lic #

Signature

~~08/25/21~~

Date \_\_\_\_\_

NEWBURYPORT

Page 10 Of 12

Address \_\_\_\_\_ Unit # \_\_\_\_\_ City \_\_\_\_\_

Location: 42 MILWAUKEE AVE # 23

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls	/	Y		
	Baseboards	1/2	Y		
	Chair Rail	/	Y		
AB	Radiator	/	Y		
CD	Floor	0.1	Y		Y
	Ceiling	DC	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	0.0	Y		
CD	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	.	Y		
AB	Door	.	Y		
CD	Door Casing	.	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	.	Y		
AB	Door	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	0.1	Y		
B	CI Casing	0.2	Y		
C	Closet Jamb	0.1	Y		
D	Closet Walls	0.2	Y		
	CI Baseboard	0.1	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	0.1	Y		
3	CI Supports	0.0	Y		
4	Closet Floor	0.1	Y		
	Closet Ceiling	0.2	Y		
A	Closet Door	.	Y		
B	CI Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	CI Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	CI Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Ceiling Molding	.	Y		
	Win > 5 feet	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on **floor** in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

Signature

08/25/21

Page 88 Of 88

Inspector (print)

Lic #

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST HALLWAY # 24

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
	Walls	0.1	Y		
	Walls	/	Y		
	Baseboards	0.2	Y	T, b	
	Chair Rail	/	Y		
A B C D	Radiator	/	Y		
	Floor	0.2	Y	T, b	Y
	Ceiling	/	Y		
A B C D	Door	0.0	Y		
	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
A B C D	Door	0.0	Y		
	Door Casing	0.1	Y		
1 2	Door Jamb	0.0	Y		
3 4	Threshold	/	Y		
A B C D	Door	/	Y		
	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B C D	Door	/	Y		
	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B C D	Door	/	Y		
	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B C D	Door	/	Y		
	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
	Shelf	/	Y		
	Supports	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	0.0	Y		
B	Cl Casing	0.1	Y	Ball Rm	
C	Closet Jamb	0.0	Y		
D	Closet Walls	0.1	Y		
	Cl Baseboard	0.2	Y	T, b	
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	0.1	Y		
	Closet Ceiling	0.0	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Window Sill	/	Y		
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
	Ceiling Molding	/	Y		
	Win > 5 feet	/	Y		
		/	Y		
		/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

IR 4220

Signature

08/25/21

Page 12 Of 12

Inspector (print)

Lic #

Signature

Date

42 MILK ST

NEWBURYPORT

Address

Unit #

City

Location: 42 MILK ST 12 KITCHEN PANTRY

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Walls	01	Y		
A B	Tile backsplash	04	Y		
A B	Baseboards	03	Y	tile	
A B	Chair Rail	/	Y		
A B	Radiator	02	Y		
A B	Floor	01	Y	tile	Y
A B	Ceiling	00	Y		
D	Door	/	Y		
D	Door Casing	/	Y		
D	Door Jamb	/	Y		
D	Threshold	/	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	02	Y		Y
B	Win Apron	01	Y		
C	Win Casing	02	Y		
D	Header Stop	01	Y	Y	
	Int Stops	02	Y		
1	Win Int Sash	161	0		
2	Exterior Sill	151	0		Y
3	Part Bead	149	0		
4	Blind Stop	137	0		
	Win Ext Sash	156	0		
A	Window Sill	/	Y		Y
B	Win Apron	/	Y		
C	Win Casing	/	Y		
D	Header Stop	/	Y		
	Int Stops	/	Y		
1	Win Int Sash	/	Y		
2	Exterior Sill	/	Y		Y
3	Part Bead	/	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	/	Y		
A B	Up Cab Frame	/	Y		
C D	Up Cab Door	/	Y		
	Up Cab Walls	/	Y		
1 2	Up Cab Shlvs	/	Y		
3 4	Supports	/	Y		
	Low Cab Fram	/	Y		
A B	Low Cab Door	/	Y		
C D	Low Cab Walls	/	Y		
	Low Cab Shlvs	/	Y		
1 2	Supports	/	Y		
3 4	Drawers	/	Y		
	Win Above 5'	/	Y		
	Pipe Chase	/	Y		
	Ceiling Molding	/	Y		
		/	Y		
		/	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

08/25/21

Page 1 Of 1

Inspector (print)

Lic # Signature

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 36 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	01	Y		
A B	Low Walls	01	Y		
A B	Baseboards	03	Y		
A B	Chair Rail	01	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	01	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	X2	
1 2	Door Jamb	02	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	02	Y	X3	
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A B	Door	01	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	01	Y		
3 4	Threshold	01	Y		
A	Closet Door	02	Y		
B	Cl Casing	01	Y		
C	Closet Jamb	02	Y		
D	Closet Walls	00	Y	X3	
	Cl Baseboard	03	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	01	Y		Y
B	Win Apron	03	Y		
C	Win Casing	01	Y		
D	Header Stop	03	Y		
	Int Stops	01	Y		
1	Win Int Sash	16.1	Y		
2	Exterior Sill	15.9	Y	X5	Y
3	Part Bead	14.6	Y		
4	Blind Stop	13.1	Y		
	Win Ext Sash	12.7	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A	Window Sill	01	Y		Y
B	Win Apron	01	Y		
C	Win Casing	01	Y		
D	Header Stop	01	Y		
	Int Stops	01	Y		
1	Win Int Sash	01	Y		
2	Exterior Sill	01	Y		Y
3	Part Bead	01	Y		
4	Blind Stop	01	Y		
	Win Ext Sash	01	Y		
A B	Fireplace	01	Y		
C D	Mantle	01	Y		
A B	Win Above 5'	01	Y		
C D	Ceiling Molding	01	Y		
			Y		
			Y		
			Y		
			Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



Micahel Sullivan

I/R-4220

Lic # Signature

Date  
08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Room # 31 Kitchen Pantry Bath # Hall # NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	02	Y		
A B	Low Walls	1	Y		
A B	Baseboards	15	Y		
A B	Chair Rail	1	Y		
A B	Radiator	01	Y		
	Floor	00	Y		Y
	Ceiling	00	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	1	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	X2	
1 2	Door Jamb	00	Y		
3 4	Threshold	1	Y		
A B	Door	00	Y		
C D	Door Casing	01	Y	X3	
1 2	Door Jamb	00	Y		
3 4	Threshold	1	Y		
A B	Door	1	Y		
C D	Door Casing	1	Y		
1 2	Door Jamb	1	Y		
3 4	Threshold	1	Y		
A	Closet Door	01	Y		
B	Cl Casing	00	Y		
C	Closet Jamb	01	Y		
D	Closet Walls	00	Y	X3	
	Cl Baseboard	15	Y		
1	Closet Pole	01	Y		
2	Closet Shelf	00	Y		
3	Cl Supports	01	Y		
4	Closet Floor	02	Y		Y
	Closet Ceiling	01	Y		
			Y		
			Y		
			Y		
			Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Window Sill	04	Y		Y
B	Win Apron	03	Y		
C	Win Casing	02	Y		
D	Header Stop	01	Y		
	Int Stops	03	Y		
1	Win Int Sash	162	Y		
2	Exterior Sill	159	Y	X5	Y
3	Part Bead	146	Y		
4	Blind Stop	131	Y		
	Win Ext Sash	127	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A	Window Sill	.	Y		Y
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		Y
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
A B	Fireplace	.	Y		
C D	Mantle	.	Y		
A B	Win Above 5'	.	Y		
C D	Ceiling Molding	.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

08/25/21

Page 84 of 88

Inspector (print)

Lic #

Signature

Date

NEWBURYPORT

Address

Unit#

City

Location: 42 MILK ST Staircase #3 3rd Floor

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	46	Y	BRICK	
A B	Low Walls	/	Y		
A B	Baseboards	56	Y	Metal	
A B	Chair Rail	/	Y		
A B	Radiator	01	Y		
	Floor	02	Y		
	Ceiling	61	Y	Metal	
A B	Door 3A	00	Y		
C D	Door Casing	02	Y	V2	
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door 2A	01	Y		
C D	Door Casing	02	Y	V2	
1 2	Door Jamb	01	Y		
3 4	Threshold	/	Y		
A B	Door Ext	00	Y		
C D	Door Casing	01	Y		
1 2	Door Jamb	00	Y		
3 4	Threshold	X	Y		
A B	Door 1A	00	Y	V2	
C D	Door Casing	01	Y		
1 2	Door Jamb	02	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	/	Y		
B	Cl Casing	/	Y		
C	Closet Jamb	/	Y		
D	Closet Walls	/	Y		
	Cl Baseboard	/	Y		
1	Closet Pole	/	Y		
2	Closet Shelf	/	Y		
3	Cl Supports	/	Y		
4	Closet Floor	/	Y		
	Closet Ceiling	/	Y		
A	Window Sill	02	Y		
B	Win Apron	01	Y		
C	Win Casing	02	Y		
D	Header Stop	01	Y		
	Int Stops	02	Y		
1	Win Int Sash	VK	Y		
2	Exterior Sill	VK	Y	X4	
3	Part Bead	VK	Y		
4	Blind Stop	/	Y		
	Win Ext Sash	VK	Y		
	Newel Post	56	Y	Metal	
	Railing Cap	41	Y		
	Handrail	01	Y		
	Balusters	56	Y		
	Lower rail	57	Y		
	Treads	02	Y		
	Risers	01	Y		
	Stringer	64	Y	Metal	
	Baseboard	37	Y		
	Floor Edge	24	Y		
	Floor Casing	36	Y		
	Shelf	/	Y		
	Support	/	Y		
	Ceiling Molding	/	Y		
C	Window above 5'	31	Y		
		.	Y		

Work Area was visually clean on \_\_\_/\_\_\_/\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_/\_\_\_/\_\_\_ End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



08/25/21

88

Michael Sullivan

I/R-4220

08/25/21

Page 800

Inspector (print)

Lic #

Signature

Date  
NEWBURYPORT

Address

Unit#

City

Location: 42 MILK ST

Staircase #4

1st to 3rd Floor

NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Up Walls	61	Y	BRICK	
A B	Low Walls	/	Y		
A B	Baseboards	/	Y		
A B	Chair Rail	/	Y		
A B	Radiator	/	Y		
	Floor	02	Y		
	Ceiling	01	Y		
A B	Door	41	Y		
C D	Door Casing	30	Y		
1 2	Door Jamb	29	Y		
3 4	Threshold	NC	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
A B	Door	/	Y		
C D	Door Casing	/	Y		
1 2	Door Jamb	/	Y		
3 4	Threshold	/	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		
		.	Y		

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A	Closet Door	.	Y		
B	Cl Casing	.	Y		
C	Closet Jamb	.	Y		
D	Closet Walls	.	Y		
	Cl Baseboard	.	Y		
1	Closet Pole	.	Y		
2	Closet Shelf	.	Y		
3	Cl Supports	.	Y		
4	Closet Floor	.	Y		
	Closet Ceiling	.	Y		
A	Window Sill	.	Y		
B	Win Apron	.	Y		
C	Win Casing	.	Y		
D	Header Stop	.	Y		
	Int Stops	.	Y		
1	Win Int Sash	.	Y		
2	Exterior Sill	.	Y		
3	Part Bead	.	Y		
4	Blind Stop	.	Y		
	Win Ext Sash	.	Y		
	Newel Post	/	Y		
	Railing Cap	/	Y		
	Handrail	/	Y		
	Balusters	/	Y		
	Lower rail	/	Y		
	Treads	01	Y		
	Risers	00	Y		
	Stringer	/	Y		
	Baseboard	/	Y		
	Floor Edge	/	Y		
	Floor Casing	/	Y		
	Shelf	.	Y		
	Support	.	Y		
	Ceiling Molding	.	Y		
C	Window above 5'	15.1	Y		
		.	Y		

Work Area was visually clean on \_\_\_\_/\_\_\_\_/\_\_\_\_ for RRP Visual Reinspection

Dust wipe in adjacent work area taken on floor in Room \_\_\_\_\_. Start Date of RRP work \_\_\_\_/\_\_\_\_/\_\_\_\_ End Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Name of Certified Lead Safe Renovator on Site

Cert #

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area



1/R-4220

Inspector (print)

Lic #	Signature
-------	-----------

08/25/21

Page 5 Of

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 342 MILK ROOM Room # 342 Kitchen 342 Pantry 342 Bath # 342 Hall # 342 Stair # 342

SIDE	SURFACE	LEAD	DA	ANGEROUS LEAD LEVEL	COMMENTS	DUST TAKEN
A B	Door	a		Y		
C D	Door Casing	oo		Y		
1 2	Door Jamb	a		Y		
3 4	Threshold	/		Y		
A B	Door	.		Y		
C D	Door Casing	.		Y		
1 2	Door Jamb	.		Y		
3 4	Threshold	.		Y		
A B	Door	.		Y		
C D	Door Casing	.		Y		
1 2	Door Jamb	.		Y		
3 4	Threshold	.		Y		
A	Window Sill	.		Y		Y
B	Win Apron	.		Y		
C	Win Casing	.		Y		
D	Header Stop	.		Y		
	Int Stops	.		Y		
1	Win Int Sash	.		Y		
2	Exterior Sill	.		Y		Y
3	Part Bead	.		Y		
4	Blind Stop	.		Y		
	Win Ext Sash	.		Y		
A	Closet Door	.		Y		
B	Cl Casing	.		Y		
C	Closet Jamb	.		Y		
D	Closet Walls	.		Y		
	Cl Baseboard	.		Y		
1	Closet Pole	.		Y		
2	Closet Shelf	.		Y		
3	Cl Supports	.		Y		
4	Closet Floor	.		Y		Y
	Closet Ceiling	.		Y		
		.		Y		
B	W. 15'	141		Y	X3	
		.		Y		
		.		Y		
		.		Y		
		.		Y		



Michael Sullivan

I/R-4220

08/25/21

Page 88 Of 90

Inspector (print)

Lic #

Signature

08/25/21

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Porch Exterior A B C D

Garage Outbuilding NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Siding	NC	Y	
	Corner Boards	/	Y	
	Lower Trim	/	Y	
	Upper Trim	NA	Y	
	Foundation	0.1	Y	
	Storm Door	.	Y	
	Door	.	Y	
	Door Casing	.	Y	
	Door Jamb	.	Y	
	Threshold	.	Y	
	Kickplate	.	Y	
	Window Sill	NC	Y	
A1	Win Casing	00	Y	
	Window Sash	VR	Y	x4
	Cellar Win Sill	NC	Y	
A2	Cel Win Sash	VR	Y	x4
	Cel Win Frame	00	Y	
	Screen Frame	/	Y	
	Newel post	.	Y	
	Railing Cap	.	Y	
	Handrail	.	Y	
	Balusters	.	Y	
	Treads	.	Y	
	Risers	.	Y	
	Stringer	.	Y	
	Floor	/	Y	
	Bulkhead	/	Y	
	Fences	1.1	Y	Metal
	Shutters	/	Y	
	Lattice	/	Y	
	Lintels	23	Y	Metal
	Windows	VR	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Storm Door	/	Y	
	Door	01	Y	
A1	Door Casing	00	Y	
	Door Jamb	01	Y	
	Threshold	NC	Y	
	Kickplate	/	Y	
	Storm Door	/	Y	
	Door	01	Y	
A2	Door Casing	00	Y	
	Door Jamb	01	Y	
	Threshold	NC	Y	
	Kickplate	/	Y	
	Window Sill	NC	Y	
A3	Win Casing	00	Y	
	Window Sash	VR	Y	x6
	Window Sill	NC	Y	
A4	Win Casing	00	Y	
	Window Sash	VR	Y	x4
	Window Sill	NC	Y	
A5	Win Casing	00	Y	
	Window Sash	VR	Y	x4
	Cellar Win Sill	.	Y	
	Cel Win Sash	.	Y	
	Cel Win Frame	.	Y	
	Screen Frame	.	Y	
	Cellar Win Sill	.	Y	
	Cel Win Sash	.	Y	
	Cel Win Frame	.	Y	
	Screen Frame	.	Y	
	Cellar Win Sill	.	Y	
	Cel Win Sash	.	Y	
	Cel Win Frame	.	Y	
	Screen Frame	.	Y	
	Drain Pipes	.	Y	
	Elec Conduit	.	Y	
	Oil Fill Pipe	.	Y	
	Overhang Trim	.	Y	
		.	Y	
		.	Y	

The Work Area was Visually Clean on \_\_\_/\_\_\_/\_\_\_ for Visual Reinspection. Start Date of RRP Work \_\_\_/\_\_\_/\_\_\_ and End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site: \_\_\_\_\_: Cert # \_\_\_\_\_

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area:



Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

08/25/21

Page 88 of 88

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Porch Exterior A B C D (100) Garage Outbuilding					NEWBURYPORT				
SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS	SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Siding	NA	Y			Storm Door	NA	Y	
	Corner Boards	NA	Y			Door	01		
	Lower Trim	NA	Y			Door Casing	41	Y	
	Upper Trim	NA	Y			Door Jamb	36	Y	
	Foundation	01	Y			Threshold	NA	Y	
	Storm Door	NA	Y			Kickplate	NA	Y	
B1	Door	00	Y			Storm Door	NA	Y	
	Door Casing	B1	Y			Door	00	Y	
	Door Jamb	00	Y			Door Casing	96	Y	
	Threshold	NA	Y			Door Jamb	00	Y	
	Kickplate	NA	Y			Threshold	NA	Y	
B1	Window Sill	71	Y			Kickplate	NA	Y	
	Win Casing	W	Y			Window Sill	97	Y	
	Window Sash	01	Y	Vent		Win Casing	69	Y	
	Center Win Sill	86	Y			Window Sash	71	Y	
	Center Win Sash	79	Y			Window Sill	56	Y	
B3	Center Win Frame	56	Y			Win Casing	61	Y	
	Screen Frame	33	Y	Metal		Window Sash	22	Y	
	Newel post	00	Y			Window Sill	71	Y	
	Railing Cap	00	Y			B5	Win Casing	61	Y
	Handrail	02	Y	Metal		Window Sash	59	Y	
	Balusters	01	Y			Center Win Sill	61	Y	
	Treads	01	Y			B6	Center Win Sash	56	Y
	Risers	00	Y			Center Win Frame	72	Y	
	Stringer	00	Y			Screen Frame	21	Y	Metal
	Floor	NA	Y			Center Win Sill	71	Y	
	Bulkhead	NA	Y			B7	Center Win Sash	69	Y
	Fences	01	Y			Center Win Frame	72	Y	
	Shutters	NA	Y			Screen Frame	16	Y	Metal
	Lattice	NA	Y			Center Win Sill	61	Y	
	Links	56	Y			B8	Center Win Sash	72	Y
	Wickets	NA	Y			Center Win Frame	51	Y	
B1	Screen Frame	61	Y	Metal		Screen Frame	26	Y	Metal
B3	Screen Frame	52	Y	Metal		Drain Pipes	06	Y	
B4	Screen Frame	41	Y	Metal		Elec Conduit	NA	Y	
B5	Screen Frame	21	Y	Metal		Oil Fill Pipe	NA	Y	
			Y			Overhang Trim	11.1	Y	B1 Door
			Y					Y	
			Y					Y	

The Work Area was Visually Clean on \_\_\_/\_\_\_/\_\_\_ for Visual Reinspection. Start Date of RRP Work \_\_\_/\_\_\_/\_\_\_ and End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site: \_\_\_\_\_: Cert # \_\_\_\_\_

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area:



Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

08/25/21

Page 88 Of 88

Date

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 MILK ST Porch Exterior A B C D E Garage Outbuilding NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Siding	.	Y	
	Corner Boards	.	Y	
	Lower Trim	.	Y	
	Upper Trim	.	Y	
	Foundation	.	Y	
	Storm Door	.	Y	
	Door	.	Y	
	Door Casing	.	Y	
	Door Jamb	.	Y	
	Threshold	.	Y	
	Kickplate	.	Y	
	Window Sill	.	Y	
	Win Casing	.	Y	
	Window Sash	.	Y	
	Ceiling Win Sill	56	Y	
	Ceiling Win Sash	41	Y	
	Ceiling Win Frame	71	Y	
	Screen Frame	12	Y	
	Newel post	.	Y	
	Railing Cap	.	Y	
	Handrail	.	Y	
	Balusters	.	Y	
	Treads	.	Y	
	Risers	.	Y	
	Stringer	.	Y	
	Floor	.	Y	
	Bulkhead	.	Y	
	Fences	.	Y	
	Shutters	.	Y	
	Lattice	.	Y	
	Screen Frame	21	Y	Melan
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Storm Door	.	Y	
	Door	.	Y	
	Door Casing	.	Y	
	Door Jamb	.	Y	
	Threshold	.	Y	
	Kickplate	.	Y	
	Storm Door	.	Y	
	Door	.	Y	
	Door Casing	.	Y	
	Door Jamb	.	Y	
	Threshold	.	Y	
	Kickplate	.	Y	
	Window Sill	.	Y	
	Win Casing	.	Y	
	Window Sash	.	Y	
	Window Sill	.	Y	
	Win Casing	.	Y	
	Window Sash	.	Y	
	Window Sill	71	Y	
	Win Casing	69	Y	
	Window Sash	54	Y	
	Ceiling Win Sill	71	Y	
	Ceiling Win Sash	64	Y	
	Ceiling Win Frame	22	Y	
	Screen Frame	16	Y	Melan
	Ceiling Win Sill	69	Y	
	Ceiling Win Sash	71	Y	
	Ceiling Win Frame	56	Y	
	Screen Frame	21	Y	Melan
	Ceiling Win Sill	59	Y	
	Ceiling Win Sash	64	Y	
	Ceiling Win Frame	22	Y	
	Screen Frame	16	Y	Melan
	Drain Pipes	.	Y	
	Elec Conduit	.	Y	
	Oil Fill Pipe	.	Y	
	Overhang Trim	.	Y	
		.	Y	
		.	Y	

The Work Area was Visually Clean on \_\_\_/\_\_\_/\_\_\_ for Visual Reinspection. Start Date of RRP Work \_\_\_/\_\_\_/\_\_\_ and End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site: \_\_\_\_\_: Cert # \_\_\_\_\_

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area:



Michael Sullivan

I/R-4220

Inspector (print)

Lic #

Signature

Page 88 Of 97

Date

08/25/21

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 Milk St Porch Exterior A B C D Garage Outbuilding NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Siding	NC	Y	
	Corner Boards	/	Y	
	Lower Trim	/	Y	
	Upper Trim	NA	Y	
	Foundation	01	Y	
	Storm Door	/	Y	
	Door	01	Y	
C	Door Casing	00	Y	
	Door Jamb	56	Y	
	Threshold	NC	Y	
	Kickplate	/	Y	
	Window Sill	/	Y	
	Win Casing	/	Y	
	Window Sash	/	Y	
	Cellar Win Sill	12.1	Y	
	Cell Win Sash	11.6	Y	
	Cell Win Frame	14.1	Y	
	Screen Frame	2.1	Y	Y5 Metal
	Newel post	0.1	Y	
	Railing Cap	02	Y	
	Handrail	/	Y	
	Balusters	01	Y	
	Treads	NC	Y	
	Risers	NC	Y	
	Stringer	/	Y	
	Floor	NC	Y	
	Bulkhead	/	Y	
	Fences	01	Y	
	Shutters	/	Y	
	Lattice	/	Y	
	Windows	51	Y	Metal
	Windows	51	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Storm Door	/	Y	
	Door	00	Y	
	Door Casing	141	Y	
C	Door Jamb	02	Y	
	Threshold	NC	Y	
	Kickplate	/	Y	
	Storm Door	/	Y	
	Door	/	Y	
	Door Casing	/	Y	
	Door Jamb	/	Y	
	Threshold	/	Y	
	Kickplate	/	Y	
	Window Sill	/	Y	
	Win Casing	/	Y	
	Window Sash	/	Y	
	Window Sill	/	Y	
	Win Casing	/	Y	
	Window Sash	/	Y	
	Window Sill	/	Y	
	Win Casing	/	Y	
	Window Sash	/	Y	
	Cellar Win Sill	/	Y	
	Cell Win Sash	/	Y	
	Cell Win Frame	/	Y	
	Screen Frame	/	Y	
	Cellar Win Sill	/	Y	
	Cell Win Sash	/	Y	
	Cell Win Frame	/	Y	
	Screen Frame	/	Y	
	Cellar Win Sill	/	Y	
	Cell Win Sash	/	Y	
	Cell Win Frame	/	Y	
	Screen Frame	/	Y	
	Drain Pipes	03	Y	
	Elec Conduit	/	Y	
	Oil Fill Pipe	/	Y	
	Overhang Trim	/	Y	
		.	Y	
		.	Y	

The Work Area was Visually Clean on \_\_\_/\_\_\_/\_\_\_ for Visual Reinspection. Start Date of RRP Work \_\_\_/\_\_\_/\_\_\_ and End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site: \_\_\_\_\_: Cert # \_\_\_\_\_

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area:



Michael Sullivan

I/R-4220

Page 88 Of 88

Inspector (print)

Lic #

Signature

08/25/21

Date

73

Address 42 MILK ST

Apt. #

City NEWBURYPORT

Location: 42 Milk St Porch Exterior A B C D Garage Outbuilding NEWBURYPORT

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Siding	✓	Y	
	Corner Boards	✓	Y	
	Lower Trim	✓	Y	
	Upper Trim	NA	(Y)	
	Foundation	01	Y	
	Storm Door	✓	Y	
	Door	00	Y	
D1	Door Casing	151	(Y)	
	Door Jamb	02	Y	
	Threshold	✓	Y	
	Kickplate	✓	Y	
	Window Sill	4.1	(Y)	
D2	Win Casing	12	(Y)	X4
	Window Sash	14	(Y)	
	Cellar Win Sill	15.1	(Y)	
D1	Cel Win Sash	16.6	(Y)	X9
	Cel Win Frame	02	(Y)	
	Screen Frame	36	(Y)	Metal
	Newel post	.	Y	
	Railing Cap	.	Y	
	Handrail	.	Y	
	Balusters	.	Y	
	Treads	.	Y	
	Risers	.	Y	
	Stringer	.	Y	
	Floor	.	Y	
	Bulkhead	.	Y	
	Fences	.	Y	
	Shutters	.	Y	
	Lattice	.	Y	
	Windows	16.1	(Y)	Metal
	Win 151	16.7	(Y)	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	
		.	Y	

SIDE	SURFACE	LEAD	DANGEROUS LEAD LEVEL	COMMENTS
	Storm Door	✓	Y	
	Door	00	Y	
	Door Casing	00	Y	
D2	Door Jamb	00	Y	
	Threshold	✓	Y	
	Kickplate	✓	Y	
	Storm Door	✓	Y	
	Door	00	Y	
D34	Door Casing	01	Y	
	Door Jamb	00	Y	
	Threshold	✓	Y	
	Kickplate	✓	Y	
	Window Sill	✓	Y	
	Win Casing	✓	Y	
	Window Sash	✓	Y	
	Window Sill	✓	Y	
	Win Casing	✓	Y	
	Window Sash	✓	Y	
	Window Sill	✓	Y	
	Win Casing	✓	Y	
	Window Sash	✓	Y	
	Cellar Win Sill	✓	Y	
	Cel Win Sash	✓	Y	
	Cel Win Frame	✓	Y	
	Screen Frame	✓	Y	
	Cellar Win Sill	✓	Y	
	Cel Win Sash	✓	Y	
	Cel Win Frame	✓	Y	
	Screen Frame	✓	Y	
	Drain Pipes	✓	Y	
	Elec Conduit	✓	Y	
	Oil Fill Pipe	✓	Y	
	Overhang Trim	16	(Y)	D2 Door
		.	Y	
		.	Y	

The Work Area was Visually Clean on \_\_\_/\_\_\_/\_\_\_ for Visual Reinspection. Start Date of RRP Work \_\_\_/\_\_\_/\_\_\_ and End Date \_\_\_/\_\_\_/\_\_\_

Name of Certified Lead Safe Renovator on Site: \_\_\_\_\_: Cert # \_\_\_\_\_

Brief Description of the Renovation, Repair, or Painting Work that Took Place in the Work Area:



# Laboratory Report



**Absolute Resource** *associates*

124 Heritage Avenue Portsmouth NH 03801

Moira Wentworth  
CREDERE Associates  
776 Main Street  
Westbrook, ME 04092

PO Number: None  
Job ID: 58406  
Date Received: 8/27/21

Project: Brown School 21001628

Attached please find results for the analysis of the samples received on the date referenced above.

Unless otherwise noted in the attached report, the analyses performed met the requirements of Absolute Resource Associates' Quality Assurance Plan. The Standard Operating Procedures are based upon USEPA SW-846, USEPA Methods for Chemical Analysis of Water and Wastewater, Standard Methods for the Examination of Water and Wastewater and other recognized methodologies. The results contained in this report pertain only to the samples as indicated on the chain of custody.

Absolute Resource Associates maintains certification with the agencies listed below. The reported results apply to the sample(s) in the condition as received at the time the laboratory took custody. This report shall not be reproduced except in full, without written approval of the laboratory. The liability of ARA is limited to the cost of the requested analyses, unless otherwise agreed upon in writing.

We appreciate the opportunity to provide laboratory services. If you have any questions regarding the enclosed report, please contact the laboratory and we will be glad to assist you.

Sincerely,  
Absolute Resource Associates

A handwritten signature in black ink, appearing to read 'A. DeWees'.

Aaron DeWees  
Chief Operating Officer

Date of Approval: 9/13/2021  
Total number of pages: 19

## Absolute Resource Associates Certifications

New Hampshire 1732  
Maine NH902

Massachusetts M-NH902



## Sample Association Table

Field ID	Matrix	Date-Time Sampled	Lab#	Analysis
CA-PCB-1	Solid	8/25/2021 13:55	58406-001	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-2	Solid	8/25/2021 14:00	58406-002	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-3	Solid	8/25/2021 13:45	58406-003	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-4	Solid	8/25/2021 8:25	58406-004	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-5	Solid	8/25/2021 8:30	58406-005	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-6	Solid	8/25/2021 8:35	58406-006	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-7	Solid	8/25/2021 9:00	58406-007	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-8	Solid	8/25/2021 11:40	58406-008	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-9	Solid	8/25/2021 11:50	58406-009	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-10	Solid	8/25/2021 12:00	58406-010	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-DUP1	Solid	8/25/2021 12:02	58406-011	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-11	Solid	8/25/2021 13:00	58406-012	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-DUP2	Solid	8/25/2021 13:02	58406-013	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-13	Solid	8/25/2021 14:15	58406-014	PCBs in solids by Soxhlet 8082 Report as received



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-001

**Sample ID:** CA-PCB-1

**Matrix:** Solid

**Sampled:** 8/25/21 13:55

Sampled: 8/25/21 13:55		Reporting		Instr Dil'n		Prep		Analysis		
Parameter	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	Reference
PCB-1016	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1221	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1232	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1242	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1248	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1254	3.4	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
PCB-1260	< 1.5	1.5	ug/g	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
Surrogate Recovery		Limits								
tetrachloro-m-xylene SUR	94	30-150	%	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A
decachlorobiphenyl SUR	106	30-150	%	1	DBV	8/31/21	14227	9/1/21	17:56	SW3540C8082A

**Note:** Elevated reporting limit due to the presence of non-target compounds.

**Sample#:** 58406-002

**Sample ID:** CA-PCB-2

**Matrix:** Solid

**Sampled:** 8/25/21 14:00

Sampled: 8/25/21 14:00		Reporting		Instr Dil'n		Prep		Analysis		
Parameter	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	Reference
PCB-1016	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1221	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1232	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1242	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1248	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1254	1.2	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
PCB-1260	< 0.82	0.82	ug/g	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
Surrogate Recovery		Limits								
tetrachloro-m-xylene SUR	91	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A
decachlorobiphenyl SUR	108	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:08	SW3540C8082A

**Note:** Elevated reporting limit due to the presence of non-target compounds.



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-003

**Sample ID:** CA-PCB-3

**Matrix:** Solid

**Sampled:** 8/25/21 13:45

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1221	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1232	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1242	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1248	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1254	<b>100</b>	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
PCB-1260	< 7.6	7.6	ug/g	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>DOR</b>	30-150	%	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A
decachlorobiphenyl SUR	<b>DOR</b>	30-150	%	50	ACA	8/31/21	14227	9/2/21	14:58	SW3540C8082A

**DOR = Diluted out of range.**

**Sample#:** 58406-004

**Sample ID:** CA-PCB-4

**Matrix:** Solid

**Sampled:** 8/25/21 8:25

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1221	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1232	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1242	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1248	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1254	<b>0.29</b>	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
PCB-1260	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>131</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A
decachlorobiphenyl SUR	<b>125</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:21	SW3540C8082A



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-005

**Sample ID:** CA-PCB-5

**Matrix:** Solid

**Sampled:** 8/25/21 8:30

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1221	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1232	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1242	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1248	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1254	<b>0.21</b>	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
PCB-1260	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>108</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A
decachlorobiphenyl SUR	<b>130</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:34	SW3540C8082A

**Sample#:** 58406-006

**Sample ID:** CA-PCB-6

**Matrix:** Solid

**Sampled:** 8/25/21 8:35

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1221	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1232	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1242	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1248	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1254	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
PCB-1260	< 0.16	0.16	ug/g	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>117</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A
decachlorobiphenyl SUR	<b>145</b>	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:46	SW3540C8082A



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-007

**Sample ID:** CA-PCB-7

**Matrix:** Solid

**Sampled:** 8/25/21 9:00

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1221	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1232	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1242	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1248	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1254	1.1	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
PCB-1260	< 0.15	0.15	ug/g	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	105	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A
decachlorobiphenyl SUR	115	30-150	%	1	DBV	8/31/21	14227	9/1/21	18:59	SW3540C8082A

**Sample#:** 58406-008

**Sample ID:** CA-PCB-8

**Matrix:** Solid

**Sampled:** 8/25/21 11:40

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1221	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1232	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1242	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1248	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1254	1.1	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
PCB-1260	< 0.13	0.13	ug/g	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	88	30-150	%	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A
decachlorobiphenyl SUR	106	30-150	%	1	DBV	8/31/21	14227	9/1/21	19:11	SW3540C8082A



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-009

**Sample ID:** CA-PCB-9

**Matrix:** Solid

**Sampled:** 8/25/21 11:50

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1221	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1232	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1242	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1248	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1254	<b>0.28</b>	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
PCB-1260	< 0.15	0.15	ug/g	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>87</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A
decachlorobiphenyl SUR	<b>93</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:10	SW3540C8082A

**Sample#:** 58406-010

**Sample ID:** CA-PCB-10

**Matrix:** Solid

**Sampled:** 8/25/21 12:00

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1221	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1232	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1242	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1248	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1254	<b>0.81</b>	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
PCB-1260	< 0.14	0.14	ug/g	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>63</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A
decachlorobiphenyl SUR	<b>65</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:23	SW3540C8082A



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-011

**Sample ID:** CA-PCB-DUP1

**Matrix:** Solid

**Sampled:** 8/25/21 12:02

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1221	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1232	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1242	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1248	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1254	<b>4.5</b>	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
PCB-1260	< 0.16	0.16	ug/g	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>85</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A
decachlorobiphenyl SUR	<b>91</b>	30-150	%	1	ACA	9/1/21	14238	9/2/21	15:35	SW3540C8082A

**Sample#:** 58406-012

**Sample ID:** CA-PCB-11

**Matrix:** Solid

**Sampled:** 8/25/21 13:00

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
PCB-1016	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1221	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1232	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1242	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1248	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1254	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
PCB-1260	< 1.3	1.3	ug/g	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
<b>Surrogate Recovery</b>	<b>Limits</b>									
tetrachloro-m-xylene SUR	<b>137</b>	30-150	%	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A
decachlorobiphenyl SUR	<b>139</b>	30-150	%	10	ACA	9/1/21	14238	9/2/21	17:04	SW3540C8082A

**Note:** Dilution was required due to sample matrix interference.



**Project ID:** Brown School 21001628

**Job ID:** 58406

**Sample#:** 58406-013

**Sample ID:** CA-PCB-DUP2

**Matrix:** Solid

**Sampled:** 8/25/21 13:02

Parameter	Reporting		Units	Instr Dil'n	Analyst	Prep Date	Analysis			Reference
	Result	Limit					Batch	Date	Time	
PCB-1016	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1221	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1232	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1242	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1248	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1254	<b>0.90</b>	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
PCB-1260	< 0.71	0.71	ug/g	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
<b>Surrogate Recovery</b>		<b>Limits</b>								
tetrachloro-m-xylene SUR	<b>115</b>	30-150	%	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A
decachlorobiphenyl SUR	<b>124</b>	30-150	%	5	ACA	9/1/21	14238	9/2/21	16:01	SW3540C8082A

**Note:** Dilution was required due to sample matrix interference.

**Sample#:** 58406-014

**Sample ID:** CA-PCB-13

**Matrix:** Solid

**Sampled:** 8/25/21 14:15

Parameter	Reporting		Units	Instr Dil'n	Analyst	Prep Date	Analysis			Reference
	Result	Limit					Batch	Date	Time	
PCB-1016	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1221	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1232	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1242	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1248	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1254	<b>18</b>	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
PCB-1260	< 2.8	2.8	ug/g	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
<b>Surrogate Recovery</b>		<b>Limits</b>								
tetrachloro-m-xylene SUR	<b>DOR</b>	30-150	%	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A
decachlorobiphenyl SUR	<b>DOR</b>	30-150	%	20	DBV	9/1/21	14238	9/10/21	9:53	SW3540C8082A

**DOR = Diluted out of range.**



# Quality Control Report



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



## MassDEP Analytical Protocol Certification Form

Laboratory Name: Absolute Resource Associates

Project #: 21001628

Project Location: Massachusetts

RTN:

**This Form provides certifications for the following data set: list Laboratory Sample ID Number(s): 58406**

Matrices: ☐ Groundwater/Surface Water ☐ Soil/Sediment ☐ Drinking Water ☐ Air ☒ Other:

**CAM Protocol** (check all that apply below):

8260 VOC CAM II A <input type="checkbox"/>	7470/7471 Hg CAM III B <input type="checkbox"/>	MassDEP VPH (GC/PID/FID) CAM IV A <input type="checkbox"/>	8082 PCB CAM V A <input checked="" type="checkbox"/>	9014 Total Cyanide/PAC CAM VI A <input type="checkbox"/>	6860 Perchlorate CAM VIII B <input type="checkbox"/>
8270 SVOC CAM II B <input type="checkbox"/>	7010 Metals CAM III C <input type="checkbox"/>	MassDEP VPH (GC/MS) CAM IV C <input type="checkbox"/>	8081 Pesticides CAM V B <input type="checkbox"/>	7196 Hex Cr CAM VI B <input type="checkbox"/>	MassDEP APH CAM IX A <input type="checkbox"/>
6010 Metals CAM III A <input type="checkbox"/>	6020 Metals CAM III D <input type="checkbox"/>	MassDEP EPH CAM IV B <input type="checkbox"/>	8151 Herbicides CAM V C <input type="checkbox"/>	8330 Explosives CAM VIII A <input type="checkbox"/>	TO-15 VOC CAM IX B <input type="checkbox"/>

**Affirmative Responses to Questions A through F are required for "Presumptive Certainty" status**

<b>A</b>	Were all samples received in a condition consistent with those described on the Chain-of-Custody, properly preserved (including temperature) in the field or laboratory, and prepared/analyzed within method holding times?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>B</b>	Were the analytical method(s) and all associated QC requirements specified in the selected CAM protocol(s) followed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>C</b>	Were all required corrective actions and analytical response actions specified in the selected CAM protocol(s) implemented for all identified performance standard non-conformances?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>D</b>	Does the laboratory report comply with all the reporting requirements specified in CAM VII A, "Quality Assurance and Quality Control Guidelines for the Acquisition and Reporting of Analytical Data"?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>E</b>	VPH, EPH, APH, and TO-15 only a. VPH, EPH, and APH Methods only: Was each method conducted without significant modification(s)? (Refer to the individual method(s) for a list of significant modifications). b. APH and TO-15 Methods only: Was the complete analyte list reported for each method?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>F</b>	Were all applicable CAM protocol QC and performance standard non-conformances identified and evaluated in a laboratory narrative (including all "No" responses to Questions A through E)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

**Responses to Questions G, H and I below are required for "Presumptive Certainty" status**


<b>G</b>	Were the reporting limits at or below all CAM reporting limits specified in the selected CAM protocol(s)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <sup>1</sup>
----------	---	--

**Data User Note:** Data that achieve "Presumptive Certainty" status may not necessarily meet the data usability and representativeness requirements described in 310 CMR 40. 1056 (2)(k) and WSC-07-350.

<b>H</b>	Were all QC performance standards specified in the CAM protocol(s) achieved?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>
<b>I</b>	Were results reported for the complete analyte list specified in the selected CAM protocol(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>

<sup>1</sup>All negative responses must be addressed in an attached laboratory narrative.

*I, the undersigned, attest under the pains and penalties of perjury that, based upon my personal inquiry of those responsible for obtaining the information, the material contained in this analytical report is, to the best of my knowledge and belief, is accurate and complete.*

Signature: 

Position: Chief Operating Officer

Printed Name: Aaron DeWees

Date: 9/13/21



## Sample Integrity Table

Parameter	Method	Matrix	Minimum Volume	Recommended Container(s)	Required Preservation	Holding Time
Volatile Organics	EPA 8260	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
Volatile Organics	EPA 8260	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	14 Days
Semivolatile Organics	EPA 8270	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Semivolatile Organics	EPA 8270	Solid	20g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Organochlorine Pesticides	EPA 8081	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Organochlorine Pesticides	EPA 8081	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
PCBs	EPA 8082	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
PCBs	EPA 8082	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
Herbicides (subcontracted)	EPA 8151	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Herbicides (subcontracted)	EPA 8151	Solid	30g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
MA DEP VPH	MADEP VPH	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP VPH	MADEP VPH	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	28 Days
MA DEP EPH	MADEP EPH	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP EPH	MADEP EPH	Solid	30g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Total Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	180 Days
Dissolved Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	Filter First 1:1 $\text{HNO}_3$ to pH <2	180 Days
Total Metals	EPA 6010	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	180 Days
Total Mercury (may be combined with Total Metals)	EPA 7470	Aqueous	100mL	125mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	28 Days
Total Mercury (may be combined with Total Metals)	EPA 7471	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	28 Days
Chromium, Hexavalent	EPA 7196	Aqueous	100mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ ( $\text{NH}_4$ ) $_2$ SO $_4$ buffer	28 Days
Chromium, Hexavalent (subcontract)	EPA 7196	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	30 Days
Cyanide, Total	EPA 9014	Aqueous	125mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ 1:1 NaOH to pH >8	14 Days
Cyanide, Total	EPA 9014	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days

Absolute Resource Associates  
124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)





**Case Narrative**

**Lab # 58406**

**Sample Receiving and Chain of Custody Discrepancies**

---

Samples were received in acceptable condition, between 0 and 6 degrees C, on ice, and in accordance with sample handling, preservation and integrity guidelines.

**Calibration**

---

PCB: Quantification is quadratic.

**Method Blank**

---

No exceptions noted.

**Surrogate Recoveries**

---

PCB: The surrogates were diluted out of the calibration range in the following samples: 58406-003 and -014.

**Laboratory Control Sample Results**

---

No exceptions noted.

**Matrix Spike/Matrix Spike Duplicate/Duplicate Results**

---

Not requested for this project.

**Other**

---

PCB: Sample dilution was required for 58406-012 and -013 due to matrix interferences.

**MassDEP Analytical Protocol Certification Form Questions A through I**

---

No explanation is needed for Questions A through I answered in the affirmative.

**Question G:** The CAM protocol reporting limits were not achieved for this project due to dilutions necessary for sample analysis. Box G is "No."



## **GLOSSARY**

%R	Percent Recovery
BLK	Blank (Method Blank, Preparation Blank)
CCB	Continuing Calibration Blank
CCV	Continuing Calibration Verification
CRM	Certified Reference Material (associated with solid Metals samples)
CRMD	Certified Reference Material Duplicate (associated with solid Metals samples)
Dil'n	Dilution
DL	Detection Limit
DUP	Duplicate
LCS	Laboratory Control Sample
LCSD	Laboratory Control Sample Duplicate
LOD	Limit of Detection
LOQ	Limit of Quantitation
MB	Methanol Blank (associated with solid VOC samples)
MLCS	Methanol Laboratory Control Sample (associated with solid VOC samples)
MLCSD	Methanol Laboratory Control Sample Duplicate (associated with solid VOC samples)
MS	Matrix Spike
MSD	Matrix Spike Duplicate
PB	Preparation Blank
QC	Quality Control
RL	Reporting Limit
RPD	Relative Percent Difference
SUR	Surrogate



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801

[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



- QC Report -

Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
SW3540C8082A	BLK14227	PCB-1016		<	0.17	ug/g				
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260		<	0.17	ug/g				
		tetrachloro-m-xylene SUR			67	%		30	150	
		decachlorobiphenyl SUR			80	%		30	150	
SW3540C8082A	LCS14227	PCB-1016			2.5	ug/g	3.33	76	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			2.5	ug/g	3.33	76	40	140
		tetrachloro-m-xylene SUR			70	%		30	150	
		decachlorobiphenyl SUR			83	%		30	150	
SW3540C8082A	LCSD14227	PCB-1016			2.8	ug/g	3.33	85	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			3.0	ug/g	3.33	89	40	140
		tetrachloro-m-xylene SUR			69	%		30	150	
		decachlorobiphenyl SUR			96	%		30	150	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
SW3540C8082A	BLK14238	PCB-1016		<	0.17	ug/g				
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260		<	0.17	ug/g				
		tetrachloro-m-xylene SUR			78	%		30	150	
		decachlorobiphenyl SUR			105	%		30	150	
SW3540C8082A	LCS14238	PCB-1016			3.5	ug/g	3.33	104	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			3.4	ug/g	3.33	102	40	140
		tetrachloro-m-xylene SUR			85	%		30	150	
		decachlorobiphenyl SUR			107	%		30	150	
SW3540C8082A	LCSD14238	PCB-1016			3.5	ug/g	3.33	106	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			3.3	ug/g	3.33	98	40	140
		tetrachloro-m-xylene SUR			83	%		30	150	
		decachlorobiphenyl SUR			103	%		30	150	





**Absolute Resource**  
associates

124 Heritage Avenue #16  
Portsmouth, NH 03801  
603-436-2001

absoluteresourceassociates.com

Company Name: Credere Associates

Company Address: 776 Main Street, Westbrooke

Report To: Maura Wentworth

Phone #: 207-828-1272 x36

Invoice to: jenn@crederealk.com

Email: jenn@crederealk.com

PO #:

Project Name: Brown School

Project #: 21001628

Project Location: NH MA ME VT

Accreditation Required? NY:

Protocol: RCRA SDWA NPDES

Reporting QAPP GW-1 S-1

Limits: EPA DW Other

Quote #

☐ NH Reimbursement Pricing

☐ VOC 8260 ☐ VOC 8260 NHDES ☐ VOC 8260 MADEP

☐ VOC 624.1 ☐ VOC BTEX MBE, only ☐ VOC 8021VT

☐ VPH MADEP ☐ GRO 8015 ☐ 1,4-Dioxane

☐ VOC 524.2 ☐ VOC 524.2 NH List ☐ Gases-List:

☐ TPH ☐ DRD 8015 ☐ EPH MADEP ☐ TPH Fingerprint

☐ 8270PAH ☐ 8270ABN ☐ 825.1 ☐ EDB

☐ 8082 PCB ☐ 8081 Pesticides ☐ 608.3 Pest/PCB

☐ PFAS 537.1

☐ O&G 1664 ☐ Mineral O&G 1664

☐ pH ☐ BOD ☐ Conductivity ☐ Turbidity ☐ Apparent Color

☐ TSS ☐ TDS ☐ TS ☐ TVS ☐ Alkalinity ☐ Acidity

☐ RCRA Metals ☐ Priority Pollutant Metals ☐ TAL Metals ☐ Hardness

☐ Total Metals-list:

☐ Dissolved Metals-list:

☐ Ammonia ☐ COD ☐ TKN ☐ TN ☐ TOC ☐ Ferrous Iron

☐ T-Phosphorus ☐ Bacteria P/A ☐ Bacteria MPN ☐ Enterococci

☐ Cyanide ☐ Sulfide ☐ Nitrate + Nitrite ☐ Ortho P ☐ Phenols

☐ Nitrate ☐ Nitrite ☐ Chloride ☐ Sulfate ☐ Bromide ☐ Fluoride

☐ Corrosivity ☐ Ignitability/FP

☐ TCLP Metals ☐ TCLP VOC ☐ TCLP SVOC ☐ TCLP Pesticide

☐ Subcontract: ☐ Grain Size ☐ Herbicides ☐ Asbestos

☐ Grab (S) or Composite (C)

SPECIAL INSTRUCTIONS PCB by 8082A Soxhlet Extraction

TAT REQUESTED ☐ Priority (24 hr)\* ☐ Expedited (48 hr)\* ☐ Standard (10 Business Days) \*Date Needed

See absoluteresourceassociates.com for sample acceptance policy and current accreditation lists.

REPORTING INSTRUCTIONS ☒ PDF (e-mail address) Wentworth@crederealk.com

☐ HARD COPY REQUIRED ☐ EDD

Relinquished by Sampler: Jenn

Relinquished by: Maura

Relinquished by: Jenn

RECEIVED ON ICE ☒ YES ☐ NO

TEMPERATURE 2 °C

Date 8/27 Time 12:55

Date 8/27 Time 14:10

Date 8/27 Time 14:10

Date 8/27 Time 14:10

Date 8/27 Time 14:10

Received by: Jenn

Received by: Maura

Received by: Jenn

Received by: Jenn

Received by: Jenn

CUSTODY RECORD

QSD-01 Revision 03/09/2020





124 Heritage Avenue #16  
Portsmouth, NH 03801  
603-436-2001

absoluteresourceassociates.com

Company Name: Credence Associates  
Company Address: 776 Main Street, Westbrook, ME  
Report To: Norco Wentworth  
Phone #: 207-828-1272 x30  
Invoice to: jean@credence.com  
Email: jean@credence.com  
PO #: \_\_\_\_\_

Project Name: Brown School  
Project #: 21001628  
Project Location: NH MAINE VT  
Accreditation Required? NY:  
Protocol: RCRA SDWA NPDES  
MCP NHDES DOD  
Reporting QAPP GW-1 S-1  
Limits: BPA-BW Other  
Quote # \_\_\_\_\_  
☐ NH Reimbursement Pricing

CHAIN-OF-CUSTODY RECORD  
AND ANALYSIS REQUEST

58406

ANALYSIS REQUEST

<input type="checkbox"/> VOC 8260	<input type="checkbox"/> VOC 8260 NHDES	<input type="checkbox"/> VOC 8260 MADEP	<input type="checkbox"/> VOC 624.1	<input type="checkbox"/> VOC BTEX MBE, only	<input type="checkbox"/> VOC 8021VT	<input type="checkbox"/> VPH MADEP	<input type="checkbox"/> GR0 8015	<input type="checkbox"/> 1,4-Dioxane	<input type="checkbox"/> VOC 524.2	<input type="checkbox"/> VOC 524.2 NH List	<input type="checkbox"/> Gases-List:	<input type="checkbox"/> TPH	<input type="checkbox"/> DR0 8015	<input type="checkbox"/> EPH MADEP	<input type="checkbox"/> TPH Fingerprint	<input type="checkbox"/> 8270PAH	<input type="checkbox"/> 8270ABN	<input type="checkbox"/> 825.1	<input type="checkbox"/> EDB	<input checked="" type="checkbox"/> 8082 PCB	<input type="checkbox"/> 8081 Pesticides	<input type="checkbox"/> 608.3 Pest/PCB	<input type="checkbox"/> PFAS 537.1	<input type="checkbox"/> O&G 1664	<input type="checkbox"/> Mineral O&G 1664	<input type="checkbox"/> pH	<input type="checkbox"/> BOD	<input type="checkbox"/> Conductivity	<input type="checkbox"/> Turbidity	<input type="checkbox"/> Apparent Color	<input type="checkbox"/> TSS	<input type="checkbox"/> TDS	<input type="checkbox"/> TS	<input type="checkbox"/> TVS	<input type="checkbox"/> Alkalinity	<input type="checkbox"/> Acidity	<input type="checkbox"/> RCRA Metals	<input type="checkbox"/> Priority Pollutant Metals	<input type="checkbox"/> TAL Metals	<input type="checkbox"/> Hardness	<input type="checkbox"/> Total Metals-list:	<input type="checkbox"/> Dissolved Metals-list:	<input type="checkbox"/> Ammonia	<input type="checkbox"/> COD	<input type="checkbox"/> TKN	<input type="checkbox"/> TN	<input type="checkbox"/> TON	<input type="checkbox"/> TOC	<input type="checkbox"/> Ferrous Iron	<input type="checkbox"/> T-Phosphorus	<input type="checkbox"/> Bacteria P/A	<input type="checkbox"/> Bacteria MPN	<input type="checkbox"/> Enterococci	<input type="checkbox"/> Cyanide	<input type="checkbox"/> Sulfide	<input type="checkbox"/> Nitrate + Nitrite	<input type="checkbox"/> Ortho P	<input type="checkbox"/> Phenols	<input type="checkbox"/> Nitrate	<input type="checkbox"/> Nitrite	<input type="checkbox"/> Chloride	<input type="checkbox"/> Sulfate	<input type="checkbox"/> Bromide	<input type="checkbox"/> Fluoride	<input type="checkbox"/> Corrosivity	<input type="checkbox"/> Ignitibility/FP	<input type="checkbox"/> TCLP Metals	<input type="checkbox"/> TCLP VOC	<input type="checkbox"/> TCLP SVOC	<input type="checkbox"/> TCLP Pesticide	<input type="checkbox"/> Subcontract	<input type="checkbox"/> Grain Size	<input type="checkbox"/> Herbicides	<input type="checkbox"/> Asbestos	<input type="checkbox"/> Grab (G) or Composite (C)
-----------------------------------	---	---	------------------------------------	---	-------------------------------------	------------------------------------	-----------------------------------	--------------------------------------	------------------------------------	--	--------------------------------------	------------------------------	-----------------------------------	------------------------------------	--	----------------------------------	----------------------------------	--------------------------------	------------------------------	--	--	---	-------------------------------------	-----------------------------------	---	-----------------------------	------------------------------	---------------------------------------	------------------------------------	---	------------------------------	------------------------------	-----------------------------	------------------------------	-------------------------------------	----------------------------------	--------------------------------------	--	-------------------------------------	-----------------------------------	---	---	----------------------------------	------------------------------	------------------------------	-----------------------------	------------------------------	------------------------------	---------------------------------------	---------------------------------------	---------------------------------------	---------------------------------------	--------------------------------------	----------------------------------	----------------------------------	--	----------------------------------	----------------------------------	----------------------------------	----------------------------------	-----------------------------------	----------------------------------	----------------------------------	-----------------------------------	--------------------------------------	--	--------------------------------------	-----------------------------------	------------------------------------	---	--------------------------------------	-------------------------------------	-------------------------------------	-----------------------------------	--

SPECIAL INSTRUCTIONS PCB by 8082A Soxhlet extraction

TAT REQUESTED  
☐ Priority (24 hr\*)  
☐ Expedited (48 hr\*)  
☐ Standard  
(10 Business Days)  
\*Date Needed \_\_\_\_\_

See absoluteresourceassociates.com  
for sample acceptance policy and  
current accreditation lists.

REPORTING INSTRUCTIONS SPDF (e-mail address) mwentworth@credence.com  
☐ HARD COPY REQUIRED ☐ EDD

RECEIVED ON ICE ☐ YES ☐ NO  
TEMPERATURE 2 °C

CUSTODY RECORD QSD-01 Revision 03/09/2020	Relinquished by Sampler: <u>[Signature]</u>	Date: <u>8/27/21</u> Time: <u>12:55</u>	Received by: <u>[Signature]</u>	Date: <u>8-27</u> Time: <u>12:55</u>
	Relinquished by: <u>[Signature]</u>	Date: <u>8/27</u> Time: <u>14:10</u>	Received by: <u>[Signature]</u>	Date: _____ Time: _____
	Relinquished by: <u>[Signature]</u>	Date: _____ Time: _____	Received by Laboratory: <u>[Signature]</u>	Date: <u>8/27/21</u> Time: <u>14:10</u>



## Sample Receipt Condition Report

58406

## Absolute Resource Associates

Job Number:

Samples Received from: ☐-UPS ☐-FedEx ☐-USPS ☒-Lab Courier ☐-Client Drop-off ☐-  
 Custody Seals - present & intact: ☐-Yes ☐-No ☒-N/A CoC signed: ☒-Yes ☐-No  
 Receipt Temp: 2 °C Samples on ice? ☒-Yes ☐-No ☐-N/A Sampled < 24 hrs ago? ☐-Yes ☒-No  
 PFAS-only real ice? ☐-Yes ☐-No ☒-N/A Any signs of freezing? ☐-Yes ☒-No

Comments:

Preservation / Analysis	Bottle Size/Type & Quantity						Check pH for ALL applicable* samples and document:
HCl	40mL(G)	250mL(P)	500mL(P)	1L(G)			
HNO <sub>3</sub>	125mL(P)	250mL(P)	500mL(P)				
H <sub>2</sub> SO <sub>4</sub>	40mL(G)	60mL(P)	125mL(P)	250mL(P)	500mL(P)		
NaOH	125mL(P)	250mL(P)					
(NH <sub>4</sub> ) <sub>2</sub> SO <sub>4</sub>	60mL(P)	125mL(P)	250mL(P)				
ZnAc-NaOH	125mL(P)	250mL(P)					
Trizma	125mL(P)	250mL(P)					
NH <sub>4</sub> Ac	125mL(P)	250mL(P)					
Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	40mL(G)	120mL(P)					
MeOH	20mL(G)	40mL(G)					
None (solid)	2oz(G)	4oz(G)	14 8oz(G)	Syringe			
None (water)	40ml (G)	60mL(P)	125mL(P)	250mL(P)	500mL(P)	1L(G)	1L (P)
Mold	Cassette	Bulk	Plate	Tape Lift			
Asbestos	Cassette	Bulk					
Lead	Cassette	Bulk	Wipe				

\*pH ✓by analyst: VOC, PFAS, TOC, O&G  
 Residual Cl not present:  
 ABN625 Pest608  
 Bacteria ResCl ✓by analyst  
 PC Dry applicable? Y N

Login Review	Yes	No	NA	Comments
Proper lab sample containers/enough volume/correct preservative?	✓			
Analyses marked on COC match bottles received?	✓			
VOC & TOC Water-no headspace?			✓	
VOC Solid-MeOH covers solid, no leaks, Prep Expiration OK?			✓	
PFAS: ARA bottles & samples/FRB same Lot#? QC rec'd, if req'd?			✓	Lot ID#: _____
Bacteria bottles provided by ARA?			✓	
Samples within holding time?	✓			
Immediate tests communicated in writing: NO <sub>3</sub> , NO <sub>2</sub> , PO <sub>4</sub> , pH, BOD, Coliform/E. coli (P/A or MPN), Enterococci, Color Surfactants, Turbidity, Odor, CrVI, Ferrous Iron, Dissolved Oxygen, Unpres 624			✓	
Date, time & ID on samples match CoC?	✓			
Rushes communicated to analyst in writing?			✓	
Subcontract note on login board?			✓	
Pesticides EPA 608 pH5-9?			✓	
Compliance samples have no discrepancies/require no flags?			✓	(Or must be rejected)
Log-in Supervisor notified immediately of following items:			✓	Discrepancies, compliance samples (NHDES, MADEP, DoD etc.) or uncommon requests.

Inspected and Received By: ADDate/Time: 8/27/21 15:04

## Peer Review Checklist

☐ Client ID/Project Manager    ☐ On Ice, Temperature OK?    ☐ Sample IDs    ☐ Analyses in Correctly  
☐ Project Name    ☐ PO# (if provided)    ☐ Matrix    ☐ -references  
☐ TAT/rushes communicated    ☐ Sub samples sent? Shipping Charge?    ☐ Date/Time collected    ☐ -wastewater methods  
☐ Received Date/Time    ☐ Issues noted above communicated?    ☐ Short HTs communicated    ☐ Notes from CoC in LIMS

Reviewed By: \_\_\_\_\_

Date: \_\_\_\_\_

Notes: (continue on back as needed)

Initials    Date    What was sent?  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice



# Laboratory Report



**Absolute Resource** *associates*

124 Heritage Avenue Portsmouth NH 03801

Moira Wentworth  
CREDERE Associates  
776 Main Street  
Westbrook, ME 04092

PO Number: None  
Job ID: 58452  
Date Received: 9/1/21

Project: Brown School 21001628

Attached please find results for the analysis of the samples received on the date referenced above.

Unless otherwise noted in the attached report, the analyses performed met the requirements of Absolute Resource Associates' Quality Assurance Plan. The Standard Operating Procedures are based upon USEPA SW-846, USEPA Methods for Chemical Analysis of Water and Wastewater, Standard Methods for the Examination of Water and Wastewater and other recognized methodologies. The results contained in this report pertain only to the samples as indicated on the chain of custody.

Absolute Resource Associates maintains certification with the agencies listed below. The reported results apply to the sample(s) in the condition as received at the time the laboratory took custody. This report shall not be reproduced except in full, without written approval of the laboratory. The liability of ARA is limited to the cost of the requested analyses, unless otherwise agreed upon in writing.

We appreciate the opportunity to provide laboratory services. If you have any questions regarding the enclosed report, please contact the laboratory and we will be glad to assist you.

Sincerely,  
Absolute Resource Associates

A handwritten signature in black ink, appearing to read 'Willie Stone', with a stylized flourish at the end.

Willie Stone  
Authorized Signature

Date of Approval: 9/13/2021  
Total number of pages: 25

## Absolute Resource Associates Certifications

New Hampshire 1732  
Maine NH902

Massachusetts M-NH902



## Sample Association Table

Field ID	Matrix	Date-Time Sampled	Lab#	Analysis
CA-SB-1	Solid	8/31/2021 10:05	58452-001	EPH in solids by MADEP Method VPH in solids by MA DEP Method
CA-SB-2	Solid	8/31/2021 10:55	58452-002	EPH in solids by MADEP Method VPH in solids by MA DEP Method
CA-SB-3	Solid	8/31/2021 12:00	58452-003	EPH in solids by MADEP Method VPH in solids by MA DEP Method
CA-SB-4	Solid	8/31/2021 13:00	58452-004	EPH in solids by MADEP Method VPH in solids by MA DEP Method
CA-PCB-12	Solid	8/31/2021 11:00	58452-005	PCBs in solids by Soxhlet 8082 Report as received
CA-PCB-14	Solid	8/31/2021 10:05	58452-006	PCBs in solids by Soxhlet 8082 Report as received
Trip Blank	Solid	8/31/2021 0:00	58452-007	VPH in solids by MA DEP Method



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-001

**Sample ID:** CA-SB-1

**Matrix:** Solid      Percent Dry: 93.2% Results expressed on a dry weight basis.

Samples prepared in methanol within a 1:1 ratio +/- 25% mL MeOH/g soil

Received on ice at 0°C, in satisfactory condition.

**Sampled:** 8/31/21 10:05

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 5.1	5.1	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
Unadjusted C9-C12 Aliphatics	< 5.1	5.1	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
methy1 t-butyl ether (MTBE)	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
benzene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
toluene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
ethylbenzene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
m&p-xylenes	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
o-xylene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
naphthalene	< 0.26	0.26	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
C5-C8 Aliphatics	< 5.1	5.1	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
C9-C12 Aliphatics	< 5.1	5.1	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
C9-C10 Aromatics	< 5.1	5.1	ug/g	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
2,5-dibromotoluene as Aromatic SUR	<b>96</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>99</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH
a,a,a-trifluorotoluene SUR	<b>92</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:09	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-002

**Sample ID:** CA-SB-2

**Matrix:** Solid      Percent Dry: 95.8% Results expressed on a dry weight basis.

Samples prepared in methanol within a 1:1 ratio +/- 25% mL MeOH/g soil

Received on ice at 0°C, in satisfactory condition.

**Sampled:** 8/31/21 10:55

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 4.2	4.2	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
Unadjusted C9-C12 Aliphatics	< 4.2	4.2	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
methyl t-butyl ether (MTBE)	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
benzene	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
toluene	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
ethylbenzene	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
m&p-xylenes	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
o-xylene	< 0.084	0.084	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
naphthalene	< 0.21	0.21	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
C5-C8 Aliphatics	< 4.2	4.2	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
C9-C12 Aliphatics	< 4.2	4.2	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
C9-C10 Aromatics	< 4.2	4.2	ug/g	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
2,5-dibromotoluene as Aromatic SUR	<b>101</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>106</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH
a,a,a-trifluorotoluene SUR	<b>91</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	17:42	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-003

**Sample ID:** CA-SB-3

**Matrix:** Solid      Percent Dry: 89.8% Results expressed on a dry weight basis.

Samples prepared in methanol within a 1:1 ratio +/- 25% mL MeOH/g soil

Received on ice at 0°C, in satisfactory condition.

**Sampled:** 8/31/21 12:00

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 4.7	4.7	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
Unadjusted C9-C12 Aliphatics	< 4.7	4.7	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
methyl t-butyl ether (MTBE)	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
benzene	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
toluene	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
ethylbenzene	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
m&p-xylenes	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
o-xylene	< 0.094	0.094	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
naphthalene	< 0.24	0.24	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
C5-C8 Aliphatics	< 4.7	4.7	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
C9-C12 Aliphatics	< 4.7	4.7	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
C9-C10 Aromatics	< 4.7	4.7	ug/g	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
2,5-dibromotoluene as Aromatic SUR	<b>96</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>99</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH
a,a,a-trifluorotoluene SUR	<b>94</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:15	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-004

**Sample ID:** CA-SB-4

**Matrix:** Solid      Percent Dry: 96.5% Results expressed on a dry weight basis.

Samples prepared in methanol at a ratio of 0.74 mL MeOH/g soil.

Received on ice at 0°C, in satisfactory condition.

**Sampled:** 8/31/21 13:00

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 4.0	4.0	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
Unadjusted C9-C12 Aliphatics	< 4.0	4.0	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
methyl t-butyl ether (MTBE)	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
benzene	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
toluene	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
ethylbenzene	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
m&p-xylenes	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
o-xylene	< 0.080	0.080	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
naphthalene	< 0.20	0.20	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
C5-C8 Aliphatics	< 4.0	4.0	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
C9-C12 Aliphatics	< 4.0	4.0	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
C9-C10 Aromatics	< 4.0	4.0	ug/g	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
2,5-dibromotoluene as Aromatic SUR	<b>98</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>101</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH
a,a,a-trifluorotoluene SUR	<b>90</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	18:48	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-007

**Sample ID:** Trip Blank

**Matrix:** Solid

Samples prepared in methanol within a 1:1 ratio +/- 25% mL MeOH/g soil

Received on ice at 0°C, in satisfactory condition.

**Sampled:** 8/31/21 0:00

Parameter	Reporting		Instr Dil'n		Prep		Analysis			Reference
	Result	Limit	Units	Factor	Analyst	Date	Batch	Date	Time	
Unadjusted C5-C8 Aliphatics	< 5.0	5.0	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
Unadjusted C9-C12 Aliphatics	< 5.0	5.0	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
methyl t-butyl ether (MTBE)	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
benzene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
toluene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
ethylbenzene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
m&p-xylenes	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
o-xylene	< 0.10	0.10	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
naphthalene	< 0.25	0.25	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
C5-C8 Aliphatics	< 5.0	5.0	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
C9-C12 Aliphatics	< 5.0	5.0	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
C9-C10 Aromatics	< 5.0	5.0	ug/g	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
2,5-dibromotoluene as Aromatic SUR	<b>97</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
2,5-dibromotoluene as Aliphatic SUR	<b>99</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH
a,a,a-trifluorotoluene SUR	<b>87</b>	70-130	%	1	LMM	9/8/21	14244	9/8/21	16:02	MA VPH

Hydrocarbon Range data exclude concentrations of any surrogate(s) and/or internal standards eluting in that range.

C5-C8 Aliphatic Hydrocarbons exclude the concentration of target analytes eluting in that range.

C9-C12 Aliphatic Hydrocarbons exclude concentration of target analytes eluting in that range AND C9-C10 Aromatics.



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-005

**Sample ID:** CA-PCB-12

**Matrix:** Solid

**Sampled:** 8/31/21 11:00

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
PCB-1016	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1221	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1232	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1242	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1248	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1254	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
PCB-1260	< 1.4	1.4	ug/g	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
<b>Surrogate Recovery</b>		<b>Limits</b>								
tetrachloro-m-xylene SUR	<b>158*</b>	30-150	%	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A
decachlorobiphenyl SUR	<b>148</b>	30-150	%	10	DBV	9/2/21	14238	9/7/21	12:22	SW3540C8082A

**Note:** Dilution was required due to sample matrix interference.

**\* This surrogate showed recovery above the acceptance limits. Since no targets were detected above the quantitation limit, there is no impact to the data.**

**Sample#:** 58452-006

**Sample ID:** CA-PCB-14

**Matrix:** Solid

**Sampled:** 8/31/21 10:05

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
PCB-1016	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1221	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1232	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1242	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1248	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1254	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
PCB-1260	< 0.16	0.16	ug/g	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
<b>Surrogate Recovery</b>		<b>Limits</b>								
tetrachloro-m-xylene SUR	<b>61</b>	30-150	%	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A
decachlorobiphenyl SUR	<b>71</b>	30-150	%	1	DBV	9/2/21	14238	9/7/21	11:32	SW3540C8082A



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-001

**Sample ID:** CA-SB-1

**Matrix:** Solid

Percent Dry: 93.2% Results expressed on a dry weight basis.

**Sampled:** 8/31/21 10:05

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
naphthalene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
2-methylnaphthalene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
phenanthrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
acenaphthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
acenaphthylene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
fluorene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
benzo(a)anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
chrysene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
benzo(b)fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
benzo(k)fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
benzo(a)pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
indeno(1,2,3-cd)pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
dibenzo(a,h)anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
benzo(g,h,i)perylene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	11:21	MA EPH
Unadjusted C11-C22 Aromatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
C9-C18 Aliphatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
C19-C36 Aliphatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
C11-C22 Aromatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
1-chloro-octadecane SUR	<b>73</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
o-terphenyl SUR	<b>78</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
2-fluorobiphenyl SUR	<b>75</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH
2-bromonaphthalene SUR	<b>43</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	13:45	MA EPH



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-002

**Sample ID:** CA-SB-2

**Matrix:** Solid

Percent Dry: 95.8% Results expressed on a dry weight basis.

**Sampled:** 8/31/21 10:55

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
naphthalene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
2-methylnaphthalene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
phenanthrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
acenaphthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
acenaphthylene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
fluorene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
benzo(a)anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
chrysene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
benzo(b)fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
benzo(k)fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
benzo(a)pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
indeno(1,2,3-cd)pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
dibenzo(a,h)anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
benzo(g,h,i)perylene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	11:51	MA EPH
Unadjusted C11-C22 Aromatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
C9-C18 Aliphatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
C19-C36 Aliphatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
C11-C22 Aromatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
1-chloro-octadecane SUR	<b>63</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
o-terphenyl SUR	<b>61</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
2-fluorobiphenyl SUR	<b>69</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH
2-bromonaphthalene SUR	<b>66</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:19	MA EPH



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-003

**Sample ID:** CA-SB-3

**Matrix:** Solid

Percent Dry: 89.8% Results expressed on a dry weight basis.

**Sampled:** 8/31/21 12:00

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
naphthalene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
2-methylnaphthalene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
phenanthrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
acenaphthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
acenaphthylene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
fluorene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
benzo(a)anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
chrysene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
benzo(b)fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
benzo(k)fluoranthene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
benzo(a)pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
indeno(1,2,3-cd)pyrene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
dibenzo(a,h)anthracene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
benzo(g,h,i)perylene	< 0.21	0.21	ug/g	1	CL	9/3/21	14245	9/8/21	12:20	MA EPH
Unadjusted C11-C22 Aromatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
C9-C18 Aliphatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
C19-C36 Aliphatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
C11-C22 Aromatics	< 21	21	ug/g	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
1-chloro-octadecane SUR	<b>72</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
o-terphenyl SUR	<b>73</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
2-fluorobiphenyl SUR	<b>68</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH
2-bromonaphthalene SUR	<b>61</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	14:53	MA EPH



**Project ID:** Brown School 2100-1628

**Job ID:** 58452

**Sample#:** 58452-004

**Sample ID:** CA-SB-4

**Matrix:** Solid

Percent Dry: 96.5% Results expressed on a dry weight basis.

**Sampled:** 8/31/21 13:00

Parameter	Reporting		Units	Instr Dil'n	Prep		Analysis			Reference
	Result	Limit			Analyst	Date	Batch	Date	Time	
naphthalene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
2-methylnaphthalene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
phenanthrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
acenaphthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
acenaphthylene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
fluorene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
benzo(a)anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
chrysene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
benzo(b)fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
benzo(k)fluoranthene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
benzo(a)pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
indeno(1,2,3-cd)pyrene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
dibenzo(a,h)anthracene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
benzo(g,h,i)perylene	< 0.20	0.20	ug/g	1	CL	9/3/21	14245	9/8/21	12:50	MA EPH
Unadjusted C11-C22 Aromatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
C9-C18 Aliphatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
C19-C36 Aliphatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
C11-C22 Aromatics	< 20	20	ug/g	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
<b>Surrogate Recovery</b>	<b>Limits</b>									
1-chloro-octadecane SUR	<b>59</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
o-terphenyl SUR	<b>62</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
2-fluorobiphenyl SUR	<b>74</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH
2-bromonaphthalene SUR	<b>73</b>	40-140	%	1	DBV	9/3/21	14245	9/8/21	15:27	MA EPH



# Quality Control Report



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



## MassDEP Analytical Protocol Certification Form

Laboratory Name: Absolute Resource Associates

Project #: 21001628

Project Location: Massachusetts

RTN:

**This Form provides certifications for the following data set: list Laboratory Sample ID Number(s): 58452**

Matrices: ☐ Groundwater/Surface Water ☒ Soil/Sediment ☐ Drinking Water ☐ Air ☐ Other:

**CAM Protocol** (check all that apply below):

8260 VOC CAM II A <input type="checkbox"/>	7470/7471 Hg CAM III B <input type="checkbox"/>	MassDEP VPH (GC/PID/FID) CAM IV A <input checked="" type="checkbox"/>	8082 PCB CAM V A <input checked="" type="checkbox"/>	9014 Total Cyanide/PAC CAM VI A <input type="checkbox"/>	6860 Perchlorate CAM VIII B <input type="checkbox"/>
8270 SVOC CAM II B <input type="checkbox"/>	7010 Metals CAM III C <input type="checkbox"/>	MassDEP VPH (GC/MS) CAM IV C <input type="checkbox"/>	8081 Pesticides CAM V B <input type="checkbox"/>	7196 Hex Cr CAM VI B <input type="checkbox"/>	MassDEP APH CAM IX A <input type="checkbox"/>
6010 Metals CAM III A <input type="checkbox"/>	6020 Metals CAM III D <input type="checkbox"/>	MassDEP EPH CAM IV B <input checked="" type="checkbox"/>	8151 Herbicides CAM V C <input type="checkbox"/>	8330 Explosives CAM VIII A <input type="checkbox"/>	TO-15 VOC CAM IX B <input type="checkbox"/>

**Affirmative Responses to Questions A through F are required for "Presumptive Certainty" status**

<b>A</b>	Were all samples received in a condition consistent with those described on the Chain-of-Custody, properly preserved (including temperature) in the field or laboratory, and prepared/analyzed within method holding times?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>B</b>	Were the analytical method(s) and all associated QC requirements specified in the selected CAM protocol(s) followed?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>C</b>	Were all required corrective actions and analytical response actions specified in the selected CAM protocol(s) implemented for all identified performance standard non-conformances?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>D</b>	Does the laboratory report comply with all the reporting requirements specified in CAM VII A, "Quality Assurance and Quality Control Guidelines for the Acquisition and Reporting of Analytical Data"?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>E</b>	VPH, EPH, APH, and TO-15 only a. VPH, EPH, and APH Methods only: Was each method conducted without significant modification(s)? (Refer to the individual method(s) for a list of significant modifications). b. APH and TO-15 Methods only: Was the complete analyte list reported for each method?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>F</b>	Were all applicable CAM protocol QC and performance standard non-conformances identified and evaluated in a laboratory narrative (including all "No" responses to Questions A through E)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

**Responses to Questions G, H and I below are required for "Presumptive Certainty" status**


<b>G</b>	Were the reporting limits at or below all CAM reporting limits specified in the selected CAM protocol(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>
----------	---	--

**Data User Note:** Data that achieve "Presumptive Certainty" status may not necessarily meet the data usability and representativeness requirements described in 310 CMR 40. 1056 (2)(k) and WSC-07-350.

<b>H</b>	Were all QC performance standards specified in the CAM protocol(s) achieved?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>
<b>I</b>	Were results reported for the complete analyte list specified in the selected CAM protocol(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>1</sup>

<sup>1</sup>All negative responses must be addressed in an attached laboratory narrative.

*I, the undersigned, attest under the pains and penalties of perjury that, based upon my personal inquiry of those responsible for obtaining the information, the material contained in this analytical report is, to the best of my knowledge and belief, is accurate and complete.*

Signature: 

Position: Chief Operating Officer

Printed Name: Aaron DeWees

Date: 9/13/21



## Sample Integrity Table

Parameter	Method	Matrix	Minimum Volume	Recommended Container(s)	Required Preservation	Holding Time
Volatile Organics	EPA 8260	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
Volatile Organics	EPA 8260	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	14 Days
Semivolatile Organics	EPA 8270	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Semivolatile Organics	EPA 8270	Solid	20g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Organochlorine Pesticides	EPA 8081	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Organochlorine Pesticides	EPA 8081	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
PCBs	EPA 8082	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
PCBs	EPA 8082	Solid	20g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	365 Days
Herbicides (subcontracted)	EPA 8151	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	7 Days
Herbicides (subcontracted)	EPA 8151	Solid	30g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
MA DEP VPH	MADEP VPH	Aqueous	40mL	2 x 40mL VOA Vials with Teflon lined septa	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP VPH	MADEP VPH	Solid	40mL	1 x 40mL VOA Vial with 10mLs Methanol <u>and</u> 1 unpreserved container for percent moisture	Cool to $\leq 6^{\circ}\text{C}$ Methanol	28 Days
MA DEP EPH	MADEP EPH	Aqueous	1L	1L Amber Glass Bottle w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$ 1:1 HCl to pH <2	14 Days
MA DEP EPH	MADEP EPH	Solid	30g	4oz Amber Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days
Total Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	180 Days
Dissolved Metals	EPA 6010	Aqueous	100mL	250mL Polyethylene Bottle	Filter First 1:1 $\text{HNO}_3$ to pH <2	180 Days
Total Metals	EPA 6010	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	180 Days
Total Mercury (may be combined with Total Metals)	EPA 7470	Aqueous	100mL	125mL Polyethylene Bottle	1:1 $\text{HNO}_3$ to pH <2	28 Days
Total Mercury (may be combined with Total Metals)	EPA 7471	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	28 Days
Chromium, Hexavalent	EPA 7196	Aqueous	100mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ ( $\text{NH}_4$ ) $_2$ SO $_4$ buffer	28 Days
Chromium, Hexavalent (subcontract)	EPA 7196	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	30 Days
Cyanide, Total	EPA 9014	Aqueous	125mL	125mL Polyethylene Bottle	Cool to $\leq 6^{\circ}\text{C}$ 1:1 NaOH to pH >8	14 Days
Cyanide, Total	EPA 9014	Solid	15g	4oz Glass Jar w/Teflon liner	Cool to $\leq 6^{\circ}\text{C}$	14 Days

Absolute Resource Associates  
124 Heritage Avenue Unit 16  
Portsmouth, NH 03801  
[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)





**Case Narrative**

**Lab # 58452**

**Sample Receiving and Chain of Custody Discrepancies**

---

Samples were received in acceptable condition, between 0 and 6 degrees C, on ice, and in accordance with sample handling, preservation and integrity guidelines.

As noted on the result page, several VPH samples did not meet the 1:1 +/-25% methanol to soil ratio.

**Calibration**

---

No exceptions noted.

PCB: Quantification is quadratic.

**Method Blank**

---

No exceptions noted.

**Surrogate Recoveries**

---

PCB: The surrogate tetrachloro-m-xylene was above acceptance criteria. Since no targets were detected above the quantitation limit, there is no impact to the data.

**Laboratory Control Sample Results**

---

No exceptions noted.

**Matrix Spike/Matrix Spike Duplicate/Duplicate Results**

---

Not requested for this project.

**Other**

---

VPH: The trap used for VPH analysis is a Tekmar STRATUM Purge Trap 9. The column used for VPH analysis is a Restek Rtx-502.2, 105m, 0.53mmID, and 3um df.

PCB: Sample dilution was required for 58452-005 due to matrix interferences.

**MassDEP Analytical Protocol Certification Form Questions A through I**

---

No explanation is needed for Questions A through I answered in the affirmative.



## **GLOSSARY**

%R	Percent Recovery
BLK	Blank (Method Blank, Preparation Blank)
CCB	Continuing Calibration Blank
CCV	Continuing Calibration Verification
CRM	Certified Reference Material (associated with solid Metals samples)
CRMD	Certified Reference Material Duplicate (associated with solid Metals samples)
Dil'n	Dilution
DL	Detection Limit
DUP	Duplicate
LCS	Laboratory Control Sample
LCSD	Laboratory Control Sample Duplicate
LOD	Limit of Detection
LOQ	Limit of Quantitation
MB	Methanol Blank (associated with solid VOC samples)
MLCS	Methanol Laboratory Control Sample (associated with solid VOC samples)
MLCSD	Methanol Laboratory Control Sample Duplicate (associated with solid VOC samples)
MS	Matrix Spike
MSD	Matrix Spike Duplicate
PB	Preparation Blank
QC	Quality Control
RL	Reporting Limit
RPD	Relative Percent Difference
SUR	Surrogate



124 Heritage Avenue Unit 16  
Portsmouth, NH 03801

[www.absoluteresourceassociates.com](http://www.absoluteresourceassociates.com)



- QC Report -

Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
MA VPH	MB14244	Unadjusted C5-C8 Aliphatics	<	5.0	ug/g					
		Unadjusted C9-C12 Aliphatics	<	5.0	ug/g					
		methyl t-butyl ether (MTBE)	<	0.10	ug/g					
		benzene	<	0.10	ug/g					
		toluene	<	0.10	ug/g					
		ethylbenzene	<	0.10	ug/g					
		m&p-xylenes	<	0.10	ug/g					
		o-xylene	<	0.10	ug/g					
		naphthalene	<	0.25	ug/g					
		C5-C8 Aliphatics	<	5.0	ug/g					
		C9-C12 Aliphatics	<	5.0	ug/g					
		C9-C10 Aromatics	<	5.0	ug/g					
		2,5-dibromotoluene as Aromatic SUR		97	%			70	130	
		2,5-dibromotoluene as Aliphatic SUR		101	%			70	130	
		a,a,a-trifluorotoluene SUR		88	%			70	130	
MA VPH	MLCS14244	Unadjusted C5-C8 Aliphatics		13	ug/g	15	83	70	130	
		Unadjusted C9-C12 Aliphatics		11	ug/g	15	75	70	130	
		methyl t-butyl ether (MTBE)		4.3	ug/g	5	86	70	130	
		benzene		4.7	ug/g	5	93	70	130	
		toluene		4.6	ug/g	5	93	70	130	
		ethylbenzene		4.6	ug/g	5	92	70	130	
		m&p-xylenes		9.3	ug/g	10	93	70	130	
		o-xylene		4.7	ug/g	5	93	70	130	
		naphthalene		5.0	ug/g	5	100	70	130	
		C5-C8 Aliphatics	<	5.0	ug/g			70	130	
		C9-C12 Aliphatics	<	5.0	ug/g			70	130	
		C9-C10 Aromatics	<	5.0	ug/g	5	98	70	130	
		2,5-dibromotoluene as Aromatic SUR		107	%			70	130	
		2,5-dibromotoluene as Aliphatic SUR		110	%			70	130	
		a,a,a-trifluorotoluene SUR		89	%			70	130	
MA VPH	MLCSD14244	Unadjusted C5-C8 Aliphatics		12	ug/g	15	78	70	130	7
		Unadjusted C9-C12 Aliphatics		11	ug/g	15	74	70	130	3
		methyl t-butyl ether (MTBE)		4.2	ug/g	5	85	70	130	2
		benzene		4.5	ug/g	5	91	70	130	3
		toluene		4.5	ug/g	5	91	70	130	2
		ethylbenzene		4.5	ug/g	5	91	70	130	2
		m&p-xylenes		9.2	ug/g	10	92	70	130	2
		o-xylene		4.6	ug/g	5	92	70	130	2
		naphthalene		5.0	ug/g	5	100	70	130	0
		C5-C8 Aliphatics	<	5.0	ug/g			70	130	
		C9-C12 Aliphatics	<	5.0	ug/g			70	130	
		C9-C10 Aromatics	<	5.0	ug/g	5	97	70	130	1
		2,5-dibromotoluene as Aromatic SUR		96	%			70	130	
		2,5-dibromotoluene as Aliphatic SUR		99	%			70	130	
		a,a,a-trifluorotoluene SUR		87	%			70	130	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
MA EPH	BLK14245	naphthalene		<	0.20	ug/g				
		2-methylnaphthalene		<	0.20	ug/g				
		phenanthrene		<	0.20	ug/g				
		acenaphthene		<	0.20	ug/g				
		acenaphthylene		<	0.20	ug/g				
		fluorene		<	0.20	ug/g				
		anthracene		<	0.20	ug/g				
		fluoranthene		<	0.20	ug/g				
		pyrene		<	0.20	ug/g				
		benzo(a)anthracene		<	0.20	ug/g				
		chrysene		<	0.20	ug/g				
		benzo(b)fluoranthene		<	0.20	ug/g				
		benzo(k)fluoranthene		<	0.20	ug/g				
		benzo(a)pyrene		<	0.20	ug/g				
		indeno(1,2,3-cd)pyrene		<	0.20	ug/g				
		dibenzo(a,h)anthracene		<	0.20	ug/g				
		benzo(g,h,i)perylene		<	0.20	ug/g				
		Unadjusted C11-C22 Aromatics		<	20	ug/g				
		C9-C18 Aliphatics		<	20	ug/g				
		C19-C36 Aliphatics		<	20	ug/g				
		C11-C22 Aromatics		<	20	ug/g				
		1-chloro-octadecane SUR		71	%			40	140	
		o-terphenyl SUR		62	%			40	140	
		2-fluorobiphenyl SUR		72	%			40	140	
		2-bromonaphthalene SUR		68	%			40	140	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
MA EPH	LCS14245	naphthalene		4.0	ug/g	6	66	40	140	
		2-methylnaphthalene		4.0	ug/g	6	67	40	140	
		phenanthrene		4.7	ug/g	6	78	40	140	
		acenaphthene		3.8	ug/g	6	63	40	140	
		acenaphthylene		3.6	ug/g	6	59	40	140	
		fluorene		4.0	ug/g	6	67	40	140	
		anthracene		4.5	ug/g	6	75	40	140	
		fluoranthene		4.5	ug/g	6	75	40	140	
		pyrene		4.5	ug/g	6	74	40	140	
		benzo(a)anthracene		4.4	ug/g	6	74	40	140	
		chrysene		4.7	ug/g	6	79	40	140	
		benzo(b)fluoranthene		4.5	ug/g	6	75	40	140	
		benzo(k)fluoranthene		5.3	ug/g	6	89	40	140	
		benzo(a)pyrene		4.7	ug/g	6	78	40	140	
		indeno(1,2,3-cd)pyrene		4.4	ug/g	6	74	40	140	
		dibenzo(a,h)anthracene		4.4	ug/g	6	73	40	140	
		benzo(g,h,i)perylene		3.9	ug/g	6	65	40	140	
		Unadjusted C11-C22 Aromatics		76	ug/g	102	75	40	140	
		C9-C18 Aliphatics	<	20	ug/g	36	52	40	140	
		C19-C36 Aliphatics		41	ug/g	48	85	40	140	
		C11-C22 Aromatics	<	20	ug/g			40	140	
		1-chloro-octadecane SUR		66	%			40	140	
		o-terphenyl SUR		75	%			40	140	
		2-fluorobiphenyl SUR		80	%			40	140	
		2-bromonaphthalene SUR		74	%			40	140	



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit	
MA EPH	LCSD14245	naphthalene		4.0	ug/g	6	67	40	140	2	25
		2-methylnaphthalene		4.1	ug/g	6	69	40	140	3	25
		phenanthrene		4.8	ug/g	6	80	40	140	3	25
		acenaphthene		4.0	ug/g	6	67	40	140	7	25
		acenaphthylene		3.8	ug/g	6	63	40	140	5	25
		fluorene		4.2	ug/g	6	70	40	140	5	25
		anthracene		4.7	ug/g	6	78	40	140	4	25
		fluoranthene		4.8	ug/g	6	80	40	140	6	25
		pyrene		4.5	ug/g	6	75	40	140	0	25
		benzo(a)anthracene		4.5	ug/g	6	75	40	140	2	25
		chrysene		4.8	ug/g	6	80	40	140	2	25
		benzo(b)fluoranthene		4.5	ug/g	6	75	40	140	0	25
		benzo(k)fluoranthene		5.2	ug/g	6	86	40	140	3	25
		benzo(a)pyrene		4.7	ug/g	6	78	40	140	1	25
		indeno(1,2,3-cd)pyrene		4.3	ug/g	6	71	40	140	4	25
		dibenzo(a,h)anthracene		4.1	ug/g	6	69	40	140	6	25
		benzo(g,h,i)perylene		4.0	ug/g	6	67	40	140	3	25
		Unadjusted C11-C22 Aromatics		71	ug/g	102	70	40	140	7	25
		C9-C18 Aliphatics		21	ug/g	36	58	40	140	11	25
		C19-C36 Aliphatics		41	ug/g	48	86	40	140	1	25
		C11-C22 Aromatics	<	20	ug/g			40	140		25
		1-chloro-octadecane SUR		71	%			40	140		
		o-terphenyl SUR		67	%			40	140		
		2-fluorobiphenyl SUR		76	%			40	140		
		2-bromonaphthalene SUR		73	%			40	140		



Method	QC ID	Parameter	Associated Sample	Result	Units	Amt Added	%R	Limits	RPD	RPD Limit
SW3540C8082A	BLK14238	PCB-1016		<	0.17	ug/g				
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260		<	0.17	ug/g				
		tetrachloro-m-xylene SUR			78	%		30	150	
		decachlorobiphenyl SUR			105	%		30	150	
SW3540C8082A	LCS14238	PCB-1016			3.5	ug/g	3.33	104	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			3.4	ug/g	3.33	102	40	140
		tetrachloro-m-xylene SUR			85	%		30	150	
		decachlorobiphenyl SUR			107	%		30	150	
SW3540C8082A	LCSD14238	PCB-1016			3.5	ug/g	3.33	106	40	140
		PCB-1221		<	0.17	ug/g				
		PCB-1232		<	0.17	ug/g				
		PCB-1242		<	0.17	ug/g				
		PCB-1248		<	0.17	ug/g				
		PCB-1254		<	0.17	ug/g				
		PCB-1260			3.3	ug/g	3.33	98	40	140
		tetrachloro-m-xylene SUR			83	%		30	150	
		decachlorobiphenyl SUR			103	%		30	150	



## AROMATIC HYDROCARBON BREAKTHROUGH CALCULATION

Method: MADEP EPH 2019 Rev 2.1

	lcs14245		
	Aliphatic Breakthrough	Acceptance	Date of Analysis
	(%)	Criteria	
naphthalene	0.1%	<5.0%	9/8/2021
2-methylnaphthalene	0.3%	<5.0%	9/8/2021

	lcsd14245		
	Aliphatic Breakthrough	Acceptance	Date of Analysis
	(%)	Criteria	
naphthalene	0.1%	<5.0%	9/8/2021
2-methylnaphthalene	0.2%	<5.0%	9/8/2021







## Sample Receipt Condition Report

58452

## Absolute Resource Associates

Job Number: 30174

Samples Received from: ☐-UPS ☐-FedEx ☐-USPS ☒-Lab Courier ☒-Client Drop-off ☐-  
 Custody Seals - present & intact: ☐-Yes ☐-No ☒-N/A CoC signed: ☒-Yes ☐-No  
 Receipt Temp: 0 °C Samples on ice? ☒-Yes ☐-No ☐-N/A Sampled < 24 hrs ago? ☐-Yes ☒-No  
 PFAS-only real ice? ☐-Yes ☐-No ☒-N/A Any signs of freezing? ☐-Yes ☒-No

Comments:

Preservation / Analysis	Bottle Size/Type & Quantity						Check pH for ALL applicable* samples and document:
HCl	40mL(G)		250mL(P)		500mL(P)	1L(G)	
HNO <sub>3</sub>	125mL(P)		250mL(P)		500mL(P)		
H <sub>2</sub> SO <sub>4</sub>	40mL(G)		60mL(P)		125mL(P)	250mL(P)	500mL(P)
NaOH	125mL(P)		250mL(P)				
(NH <sub>4</sub> ) <sub>2</sub> SO <sub>4</sub>	60mL(P)		125mL(P)		250mL(P)		
ZnAc-NaOH	125mL(P)		250mL(P)				
Trizma	125mL(P)		250mL (P)				
NH <sub>4</sub> Ac	125mL(P)		250mL (P)				
Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	40mL(G)		120mL(P)				
MeOH	20mL(G)		40mL(G)				
None (solid)	2oz(G)		4oz(G)	5	8oz(G)	Syringe	
None (water)	40ml (G)		60mL(P)	6	125mL(P)	250mL(P)	500mL(P)
Mold	Cassette		Bulk		Plate		Tape Lift
Asbestos	Cassette		Bulk				
Lead	Cassette		Bulk		Wipe		

\*pH ✓ by analyst: VOC, PFAS, TOC, O&G  
 Residual Cl not present:  
 ABN625 Pest608  
 Bacteria ResCl ✓ by analyst  
 -05 + -06 are building materials  
 PC Dry applicable (Y) N

Login Review	Yes	No	NA	Comments
Proper lab sample containers/enough volume/correct preservative?	✓			
Analyses marked on COC match bottles received?	✓			
VOC & TOC Water-no headspace?	✓			
VOC Solid-MeOH covers solid, no leaks, Prep Expiration OK?	✓			
PFAS: ARA bottles & samples/FRB same Lot#? QC rec'd, if req'd?			✓	Lot ID#: _____
Bacteria bottles provided by ARA?			✓	
Samples within holding time?	✓			
Immediate tests communicated in writing: NO <sub>3</sub> , NO <sub>2</sub> , O-PO <sub>4</sub> , pH, BOD, Coliform/E. coli (P/A or MPN), Enterococci, Color Surfactants, Turbidity, Odor, CrVI, Ferrous Iron, Dissolved Oxygen, Unpres 624			✓	
Date, time & ID on samples match CoC?	✓			
Rushes communicated to analyst in writing?			✓	
Subcontract note on login board?			✓	
Pesticides EPA 608 pH5-9?			✓	
Compliance samples have no discrepancies/require no flags?			✓	(Or must be rejected)
Log-in Supervisor notified immediately of following items:			✓	Discrepancies, compliance samples (NHDES, MADEP, DoD etc.) or uncommon requests.

Inspected and Received By: 30

Date/Time: 9/11/21 17:16

## Peer Review Checklist

☐ Client ID/Project Manager ☐ On Ice, Temperature OK? ☐ Sample IDs ☐ Analyses in Correctly  
☐ Project Name ☐ PO# (if provided) ☐ Matrix -references  
☐ TAT/rushes communicated ☐ Sub samples sent? Shipping Charge? ☐ Date/Time collected -wastewater methods  
☐ Received Date/Time ☐ Issues noted above communicated? ☐ Short HT's communicated ☐ Notes from CoC in LIMS

Reviewed By: 30 9/11/21

Date: \_\_\_\_\_

Notes: (continue on back as needed)

Initials Date What was sent?  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice  
 Uploaded / PDF \_\_\_\_\_ Report / Data / EDD / Invoice





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106

Tel/Fax: (207) 517-6921 / (207) 517-6922

<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311

Customer ID: CRED25

Customer PO:

Project ID:

**Attention:** Moira Wentworth  
Credere Associates, LLC  
776 Main Street  
Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Tape Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number: Client Sample ID: Sample Location:	622101311-0022 CA-TL-01 Boiler Room	622101311-0023 CA-TL-02 Boys Locker Room	622101311-0024 CA-TL-DUP Boys Locker Room	622101311-0025 CA-TL-03 Boys Locker Hallway	622101311-0026 CA-TL-04 C-1 Entry
Spore Types	Category	Category	Category	Category	Category
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	-	-
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium++	-	-	-	-	-
Cladosporium	-	-	-	-	-
Curvularia	-	-	-	-	-
Epicoccum	-	-	-	-	-
Fusarium++	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	-	-	-	-	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	-	-	-	-	-
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	-	-	-	-	-

**Sample Comment:** 622101311-0022 - None Detected

**Sample Comment:** 622101311-0023 - None Detected

**Sample Comment:** 622101311-0024 - None Detected

**Sample Comment:** 622101311-0025 - None Detected

**Sample Comment:** 622101311-0026 - None Detected

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

\* = Sample contains fruiting structures and/or hyphae associated with the spores.

Samantha Voigt, Laboratory Manager  
or other Approved Signatory

No discernable field blank was submitted with this group of samples.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





# EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106  
 Tel/Fax: (207) 517-6921 / (207) 517-6922  
<http://www.EMSL.com> / [portlandlab@emsl.com](mailto:portlandlab@emsl.com)

EMSL Order: 622101311  
 Customer ID: CRED25  
 Customer PO:  
 Project ID:

**Attention:** Moira Wentworth  
 Credere Associates, LLC  
 776 Main Street  
 Westbrook, ME 04092

**Phone:** (207) 828-1272

**Fax:** (207) 887-1051

**Collected Date:** 08/25/2021

**Received Date:** 08/26/2021

**Analyzed Date:** 09/09/2021

**Project:** Brown School / 21001628

## Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Tape Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number: Client Sample ID: Sample Location:	622101311-0027 CA-TL-05 T1-1 Bath				
<b>Spore Types</b>	<b>Category</b>				
Alternaria (Ulocladium)	-				
Ascospores	-				
Aspergillus/Penicillium	-				
Basidiospores	-				
Bipolaris++	-				
Chaetomium++	-				
Cladosporium	-				
Curvularia	-				
Epicoccum	-				
Fusarium++	-				
Ganoderma	-				
Myxomycetes++	-				
Pithomyces++	-				
Rust	-				
Scopulariopsis/Microascus	-				
Stachybotrys/Memnoniella	-				
Unidentifiable Spores	-				
Zygomycetes	-				
Hyphal Fragment	-				
Insect Fragment	-				
Pollen	-				
Fibrous Particulate	-				

**Sample Comment:** 622101311-0027 - None Detected

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

\* = Sample contains fruiting structures and/or hyphae associated with the spores.

Samantha Voigt, Laboratory Manager  
 or other Approved Signatory

No discernable field blank was submitted with this group of samples.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 09/10/2021 10:59 AM

For information on the fungi listed in this report, please visit the Resources section at [www.emsl.com](http://www.emsl.com)





EMSL ANALYTICAL, INC.  
TESTING LABS • PRODUCTS • TRAINING

## Microbiology Chain of Custody Form

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.  
200 Route 130 North  
Cinnaminson, NJ 08077

PHONE: (800) 220-3675

EMAIL: CinnMicroLab@emsl.com

622101311

If Bill-To is the same as Report-To leave this section blank. Third-party billing requires written authorization.

Customer Information	Customer ID:	Billing ID:
	Company Name: <u>Credere Associates</u>	Company Name: <u>Same</u>
	Contact Name: <u>Maura Wentworth</u>	Billing Contact:
	Street Address: <u>776 Main Street</u>	Street Address:
	City, State, Zip: <u>Westbrook, ME 04092</u> Country: <u>USA</u>	City, State, Zip: Country:
	Phone: <u>207-828-1272 x36</u>	Phone:
Email(s) for Report: <u>mwentworth@credereallc.com</u>	Email(s) for Invoice:	

## Project Information

Project Name/No: <u>Brown School / 21001628</u>	Purchase Order:
EMSL LIMS Project ID: (If applicable, EMSL will provide)	State of Connecticut (CT) must select project location: <input type="checkbox"/> Commercial (Taxable) <input type="checkbox"/> Residential (Non-taxable)
State Samples Collected: <u>MA</u> Zip Code Samples Collected: <u>01950</u>	
Sampled By Name: <u>C. Beahm</u>	Sampled By Signature: <u>[Signature]</u>
	No. of Samples in Shipment: <u>27</u>

Sterile, Sodium Thiosulfate Preserved Bottle Used: ☐ Biocide Used in Source (specify)Public Water Supply Samples: ☐ Note: All results may automatically be reported to DOH if required by State.

Turn-Around-Time (TAT) Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.	
<input type="checkbox"/> 3 Hour	<input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 32* Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input checked="" type="checkbox"/> 2 Week

## MICROBIOLOGY TEST CODES

<b>M001</b> Air-O-Cell	<b>M174</b> MoldSnap	<b>M012</b> <i>Pseudomonas aeruginosa</i> (P/A***)	<b>M115</b> Sewage Screen - Water (P/A***)
<b>M030</b> Micro 5	<b>M032</b> Allergenco-D	<b>M024</b> <i>Pseudomonas aeruginosa</i> (MFT*)	<b>M116</b> Sewage Screen - Water (MPN**)
<b>M041</b> Fungal Direct Examination		<b>M015</b> Heterotrophic Plate Count	<b>M117</b> Sewage Screen - Swab (P/A***)
<b>M169</b> Pollen ID & Enumeration		<b>M017</b> Total Coliform & <i>E. Coli</i> (Colilert P/A***)	<b>M013</b> Sewage Screen - Swab (MFT*)
<b>M280</b> Dust Characterization Level-1		<b>M018</b> Total Coliform & <i>E. Coli</i> (MFT*)	<b>M730</b> Methicillin-resistant <i>Staph. aureus</i> (MRSA)
<b>M281</b> Dust Characterization Level-2		<b>M114</b> Total Coliform & <i>E. Coli</i> Enumeration (Colilert MPN**)	<b>M031</b> Rapid-growing non-TB <i>Mycobacteria</i> Detection & Enumeration
<b>M005</b> Viable Fungi-Air Samples (Genus ID & Count)		<b>M019</b> Fecal Coliform (MFT*)	<b>M014</b> Endotoxin Analysis
<b>M006</b> Viable Fungi-Air Samples (Includes <i>Penicillium</i> , <i>Aspergillus</i> , <i>Cladosporium</i> , <i>Stachybotrys</i> Species ID & Count)		<b>M020</b> Fecal <i>Streptococcus</i> (MFT*)	<b>M044</b> Group Allergen (Cat, Dog, Cockroach, Dust Mite)
<b>M007</b> Culturable Fungi-Surface Samples (Genus ID & Count)		<b>M029</b> <i>Enterococci</i> (MFT*)	<b>M095</b> Bacteroides
<b>M008</b> Culturable Fungi-Surface Samples (Includes <i>Penicillium</i> , <i>Aspergillus</i> , <i>Cladosporium</i> , <i>Stachybotrys</i> Species ID & Count)		<b>M129</b> <i>Enterococci</i> (Enterolert P/A***)	Other - See Analytical Price Guide for Test Code
<b>M009</b> Bacteria Culture Gram Stain & Count		<b>M180</b> Real Time qPCR-ERMI 36 Panel	<b>Legionella Analysis</b> Please use EMSL <i>Legionella</i> COC
<b>M010</b> Bacteria Count & ID - 3 Most Prominent		<b>M025</b> Sewage Screen - Water (MFT*)	
<b>M011</b> Bacteria Count & ID - 5 Most Prominent		*MFT= Membrane Filtration Technique	
		**MPN = Most Probable Number	
		***P/A = Presence/Absence	

Sample #	Sample Location/Description	Sample Type (Matrix)	Potable / Non-Potable (Only for Water)	Test Code	Volume/Area	Date / Time Collected	Temperature (Lab Use Only)
Example: Sample 1	Kitchen	Water	Potable	M017	1,000 ml	1/1/2021 3:30pm	
CA-AIR-01	Boiler Room	Air		M032	150L	8/25/21 1105	
CA-AIR-02	Outside					8/25/21 1105	
CA-AIR-03	Gym/Cafe					8/25/21 1135	
CA-AIR-04	Kitchen					8/25/21 1140	
CA-AIR-05	Boys Locker Room					8/25/21 1155	
CA-AIR-06	Room 14					8/25/21 1225	

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Method of Shipment: <u>Walk in</u>	Sample Condition Upon Receipt:
Relinquished by: <u>[Signature]</u>	Received by: <u>[Signature]</u>
Date/Time: <u>8/26/21 1:55</u>	Date/Time: <u>8/26/21 4:00pm</u>
Relinquished by:	Received by:
Date/Time:	Date/Time:

Controlled Document - COC-34 Micro R13 03/02/2021



AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.







## **APPENDIX F**

### **DATA USABILITY ASSESSMENT**



**Data Usability Assessment (DUA)**  
**Brown School**  
**42 Milk Street, Newburyport, Massachusetts**

In accordance with Sections 310 CMR 40.0017 and 310 CMR 40.0191 of the MCP, a Data Usability Assessment is required to more formally document that data is scientifically valid and defensible, and of a sufficient level of precision and accuracy and completeness to support “Presumptive Certainty”. Pursuant to 310 CMR 40.0191 of the MCP, the analytical data used to support this report was reviewed utilizing procedures outlined in MassDEP’s *Compendium of Quality Assurance/Quality Control (QA/QC) Requirements and Performance Standards for Selected Analytical Methods* (CAM) (WSC-02-320, July 1, 2010). In addition, the data utilized and relied upon in this report was evaluated per the guidance set forth by MassDEP *WSC Policy #07-350 MCP Representativeness Evaluations and Data Usability Assessments of September 19, 2007*.

Credere has reviewed the following laboratory analytical data reports for precision, bias, accuracy, representativeness, comparability, and completeness:

- Absolute Resource Associates Job ID 58452
- Absolute Resource Associates Job ID 58581
- Absolute Resource Associates Job ID 58406

The following samples were included in the above reports and were reviewed as part of this DUA:

Field Sample ID	Laboratory Sample ID
CA-SB-1	58452-001
CA-SB-3	58452-003
CA-PCB-12	58452-005
Trip Blank	58452-007
CA-MW-2	58581-002
Trip Blank	58581-004
CA-PCB-2	58406-2
CA-PCB-4	58406-4
CA-PCB-6	58406-6
CA-PCB-8	58406-8
CA-PCB-10	58406-10
CA-PCB-11	58406-12
CA-PCB-13	58406-14

Field Sample ID	Laboratory Sample ID
CA-SB-2	58452-002
CA-SB-4	58452-004
CA-PCB-14	58452-006
CA-MW-1	58581-001
CA-MW-3	58581-003
CA-PCB-1	58406-1
CA-PCB-3	58406-3
CA-PCB-5	58406-5
CA-PCB-7	58406-7
CA-PCB-9	58406-9
CA-PCB-DUP1	58406-11
CA-PCB-DUP2	58406-13

CA-PCB-DUP1 is a field duplicate for CA-PCB-10  
CA-PCB-DUP2 is a field duplicate for CA-PCB-11

### **Precision**

Precision is a measure of the mutual agreement between concentrations of samples (e.g., duplicates) collected at the same time from the same location. Precision is measured by performing duplicate measurements in the field or laboratory. Precision is expressed in terms of RPD using the following equation:

$$RPD = [(C1-C2) / (C1+C2)/2] \times 100$$





Where:

C1 = The larger of the two concentrations.

C2 = The smaller of the two concentrations.

The following duplicate pairs were assessed:

- CA-PCB-DUP1 was collected as a PCB building material duplicate for CA-PCB-10
- CA-PCB-DUP2 was collected as a PCB building material duplicate for CA-PCB-11

Analyte results were either non-detect (for at least one sample), less than 5 times the laboratory reporting limit (for at least one sample), or the calculated RPDs were less than the acceptable limit of 50% for air and 30% for aqueous samples, with the exception of the following:

- The RPD between the duplicate pair CA-PCB-DUP1 and CA-PCB-10 was 138% for the caulk sample. These results have been qualified as estimated. As one result is below the criteria of 1 mg/kg and one is above, both results are considered to exceed 1 mg/kg for decision making purposes.

### **Bias**

Bias is the systematic or persistent distortion of a measurement process that causes errors in one direction. Bias assessments are made using personnel, equipment, and spiking materials or reference materials as independent as possible from those used in the calibration of the measurement system. Bias assessments were based on the analysis of spiked samples so that the effect of the matrix on recovery is incorporated into the assessment. A documented spiking protocol and consistency in following that protocol are important in obtaining meaningful data quality estimates.

The laboratory provides quality control non-conformance reports that indicate if LCS/LCSD and had low, failing, or high recoveries, and if the sample result was affected. Likewise, the laboratory reports any compounds that had failing RPDs in the LCS/LCSD pair. This indicates the percent difference between the laboratory sample and its duplicate or the spike and its duplicate.

No laboratory non-conformances that would indicate bias were observed.

### **Accuracy**

Accuracy is a statistical measurement of correctness and includes components of random error (variability due to imprecision) and systemic error. It, therefore, reflects the total error associated with a measurement. A measurement is accurate when the value reported does not differ from the true value or known concentration of the spike or standard. Surrogate compound recoveries are also used to assess accuracy and method performance for each sample analyzed. Analysis of performance evaluation samples are also used to provide additional information for assessing the accuracy of the analytical data being produced. Both accuracy and precision are calculated for each analytical batch, and the associated sample results are interpreted by considering these specific measurements. No accuracy non-conformances were identified except for the following:



- The surrogate tetrachloro-m-xylene was above the upper limit for CA-PCB-12; however, since this would indicate a high bias and the results were below the reporting limits, data is not considered impacted.
- The surrogates for CA-PCB-3 and CA-PCB-13 were diluted out of range due to elevated PCB concentrations in the parent sample. Surrogates cannot be used to assess the accuracy for these samples. Since the concentration is well above the comparison criteria of 50 mg/kg for CA-PCB-3 and well below 50 mg/kg but well above 1 mg/kg for CA-PCB-13, the results are considered usable.

### **Representativeness**

Sample representativeness was assessed through an analysis of the blank results. The concentrations and frequencies of target analytes detected in blanks provide an indication of data representativeness. The five times and ten times rules were used to eliminate potential false positive results indicated by the blank data. Regulatory criteria were considered when using the five- and ten-times rule to avoid elevation of the reporting limit above the criteria for certain compounds. There were no blank non-conformances encountered during review of the data.

Sample representativeness was also assessed through an evaluation of the sample results compared to the sample design as specified in the SSQAPP to determine if the results are representative of the environment from which the samples were collected. No blank nonconformances were identified.

### **Comparability**

Comparability is the confidence with which one data set can be compared to another data set (i.e., how well the data can be reproduced). The objective for this quality assurance/quality control (QA/QC) program is to produce data with the greatest possible degree of comparability. Comparability was achieved by using standard methods for sampling and analysis, reporting data in standard units, normalizing results to standard conditions and using standard and comprehensive reporting formats. Complete field documentation was used, including standardized data collection forms to support the assessment of comparability between data sets.

### **Completeness**

Completeness is calculated by comparing the number of samples successfully analyzed to the number of samples collected. The goal for completeness is 95 percent. The completeness for this project was 100 percent, as there were no samples that were not analyzed due to holding time violations, samples spilled or broken, or any other reason.

### **Presumptive Certainty**

In accordance with WSC-02-320, laboratory data sets that meet Presumptive Certainty status will satisfy the QA/QC requirements set forth in 310 CMR 40.0017 and 40.0191 “regarding the scientific defensibility, precision and accuracy, and reporting of analytical data” and may be used in data usability and representativeness assessments consistent with the guidance described in the MassDEP Policy #WSC-07-350. In accordance with the WSC #07-350, CAM compliant data are



of known accuracy, precision and sensitivity and therefore should not require an Analytical Data Usability Assessment. The CAM provides the regulated community with a compilation of recommended laboratory procedures (MCP Analytical Methods) for the most common constituents of concern that may be used to support MCP Response Actions. These procedures include detailed method-specific QC requirements and performance standards for achievement of a Presumptive Certainty status.

Presumptive certainty as defined in WSC-02-320 includes the following:

- Compliance with all CAM Requirements.
- Responded “Yes” to Questions A through F on the MassDEP Analytical Protocol Certification Form.
- Responded either “Yes” or “No” to Questions G through I on the MassDEP Analytical Protocol Certification Form.
- Signed and dated MassDEP Analytical Protocol Certification Form.

The laboratory reports for the data collected during this reporting period met Presumptive Certainty. These reports were reviewed for usability and determined acceptable for use in any risk characterization. No data was excluded based on the usability assessment. Specifically, where responses to Questions A through F result in a “No” response, individual cases were reviewed and corrective action was considered acceptable as reported in the case narrative.

### **Data Usability Assessment Conclusions**

The laboratory reports for all sampling events during this reporting period met Presumptive Certainty with limited exception to Question G that are acceptably covered in the case narrative. These reports were reviewed for usability and determined acceptable for use in the risk characterization. Possible data usability issues with a potential to affect data quality as outlined in the laboratory case narratives were review. While multiple methodology notations were outlined, with some minor effects resulting in J qualification, no major issues were reported that would make the data unusable. No QA/QC issues were reported by the laboratory or resulting from field operations that will affect data usability for MCP decision-making. No data were discarded/rejected due to QA/QC issues.