123 State Street, Newburyport

Continued Meeting on Application for

Demolition Permit

October 8, 2020



123 State Street, Newburyport Recap of Prior Meeting and Updates

Recap of Prior Meeting and Updates

- Commission passed motion that the form of the proposed rear addition was acceptable as shown on the plans presented.
- Commission requested additional details/revisions to plans including:
 - Details regarding items to be refurbished on original structure;
 - Skirting along two side bump outs;
 - Notations on the reuse of arched windows in rear of structure; and
 - Details regarding the siding.
- Above have all been added to the plans.
- Notably, Applicant is now using cedar clapboard with 4-inch reveal and adding corner boards.

Elevation Legend

Area of existing exterior wall (to remain)

Area of existing exterior wall (to be removed)

NOTE:

All Second Empire Cottage detailing to remain

Existing Exterior Wall Elevation Square Footage

<u> </u>	,		
	Area to remain	Area to be removed	Total Area
Front (West) Elevation	1,046 SF	0 SF	1,046 SF
Side (South) Elevation	891 SF	368 SF	1,259 SF
Rear (East) Elevation	792 SF	570 SF	1,362 SF
Side (North) Elevation	972 SF	288 SF	1,260 SF
Total	3,701 SF (75%)	1,226 SF (25%)	4,927 SF

NOTE:

- Roof planes not included in area calculations
- Refer to Typical Dormer Square Footage for more info.

Typical Dormer Square Footage

Dormer cheek wall (single wall) = 3 square feet

Total number of dormer cheek walls = 20 (x) 3 SF per wall = 60 total square feet

Total cheek walls (to be removed) = 4 walls (x) 3 SF per wall = 12 total square feet Total cheek walls (to remain) = 16 walls (x) 3 SF per wall = 48 total square feet





Existing Exterior Elevations

Scale: 1/8" = 1'-0"

Crane Properties

Elevation Legend

Area of existing exterior wall (to remain)

Area of existing exterior wall (to be removed)

NOTE:

All Second Empire Cottage detailing to remain

Existing Exterior Wall Elevation Square Footage Area to remain Area to be removed Total Area Front (West) Elevation 1,046 SF 0 SF 1,046 SF Side (South) Elevation 891 SF 368 SF 1,259 SF Rear (East) Elevation 792 SF 570 SF 1,362 SF

288 SF

1,226 SF (25%)

1,260 SF

4,927 SF

Total NOTE:

Side (North) Elevation

- Roof planes not included in area calculations
- Refer to Typical Dormer Square Footage for more info.

972 SF

3,701 SF (75%)

Typical Dormer Square Footage

Dormer cheek wall (single wall) = 3 square feet

Total number of dormer cheek walls = 20 (x) 3 SF per wall = 60 total square feet

Total cheek walls (to be removed) = 4 walls (x) 3 SF per wall = 12 total square feet Total cheek walls (to remain) = 16 walls (x) 3 SF per wall = 48 total square feet





Existing Exterior Elevations
Scale: 1/8" = 1'-0"

Crane Properties

Proposed Work for Second Empire Restoration:

- 1. All existing Second Empire Architectural Details to remain unless otherwise noted.
- 2. All existing Second Empire Architectural Woodwork is to be stripped and refinished, repaired if needed, or replaced in kind if deemed unrepairable in the field.

Existing Architectural Woodwork will include:

- Existing Roof edge, with internal gutter
- Existing Dormers: Arched roof edge trim, decorative corner bracket and panel infill
- Existing Frieze: Frieze board & decorative brackets and wood moldings (shadow board)
- Front Porch: roof edge, columns with decorative bracket detail, and railings
- All existing Second Empire window/door casings & sills are to remain unless noted on plans.
- 3. Existing Roofing
 - Existing slate roof to remain. The existing slate tile has been previously painted. The paint is to be stripped and the slate returned to its natural color. Individual tiles to be repair if needed, or replaced in kind if missing.
 - The existing arched dormer roof to be cleaned and inspected, and repaired if needed.
 - The existing low pitched roofs including Main roof, and single story bump out, is to be inspected, and repaired if need.

- 4. All replacement windows, and new windows, to be the Marvin Elevate Collection with simulated divided lights with 2/2 pattern to match Second Empire Cottage window style
- 5. Siding: Existing asbestos siding to be removed entirely and be replaced with new Cedar clapboard siding with 4" exposure, and 1x6 composite (Boral) corner boards.


Existing Mansard Roof
roof edge to be refinished or repair if needed
existing slate to remain - paint to be stripped
refer to notes regarding Architectural
Woodwork for roof edge for more info.



savoie nolan

Crane Properties


Refer to Proposed Front Elevation for typical notes regarding the proposed work for Second Empire Restoration:






September 30, 2020

Refer to Proposed Front Elevation for typical notes regarding the proposed work for Second Empire Restoration:





Refer to Proposed Front Elevation for typical notes regarding the proposed work for Second Empire Restoration:





September 30, 2020