

This is a corner stone under the north east corner





This is a corner stone under the north west corner





This is one of three beams that run left to right or north and south that have been altered and supported inside the house



This is a center beam that was damaged by moisture penetrating through from the outside 25 years ago and had to have supports put in under the interior and exterior beams.





This is a center beam that was cut in order to put in a set of stairs 60 years ago.

