## Massachusetts Cultural Resource Information System

## **Scanned Record Cover Page**

Inventory No: NWB.608

**Historic Name:** 

**Common Name:** 

Address: 315 High St

City/Town: Newburyport

Village/Neighborhood:

**Local No:** 254; 42-48

Year Constructed: R 1790

Architect(s):

Architectural Style(s): Federal

Use(s): Multiple Family Dwelling House; Single Family Dwelling


House

Significance: Architecture

Area(s): NWB.A: High Street District

NWB.L: Newburyport Historic District

**Designation(s):** Nat'l Register District (8/2/1984)



The Massachusetts Historical Commission (MHC) has converted this paper record to digital format as part of ongoing projects to scan records of the Inventory of Historic Assets of the Commonwealth and National Register of Historic Places nominations for Massachusetts. Efforts are ongoing and not all inventory or National Register records related to this resource may be available in digital format at this time.

The MACRIS database and scanned files are highly dynamic; new information is added daily and both database records and related scanned files may be updated as new information is incorporated into MHC files. Users should note that there may be a considerable lag time between the receipt of new or updated records by MHC and the appearance of related information in MACRIS. Users should also note that not all source materials for the MACRIS database are made available as scanned images. Users may consult the records, files and maps available in MHC's public research area at its offices at the State Archives Building, 220 Morrissey Boulevard, Boston, open M-F, 9-5.

Users of this digital material acknowledge that they have read and understood the MACRIS Information and Disclaimer (http://mhc-macris.net/macrisdisclaimer.htm)

Data available via the MACRIS web interface, and associated scanned files are for information purposes only. THE ACT OF CHECKING THIS DATABASE AND ASSOCIATED SCANNED FILES DOES NOT SUBSTITUTE FOR COMPLIANCE WITH APPLICABLE LOCAL, STATE OR FEDERAL LAWS AND REGULATIONS. IF YOU ARE REPRESENTING A DEVELOPER AND/OR A PROPOSED PROJECT THAT WILL REQUIRE A PERMIT, LICENSE OR FUNDING FROM ANY STATE OR FEDERAL AGENCY YOU MUST SUBMIT A PROJECT NOTIFICATION FORM TO MHC FOR MHC'S REVIEW AND COMMENT. You can obtain a copy of a PNF through the MHC web site <a href="https://www.sec.state.ma.us/mhc">(www.sec.state.ma.us/mhc)</a> under the subject heading "MHC Forms."

Commonwealth of Massachusetts
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Massachusetts 02125
www.sec.state.ma.us/mhc

This file was accessed on:

Tuesday, April 22, 2014 at 10:43 AM

IMPORTANCE of site to area: Grad Little None SITE endangered by  IMPORTANCE of site to area: Grad Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material;  WALL COVER: Wood Color Structure on map below  ROOF: didge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Fron/Side Centered Double Features:  Windows: Spacing: degular/Irregular Identical/Varied Corners Plain Pilasters Quoins Obscured  OUTBUILDINGS  5. Indicate location of structure on map below  Area 132  Photo C  Property has Type feet frontage on street Recorder Latting For Latting	JUL • 69 •	NW	B. 608 Qua Q (254)			
Boston Street 3/5 August 15: ant to: name lon    Interpretation    Importance of site to area: Great Little None    Importance of Date    Importance of D			Town Herbury point			
original Use present Use  Ty Present Owner Gor Hamman  ation Date Style  Ty Source of Date  WIN/City Architect  Deteriorated Moved Altered  IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Stoke Stoke Other  STORIES: 1 2 3 4 CHIMNEYS: 1 2 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard  Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  5. Indicate location of structure on map below  Recorder Allow Material  LANDSCAPING  6. Footage of structure from street Property has 17% feet frontage on street  Recorder Allow Material  For Land Sludd Comm.  Photo	62.		Street 3315 Kich 3			
with the side)  Present Use  Ty Present Owner Gor Hamman  Atton Date Style  Ty Source of Date  Win/City Architect  Deteriorated Moved Altered  IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low  WALL COVER: Wood  STORIES: 12 3 4 CHIMNEYS: 12 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency  PORCHES: 12 3 4 Portico Balcony  Recessed  ROOF: Ridge Gambrel Flat Hip Mansard  Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Fron/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Fronl/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  5. Indicate location of structure on map below  Recorder  Recorder  Recorder  Recorder  Recorder  Property has 17 feet frontage on street  Recorder  Recorder  Photo  Photo			Name 0565-Nub			
The present Use  The present Use  The present Owner Low Hamman  Attachments: Wings Ell Shed Dependency  Porches: 12 3 4 Portico Balcony  Porches: 12 3 4 Portico Balcony  FACADE: Gable End: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  Area 132  Photo  Property has The feat front Structure from street To Property has The Structure on map below  Area 132  Photo  Property has The Administration of Structure from street To Property has The Structure on street Recorder Agents of Structure from street To Property has The Structure on street Recorder Agents of Structure from street To Property has The Structure from street To Property has The Structure on street Recorder Agents of Structure from street To Property has The Study Complex Property Has The Study Comp			Original Use Taxeline			
ation Date Style  y Source of Date  wn/City Architect  Deteriorated Moved Altered  IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Stroke Stone Other  STORIES: 1 2 3 4 CHIMNEYS: 1 2 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell) Shed Dependency Simple/Complex  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard  Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  5. Indicate location of structure on map below  Recorder Alman Ambreta Simple/Complex Ornament  For Lian Slaud Som.  Property has 1/7 feet frontage on street  Recorder Alman Ambreta Simple/Complex Ornament  For Lian Slaud Som.			Present Use			
WALL COVER: Wood  STORIES: 12 3 4 CHIMNEYS: 12 3 4  ATTACHMENTS: Wings Ell) Shed Dependency  PORCHES: 12 3 4 Portico Balcony  Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  OUTBUILDINGS  LANDSCAPING  ANDEL OF AUGULA Architect  Wendows: Source of Date  wn/City Architect  Deteriorated Moved Altered  Waltered  4. DESCRIPTION  Material:  Brick Stone Other  Simple/Complex  Simple/Complex  Recessed  Recessed  Recessed  Roof: Ridge Gambrel Flat Hip Mansard  Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Cornerst Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  Recorder  Recorder  Recorder  Recorder  Recorder  Recorder  Photo  Photo		су	Present Owner Lev Hannan			
IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Brick Stone Other  STORIES: 1(2) 3 4 CHIMNEYS: 1(2) 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: (1) 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners Plain Pilasters Quoins Obscured  OUTBUILDINGS LANDSCAPING  5. Indicate location of structure on map below 6. Footage of structure from street / Property has fy feet frontage on street  Recorder Recorder  Recorder Plain Pilasters Quoins Obscured  Recorder Recorder Recorder  Property has fy feet frontage on street  Recorder Recorder Recorder  Property has fy feet frontage on street  Recorder Recorder Recorder		ation	DateStyle			
IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material: WALL COVER: Wood STORIES: 12 3 4 CHIMNEYS: 12 3 4 Center End Cluster Elaborate Irregular ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex PORCHES: 12 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament Entrance: Front/Side Centered Double Features: Windows: Spacing: Regular/Irregular Identical/Varied Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS LANDSCAPING  5. Indicate location of structure on map below 6. Footage of structure from street / Ornament Recorder Recorde		ıy	Source of Date			
IMPORTANCE of site to area: Great Little None SITE endangered by  4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Brick Stone Other  STORIES: 1 2 3 4 CHIMNEYS: 1 2 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS LANDSCAPING  5. Indicate location of structure on map below 6. Footage of structure from street / Property has 1/5 feet frontage on street  Recorder Asymmetry  Recorder For Study Simple/Complex Ornament  Recorder Asymmetry  Recorder Asymmetry  For Study Simple/Complex Ornament  Recorder Asymmetry  Recorder Asymmetry  Recorder Asymmetry  Recorder Asymmetry  Recorder Asymmetry  Property has 1/5 feet frontage on street  Recorder Asymmetry  R		wn/City	Architect			
4. DESCRIPTION  FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Brick Stone Other  STORIES: 1 2 3 4 CHIMNEYS: 1 2 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  OUTBUILDINGS  5. Indicate location of structure on map below  6. Footage of structure/from street // Property has 1/5 feet frontage on street  Recorder  For Material:  MALL COVER: Wood Brick Stone Other  Simple/Complex  Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  OUTBUILDINGS  5. Indicate location of structure on map below  6. Footage of structure/from street // Property has 1/5 feet frontage on street  Recorder  For Material:  Photo	o, compilion, paccion con 1	Deteriorated	Moved Altered			
FOUNDATION/BASEMENT: High Regular Low Material:  WALL COVER: Wood Called Profession Brick Stone Other  STORIES: 1(2) 3 4 CHIMNEYS: 1(2) 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: 1) 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied Corners Plain Pilasters Quoins Obscured  OUTBUILDINGS LANDSCAPING  5. Indicate location of structure on map below 6. Footage of structure from street / Property has 1/2 feet frontage on street  Recorder Recorder Recorder Photo	IMPORTANCE of site to area: Great Little None SITE endangered by					
WALL COVER: Wood  STORIES: 123 4 CHIMNEYS: 123 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency  PORCHES: 1)2 3 4 Portico Balcony  ROOF: Ridge Gambrel Flat Hip Mansard  Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  5. Indicate location of structure on map below  6. Footage of structure/from street  Property has 175 feet frontage on street  Recorder  For Man Sludd Complex  Photo	4. DESCRIPTION					
STORIES: 1 2 3 4 CHIMNEYS: 1 2 3 4 Center End Cluster Elaborate Irregular  ATTACHMENTS: Wings Ell Shed Dependency  PORCHES: 1 2 3 4 Portico Balcony  Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  5. Indicate location of structure on map below  Recorder  Recorder  For  Recorder  Photo  Photo  Photo	FOUNDATION/BASEMENT: High Regular Low Material: / Such dans					
ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  5. Indicate location of structure on map below  Recorder  Recorder  For Landscape on street  Recorder  Photo	WALL COVER: Wood asked Sheet Brick Stone Other					
ATTACHMENTS: Wings Ell Shed Dependency Simple/Complex  PORCHES: 1 2 3 4 Portico Balcony Recessed  ROOF: Ridge Gambrel Flat Hip Mansard						
ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork  FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  5. Indicate location of structure on map below  Recorder  Recorder  Recorder  Property has 75 feet frontage on street  Recorder  Photo	ATTACHMENTS: Wings Ell Shed De	ependency				
FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament  Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  Jany LANDSCAPING  5. Indicate location of structure on map below  Recorder  Recorder  Property has 175 feet frontage on street  Recorder  Photo	PORCHES: 1)2 3 4 Portico Balc	eony	Recessed			
Entrance: Front/Side Centered Double Features:  Windows: Spacing: Regular/Irregular Identical/Varied						
Windows: Spacing: Regular/Irregular Identical/Varied  Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  Sange  LANDSCAPING  6. Footage of structure from street / O Property has 1/5 feet frontage on street  Recorder  Recorder  For Aud Shud Com.	FACADE: Gable End: Front/Side Symmetrical/Asymmetrical Simple/Complex Ornament					
Corners: Plain Pilasters Quoins Obscured  OUTBUILDINGS  LANDSCAPING  5. Indicate location of structure on map below Property has 1/2 feet frontage on street  Recorder  For Audi Sudday  Photo Photo	Entrance: Front/Side Centered Double Features:					
OUTBUILDINGS  Sarage  LANDSCAPING  5. Indicate location of structure on map below  Property has 1/5 feet frontage on street  Recorder  For And Sludy Com.  Photo  Photo	Windows: Spacing: Regular/Irregular Identical/Varied 6 000 6					
5. Indicate location of structure on map below  Brooks 132  6. Footage of structure from street  Property has 75 feet frontage on street  Recorder Sludy Com.  Photo	Corners Plain Pilasters Quoins C	Obscured	0.			
5. Indicate location of structure on map below  Brooks 132  6. Footage of structure from street  Property has 75 feet frontage on street  Recorder Sludy Com.  Photo	OUTBUILDINGS Sarage		LANDSCAPING Fay			
Recorder Educat to Burks  For Aust Study Com.  Area 132 Photo 4			Footage of structure from street /0			
Kyrstr For Kist Study Com.  Area 132 Photo 6	Brodie C/2 1	D	C1 1 4/ B 1			
Area 132 Photo 4	- K. I ST		N' T OTO P			
	12	0				
	Mar VI	P.	noto			

NOTE: Recorder should obtain written permission from Commission or sponsoring organization before using this form. (See Reverse Side)

FOR USE WITH IMP	PORTANT STRUCTURES (In	ndicate any interior features of not	
Fireplace	709178		
Stairway			
Other			
113 112 12 1 EN	Present Owner 2 20		
		MPORTANCE OF SITE (Refer and	
on theme circled	on front of form)	Military Affairs Religion/Philosophy	Education Government
	Architect		
	one SITE endangered by		
REFERENCE (When		ined? What book, records, etc.)	
	Velomia) Lagromanya (V		
		on Side Centered Double Fortun	
		n) Filastors Quoins Obscured	
BIBLIOGRAPHY	LANDSCAPING ALL		
	Recorder 28 24 Years		
		281 - A	
		N FOW	
Original Owner:	Pook Number Doge	- 262 / 841	Pagistry of Doods
Deed Information: 1	Book Number Page	-acomo anona-la	Registry of Deeds