



The above photo is a panorama shot of a large portion of the unpermitted landscaping done on the northern end of the property. The arrows indicate three of the large stones present. The below photo shows an aerial photo from the spring of 2020 in which several of the large stones present can be seen (circles).





The above photo shows the imitation stone facing added to the existing concrete blocks.

6.5-28. Special Provisions for the Barrier Beach

B. Specific performance standards for the Barrier Beach are:

12. Construction or alteration of any coastal engineering structures shall require review and approval by the Conservation Commission.



The above two photos show the top of one section of the stone facing connected to the blocks by a line of concrete.



The above photo shows the demolished garage foundation.