

Cushing House

Restoration and Reconstruction of Architectural Elements



Museum of Old Newbury January 2022

Project Overview

This three phased project will address the exterior elements of the cornice moldings on each elevation of the Cushing House, to include:

- Crown, rope band, bead, and dentil moldings
- Gutters
- Frieze board trim blocks
- Soffit and fascia trim
- Shutters

Project Overview

- Phase one will include two facades of the Cushing House
- Elements will be custom milled to match the originals
- Shutters will be reconstructed to match the originals on the north elevation. Salvaged shutters will be restored to replace severely damaged ones.

Garden Side Elevation



Museum of Old Newbury January 2022

Salvaged Fragments



- Many of the elements are unstable and cause a safety hazard to those visiting the museum and gardens . This is true of both the cornice details and the shutters.

Details of rotted elements




Museum of Old Newbury January 2022

North elevation



Museum of Old Newbury January 2022

East elevation



Museum of Old Newbury January 2022

North, east, and west elevations showing shutter damage

